

Final Report

Department of National Defence

DESIGNATED SUBSTANCES SURVEY

Building A-243

17 Hangar Road, Borden, Ontario

DCC Project: BN300075

Contract: KN75955

March 23, 2022

Arcadis Project: 30094312

DESIGNATED SUBSTANCES SURVEY



Viraj Daruwala

Occupational Hygiene Specialist



Paul Smith, B. Sc., IHT
Project Manager



Wayne J. Cormack, M.Eng., CIH
Senior Consultant

Building A-243
17 Hangar Road
Borden, Ontario

Prepared for:
Department of National Defence

DCC Project: BN300075
Contract: KN75955

Prepared by:
Arcadis Canada Inc.
121 Granton Drive, Suite 12
Richmond Hill, Ontario L4B 3N4
Tel 905 764.9380

Our Ref.:
30094312

Date:
March 23, 2022

This document is intended only for the use of the individual or entity for which it was prepared and may contain information that is privileged, confidential and exempt from disclosure under applicable law. Any dissemination, distribution or copying of this document is strictly prohibited.

EXECUTIVE SUMMARY

Arcadis Canada Inc. (Arcadis) was retained by Defence Construction Canada (DCC) on behalf of the Department of National Defence (DND) to conduct a designated substances survey at Building A-243, located at 17 Hanger Road, Borden, Ontario.

The objective of the project was to conduct a designated substances survey to assist DND in meeting their obligations to manage designated substances and hazardous materials as required by DND/CF Asbestos Management Directive (2007) and COHS Regulations Part X, Division II. DND also references Ontario Regulation 278/05 – *Asbestos in Construction Projects and in Buildings and Repair Operations* and the Ontario Regulation 490/09 – Designated Substances.

Building A-243 is a refinishing facility which includes various offices, classrooms and fabrication rooms. It is a two-storey, rectangular structure with a gross floor area of 1393.55 m², flat roof and fixed windows. It was constructed in 1985. There is also a Paints, Oils and Lubricants (POL) Shed, which is part of the main building.

Table ES-1 Summary of Designated Substances and Hazardous Materials

| Hazardous Material or Designated Substance | Description of Homogenous Material | Concentration | Location | Estimated Quantity | Condition | Accessibility | Potential Release of Fibers | Action Level | Abatement Requirements | Notes |
|--|--|---------------|-------------------------|--------------------|-----------|---------------|-----------------------------|--------------|------------------------|-------|
| Potential asbestos-containing materials | Various building materials ⁽¹⁾ | N/A | Throughout the building | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| Silica | Various building materials ⁽²⁾ | N/A | Throughout the building | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| PCBs | T12 light ballasts (to be confirmed by electrician at time of removal) | N/A | Room 203 | N/A | N/A | N/A | N/A | N/A | N/A | N/A |
| ODSs | Wall-mounted air conditioners | N/A | Room 101 | One | N/A | N/A | N/A | N/A | N/A | N/A |
| ODSs | Window-mounted air conditioners | N/A | Rooms 102 and 105 | Two | N/A | N/A | N/A | N/A | N/A | N/A |
| ODSs | Drink fridge | N/A | Room 202 | One | N/A | N/A | N/A | N/A | N/A | N/A |
| ODSs | Mini-fridge | N/A | Room 102 | One | N/A | N/A | N/A | N/A | N/A | N/A |
| ODSs | Ceiling-mounted air conditioner | N/A | Room 205 | One | N/A | N/A | N/A | N/A | N/A | N/A |
| Mould | 2'x4' ceiling tiles | N/A | Room 205 | N/A | N/A | N/A | N/A | N/A | N/A | N/A |

NOTES:

- (1) Potential asbestos-containing materials observed in the subject included boiler insulation, ceramic floor tile grout and mortar beds, exterior window caulking and roofing materials.
- (2) Materials observed in the subject building which should be considered to contain silica included concrete, concrete blocks, brick, mortar, drywall, drywall joint compound, ceramic floor tile grout and mortar beds.

CONTENTS

| | |
|--|------|
| EXECUTIVE SUMMARY | ES-1 |
| ACRONYMS AND ABBREVIATIONS | AC-1 |
| 1 INTRODUCTION | 1-1 |
| 1.1 Scope of Work..... | 1-1 |
| 1.2 Building Summary Information | 1-2 |
| 1.3 Summary of Past Designated Substances Survey Reporting | 1-2 |
| 2 BACKGROUND INFORMATION ON DESIGNATED SUBSTANCES AND HAZARDOUS MATERIALS | 2-1 |
| 2.1 Asbestos..... | 2-3 |
| 2.1.1 Provincial Government Requirements | 2-3 |
| 2.1.2 Federal Government Requirements – Canada Occupational Health and Safety Regulations- Hazardous | 2-4 |
| 2.1.3 Federal Government Requirements – National Joint Council Directive | 2-4 |
| 2.1.4 DND Asbestos Management Directive | 2-5 |
| 2.2 Lead | 2-5 |
| 2.3 Mercury | 2-6 |
| 2.4 Silica | 2-6 |
| 2.5 Other Designated Substances | 2-7 |
| 2.6 PCBs | 2-8 |
| 2.7 Urea Formaldehyde Foam Insulation (UFFI) | 2-9 |
| 2.8 Ozone-Depleting Substances and Other Halocarbons | 2-9 |
| 2.9 Biological Hazards..... | 2-10 |
| 2.9.1 Mould | 2-10 |
| 2.9.2 Animal Droppings..... | 2-10 |
| 2.9.3 Raccoon Feces | 2-11 |
| 2.9.4 Mouse Droppings | 2-11 |
| 3 METHODOLOGY | 3-1 |
| 3.1 Asbestos..... | 3-1 |
| 3.2 Lead | 3-2 |

| | | |
|-----|---|-----|
| 3.3 | Mercury | 3-2 |
| 3.4 | Silica | 3-2 |
| 3.5 | Other Designated Substances and Hazardous Materials | 3-2 |
| 3.6 | PCBs | 3-3 |
| 3.7 | Urea Formaldehyde Foam Insulation | 3-3 |
| 3.8 | Ozone-Depleting Substances and Other Halocarbons | 3-3 |
| 3.9 | Biological Hazards | 3-3 |
| 4 | DISCUSSIONS AND SUMMARY OF RESULTS | 4-1 |
| 4.1 | Asbestos | 4-1 |
| 4.2 | Lead | 4-3 |
| 4.3 | Mercury | 4-4 |
| 4.4 | Silica | 4-4 |
| 4.5 | Other Designated Substances and Hazardous Materials | 4-4 |
| 4.6 | PCBs | 4-4 |
| 4.7 | Urea Formaldehyde Foam Insulation (UFFI) | 4-5 |
| 4.8 | Ozone-Depleting Substances and Other Halocarbons | 4-5 |
| 4.9 | Biological Hazards | 4-5 |
| 5 | CONCLUSIONS AND RECOMMENDATIONS | 5-1 |
| 5.1 | Ongoing Management | 5-1 |
| 5.2 | Construction Projects | 5-1 |
| 6 | LIMITATIONS AND SERVICE CONSTRAINTS | 6-1 |
| 7 | REFERENCES | 7-1 |

TABLES

| | |
|--|------|
| Table ES-1 Summary of Designated Substances and Hazardous Materials..... | ES-2 |
| Table 3.1 Bulk Material Samples (From O.Reg. 278/05) | 3-1 |
| Table 4.1 Summary of Materials Sampled and Confirmed to be Non-Asbestos-Containing – Building A - 243 | 4-2 |
| Table 4.2 Surface Coating – Sampling Summary – Building A - 243 | 4-3 |
| Table 4.3 Summary of Rooms with Similar Surface Coatings – Building A - 243..... | 4-3 |

APPENDICES

| | |
|------------|---|
| Appendix A | Floor Plans |
| Appendix B | Laboratory Reports |
| Appendix C | Summary of Results of Analyses of Bulk Samples for Asbestos Content – Building A - 243 |
| Appendix D | Photographs |
| Appendix E | Asbestos Condition Assessment and Response Chart |
| Appendix F | MOL – Sample List of Suspect Asbestos-Containing Building Materials |

ACRONYMS AND ABBREVIATIONS

| | |
|---------|---|
| ACM | Asbestos-Containing Material |
| Arcadis | Arcadis Canada Inc. |
| CLC | Canada Labour Code |
| CAF | Canadian Armed Forces |
| COHSR | Canada Occupational Health and Safety Regulations |
| DCC | Defence Construction Canada |
| DND | Department of National Defence |
| DSHMS | Designated Substances and Hazardous Materials Survey |
| HWH | Hot Water Heating |
| MOL | Ministry of Labour |
| OEL | Occupational Exposure Limit |
| OHSA | Occupational Health and Safety Act |
| OSHA | United States Occupational Health and Safety Administration |
| PCBs | Polychlorinated Biphenyls |
| PLM | Polarized Light Microscopy |
| POL | Paints, Oils and Lubricants |
| TEM | Transmission Electron Microscopy |
| UFFI | Urea Formaldehyde Foam Insulation |
| USEPA | United States Environmental Protection Agency |

1 INTRODUCTION

Arcadis Canada Inc. (Arcadis) was retained by Defence Construction Canada (DCC) on behalf of the Department of National Defence (DND) to conduct a designated substances survey at Building A-243, located at 17 Hangar Road, Borden, Ontario.

The objective of the project was to conduct a designated substances survey to identify any hazards in order to assist DND in meeting their obligations to manage designated substance and hazardous materials as required by DND/CF Asbestos Management Directive (2007) and COHS Regulations Part X, Division II. DND also references Ontario Regulation 278/05 – *Asbestos in Construction Projects and in Buildings and Repair Operations* and the Ontario Regulation 490/09 – *Designated Substances*.

1.1 Scope of Work

The scope of work for the designated substances and hazardous materials survey was based on the DCC Statement of Work (SOW) dated May 20, 2021 and the Arcadis proposal to DCC dated July 19, 2021, and included the following tasks:

1. Submitting a Health and Safety Plan (HASP) prior to commencing field work on the project, and a detailed schedule.
2. Reviewing all reports provided by DCC.
3. Conducting a room-by-room survey of designated substances and hazardous materials (asbestos, UFFI, lead, mercury, chromium, arsenic, silica, PCBs, ozone-depleting substances and biological hazards) in the building. Collecting bulk samples of materials for asbestos analysis and paint chip samples for analysis of arsenic, chromium, lead, mercury and PCBs. Repairing all sample locations.
4. Notifying DCC immediately if any conditions that pose an immediate significant threat to human health or the environment are discovered, such as asbestos debris, suspect mould and animal droppings.
5. Sending samples for laboratory analysis.
6. Preparing and submitting draft and final reports in the format outlined in the SOW. Inputting the survey data into the required fields of the asbestos database and paint chart provided by DCC.

Mr. Dwayne Kellyman and Mr. Viraj Daruwala of Arcadis visited the site on October 12, 2021, to conduct the designated substances survey.

1.2 Building Summary Information

Building A-243 is a refinishing facility which includes various offices, classrooms and fabrication rooms. It is a two-storey, rectangular structure with a gross floor area of 1393.55 m², flat roof and fixed windows. It was constructed in 1985. There is also a Paints, Oils and Lubricants (POL) Shed, which is part of the main building.

Exterior finishes include metal sidings and parging cement. Interior finishes include vinyl floor tiles, vinyl sheet flooring, concrete, and ceramic tile; drywall, wood, and concrete block walls; and drywall, ceiling tiles and metal deck ceilings.

1.3 Summary of Past Designated Substances Survey Reporting

Arcadis reviewed the Maple Environmental Inc. report entitled *Designated Substance and Detailed Asbestos Building Materials Survey Report*, dated March 2011 in preparing this report.

2 BACKGROUND INFORMATION ON DESIGNATED SUBSTANCES AND HAZARDOUS MATERIALS

Canada Labour Code

Requirements related to disclosing the presence of hazardous substances (including designated substances) in federal government buildings are specified in Part II of the Canada Labour Code, sections 125(1)y and 125(1)(z.14), which state that employers shall:

- “ensure that the activities of every person granted access to the workplace do not endanger the health and safety of employees [Section y]; and
- take all reasonable care to ensure that all of the persons granted access to the workplace, other than the employer’s employees, are informed of every known or foreseeable health or safety hazard to which they are likely to be exposed in the workplace [Section z.14]”.

Canada Occupational Health and Safety Regulations

The requirement for employers to keep and maintain a record of all hazardous substances that are used, produced, handled or stored for use in the work place and the criteria to employ in carrying out an investigation into potential exposure to a hazardous substance are specified in Part X – Hazardous Substances – of the Canada Occupational Health and Safety Regulations.

Ontario Occupational Health and Safety Act (OHSA)

A decision of the Ontario Superior Court of Justice ⁽¹⁾ confirms that when construction or redevelopment work is undertaken by a company whose primary activity is construction or redevelopment work at the site of a federally-regulated employer, the provincial health and safety laws will apply. The *Ontario Occupational Health and Safety Act* and regulations made thereunder would therefore apply to any construction work undertaken at the subject site.

The *Occupational Health and Safety Act (OHSA)* sets out, in very general terms, the duties of employers and others to protect workers from health and safety hazards on the job. These duties include, but are not limited to:

- taking all reasonable precautions to protect the health and safety of workers [clause 25(2)(h)];
- ensuring that equipment, materials and protective equipment are maintained in good condition [clause 25(1)(b)];
- providing information, instruction and supervision to protect worker health and safety [clause 25(2)(a)]; and

⁽¹⁾ Gowlings OHS Law Report – December 2007.

- acquainting a worker or a person in authority over a worker with any hazard in the work and in the handling, storage, use, disposal and transport of any article, device, equipment or a biological, chemical or physical agent [clause 25(2)(d)].

In addition, Section 30 of the OHSA deals with the presence of designated substances on construction projects. Compliance with the OHSA and its regulations requires action to be taken where there is a designated substance hazard on a construction project.

Section 30 of the OHSA requires the owner of a project to determine if designated substances are present on a project and, if so, to inform all potential contractors as part of the bidding process. Contractors who receive this information are to pass it onto other contractors and subcontractors who are bidding for work on the project.

Regulation for Construction Projects, O.Reg. 213/91

The Regulation for Construction Projects, O.Reg. 213/91, applies to all construction projects. The following sections of the regulation would apply to situations where there is the potential for workers to be exposed to designated substances:

| | | |
|------------|-----|--|
| Section 14 | (5) | A competent person shall perform tests and observations necessary for the detection of hazardous conditions on a project. |
| Section 21 | (1) | A worker shall wear such protective clothing and use such personal protective equipment or devices as are necessary to protect the worker against the hazards to which the worker may be exposed. |
| | (2) | A worker's employer shall require the worker to comply with subsection (1). |
| | (3) | A worker required to wear personal protective clothing or use personal protective equipment or devices shall be adequately instructed and trained in the care and use of the clothing, equipment or device before wearing or using it. |
| Section 30 | | Workers who handle or use substances likely to endanger their health shall be provided with washing facilities with clean water, soap and individual towels. |
| Section 46 | (1) | A project shall be adequately ventilated by natural or mechanical means, if a worker may be injured by inhaling a noxious dust or fume. |
| | (2) | If it is not practicable to provide natural or mechanical ventilation in the circumstances described in clause (1)(a), respiratory protective equipment suitable for the hazard shall be provided and be used by the workers. |
| Section 59 | | If the dissemination of dust is a hazard to a worker, the dust shall be adequately controlled or each worker who may be exposed to the hazard shall be provided with adequate personal protective equipment. |

Regulation for Designated Substances (O.Reg. 490/09)

The Designated Substance Regulation (O.Reg. 490/09) specifies occupational exposure limits (OELs) for eleven designated substances in Ontario (asbestos, lead, mercury, silica, vinyl chloride, acrylonitrile, isocyanates, benzene, arsenic, ethylene oxide and coke oven emissions) and requires an assessment and a control program to ensure compliance with these OELs.

Although O.Reg. 490/09 and the OELs do not apply to an employer on a construction project, or to their workers at the project (O.Reg.490/09, Section 14, Exception – Construction), employers still have a responsibility to protect the health of their workers and to comply with the OHSA and other applicable regulations. Section 25(2)(h) of the OHSA requires that employers take "every precaution reasonable in the circumstances for the protection of a worker".

Other regulatory requirements (and guidelines) which apply to control of exposure to designated substances and hazardous materials are referenced in the sections below.

2.1 Asbestos

Asbestos has been widely used in buildings, both in friable applications (materials which can be crumbled, pulverized or powdered by hand pressure, when dry) such as pipe and tank insulation, sprayed-on fireproofing and acoustic texture material, and in non-friable manufactured products such as floor tile, gaskets, cement board and so on. The use of asbestos in friable applications was curtailed around the mid-1970s. The use of asbestos in certain non-friable materials continued beyond the mid-1970s. The import, sale or use of asbestos products was banned in Canada, effective December 30, 2018.

2.1.1 Provincial Government Requirements

Control of exposure to asbestos is governed in Ontario by Regulation 278/05 – *Designated Substance – Asbestos on Construction Projects and in Buildings and Repair Operations*. Disposal of asbestos waste (friable and non-friable materials) is governed by Ontario Regulation 278/05 and by Ontario Regulation 347, Waste Management – General. O.Reg. 278/05 classifies asbestos work operations into three types (Type 1, 2 and 3), and specifies procedures to be followed in conducting asbestos abatement work.

O. Reg. 278/05 prescribes certain requirements for asbestos management in buildings. For on-going asbestos management in buildings, building owners are required to:

- prepare (and keep on the premises) a record (i.e., asbestos survey report) of the locations of all friable and non-friable asbestos-containing materials in a building;
- inspect asbestos-containing materials at reasonable intervals to determine their condition and update the asbestos survey record at least once in each 12-month period, and whenever asbestos-containing material is removed or discovered;

- give any person who is an occupier⁽²⁾ of the building written notice of any information in the asbestos survey record that relates to the area occupied by the person;
- give contractors written notice of the information in the asbestos survey record if the work to be carried out by contractor may involve asbestos-containing material or may be carried out in close proximity to and may disturb asbestos-containing material;
- advise staff of the information in the asbestos survey record, if work is to be performed in a facility that contains asbestos-containing material;
- provide training for staff based on the responsibilities and duties to be undertaken in relation to asbestos management;
- clean up any fallen asbestos-containing fireproofing or acoustical or thermal insulation (if the material is being disturbed so that exposure to the material is likely to occur);
- repair, seal, remove or permanently enclose asbestos-containing fireproofing as thermal insulation if it is readily apparent that material will continue to fall because of deterioration; and,
- perform work operations which involve disturbance (i.e., cleanup, removal, repair, etc.) of asbestos-containing materials in accordance with the measures and procedures (Type 1, 2 and 3 operations) specified in O. Reg. 278/05.

2.1.2 Federal Government Requirements – Canada Occupational Health and Safety Regulations- Hazardous

The Canada Labour Code Part II – Canada Occupational Health and Safety Regulations, Division II – Hazardous Substances Other Than Hazardous Products prescribes requirements for Asbestos Exposure Management Programs.

2.1.3 Federal Government Requirements – National Joint Council Directive

The National Joint Council Directive, Part XI – Hazardous Substances – 11.6 Asbestos Management – states:

11.6.1 The employer shall comply with federal, provincial, territorial and municipal regulations, statutes and requirements with respect to asbestos-containing materials (ACM) in any government-owned, managed or leased facilities.

11.6.2 An asbestos management program and code of practice meeting the intent of the appropriate standard shall be followed if material containing asbestos may exist in any building or facility.

⁽²⁾ An “occupier” is defined as:

- (a) a person who is in physical possession of premises, or
- (b) a person who has responsibility for and control over the condition of premises or the activities carried on there, or control over persons allowed to enter the premises.

11.6.3 As a minimum requirement, departments and agencies will comply with Public Works and Government Services Canada Policy DP 057 and Code of Practice on Asbestos Management.

2.1.4 DND Asbestos Management Directive

The Department of National Defence (DND) Asbestos Management Directive, March 2007, was developed in order to establish a standard and consistent approach for the management of asbestos-containing materials. The Directive identifies organizational roles and responsibilities, and establishes a comprehensive approach for the identification, management, removal and disposal of asbestos-containing materials within DND buildings and facilities. CFB Borden considers asbestos-containing materials to be 0.5% or more asbestos, by dry weight, in accordance with O. Reg. 278/05.

2.2 Lead

Lead is a heavy metal that can be found in construction materials such as paints, coatings, mortar, concrete, pipes, solder, packings, sheet metal, caulking, glazed ceramic products and cable splices. Lead has been used historically in exterior and interior paints.

The Surface Coating Materials Regulations (SOR/2016-193) made pursuant to the Canada *Consumer Product Safety Act* states that a surface coating material must not contain more than 90 mg/kg total lead. Health Canada defines a lead-containing surface coating as a paint or similar material that dries to a solid film that contains over 90 mg/kg dry weight of lead.

Information from the United States Occupational Health and Safety Administration (OSHA) suggests that the improper removal of lead paint containing 600 mg/kg lead results in airborne lead concentrations that exceed half of the permissible exposure limit. Lead concentrations as low as 90 mg/kg may present a risk to pregnant women and children⁽³⁾.

The National Plumbing Code allowed lead as an acceptable material for pipes until 1975 and in solder until 1986.

The Ontario Ministry of Labour *Guideline, Lead on Construction Projects*, dated April 2011, provides guidance in the measures and procedures that should be followed when handling lead-containing materials during construction projects. In the guideline, lead-containing construction operations are classified into three groups - Type 1 (low risk), Type 2 (medium risk) and Type 3 (high risk) based on presumed airborne concentrations of lead. Any operation that may expose a worker to lead that is not a Type 1, Type 2, or Type 3b operation, is classified as a Type 3a operation. Type 3a operations include, but are not limited to, for example, welding or high temperature cutting of lead-containing coatings or materials indoors or in a confined space and removal of lead-containing coatings or materials using power tools without an effective

⁽³⁾ *Lead-Containing Paints and Coatings: Preventing Exposure in the Construction Industry*. WorkSafe BC, 2011.

dust collection system equipped with a HEPA filter. Type 3b operations include abrasive blasting of lead-containing coatings or materials and removal of lead-containing dust using an air mist extraction system.

2.3 Mercury

Mercury has been used in electrical equipment such as alkaline batteries, fluorescent light bulbs (lamps), high intensity discharge (HID) lights (mercury vapour, high pressure sodium and metal halide), “silent switches” and in instruments such as thermometers, manometers and barometers, pressure gauges, float and level switches and flow meters. Mercury-containing lamps, the bulk of which are 1.22 m (four foot) fluorescent lamps contain between 7 and 40 mg of mercury each. Mercury compounds have also been used historically as additives in latex paint to protect the paint from mildew and bacteria during production and storage.

The intentional addition of mercury to Canadian-produced consumer paints for interior use was prohibited in 1991. Mercury may have remained in paints after 1991, however, as a result of impurities in the paint ingredients or cross-contamination due to other manufacturing processes. The Surface Coating Materials Regulations (SOR/2016-193) made pursuant to the Canada *Consumer Product Safety Act* states that a surface coating material must not contain more than 10 mg/kg mercury.

Mercury-containing thermostats and silent light switches are mercury tilt switches which are small tubes with electrical contacts at one end of the tube. A mercury tilt switch is usually present when no switch is visible. Mercury switches often have the word “TOP” stamped on the upper end of the switch, which is visible after removing the cover plate. If mercury switches are to be removed, the entire switch should be removed and placed into a suitable container for storage and disposal.

Waste light tubes generated during renovations or building demolition and waste mercury from equipment must either be recycled or disposed of in accordance with the requirements of Ont. Reg. 347 – *Waste Management, General*.

Waste mercury in amounts less than 5 kg (per month) are exempt from the generator registration requirements prescribed by O.Reg. 347 – *Waste Management – General*. Waste mercury from mercury switches or gauges should, however, be properly collected and shipped to a recycling facility or disposed of as a hazardous waste. Removal of mercury-containing equipment (e.g., switches, gauges, controls, etc.) should be carried out in a manner which prevents spillage and exposure to workers.

The Environment and Climate Change Canada (ECCC) document *Code of Practice for the Environmentally Sound Management of End-Of-Life Lamps Containing Mercury*, February 2017 is a voluntary tool developed to complement provincial initiatives, and to promote best practices for managing end-of-life mercury-containing lamps.

2.4 Silica

Silica exists in several forms of which crystalline silica is of most concern with respect to potential worker exposures. Quartz is the most abundant type of crystalline silica. Some commonly used construction

materials containing silica include brick, refractory brick, concrete, concrete block, cement, mortar, rock and stone, sand, fill dirt, topsoil and asphalt containing rock or stone.

The Ontario Ministry of Labour *Guideline, Silica on Construction Projects*, dated April 2011, provides guidance in controlling exposure to silica dust during construction activities. In the guideline, silica-containing construction operations are classified into three groups – Type 1 (low risk), Type 2 (medium risk) and Type 3 (high risk) based on presumed airborne concentrations of respirable crystalline silica in the form of cristobalite, tridymite, quartz and tripoli.

2.5 Other Designated Substances

Vinyl chloride vapours may be released from polyvinyl chloride (PVC) products in the event of heating or as a result of decomposition during fire. PVC is used in numerous materials that may be found in building construction, including, for example, piping, conduits, siding, window and door frames, plastics, garden hoses, flooring and wire and cable protection.

Acrylonitrile is used to produce nitrile-butadiene rubber, acrylonitrile-butadiene-styrene (ABS) polymers and styrene-acrylonitrile (SAN) polymers. Products made with ABS resins which may be found in buildings include telephones, bottles, packaging, refrigerator door liners, plastic pipe, building panels and shower stalls. Acrylonitrile can be released into the air by combustion of products containing ABS.

Isocyanates are a class of chemicals used in the manufacture of certain types of plastics, foams, coatings and other products. Isocyanate-based building construction materials may include rigid foam products such as foam-core panels and spray-on insulation and paints, coatings, sealants and adhesives. Isocyanates may be inhaled if they are present in the air in the form of a vapour, a mist or a dust.

Benzene is a clear, highly flammable liquid used mainly in the manufacture of other chemicals. The commercial use of benzene as a solvent has practically been eliminated, however it continues to be used as a solvent and reactant in laboratories.

Arsenic is a heavy metal used historically in pesticides and herbicides. The primary use in building construction materials was its use in the wood preservative chromated copper arsenate (CCA). CCA was used to pressure treat lumber since the 1940s. Pressure-treated wood containing CCA is no longer being produced for use in most residential settings.

Ethylene oxide is a colourless gas at room temperature. It has been used primarily for the manufacture of other chemicals, as a fumigant and fungicide and for sterilization of hospital equipment.

Coke oven emissions are airborne contaminants emitted from coke ovens and are not a potential hazard associated with building construction materials.

2.6 PCBs

The management of equipment classified as waste and containing Polychlorinated Biphenyls (PCBs) at concentrations of 50 parts per million (mg/kg) or greater is regulated by *Ontario Regulation 362, Waste Management – PCBs*. Under this regulation, PCB waste is defined as any waste material containing PCBs in concentrations of 50 mg/kg or greater. Any equipment containing PCBs at or greater than this level, such as transformers, switchgear, light ballasts and capacitors, which is removed from service due to age, failure or as a result of decommissioning, is considered to constitute a PCB waste. Although current federal legislation (effective 1 July 1980) has prohibited the manufacture and sale of new equipment containing PCBs since that time, continued operation of equipment supplied prior to this date and containing PCBs is still permitted. Handling, storage and disposition of such equipment is, however, tightly regulated and must be managed in accordance with provincial and federal government requirements as soon as it is taken out of service or becomes unserviceable.

In most institutional, commercial facilities and in smaller industrial facilities, the primary source of equipment potentially containing PCBs is fluorescent and H.I.D. light ballasts. Small transformers may also be present. In larger industrial facilities, larger transformers and switch gear containing, or potentially containing, PCBs may also be present.

PCBs were also commonly added to industrial paints from the 1940s to the late 1970s. PCBs were added directly to the paint mixture to act as a fungicide, to increase durability and flexibility, to improve resistance to fires and to increase moisture resistance. The use of PCBs in new products was banned in Canada in the 1970s. PCB amended paints were used in specialty industrial/institutional applications prior to the 1970s including government buildings and equipment such as industrial plants, radar sites, ships as well as non-government rail cars, ships, grain bins, automobiles and appliances. PCB caulking was used in the 1950s and through the 1970s to seal the joints of brick, masonry, stone and metal window frames.

Removal of in-service equipment containing PCBs, such as fluorescent light ballasts, capacitors and transformers, is subject to the requirements of the federal *PCB Regulations* (discussed below).

The *PCB Regulations*, which came into force on 5 September 2008, were made under the *Canadian Environmental Protection Act*, 1999 (CEPA 1999) with the objective of addressing the risks posed by the use, storage and release to the environment of PCBs, and to accelerate their destruction. The *PCB Regulations* set different end-of-use deadlines for equipment containing PCBs at various concentration levels.

The Regulations Amending the PCB Regulations and Repealing the Federal Mobile PCB Treatment and Destruction Regulations were published on 23 April 2014, in the Canada Gazette, Part II, and came into force on 1 January 2015. The most notable part of the amendments is the addition of an end-of-use deadline date of 31 December 2025 for specific electrical equipment located at electrical generation, transmission and distribution facilities.

When the PCB materials are classified as waste, jurisdiction falls under the Ontario Ministry of the Environment and Climate Change (MOECC) and O.Reg. 362. All remedial and PCB management work

must be carried out under the terms of a Director's Instruction issued by an MOE District Office (for quantities of PCB fluid greater than 50 litres). The PCB waste stream, regardless of quantity, must be registered with the MOE, in accordance with O.Reg. 347, *General – Waste Management*. O.Reg. 362 applies to any equipment containing greater than 1 kg of PCBs.

2.7 Urea Formaldehyde Foam Insulation (UFFI)

Urea formaldehyde foam insulation (UFFI) is a polymer manufactured at point-of-use by blending urea formaldehyde resin with a phosphoric acid catalyst and compressed air at a nozzle tip. This nozzle was used to inject the freshly mixed foam product into enclosed wall cavities. UFFI was introduced in Canada in the 1970s. In response to concerns about the health effects of formaldehyde gas, the installation of UFFI was banned in Canada in 1980.

2.8 Ozone-Depleting Substances and Other Halocarbons

In Canada, the federal, provincial and territorial governments have legislation in place for the protection of the ozone layer and management of ozone-depleting substances and their halocarbon alternatives. The use and handling of these substances are regulated by the provinces and territories in their respective jurisdictions, and through the *Federal Halocarbon Regulations*, 2003 (FHR 2003) for refrigeration, air-conditioning, fire-extinguishing and solvent systems under federal jurisdiction.

The FHR 2003 were established in August 2003 and amended in July 2009 under the authority of the *Canadian Environmental Protection Act*, 1999. The purpose of the FHR 2003 is to reduce and prevent emissions of ozone-depleting substances and of their halocarbon alternatives to the environment from air-conditioning units, refrigeration, fire-extinguishing and solvent systems that are:

- located on federal or aboriginal lands; or
- owned by federal departments, board agencies, Crown corporations, or federal works and undertakings.

Ontario Regulation 347, *General – Waste Management*, has also been amended to provide for more strict control of CFCs. The requirements under the amended regulation apply primarily to the keeping of records for the receipt or recycling of CFC waste.

The FHR 2003 replaced the former Federal Halocarbon Regulations and incorporated new provisions to achieve an orderly transition from CFCs and Halons to alternative substances and technologies, reflecting *Canada's Strategy to Accelerate the Phase-Out of CFC and Halon Uses and to Dispose of the Surplus Stocks*.

Under the FHR 2003, a person who installs, services, leak tests, or charges a refrigeration system or an air conditioning system or does any other work on the system that may result in the release of a halocarbon must do so in accordance with the *Environmental Code of Practice for the Elimination of Fluorocarbon Emissions from Refrigeration and Air Conditioning Systems*.

Some of the requirements of FHR 2003 include:

- certification is required for all persons testing, repairing, filling or emptying equipment containing ozone-depleting substances and their halocarbon alternatives;
- no person shall store, transport or purchase a halocarbon unless it is in a container designed and manufactured to be refilled and to contain that specific type of halocarbon;
- before dismantling, decommissioning or destruction of any system, a person shall recover all halocarbons contained in the system into a container designed and manufactured to be refilled and to contain that specific type of halocarbon;
- before dismantling, decommissioning or destruction or destroying a system, a person shall affix a notice to the system containing information as required in Column 3, Item 1 of Schedule 2. This information includes the name and address of the owner of the system; name of the operator of the system, specific location of the system before its dismantling, decommissioning or destruction; description of the system; name of service technician who recovered the halocarbons; certificate number of the service technician (if applicable); name of employer of service technician (if applicable); type and quantity of halocarbon and date recovered; type and charging capacity of the system; and final destination of the system; and
- in the case of dismantling, decommissioning or destruction of any system, the owner shall keep a record of the information contained in the notice as described above.

2.9 Biological Hazards

2.9.1 Mould

Moulds are forms of fungi that are found everywhere both indoors and outdoors all year round. Outdoors, moulds live in the soil, on plants and on dead and decaying matter. More than 1000 different kinds of indoor moulds have been found in buildings. Moulds spread and reproduce by making spores, which are all small and light-weight, able to travel through air, capable of resisting dry, adverse environmental conditions, and hence capable of surviving a long time. Moulds need moisture and nutrients to grow and their growth is stimulated by warm, damp and humid conditions.

Control of exposure to mould is required under Section 25(2)(h) of the Ontario *Occupational Health and Safety Act*, which states that employers shall take every precaution reasonable in the circumstances for the protection of workers. Recommended work practices are outlined in the following documents:

- *Mould Guidelines for the Canadian Construction Industry*. Standard Construction Document CCA 82 2004. Canadian Construction Association.
- *Mould Abatement Guidelines*. Environmental Abatement Council of Ontario. Edition 3. 2015.

2.9.2 Animal Droppings

Histoplasmosis is an infectious disease caused by inhaling the spores of a fungus called *Histoplasma capsulatum*. Histoplasmosis primarily affects a person's lungs, and its symptoms vary greatly. Histoplasmosis can appear as a mild, flu-like respiratory illness and has a combination of symptoms,

including malaise (a general ill feeling), fever, chest pain, dry or non productive cough, headache, loss of appetite, shortness of breath, joint and muscle pains, chills, and hoarseness. Chronic lung disease due to histoplasmosis resembles tuberculosis and can worsen over months or years. ⁴

H capsulatum grows in soils throughout the world. The fungus seems to grow best in soils having a high nitrogen content, especially those enriched with bird manure or bat droppings. The organism can be carried on the wings, feet and beaks of birds and infect soil under roosting sites or manure accumulations inside or outside buildings. Active and inactive roosts of blackbirds have been found heavily contaminated by *H capsulatum*. On the other hand, fresh bird droppings on surfaces such as sidewalks and window sills have not been shown to present a health risk for histoplasmosis because birds themselves do not appear to be infected by *H capsulatum*. Rather, bird manure is primarily a nutrient source for the growth of *H capsulatum* already present in the soil. Unlike birds, bats can become infected with *H capsulatum* and consequently can excrete the organism in their droppings.

In addition to *H capsulatum*, inhalation exposure to *Cryptococcus neoformans* may also be a health risk for workers in environments containing accumulations of bat droppings or bird manure. *C neoformans* is the infectious agent of the fungal disease cryptococcosis. Formerly a rare disease, the incidence of cryptococcosis has increased in recent years because of its frequent occurrence in AIDS patients. *C neoformans* and *H capsulatum* are only two of the more than 100 microorganisms that have been reported with increased frequency among HIV-infected persons, and cryptococcosis and histoplasmosis are both classified as AIDS-indicator opportunistic infectious diseases.

2.9.3 Raccoon Feces

A roundworm commonly known as Raccoon Roundworm (*Baylisascaris*) lives in the digestive tracts of raccoons, and can potentially cause a serious infection in humans if infected roundworm eggs in soil, water or an object that has been contaminated with raccoon feces are accidentally ingested.

2.9.4 Mouse Droppings

Hantaviruses are found in the droppings, urine and saliva of infected rodents and humans can contract the virus from breathing in airborne particles or from being bitten. In Canada, a hantavirus capable of causing disease in humans – named Sin Nombre virus – has been identified in deer mice. Although the risk in Canada is low, when it happens, the disease can be very severe.

Exposure to hantaviruses can cause a rare, but often fatal, disease called Hantavirus pulmonary syndrome (HPS). The earliest documented case of HPS in Canada was contracted in Alberta in 1989. Since then,

⁴ *Histoplasmosis — Protecting Workers at Risk*, Revised Edition, United States Department of Health and Human Services, Centers for Disease Control and Prevention, National Institute for Occupational Safety and Health (NIOSH), December 2004.

there have been over 70 confirmed cases. Most of the cases occurred in western Canada (Manitoba, Saskatchewan, Alberta and British Columbia), except for one case in Quebec.⁵

Hantavirus is typically transmitted by breathing particles in air from the droppings, urine and saliva of infected rodents. However, there have been a small number of reported cases of HPS believed to have been contracted through rodent bites.

⁵ Health Canada – “It’s Your Health – Hantaviruses” – August 2009.

3 METHODOLOGY

All areas of the building were surveyed, with the exception of the roof.

Arcadis reviewed the Maple Environmental Inc. report entitled *Designated Substance and Detailed Asbestos Building Materials Survey Report*, dated March 2011 in preparing this report.

3.1 Asbestos

Bulk sampling was performed in accordance with the requirements of O. Reg. 278/05 as follows:

- the minimum number of bulk samples to be collected from an area of homogeneous material is set out in Table 1 of the regulation (Table 3.1 is reproduced below).
- if analysis establishes that a bulk material sample contains 0.5 per cent or more asbestos by dry weight:
 - (a) it is not necessary to analyze other bulk material samples taken from the same area of homogeneous material; and
 - (b) the entire area of homogeneous material from which the bulk materials sample was taken is deemed to be asbestos-containing material.

Table 3.1 Bulk Material Samples (From O.Reg. 278/05)

| Item | Type of Material | Size of Area of Homogeneous Material | Minimum Number of Bulk Material Samples to be Collected |
|------|--|---|---|
| 1 | Surfacing material, including without limitation material that is applied to surfaces by spraying, by trowelling or otherwise, such as acoustical plaster on ceilings and fireproofing materials on structural members | Less than 90 square metres | 3 |
| | | 90 or more square metres, but less than 450 square metres | 5 |
| | | 450 or more square metres | 7 |
| 2 | Thermal insulation, except as described in Item 3 | Any size | 3 |
| 3 | Thermal insulation patch | Less than 2 linear metres or 0.5 square metres | 1 |
| 4 | Other material | Any size | 3 |

These Ontario Regulation 278/05 minimum bulk sample number requirements are consistent with the bulk sampling requirements specified in the DND Asbestos Management Directive.

In practice, application of the Table 3.1 requirements means that the specified minimum number of negative (i.e., less than 0.5% asbestos) bulk sample analysis results will be required in order to classify a material as non-asbestos. Area of homogeneous material means an area in a building constructed at the same time. Homogeneous material is defined as material that is uniform in colour and texture.

Bulk sampling was “non-destructive”, therefore certain materials including but not limited to, ceramic tile grout and mortar beds, were only sampled from areas of existing damage, if any.

Analysis of bulk samples was performed following EPA Method 600/R-93/116 in conformity with the requirements specified in O. Reg. 278/05. A “stop positive” protocol was utilized whereby one positive (more than 0.5%) sample result from a homogeneous area can be considered evidence that all suspect material in that homogeneous area contains asbestos without analysing the remaining samples.

The “*Asbestos Condition Assessment and Response Chart*” in the DND Asbestos Management Directive was used in identifying required response actions. A copy of the Chart is provided in Appendix E.

3.2 Lead

Samples of select, representative paint applications collected during the course of the site inspection were forwarded to ALS Environmental Inc. for analysis of lead content.

Information on paint sample location, substrate material, sample description and other locations with the same paint application was recorded and reported in Tables 4.2 and 4.3.

3.3 Mercury

The presence of equipment which may contain mercury, such as fluorescent light tubes, thermometers, gauges, etc. observed during the course of our site inspection was recorded.

Paint samples, discussed above in Section 3.2, were also analysed for mercury.

3.4 Silica

The presence of silica-containing materials observed during the course of our site inspection was documented. Silica is known to be a constituent of brick, concrete, cement, etc. Sampling and laboratory analysis are not required to make this determination.

3.5 Other Designated Substances and Hazardous Materials

Paint samples were collected for analysis of arsenic and chromium.

3.6 PCBs

Fluorescent lights were inspected during the course of our survey to determine whether they were the T12 type and may therefore contain PCB ballasts.

Transformers were investigated to determine whether they were the “dry” type which do not contain PCB dielectric fluids, or the “wet” type which can contain PCBs.

Paint samples were collected for analysis of PCBs.

3.7 Urea Formaldehyde Foam Insulation

Investigations for the potential presence of UFFI entailed inspection of exterior and interior openings (i.e., “nozzle holes”) made for installation of insulation and limited visual observation of the wall cavity and insulating materials at select, representative locations.

3.8 Ozone-Depleting Substances and Other Halocarbons

The presence of Ozone Depleting Substances (ODSs) and other Halocarbons was reviewed within the building and recorded.

3.9 Biological Hazards

The presence of “suspect” mould observed during the course of our site inspection was documented. “Suspect” mould is typically a coloured, textured substance or discolouration or staining on a building material surface which, based on our experience, may be mould growth. The adjective “suspect” is used where the presence of mould has not been confirmed by laboratory analysis.

The inspection of mould was limited to visual observations of readily accessible surfaces and did not include intrusive inspections of wall cavities.

The presence of any animal droppings observed was also noted.

4 DISCUSSIONS AND SUMMARY OF RESULTS

4.1 Asbestos

The results of the bulk sample analyses for asbestos content are provided in Appendix C, and the laboratory report is provided in Appendix B. Sample locations are shown on the floor plans provided in Appendix A. A summary of building materials sampled and found not to contain asbestos is presented in Table 4.1.

Photographs are presented in Appendix D.

Potential asbestos-containing materials are materials which could contain asbestos, but which were not sampled as such sampling could cause significant damage. Potential asbestos-containing materials observed at this site include boiler insulation, mortar beds and grout under ceramic floor tiles, exterior window caulking and roofing materials.

Areas where potential asbestos-containing materials were observed are as follows:

- Mechanical Room – insulation inside the boiler; and
- Rooms 106, 107, 108 and 124 – ceramic tile grout and mortar beds.

Other potential asbestos-containing materials may also be present. A list of possible asbestos-containing materials in buildings from the Ministry of Labour “Sample List of Suspect Asbestos-Containing Materials” is provided in Appendix F.

Asbestos was not detected in any of the samples collected by Arcadis or Maple Environmental Inc.

Table 4.1 Summary of Materials Sampled and Confirmed to be Non-Asbestos-Containing – Building A - 243

| Material | Substrate | Sample Locations |
|---|----------------------------|--|
| 2'x4' ceiling tile – pinhole and medium fissures | N/A | Room 105, Room 103 and Room 102 |
| Vinyl baseboard – turquoise | Concrete block and drywall | Room 102, Room 103 and Room 105 |
| Turquoise vinyl baseboard mastic | Concrete block | Room 102, Room 103 and Room 105 |
| Stone mortar | Concrete block | Corridor 1 and Corridor 2 |
| Vinyl baseboard – beige | Concrete block | Corridor 1 and Corridor 2 |
| Beige vinyl baseboard – mastic | Concrete block | Corridor 1 and Corridor 2 |
| Drywall joint compound | Drywall | Room 105, Room 114, Room 123, Corridor 3, Room 103 and Room 205 |
| Vinyl sheet flooring – turquoise | Concrete | Room 105, Corridor 1 and Corridor 2 |
| Vinyl sheet flooring – beige | Concrete | Corridor 1, Corridor 2 and Corridor 3 |
| Block filler paint | Concrete block wall | Room 114, Room 125, Room 116, Room 109, Stair 1, Electrical Room and Boiler Room |
| Concrete block mortar | Concrete block | Room 109, Room 110 and Stairwell 1 |
| Door frame caulking – white | Concrete block | Corridor 1, Corridor 2 and Room 114 |
| Vinyl sheet flooring – black | Concrete | Room 123 and Room 124 |
| Black vinyl sheet flooring mastic | Concrete | Room 123 |
| 2'x4' ceiling tile – pinhole and long fissure | N/A | Room 123 |
| Window glazing | Metal | Room 123 |
| 12" vinyl floor tile – white with black flecks | Wood | Room 205 |
| 12" vinyl floor tile mastic – white with black flecks | Wood | Room 205 |
| Parging cement | Concrete | Exterior |

Based on visual observations, and results of laboratory analyses of samples collected by Arcadis asbestos-containing materials (ACM) were not found to be present in the subject building.

Glass fibre pipe insulation is readily visually distinguishable (typically yellow in colour) from asbestos-containing insulation materials and was, therefore, not tested for asbestos content.

Asbestos may be present in materials which were not sampled during the course of the designated substances survey carried out by Arcadis, including, but not limited to, roofing materials, materials inside the boiler, ceramic tile grout and mortar beds, components of electrical equipment, for example, electric wiring insulation, non-metallic sheathed cable, electrical panel partitions, arc chutes, high-grade electrical paper. The major use of asbestos electrical paper is insulation for high temperature, low voltage applications such as in motors, generators, transformers, switch gears and other heavy electrical apparatuses. Asbestos may also be present in locations that are presently inaccessible (e.g., above solid ceilings, behind walls). Asbestos may also be present in the form of vermiculite insulation in cavities in concrete or cement block walls (used as fill-in insulation). Confirmatory testing of any such materials could

be undertaken as the need arises (ie., at the time of renovations) or the material can be assumed to contain asbestos based on the findings in adjacent areas.

4.2 Lead

Samples of representative paint were collected by Arcadis during the course of the survey. The samples were submitted to ALS for analysis of lead (as well as mercury, arsenic, chromium and PCBs). The results of analysis are presented in Table 4.2 and photographs of paint applications are presented in Appendix D.

Lead was not detected at a level above 90 µg/g (Surface Coating Materials Regulations SOR/2016-193 criterion value) in all of the paint samples analysed. Lead may be present in lead pipe, in the solder on the seals of bell joints of any cast iron drainpipe and in the solder on the sweated-on joints between copper pipe and fittings.

Paint applications were observed to be in good condition.

Table 4.2 Surface Coating – Sampling Summary – Building A - 243

| Sample ID | Sample Location | Substrate Material | Sample Description | Condition | Analytical Results (µg/g) | | | | |
|----------------|-----------------|--------------------|-----------------------|-----------|---------------------------|----------------------|-----------------|--------------------|-----------------|
| | | | | | Arsenic (10 µg/g*) | Chromium (500 µg/g*) | Lead (90 µg/g^) | Mercury (10 µg/g^) | PCBs (50 µg/g") |
| P-1 (Photo 14) | Room 109 | Block wall | White wall paint | Good | <1.0 | 14.3 | 4.7 | 0.071 | 0.14 |
| P-2 (Photo 27) | Room 114 | Drywall | White wall paint | Good | <1.0 | 19.9 | 7.6 | <0.050 | <2.6 |
| P-3 (Photo 25) | Exterior | Metal | Light blue door paint | Good | <1.0 | 12.3 | 16.7 | 0.155 | <3.0 |

< = Less than.

Analytical Results: *No current regulated amounts for arsenic and chromium. Numbers taken from SOW Appendix E. Any concentration above stated numbers. ^SOR/2005-109 Surface Coating Materials Regulations, "SOR/2008-273 PCB Regulation.

Bolded areas indicate elevated levels of contaminants. Use Caution. Follow MOL Guideline for Lead, wet surfaces down before disturbing them. Notify Base Environmental Officer of the need to dispose of contaminated paint prior to disturbing it.

Table 4.3 Summary of Rooms with Similar Surface Coatings – Building A - 243

| Paint Description | Rooms with Similar Surface Coating/Paint Colour |
|-----------------------|--|
| P-1/ White wall paint | Rooms 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 121, 122, 123, 124, 125, 203, 204, Corridor 2, Corridor 3, Stairwell 1, POL Shed and Mechanical Room |
| P-2/ White wall paint | Rooms 101, 102, 103, 105, 109, 112, 113, 114, 122 and 123 |
| P-3/ Blue door paint | Exterior |

4.3 Mercury

During the course of our site inspections, fluorescent lights were observed throughout the buildings. Mercury should be assumed to be present as a gas in all fluorescent light tubes.

Proper procedures for removing and handling mercury-containing fluorescent light tubes typically involve:

- ensuring that electrical power to light fixtures has been disconnected and locked out;
- taking all necessary precautions to ensure that fluorescent lamp tubes are removed in a manner that prevents breakage; and
- transporting fluorescent lamp tubes to a licensed processing location for separation and recovery of mercury.

Samples of paint collected during the survey were analysed for mercury. The results of analysis are presented in Table 4.2. Mercury was not detected at a level above 10 µg/g (Surface Coating Materials Regulations SOR/2016/193 criterion value) in any of the paint samples analysed.

4.4 Silica

Materials observed in the subject building which should be considered to contain silica included concrete, concrete blocks, brick, mortar, drywall, drywall joint compound, ceramic floor tile grout and mortar beds.

4.5 Other Designated Substances and Hazardous Materials

No other designated substances (vinyl chloride, acrylonitrile, benzene, isocyanates, ethylene oxide and coke oven emissions) were observed to be present in the subject building, and none would be expected to be encountered in any building materials in a form that would represent an exposure concern.

Samples of paint collected during the survey were analysed for arsenic and chromium. The results of analysis are presented in Table 4.2.

Arsenic was not detected at an amount above the level of 10 µg/g in any of the paint samples analysed.

Chromium was not detected at an amount above the level of 500 µg/g in any of the paint samples analysed.

4.6 PCBs

Light ballasts, such as those associated with the type of fluorescent lights (T8s) observed throughout the building, are usually an electronic-type which do not contain PCBs, however, this would be confirmed by an electrician at the time of dismantling of the lights.

Light ballasts, such as those associated with the type of fluorescent lights (T12s) identified in Room 203 are typically a magnetic type which may contain PCBs. Inspection of product codes and date codes on the ballasts can be used to determine the likely presence or absence of PCBs.

PCBs were not detected at a level above the criterion level of 50 µg/g in any of the three paint samples analysed.

No transformers were observed in the building.

4.7 Urea Formaldehyde Foam Insulation (UFFI)

UFFI was not observed during the course of the investigation.

4.8 Ozone-Depleting Substances and Other Halocarbons

During the course of our site inspections, equipment potentially containing Ozone-Depleting Substances and other Halocarbons included:

- Wall-mounted air conditioner in Room 101;
- Window mounted air conditioners in Rooms 102 and 105;
- Drink fridge in Room 202;
- Mini-fridge in Room 102, and
- Ceiling-mounted air conditioners in Room 205.

4.9 Biological Hazards

No animal droppings were observed during the site investigation.

Suspect mould growth was observed on the 2'x4' ceiling tiles in Room 205.

The investigation of mould was limited to visual observations of readily accessible surfaces and did not include intrusive investigations of wall cavities.

5 CONCLUSIONS AND RECOMMENDATIONS

We recommend the following on the basis of the findings of the designated substances survey outlined in this report.

5.1 Ongoing Management

1. If any potential asbestos-containing materials that have not been tested for asbestos may be affected by maintenance or other work activities, they should be tested prior to their disturbance or assumed to contain asbestos and handled accordingly.
2. If work activities may cause exposure to metallic elements in paint, develop an exposure control plan, write safe work procedures and implement controls.
3. If work activities may cause exposure to metallic elements in paint, develop an exposure control plan, write safe work procedures and implement controls in accordance with *MOL Guideline – Lead on Construction Projects*.
4. If silica-containing materials will be affected by sanding, drilling, chipping, grinding, cutting, sawing, sweeping or blasting, the measures and procedures outlined in the Ontario Ministry of Labour *Guideline, Silica on Construction Projects*, April 2011, should be followed.
5. Comply with the requirements of FHR 2003 when installing, servicing, testing, charging or doing any other work on a refrigeration system or an air conditioning system that may result in the release of a halocarbon.

5.2 Construction Projects

1. If there are any materials which may contain asbestos and which were not tested during the course of the hazardous building materials survey, and which may be disturbed during construction activities, a “destructive” survey may be required to access and sample potential asbestos-containing materials not sampled.
2. If asbestos-containing materials are found to be present and will be affected by any construction and/or demolition work, they must be removed/handled in accordance with work practices and procedures specified in Ontario Regulation 278/05 and the DND Asbestos Management Directive. Requirements for air sampling for asbestos fibres during and upon completion of asbestos abatement operations are prescribed in the Canada Occupational Health and Safety Regulations made under the Canada Labour Code.
3. If lead-containing materials will be disturbed during the course of construction work, the measures and procedures outlined in The Ministry of Labour Guideline, *Lead on Construction Projects*, dated April 2011, should be followed. For building materials that are to be disposed at a landfill, all painted waste materials and associated substrate (concrete, plaster, wood, etc.) must undergo Toxicity Characteristic Leachate Properties (TCLP) testing to determine disposal procedures. The acceptable level for non-regulated disposal of lead-containing waste is less than 5 mg/L as

determined through analytical TCLP. The disposal of lead-containing waste is regulated under the Federal *Transportation of Dangerous Goods Act* and by the Ontario Ministry of Environment and Climate Change.

4. TCLP testing will also be required for arsenic, chromium and mercury. The acceptable levels for non-regulated disposal of waste containing arsenic, chromium and mercury are 5.0 mg/L, 8.0 mg/L and 0.2 mg/L, respectively.
5. If silica-containing materials will be disturbed during the course of construction work, the measures and procedures outlined The Ministry of Labour *Guideline, Silica on Construction Projects*, April 2011, should be followed.
6. If any fluorescent light tubes are removed, the light tubes should be recycled for mercury. The Environmental and Climate Change Canada (ECCC) document *Code of Practice for the Environmentally Sound Management of End-of-Life Lamps Containing Mercury*, February 2017 provides guidance for managing end-of-life mercury-containing lamps.
7. Prior to undertaking renovation activities that involve fluorescent lights, ensure that a licensed electrician inspects ballasts to determine whether or not any light ballasts may contain PCBs. Guidance in identification of PCB ballasts is provided in the Environment Canada publication titled "Identification of Lamp Ballasts Containing PCBs. Report EPS 2/CC/2 (revised)", August 1991.
8. Workers involved in the demolition of any mould-impacted materials encountered during any renovation or demolition activities should wear appropriate protective clothing and equipment and follow decontamination practices as outlined in the Canadian Construction Association Standard Construction Document CCA-82 2004 – *Mould Guidelines for the Canadian Construction Industry*, and the Mould Abatement Guidelines. Environmental Abatement Council of Ontario. Edition 3. 2015.
9. If caulking will be impacted by planned construction work, it should be tested for PCBs prior to commencement of the work.

6 LIMITATIONS AND SERVICE CONSTRAINTS

The opinions, conclusions and recommendations presented in this report are limited to the information obtained during the performance of the specific scope of service identified in the report. To the extent that Arcadis relied upon any information prepared by other parties not under direct contract to Arcadis, no representation as to the accuracy or completeness of such information is made. This report is an instrument of professional service and the services described in the report were performed in accordance with generally accepted standards and level of skill and care ordinarily exercised by members of the profession working under similar conditions including comparable budgetary and schedule constraints. No warranty, guarantee or certification express or implied, is intended or given with respect to Arcadis' services, opinions, conclusions or recommendations.

Arcadis' observations, the results of any testing and Arcadis' opinions, conclusions and recommendations apply solely to conditions existing at the specific times when and specific locations where Arcadis' investigative work was performed. Arcadis affirms that data gathered and presented in this report was collected in an appropriate manner in accordance with generally accepted methods and practices. Arcadis cannot be responsible for decisions made by our client solely on the basis of economic factors. Observation and testing activities such as those conducted by Arcadis are inherently limited and do not represent a conclusive or complete characterization. Arcadis analyzed only the substances, conditions and locations described in the report at the time indicated. Conditions in other parts of the project site, building or area may vary from conditions at the specific locations where observations were made and where testing was performed by Arcadis. Additionally, other building material hazards which were not identified by Arcadis, may also be present in un-accessed areas and in walls, ceilings, cavities, and floors.

This report is expressly for the sole and exclusive use of Defence Construction Canada (DCC) for whom this report was originally prepared and for the particular purpose outlined in the report. Reuse of this report or any portion thereof for other than its intended purpose, or if modified, or if used by third parties, shall be at the user's sole risk. This report must be presented in its entirety.

7 REFERENCES

Relevant documents referenced for this project included:



- The DCC Statement of Work dated May 20, 2021;
- Arcadis proposal to DCC dated July 19, 2021; and
- Department of National Defence (DND) Asbestos Management Directive, March 2007.


APPENDIX A

Floor Plans



LEGEND

| | |
|---|---|
| Title: SITE LOCATION | |
|  | Project: DESIGNATED SUBSTANCES SURVEY BLDG A243 17 HANGAR ROAD, BORDEN, ONTARIO |
| | Client: DEFENCE CONSTRUCTION CANADA |
| Date: January 2022 | |
|  | |
| FIGURE 1 | |




LEGEND

- 103 FUNCTIONAL SPACE
- A1-A BULK ASBESTOS SAMPLE LOCATIONS
- P-1 BULK PAINT SAMPLE LOCATIONS




NOTE:
Potential asbestos-containing materials observed at this site include ceramic tiles mortar bed and grout, roofing materials, Boiler insulation and exterior window caulking.

last saved 26-Jan-22 by dlogan

| | |
|--|---|
| Title: FIRST FLOOR | |
| | Project: DESIGNATED SUBSTANCES SURVEY BLDG A243 17 HANGAR ROAD, BORDEN, ONTARIO |
| Date: January 2022 | Client: DEFENCE CONSTRUCTION CANADA |
| <div style="display: flex; justify-content: space-between; align-items: center;"> <div style="text-align: center;"> <p>Metres</p> <p>1:140</p> </div> <div style="border: 1px solid black; padding: 5px; font-weight: bold; font-size: 1.2em;">FIGURE 2</div> </div> | |



LEGEND

-  FUNCTIONAL SPACE
-  BULK ASBESTOS SAMPLE LOCATIONS
-  BULK PAINT SAMPLE LOCATIONS

NOTE:
Potential asbestos-containing materials observed at this site include ceramic tiles mortar bed and grout, roofing materials, Boiler insulation and exterior window caulking.

Title:

SECOND FLOOR



Project:

**DESIGNATED SUBSTANCES SURVEY
BLDG A243
17 HANGAR ROAD, BORDEN, ONTARIO**

Date:

January 2022

Client:

DEFENCE CONSTRUCTION CANADA




FIGURE 3

APPENDIX B

Laboratory Reports



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
 Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552117361
 Customer ID: 55DCSL97
 Customer PO: 30094312
 Project ID:

Attn: Viraj Daruwala
 ARCADIS Canada Inc.
 121 Granton Drive
 Unit 12
 Richmond Hill, ON L4B 3N4
Proj: 30094312 - CFB Building

Phone: (905) 882-5984
Fax: (905) 882-8962
Collected:
Received: 10/21/2021
Analyzed: 10/29/2021

Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

Client Sample ID: A1-A **Lab Sample ID:** 552117361-0001

Sample Description: 105/2'x4' ceiling tile – pinhole and medium fissures

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|------------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Gray/White | 70.0% | 30.0% | None Detected | |

Client Sample ID: A1-B **Lab Sample ID:** 552117361-0002

Sample Description: 103/2'x4' ceiling tile – pinhole and medium fissures

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|------------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Gray/White | 70.0% | 30.0% | None Detected | |

Client Sample ID: A1-C **Lab Sample ID:** 552117361-0003

Sample Description: 102/2'x4' ceiling tile – pinhole and medium fissures

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|------------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Gray/White | 70.0% | 30.0% | None Detected | |

Client Sample ID: A2-A **Lab Sample ID:** 552117361-0004

Sample Description: 102/Vinyl baseboard – turquoise

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|---------------------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM Grav. Reduction | 10/28/2021 | Green | 0.0% | 100% | None Detected | |
| TEM Grav. Reduction | 10/28/2021 | Green | 0.0% | 100.0% | None Detected | |

Client Sample ID: A2-B **Lab Sample ID:** 552117361-0005

Sample Description: 103/Vinyl baseboard – turquoise

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Green | 0.0% | 100.0% | None Detected | |

Client Sample ID: A2-C **Lab Sample ID:** 552117361-0006

Sample Description: 105/Vinyl baseboard – turquoise

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Green | 0.0% | 100.0% | None Detected | |

Client Sample ID: A3-A **Lab Sample ID:** 552117361-0007

Sample Description: 102/Turquoise vinyl baseboard mastic

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|--------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Yellow | 0.0% | 100.0% | None Detected | |



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
 Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552117361
 Customer ID: 55DCSL97
 Customer PO: 30094312
 Project ID:

Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

Client Sample ID: A3-B **Lab Sample ID:** 552117361-0008
Sample Description: 103/Turquoise vinyl baseboard mastic

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|--------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Yellow | 0.0% | 100.0% | None Detected | |

Client Sample ID: A3-C **Lab Sample ID:** 552117361-0009
Sample Description: 105/Turquoise vinyl baseboard mastic

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|--------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Yellow | 0.0% | 100.0% | None Detected | |

Client Sample ID: A4-A **Lab Sample ID:** 552117361-0010
Sample Description: Cor 1/Stone mortar

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Gray | 0.0% | 100.0% | None Detected | |

Client Sample ID: A4-B **Lab Sample ID:** 552117361-0011
Sample Description: Cor 2/Stone mortar

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Gray | 0.0% | 100.0% | None Detected | |

Client Sample ID: A4-C **Lab Sample ID:** 552117361-0012
Sample Description: Cor 2/Stone mortar

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Gray | 0.0% | 100.0% | None Detected | |

Client Sample ID: A5-A **Lab Sample ID:** 552117361-0013
Sample Description: Cor 1/Vinyl baseboard – beige

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM Grav. Reduction | 10/28/2021 | Beige | 0.0% | 100% | None Detected | |
| TEM Grav. Reduction | 10/28/2021 | Beige | 0.0% | 100.0% | None Detected | |

Client Sample ID: A5-B **Lab Sample ID:** 552117361-0014
Sample Description: Cor 2/Vinyl baseboard – beige

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Beige | 0.0% | 100.0% | None Detected | |

Client Sample ID: A5-C **Lab Sample ID:** 552117361-0015
Sample Description: Cor 1/Vinyl baseboard – beige

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Beige | 0.0% | 100.0% | None Detected | |



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552117361
Customer ID: 55DCSL97
Customer PO: 30094312
Project ID:

Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

Client Sample ID: A6-A **Lab Sample ID:** 552117361-0016

Sample Description: Cor 1/Beige vinyl baseboard mastic

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|--------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Yellow | 0.0% | 100.0% | None Detected | |

Client Sample ID: A6-B **Lab Sample ID:** 552117361-0017

Sample Description: Cor 2/Beige vinyl baseboard mastic

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|-----------------------|----------------------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | | | | Insufficient Material | Sample bag is empty. |

Client Sample ID: A6-C **Lab Sample ID:** 552117361-0018

Sample Description: Cor 1/Beige vinyl baseboard mastic

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|--------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Yellow | 0.0% | 100.0% | None Detected | |

Client Sample ID: A7-A **Lab Sample ID:** 552117361-0019

Sample Description: 105/Drywall joint compound

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A7-B **Lab Sample ID:** 552117361-0020

Sample Description: 114/Drywall joint compound

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A7-C **Lab Sample ID:** 552117361-0021

Sample Description: 123/Drywall joint compound

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A7-D **Lab Sample ID:** 552117361-0022

Sample Description: Cor 3/Drywall joint compound

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A7-E **Lab Sample ID:** 552117361-0023

Sample Description: 103/Drywall joint compound

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | White | 0.0% | 100.0% | None Detected | |



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552117361
Customer ID: 55DCSL97
Customer PO: 30094312
Project ID:

Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

Client Sample ID: A7-F **Lab Sample ID:** 552117361-0024
Sample Description: 205/Drywall joint compound

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A7-G **Lab Sample ID:** 552117361-0025
Sample Description: 205/Drywall joint compound

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A8-A **Lab Sample ID:** 552117361-0026
Sample Description: 105/Vinyl sheet flooring – turquoise

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|---------------------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM Grav. Reduction | 10/28/2021 | Green | 0.0% | 100% | None Detected | |
| TEM Grav. Reduction | 10/28/2021 | Green | 0.0% | 100.0% | None Detected | |

Client Sample ID: A8-B **Lab Sample ID:** 552117361-0027
Sample Description: Cor 1/Vinyl sheet flooring – turquoise

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|------------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Blue/Green | 0.0% | 100.0% | None Detected | |

Client Sample ID: A8-C **Lab Sample ID:** 552117361-0028
Sample Description: Cor 2/Vinyl sheet flooring – turquoise

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|------------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Blue/Green | 0.0% | 100.0% | None Detected | |

Client Sample ID: A9-A **Lab Sample ID:** 552117361-0029
Sample Description: Cor 1/Vinyl sheet flooring – beige

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|---------------------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM Grav. Reduction | 10/28/2021 | Beige | 0.0% | 100% | None Detected | |
| TEM Grav. Reduction | 10/28/2021 | Beige | 0.0% | 100.0% | None Detected | |

Client Sample ID: A9-B **Lab Sample ID:** 552117361-0030
Sample Description: Cor 2/Vinyl sheet flooring – beige

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Beige | 0.0% | 100.0% | None Detected | |

Client Sample ID: A9-C **Lab Sample ID:** 552117361-0031
Sample Description: Cor 3/Vinyl sheet flooring – beige

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Beige | 0.0% | 100.0% | None Detected | |



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552117361
Customer ID: 55DCSL97
Customer PO: 30094312
Project ID:

Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

Client Sample ID: A10-A **Lab Sample ID:** 552117361-0032
Sample Description: 114/Block filler paint

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A10-B **Lab Sample ID:** 552117361-0033
Sample Description: 125/Block filler paint

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A10-C **Lab Sample ID:** 552117361-0034
Sample Description: 116/Block filler paint

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A10-D **Lab Sample ID:** 552117361-0035
Sample Description: 109/Block filler paint

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A10-E **Lab Sample ID:** 552117361-0036
Sample Description: Stair 1/Block filler paint

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A10-F **Lab Sample ID:** 552117361-0037
Sample Description: Boiler room/Block filler paint

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A10-G **Lab Sample ID:** 552117361-0038
Sample Description: Electrical room/Block filler paint

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A11-A **Lab Sample ID:** 552117361-0039
Sample Description: 109/Concrete block mortar

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Gray | 0.0% | 100.0% | None Detected | |



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
 Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552117361
 Customer ID: 55DCSL97
 Customer PO: 30094312
 Project ID:

Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

Client Sample ID: A11-B **Lab Sample ID:** 552117361-0040
Sample Description: 110/Concrete block mortar

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Gray | 0.0% | 100.0% | None Detected | |

Client Sample ID: A11-C **Lab Sample ID:** 552117361-0041
Sample Description: Stair 1/Concrete block mortar

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Gray | 0.0% | 100.0% | None Detected | |

Client Sample ID: A12-A **Lab Sample ID:** 552117361-0042
Sample Description: Cor 1/Door frame caulking - white

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM Grav. Reduction | 10/28/2021 | White | 0.0% | 100% | None Detected | |
| TEM Grav. Reduction | 10/28/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A12-B **Lab Sample ID:** 552117361-0043
Sample Description: Cor 2/Door frame caulking – white

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A12-C **Lab Sample ID:** 552117361-0044
Sample Description: 114/Door frame caulking – white

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | White | 0.0% | 100.0% | None Detected | |

Client Sample ID: A13-A **Lab Sample ID:** 552117361-0045
Sample Description: 123/Vinyl sheet flooring – black

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM Grav. Reduction | 10/28/2021 | Green | 2.6% | 97.4% | None Detected | |
| TEM Grav. Reduction | 10/28/2021 | Green | 0.0% | 100.0% | None Detected | |

Client Sample ID: A13-B **Lab Sample ID:** 552117361-0046
Sample Description: 124/Vinyl sheet flooring – black

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|------------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Gray/Black | <1% | 100.0% | None Detected | |

Client Sample ID: A13-C **Lab Sample ID:** 552117361-0047
Sample Description: 123/Vinyl sheet flooring – black

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Green | 2.0% | 98.0% | None Detected | |



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
 Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552117361
 Customer ID: 55DCSL97
 Customer PO: 30094312
 Project ID:

Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

Client Sample ID: A14-A **Lab Sample ID:** 552117361-0048
Sample Description: 123/Black vinyl sheet flooring mastic

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|--------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Yellow | 0.0% | 100.0% | None Detected | |

Client Sample ID: A14-B **Lab Sample ID:** 552117361-0049
Sample Description: 123/Black vinyl sheet flooring mastic

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|--------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Yellow | 0.0% | 100.0% | None Detected | |

Client Sample ID: A14-C **Lab Sample ID:** 552117361-0050
Sample Description: 123/Black vinyl sheet flooring mastic

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|--------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Yellow | 0.0% | 100.0% | None Detected | |

Client Sample ID: A15-A **Lab Sample ID:** 552117361-0051
Sample Description: 123/2'x4' ceiling tile- pinholes and long fissures

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|------------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Gray/White | 70.0% | 30.0% | None Detected | |

Client Sample ID: A15-B **Lab Sample ID:** 552117361-0052
Sample Description: 123/2'x4' ceiling tile- pinholes and long fissures

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|------------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Gray/White | 70.0% | 30.0% | None Detected | |

Client Sample ID: A15-C **Lab Sample ID:** 552117361-0053
Sample Description: 123/2'x4' ceiling tile- pinholes and long fissures

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|------------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Gray/White | 60.0% | 40.0% | None Detected | |

Client Sample ID: A16-A **Lab Sample ID:** 552117361-0054
Sample Description: 123/Window glazing

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM Grav. Reduction | 10/28/2021 | Black | 0.0% | 100% | None Detected | |
| TEM Grav. Reduction | 10/28/2021 | Black | 0.0% | 100.0% | None Detected | |

Client Sample ID: A16-B **Lab Sample ID:** 552117361-0055
Sample Description: 123/Window glazing

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Gray | 0.0% | 100.0% | None Detected | |



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
 Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552117361
 Customer ID: 55DCSL97
 Customer PO: 30094312
 Project ID:

Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

Client Sample ID: A16-C **Lab Sample ID:** 552117361-0056
Sample Description: 123/Window glazing

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Gray | 0.0% | 100.0% | None Detected | |

Client Sample ID: A17-A **Lab Sample ID:** 552117361-0057
Sample Description: 205/12" white vinyl floor tile: white with black flecks

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|---------------------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM Grav. Reduction | 10/28/2021 | Green | 0.0% | 100% | None Detected | |
| TEM Grav. Reduction | 10/28/2021 | Green | 0.0% | 100.0% | None Detected | |

Client Sample ID: A17-B **Lab Sample ID:** 552117361-0058
Sample Description: 205/12" white vinyl floor tile: white with black flecks

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|------------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Gray/Black | 0.0% | 100.0% | None Detected | |

Client Sample ID: A17-C **Lab Sample ID:** 552117361-0059
Sample Description: 205/12" white vinyl floor tile: white with black flecks

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Green | 0.0% | 100.0% | None Detected | |

Client Sample ID: A18-A **Lab Sample ID:** 552117361-0060
Sample Description: 205/12" white vinyl floor tile mastic

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|--------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Yellow | 0.0% | 100.0% | None Detected | |

Client Sample ID: A18-B **Lab Sample ID:** 552117361-0061
Sample Description: 205/12" white vinyl floor tile mastic

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|--------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Yellow | 0.0% | 100.0% | None Detected | |

Client Sample ID: A18-C **Lab Sample ID:** 552117361-0062
Sample Description: 205/12" white vinyl floor tile mastic

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|--------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Yellow | 0.0% | 100.0% | None Detected | |

Client Sample ID: A19-A **Lab Sample ID:** 552117361-0063
Sample Description: Exterior/Parging cement

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|---------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Gray | <1% | 100.0% | None Detected | |



EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3
Phone/Fax: (289) 997-4602 / (289) 997-4607
<http://www.EMSL.com> / torontolab@emsl.com

EMSL Canada Order 552117361
Customer ID: 55DCSL97
Customer PO: 30094312
Project ID:

Test Report: Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05 via EPA600/R-93/116 Method

Client Sample ID: A19-B

Lab Sample ID: 552117361-0064

Sample Description: Exterior/Parging cement

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/28/2021 | Gray | <1% | 100.0% | None Detected | |

Client Sample ID: A19-C

Lab Sample ID: 552117361-0065

Sample Description: Exterior/Parging cement

| TEST | Analyzed Date | Color | Non-Asbestos | | Asbestos | Comment |
|------|------------------|-------|--------------|-------------|---------------|---------|
| | | | Fibrous | Non-Fibrous | | |
| PLM | 10/29/2021 | Gray | <1% | 100.0% | None Detected | |

Analyst(s):

Caroline Allen PLM Grav. Reduction (8)
Ramon Buenaventura PLM (21)
Sandy Burany, Ph.D TEM Grav. Reduction (8)
Steve Grise PLM (35)

Reviewed and approved by:

Matthew Davis or other approved signatory
or Other Approved Signatory

None Detected = <0.1%. EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. Estimation of uncertainty available upon request. This report is a summary of multiple methods of analysis, fully compliant reports are available upon request. A combination of PLM and TEM analysis may be necessary to ensure consistently reliable detection of asbestos. This report must not be used to claim product endorsement by NVLAP of any agency or the U.S. Government.

Samples analyzed by EMSL Analytical, Inc. Woburn, MA NVLAP Lab Code 101147-0, CT PH-0315, MA AA000188, RI AAL-139, VT AL998919, ME LB-0039

Initial report from: 10/29/2021 10:16:05



ARCADIS Canada Inc.
ATTN: Dwayne Kellyman
1050 Morrison Drive
Unit 201
Ottawa ON K2H 8K7

Date Received: 18-OCT-21
Report Date: 28-OCT-21 19:40 (MT)
Version: FINAL

Client Phone: 613-721-0555

Certificate of Analysis

Lab Work Order #: L2652690
Project P.O. #: NOT SUBMITTED
Job Reference: 30094312
C of C Numbers:
Legal Site Desc: CFB BORDEN BLDG. A-243

Emily Smith
Account Manager

[This report shall not be reproduced except in full without the written authority of the Laboratory.]

ADDRESS: 190 Colonnade Road, Unit 7, Ottawa, ON K2E 7J5 Canada | Phone: +1 613 225 8279 | Fax: +1 613 225 2801
ALS CANADA LTD Part of the ALS Group An ALS Limited Company

ALS ENVIRONMENTAL ANALYTICAL REPORT

| Sample Details/Parameters | | Result | Qualifier* | D.L. | Units | Extracted | Analyzed | Batch |
|--|--|--------|------------|--------|-------|-----------|-----------|----------|
| L2652690-1 P1-WHITE PAINT ON BLOCK WALL, ROOM 109 Sampled By: V. DARUWALA on 12-OCT-21 Matrix: PRODUCT | | | | | | | | |
| Physical Tests | | | | | | | | |
| % Moisture | | <0.25 | | 0.25 | % | 21-OCT-21 | 22-OCT-21 | R5626202 |
| Metals | | | | | | | | |
| Arsenic (As) | | <1.0 | | 1.0 | ug/g | 20-OCT-21 | 21-OCT-21 | R5626301 |
| Chromium (Cr) | | 14.3 | | 0.50 | ug/g | 20-OCT-21 | 21-OCT-21 | R5626301 |
| Lead (Pb) | | 4.7 | | 1.0 | ug/g | 20-OCT-21 | 21-OCT-21 | R5626301 |
| Mercury (Hg) | | 0.071 | | 0.050 | mg/kg | 20-OCT-21 | 21-OCT-21 | R5625986 |
| Polychlorinated Biphenyls | | | | | | | | |
| Aroclor 1016 | | <0.040 | DLIS | 0.040 | mg/kg | 26-OCT-21 | 26-OCT-21 | R5629084 |
| Aroclor 1221 | | <0.040 | DLIS | 0.040 | mg/kg | 26-OCT-21 | 26-OCT-21 | R5629084 |
| Aroclor 1232 | | <0.040 | DLIS | 0.040 | mg/kg | 26-OCT-21 | 26-OCT-21 | R5629084 |
| Aroclor 1242 | | <0.040 | DLIS | 0.040 | mg/kg | 26-OCT-21 | 26-OCT-21 | R5629084 |
| Aroclor 1248 | | <0.040 | DLIS | 0.040 | mg/kg | 26-OCT-21 | 26-OCT-21 | R5629084 |
| Aroclor 1254 | | 0.080 | DLIS | 0.040 | mg/kg | 26-OCT-21 | 26-OCT-21 | R5629084 |
| Aroclor 1260 | | 0.057 | DLIS | 0.040 | mg/kg | 26-OCT-21 | 26-OCT-21 | R5629084 |
| Aroclor 1262 | | <0.040 | DLIS | 0.040 | mg/kg | 26-OCT-21 | 26-OCT-21 | R5629084 |
| Aroclor 1268 | | <0.040 | DLIS | 0.040 | mg/kg | 26-OCT-21 | 26-OCT-21 | R5629084 |
| Total PCBs | | 0.14 | DLIS | 0.12 | mg/kg | 26-OCT-21 | 26-OCT-21 | R5629084 |
| Surrogate: d14-Terphenyl | | 97.5 | | 50-140 | % | 26-OCT-21 | 26-OCT-21 | R5629084 |
| L2652690-2 P2-WHITE PAINT ON DRYWALL, ROOM 114 Sampled By: V. DARUWALA on 12-OCT-21 Matrix: PRODUCT | | | | | | | | |
| Physical Tests | | | | | | | | |
| % Moisture | | <0.25 | | 0.25 | % | 21-OCT-21 | 22-OCT-21 | R5626202 |
| Metals | | | | | | | | |
| Arsenic (As) | | <1.0 | | 1.0 | ug/g | 20-OCT-21 | 21-OCT-21 | R5626301 |
| Chromium (Cr) | | 19.9 | | 0.50 | ug/g | 20-OCT-21 | 21-OCT-21 | R5626301 |
| Lead (Pb) | | 7.6 | | 1.0 | ug/g | 20-OCT-21 | 21-OCT-21 | R5626301 |
| Mercury (Hg) | | <0.050 | | 0.050 | mg/kg | 20-OCT-21 | 21-OCT-21 | R5625986 |
| Polychlorinated Biphenyls | | | | | | | | |
| Aroclor 1016 | | <0.85 | DLR | 0.85 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1221 | | <0.85 | DLR | 0.85 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1232 | | <0.85 | DLR | 0.85 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1242 | | <0.85 | DLR | 0.85 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1248 | | <0.85 | DLR | 0.85 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1254 | | <0.85 | DLR | 0.85 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1260 | | <0.85 | DLR | 0.85 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1262 | | <0.85 | DLR | 0.85 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1268 | | <0.85 | DLR | 0.85 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Total PCBs | | <2.6 | DLR | 2.6 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Surrogate: d14-Terphenyl | | 99.8 | | 50-140 | % | 27-OCT-21 | 27-OCT-21 | R5629084 |
| L2652690-3 P3-LIGHT BLUE PAINT ON EXTERIOR DOOR, EXTERIOR Sampled By: V. DARUWALA on 12-OCT-21 Matrix: PRODUCT | | | | | | | | |

* Refer to Referenced Information for Qualifiers (if any) and Methodology.

ALS ENVIRONMENTAL ANALYTICAL REPORT

| Sample Details/Parameters | | Result | Qualifier* | D.L. | Units | Extracted | Analyzed | Batch |
|---------------------------|--|--------|------------|--------|-------|-----------|-----------|----------|
| L2652690-3 | P3-LIGHT BLUE PAINT ON EXTERIOR DOOR, EXTERIOR | | | | | | | |
| Sampled By: | V. DARUWALA on 12-OCT-21 | | | | | | | |
| Matrix: | PRODUCT | | | | | | | |
| Physical Tests | | | | | | | | |
| % Moisture | | <0.25 | | 0.25 | % | 21-OCT-21 | 22-OCT-21 | R5626202 |
| Metals | | | | | | | | |
| Arsenic (As) | | <1.0 | | 1.0 | ug/g | 20-OCT-21 | 21-OCT-21 | R5626301 |
| Chromium (Cr) | | 12.3 | | 0.50 | ug/g | 20-OCT-21 | 21-OCT-21 | R5626301 |
| Lead (Pb) | | 16.7 | | 1.0 | ug/g | 20-OCT-21 | 21-OCT-21 | R5626301 |
| Mercury (Hg) | | 0.155 | | 0.050 | mg/kg | 20-OCT-21 | 21-OCT-21 | R5625986 |
| Polychlorinated Biphenyls | | | | | | | | |
| Aroclor 1016 | | <1.0 | DLR | 1.0 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1221 | | <1.0 | DLR | 1.0 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1232 | | <1.0 | DLR | 1.0 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1242 | | <1.0 | DLR | 1.0 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1248 | | <1.0 | DLR | 1.0 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1254 | | <1.0 | DLR | 1.0 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1260 | | <1.0 | DLR | 1.0 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1262 | | <1.0 | DLR | 1.0 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Aroclor 1268 | | <1.0 | DLR | 1.0 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Total PCBs | | <3.0 | DLR | 3.0 | mg/kg | 27-OCT-21 | 27-OCT-21 | R5629084 |
| Surrogate: d14-Terphenyl | | 101.5 | | 50-140 | % | 27-OCT-21 | 27-OCT-21 | R5629084 |
| | | | | | | | | |

* Refer to Referenced Information for Qualifiers (if any) and Methodology.

QC Samples with Qualifiers & Comments:

| QC Type Description | Parameter | Qualifier | Applies to Sample Number(s) |
|---------------------|--------------|-----------|-----------------------------|
| Duplicate | Aroclor 1254 | DUP-H | L2652690-1, -2, -3 |
| Duplicate | Aroclor 1260 | DUP-H | L2652690-1, -2, -3 |
| Matrix Spike | Aroclor 1242 | MS-B | L2652690-1, -2, -3 |
| Matrix Spike | Aroclor 1254 | MS-B | L2652690-1, -2, -3 |
| Matrix Spike | Aroclor 1260 | MS-B | L2652690-1, -2, -3 |

Sample Parameter Qualifier key listed:

| Qualifier | Description |
|-----------|---|
| DLIS | Detection Limit Adjusted: Insufficient Sample |
| DLR | Detection Limit Raised due to required dilution, limited sample amount, and/or high moisture content (soil samples) |
| DUP-H | Duplicate results outside ALS DQO, due to sample heterogeneity. |
| MS-B | Matrix Spike recovery could not be accurately calculated due to high analyte background in sample. |

Test Method References:

| ALS Test Code | Matrix | Test Description | Method Reference** |
|---|--------|-----------------------------------|---------------------------------|
| HG-PAINT-WT | Misc. | Mercury by CVAA in Paint Chips | SW846 7470A |
| MET-200.2-CCMS-WT | Misc. | Metals in Paint and Miscellaneous | EPA 200.2/EPA6020A(mod) |
| Paint samples are digested with nitric and hydrochloric acids, followed by analysis by CRC ICPMS. | | | |
| MOISTURE-WT | Soil | % Moisture | CCME PHC in Soil - Tier 1 (mod) |
| PCB9-WT | Soil | PCBs | EPA 8270 |
| A representative sub-sample of a soil sample is mixed with methanol and extracted with toluene using a shaker technique. An aliquot of the separated toluene is analyzed by GC/MSD. | | | |

** ALS test methods may incorporate modifications from specified reference methods to improve performance.

The last two letters of the above test code(s) indicate the laboratory that performed analytical analysis for that test. Refer to the list below:

| Laboratory Definition Code | Laboratory Location |
|----------------------------|---|
| WT | ALS ENVIRONMENTAL - WATERLOO, ONTARIO, CANADA |

Chain of Custody Numbers:

GLOSSARY OF REPORT TERMS

Surrogates are compounds that are similar in behaviour to target analyte(s), but that do not normally occur in environmental samples. For applicable tests, surrogates are added to samples prior to analysis as a check on recovery. In reports that display the D.L. column, laboratory objectives for surrogates are listed there.

mg/kg - milligrams per kilogram based on dry weight of sample

mg/kg ww_t - milligrams per kilogram based on wet weight of sample

mg/kg lw_t - milligrams per kilogram based on lipid weight of sample

mg/L - unit of concentration based on volume, parts per million.

< - Less than.

D.L. - The reporting limit.

N/A - Result not available. Refer to qualifier code and definition for explanation.

Test results reported relate only to the samples as received by the laboratory.

UNLESS OTHERWISE STATED, ALL SAMPLES WERE RECEIVED IN ACCEPTABLE CONDITION.

Analytical results in unsigned test reports with the DRAFT watermark are subject to change, pending final QC review.

Quality Control Report

Workorder: L2652690

Report Date: 28-OCT-21

Page 2 of 3

Client: ARCADIS Canada Inc.
1050 Morrison Drive Unit 201
Ottawa ON K2H 8K7

Contact: Dwayne Kellyman

| Test | Matrix | Reference | Result | Qualifier | Units | RPD | Limit | Analyzed |
|--------------------------|-----------------|--------------------|--------|-----------|-------|-----|--------|-----------|
| PCB9-WT | | Soil | | | | | | |
| Batch | R5629084 | | | | | | | |
| WG3644514-4 | DUP | WG3644514-1 | | | | | | |
| Aroclor 1016 | | <15 | <18 | RPD-NA | mg/kg | N/A | 50 | 26-OCT-21 |
| Aroclor 1221 | | <15 | <18 | RPD-NA | mg/kg | N/A | 50 | 26-OCT-21 |
| Aroclor 1232 | | <15 | <18 | RPD-NA | mg/kg | N/A | 50 | 26-OCT-21 |
| Aroclor 1242 | | <15 | <18 | RPD-NA | mg/kg | N/A | 40 | 26-OCT-21 |
| Aroclor 1248 | | <15 | <18 | RPD-NA | mg/kg | N/A | 40 | 26-OCT-21 |
| Aroclor 1254 | | 2460 | 1520 | DUP-H | mg/kg | 47 | 40 | 26-OCT-21 |
| Aroclor 1260 | | <252 | 154 | DUP-H | mg/kg | 48 | 40 | 26-OCT-21 |
| Aroclor 1262 | | <252 | <18 | RPD-NA | mg/kg | N/A | 50 | 26-OCT-21 |
| Aroclor 1268 | | <252 | <18 | RPD-NA | mg/kg | N/A | 50 | 26-OCT-21 |
| WG3644514-3 | LCS | | | | | | | |
| Aroclor 1242 | | | 103.6 | | % | | 60-140 | 26-OCT-21 |
| Aroclor 1248 | | | 88.1 | | % | | 60-140 | 26-OCT-21 |
| Aroclor 1254 | | | 98.3 | | % | | 60-140 | 26-OCT-21 |
| Aroclor 1260 | | | 117.8 | | % | | 60-140 | 26-OCT-21 |
| WG3644514-2 | MB | | | | | | | |
| Aroclor 1016 | | | <0.010 | | mg/kg | | 0.01 | 26-OCT-21 |
| Aroclor 1221 | | | <0.010 | | mg/kg | | 0.01 | 26-OCT-21 |
| Aroclor 1232 | | | <0.010 | | mg/kg | | 0.01 | 26-OCT-21 |
| Aroclor 1242 | | | <0.010 | | mg/kg | | 0.01 | 26-OCT-21 |
| Aroclor 1248 | | | <0.010 | | mg/kg | | 0.01 | 26-OCT-21 |
| Aroclor 1254 | | | <0.010 | | mg/kg | | 0.01 | 26-OCT-21 |
| Aroclor 1260 | | | <0.010 | | mg/kg | | 0.01 | 26-OCT-21 |
| Aroclor 1262 | | | <0.010 | | mg/kg | | 0.01 | 26-OCT-21 |
| Aroclor 1268 | | | <0.010 | | mg/kg | | 0.01 | 26-OCT-21 |
| Surrogate: d14-Terphenyl | | | 99.4 | | % | | 50-140 | 26-OCT-21 |
| WG3644514-5 | MS | WG3644514-1 | | | | | | |
| Aroclor 1242 | | | N/A | MS-B | % | | - | 26-OCT-21 |
| Aroclor 1254 | | | N/A | MS-B | % | | - | 26-OCT-21 |
| Aroclor 1260 | | | N/A | MS-B | % | | - | 26-OCT-21 |

Quality Control Report

Workorder: L2652690

Report Date: 28-OCT-21

Client: ARCADIS Canada Inc.
1050 Morrison Drive Unit 201
Ottawa ON K2H 8K7

Page 3 of 3

Contact: Dwayne Kellyman

Legend:

| | |
|-------|---|
| Limit | ALS Control Limit (Data Quality Objectives) |
| DUP | Duplicate |
| RPD | Relative Percent Difference |
| N/A | Not Available |
| LCS | Laboratory Control Sample |
| SRM | Standard Reference Material |
| MS | Matrix Spike |
| MSD | Matrix Spike Duplicate |
| ADE | Average Desorption Efficiency |
| MB | Method Blank |
| IRM | Internal Reference Material |
| CRM | Certified Reference Material |
| CCV | Continuing Calibration Verification |
| CVS | Calibration Verification Standard |
| LCSD | Laboratory Control Sample Duplicate |

Sample Parameter Qualifier Definitions:

| Qualifier | Description |
|-----------|--|
| DUP-H | Duplicate results outside ALS DQO, due to sample heterogeneity. |
| MS-B | Matrix Spike recovery could not be accurately calculated due to high analyte background in sample. |
| NSS | Non-standard sample matrix. Modified methods were used for sample processing and analysis. |
| RPD-NA | Relative Percent Difference Not Available due to result(s) being less than detection limit. |

Hold Time Exceedances:

All test results reported with this submission were conducted within ALS recommended hold times.

ALS recommended hold times may vary by province. They are assigned to meet known provincial and/or federal government requirements. In the absence of regulatory hold times, ALS establishes recommendations based on guidelines published by the US EPA, APHA Standard Methods, or Environment Canada (where available). For more information, please contact ALS.

The ALS Quality Control Report is provided to ALS clients upon request. ALS includes comprehensive QC checks with every analysis to ensure our high standards of quality are met. Each QC result has a known or expected target value, which is compared against pre-determined data quality objectives to provide confidence in the accuracy of associated test results.

Please note that this report may contain QC results from anonymous Sample Duplicates and Matrix Spikes that do not originate from this Work Order.

Chain of Custody (COC) / Analytic Request Form



COC Number: 17 -

Page of

Canada Toll Free: 1 800 668 9878

L2652690-COFC

www.alsglobal.com

[illegible]

REFER TO BACK PAGE FOR ALS LOCATIONS AND SAMPLING INFORMATION

WHITE - LABORATORY COPY YELLOW - CLIENT COPY

JUNE 2018 FRONT

Failure to complete all portions of this form may delay analysis. Please fill in this form LEGIBLY. By the use of this form the user acknowledges and agrees with the Terms and Conditions as specified on the back page of the white - report copy.

1. If any water samples are taken from a **Regulated Drinking Water (DW) System**, please submit using an **Authorized DW COC form**.

APPENDIX C

Summary of Results of Analyses of Bulk Samples for Asbestos Content – Building A-243

Table C.1 Summary of Results of Analyses of Bulk Samples for Asbestos Content – Building A - 243

| Sample No. | Sample Location | Sample Description | Asbestos Content |
|-----------------|-----------------|--|---|
| A1-A | Room 105 | 2'x4' ceiling tile – pinhole and medium fissures | None Detected |
| A1-B (Photo 4) | Room 103 | 2'x4' ceiling tile – pinhole and medium fissures | None Detected |
| A1-C | Room 102 | 2'x4' ceiling tile – pinhole and medium fissures | None Detected |
| A2-A | Room 102 | Vinyl baseboard – turquoise | None Detected None Detected (TEM) |
| A2-B (Photo 6) | Room 103 | Vinyl baseboard – turquoise | None Detected |
| A2-C | Room 105 | Vinyl baseboard – turquoise | None Detected |
| A3-A (Photo 5) | Room 102 | Turquoise vinyl baseboard mastic | None Detected |
| A3-B | Room 103 | Turquoise vinyl baseboard mastic | None Detected |
| A3-C | Room 105 | Turquoise vinyl baseboard mastic | None Detected |
| A4-A (Photo 10) | Corridor 1 | Stone mortar | None Detected |
| A4-B | Corridor 2 | Stone mortar | None Detected |
| A4-C | Corridor 2 | Stone mortar | None Detected |
| A5-A (Photo 8) | Corridor 1 | Vinyl baseboard – beige | None Detected None Detected (TEM) |
| A5-B | Corridor 2 | Vinyl baseboard – beige | None Detected |
| A5-C | Corridor 1 | Vinyl baseboard – beige | None Detected |
| A6-A (Photo 9) | Corridor 1 | Beige vinyl baseboard mastic | None Detected |
| A6-B | Corridor 2 | Beige vinyl baseboard mastic | Insufficient material (sample bag is empty) |
| A6-C | Corridor 1 | Beige vinyl baseboard mastic | None Detected |
| A7-A (Photo 7) | Room 105 | Drywall joint compound | None Detected |
| A7-B | Room 114 | Drywall joint compound | None Detected |
| A7-C | Room 123 | Drywall joint compound | None Detected |
| A7-D | Corridor 3 | Drywall joint compound | None Detected |
| A7-E | Room 103 | Drywall joint compound | None Detected |

FINAL REPORT – DESIGNATED SUBSTANCES SURVEY – BUILDING A-243

| Sample No. | Sample Location | Sample Description | Asbestos Content |
|------------------|-----------------|----------------------------------|--------------------------------------|
| A7-F | Room 205 | Drywall joint compound | None Detected |
| A7-G | Room 205 | Drywall joint compound | None Detected |
| A8-A (Photo 11) | Room 105 | Vinyl sheet flooring – turquoise | None Detected None Detected (TEM) |
| A8-B | Corridor 1 | Vinyl sheet flooring – turquoise | None Detected |
| A8-C | Corridor 2 | Vinyl sheet flooring – turquoise | None Detected |
| A9-A | Corridor 1 | Vinyl sheet flooring – beige | None Detected None Detected (TEM) |
| A9-B (Photo 12) | Corridor 2 | Vinyl sheet flooring – beige | None Detected |
| A9-C | Corridor 3 | Vinyl sheet flooring – beige | None Detected |
| A10-A | Room 114 | Block filler paint | None Detected |
| A10-B | Room 125 | Block filler paint | None Detected |
| A10-C (Photo 13) | Room 116 | Block filler paint | None Detected |
| A10-D | Room 109 | Block filler paint | None Detected |
| A10-E | Stairwell 1 | Block filler paint | None Detected |
| A10-F | Boiler Room | Block filler paint | None Detected |
| A10-G | Electrical Room | Block filler paint | None Detected |
| A11-A | Room 109 | Concrete block mortar | None Detected |
| A11-B (Photo 15) | Room 110 | Concrete block mortar | None Detected |
| A11-C | Stairwell 1 | Concrete block mortar | None Detected |
| A12-A | Corridor 1 | Door frame caulking – white | None Detected None Detected (TEM) |
| A12-B (Photo 16) | Corridor 2 | Door frame caulking – white | None Detected |
| A12-C | Room 114 | Door frame caulking – white | None Detected |
| A13-A (Photo 18) | Room 123 | Vinyl sheet flooring – black | None Detected |

FINAL REPORT – DESIGNATED SUBSTANCES SURVEY – BUILDING A-243

| Sample No. | Sample Location | Sample Description | Asbestos Content |
|------------------|-----------------|---|--------------------------------------|
| | | | None Detected (TEM) |
| A13-B | Room 124 | Vinyl sheet flooring – black | None Detected |
| A13-C | Room 123 | Vinyl sheet flooring – black | None Detected |
| A14-A (Photo 17) | Room 123 | Black vinyl sheet flooring mastic | None Detected |
| A14-B | Room 123 | Black vinyl sheet flooring mastic | None Detected |
| A14-C | Room 123 | Black vinyl sheet flooring mastic | None Detected |
| A15-A (Photo 19) | Room 123 | 2'x4' ceiling tile – pinholes and long fissures | None Detected |
| A15-B | Room 123 | 2'x4' ceiling tile – pinholes and long fissures | None Detected |
| A15-C | Room 123 | 2'x4' ceiling tile – pinholes and long fissures | None Detected |
| A16-A | Room 123 | Window glazing | None Detected None Detected (TEM) |
| A16-B | Room 123 | Window glazing | None Detected |
| A16-C (Photo 20) | Room 123 | Window glazing | None Detected |
| A17-A (Photo 23) | Room 205 | 12" white vinyl floor tile – white with black flecks | None Detected None Detected (TEM) |
| A17-B | Room 205 | 12" white vinyl floor tile – white with black flecks | None Detected |
| A17-C | Room 205 | 12" white vinyl floor tile – white with black flecks | None Detected |
| A18-A (Photo 24) | Room 205 | 12" white vinyl floor tile (white with black flecks) – mastic | None Detected |
| A18-B | Room 205 | 12" white vinyl floor tile (white with black flecks) – mastic | None Detected |
| A18-C | Room 205 | 12" white vinyl floor tile (white with black flecks) – mastic | None Detected |
| A19-A | Exterior | Parging cement | None Detected |
| A19-B | Exterior | Parging cement | None Detected |
| A19-C | Exterior | Parging cement | None Detected |

NOTE:

Bulk samples were analyzed by Polarized Light Microscopy (PLM) analysis, except where “TEM” is noted, in which case Transmission Electron Microscopy analysis was also performed.

APPENDIX D

Photographs

Project Photographs

BuildingA - 243
CFB Borden, Ontario



Photo: 1

Date:

October 12, 2021.

Location/Description:

General East view of Building A – 243.



Photo: 2

Date:

October 12, 2021.

Location/Description:

General North view of Building A – 243.



Photo: 3

Date:

October 12, 2021.

Location/Description:

General South view of Building A – 243.

Project Photographs

Building A - 243
CFB Borden, Ontario




Photo: 4

Date:

October 12, 2021.

Location/Description:

Room 103/Sample A1-B –
Non-asbestos-containing 2'x4'
ceiling tile with pinholes and
fissures.




Photo: 5

Date:

October 12, 2021.

Location/Description:

Room 102/Sample A3-A –
Non-asbestos-containing
mastic behind baseboard –
turquoise.




Photo: 6

Date:

October 12, 2021.

Location/Description:

Room B001/Sample A2-B –
Non-asbestos-containing vinyl
baseboard – turquoise.

Project Photographs

Building A - 243
CFB Borden, Ontario




Photo: 7

Date:

October 12, 2021.

Location/Description:

Room 105/Sample A7-A –
Non-asbestos-containing
drywall joint compound.




Photo: 8

Date:

October 12, 2021.

Location/Description:

Corridor-1/Sample A5-A –
Non-asbestos-containing
beige vinyl baseboard.




Photo: 9

Date:

October 12, 2021.

Location/Description:

Corridor-1/Sample A6-A –
Non-asbestos-containing
mastic behind beige vinyl
baseboard.

Project Photographs

Building A - 243
CFB Borden, Ontario



Photo: 10

Date:

October 12, 2021.

Location/Description:

Corridor-1/Sample A4-A –
Non-asbestos-containing
stone mortar.



Photo: 11

Date:

October 12, 2021.

Location/Description:

Room 105/Sample A8-A –
Non-asbestos-containing
turquoise vinyl sheet flooring.



Photo: 12

Date:

October 12, 2021.

Location/Description:

Corridor-2/Sample A9-B –
Non-asbestos-containing
beige vinyl sheet flooring.

Project Photographs

Building A - 243
CFB Borden, Ontario




Photo: 13

Date:

October 12, 2021.

Location/Description:

Room 116/Sample A10-C –
Non-asbestos-containing
block filler paint.




Photo: 14

Date:

October 12, 2021.

Location/Description:

Room 109/Sample P-1 –
White paint on block wall. No
parameters exceeded.




Photo: 15

Date:

October 12, 2021.

Location/Description:

Room 110/Sample A11-B –
Non-asbestos-containing
concrete block mortar.

Project Photographs

Building A - 243
CFB Borden, Ontario




Photo: 16

Date:

October 12, 2021.

Location/Description:

Corridor-2/Sample A12-B –
Non-asbestos-containing
white door frame caulking.



Photo: 17

Date:

October 12, 2021.

Location/Description:

Room 123/Sample A14-A –
Non-asbestos-containing
mastic behind black vinyl
sheet flooring.



Photo: 18

Date:

October 12, 2021.

Location/Description:

Room 123/Sample A13-A –
Non-asbestos-containing
black vinyl sheet flooring.

Project Photographs

Building A - 243
CFB Borden, Ontario




Photo: 19

Date:

October 12, 2021.

Location/Description:

Room 123/Sample A15-A – Non-asbestos-containing 2'x4' ceiling tile with pinholes and long fissures.




Photo: 20

Date:

October 12, 2021.

Location/Description:

Room 123/Sample A16-C – Non-asbestos-containing window glazing.



Photo: 21

Date:

October 12, 2021.

Location/Description:

View inside the POL shed at Building A-243.

Project Photographs

Building A - 243
CFB Borden, Ontario



Photo: 22

Date:

October 12, 2021.

Location/Description:

Room 205/View of suspect mould growth on non-asbestos ceiling tile.




Photo: 23

Date:

October 12, 2021.

Location/Description:

Room 205/Sample A17-A – Non-asbestos containing 12" vinyl floor tile with black flecks.




Photo: 24

Date:

October 12, 2021.

Location/Description:

Room 205/Sample A18-B – Non-asbestos containing mastic behind 12" vinyl floor tile with black flecks.

Project Photographs

Building A - 243
CFB Borden, Ontario




Photo: 25

Date:

October 12, 2021.

Location/Description:

Exterior/Sample P-3 – Light blue paint on exterior door. No parameters exceeded.



Photo: 26

Date:

October 12, 2021.

Location/Description:

Boiler Room/Boiler – May contain asbestos-containing material.




Photo: 27

Date:

October 12, 2021.


Location/Description:

Room 114 /Sample P-2 – White paint on drywall wall. No parameters exceeded.

APPENDIX E

Asbestos Condition Assessment and Response Chart

ASBESTOS CONDITION ASSESSMENT
AND RESPONSE CHART



- ACTION 1 – Restrict access to the area and clean up the ACM debris using appropriate asbestos procedures.
- ACTION 2 – Restricted Entry into areas that contain, or may contain ACM Debris. All entry into the area will require at a minimum Type 2 procedures until the ACM debris have been cleaned up, and the source of the debris have been stabilized or removed.
- ACTION 3 – Asbestos removal required for compliance. Develop scope of work and utilize appropriate removal procedures.
- ACTION 4 – Limited Entry: personnel who enter into these areas have to be aware of the presence of the type and location of the ACM. If any entry into the area may cause a disturbance of the ACM, Type 2 procedures must be used for entry until the ACM is removed.
- ACTION 5 – ACM may be repaired if the ACM is considered to be in Fair Condition (less than 10% damaged), and it is unlikely for the material to be damaged, or disturbed again. Once the ACM has been repaired it may be treated as in GOOD condition (less than 1% damaged).
- ACTION 6 – No remedial action is required. The materials are to be managed in accordance with the Asbestos Management Directive.
- NOTE: *Pro Active Removal may be a part of an Asbestos Management plan or for removal of ACM that are in locations that may not be desirable regardless of the materials condition.*

APPENDIX F

MOL – Sample List of Suspect Asbestos-Containing Building Materials

Appendix 2 – Sample List of Suspect Asbestos-Containing Building Materials

Issued: November 2007

Content last reviewed: May 2011

There are an estimated 3000 products that contain asbestos. In Ontario asbestos was widely used in sprayed-on material and in pipe and boiler insulation until 1973^[3]. The use of many other asbestos containing materials continued until the mid 1980's. Asbestos is still used in the manufacture of a limited number of products, including some floor tiles, cement products, friction materials and textiles. The following list was adapted from the United States Environmental Protection Agency's (EPA) Sample List of Suspect Asbestos Containing Materials^[4]. It is not an all inclusive list but is intended as a general guide to show which types of building materials may contain asbestos.

Possible Asbestos-Containing Materials in Buildings

- Acoustical Plaster
- Adhesives
- Asphalt Floor Tile
- Base Flashing
- Blown-in (Loose fill) Insulation
- Boiler Insulation
- Breaching Insulation
- Caulking/Putties
- Ceiling Tiles and Lay-in Panels
- Cement Pipes
- Cement Siding
- Cement Wallboard
- Construction Mastics (floor tile, carpet, ceiling tile, etc.)
- Cooling Towers
- Decorative Plaster
- Ductwork Flexible Fabric Connections
- Electrical Cloth
- Electrical Panel Partitions
- Electrical Wiring Insulation
- Elevator Brake Shoes
- Elevator Equipment Panels
- Fire Doors
- Fireproofing Materials
- Flooring Backing
- Heating and Electrical Ducts
- High Temperature Gaskets
- HVAC Duct Insulation
- Joint Compounds
- Pipe Insulation (corrugated air-cell, block, etc.)
- Roofing Felt
- Roofing Shingles
- Spackling Compounds
- Sprayed-on Insulation

- Taping Compounds (thermal)
- Textured Paints/Coatings
- Thermal Paper Products
- Vinyl Floor Tile
- Vinyl Sheet Flooring
- Vinyl Wall Coverings
- Wallboard

[3] J.S. Dupre, J.F. Mustard & R.J. Uffin, *Report of the Royal Commission on Matters of Health and Safety Arising from the Use of Asbestos in Ontario*, Ontario Ministry of the Attorney General, Toronto, Ontario, 1984, page 12.

[4] US Environmental Protection Agency.

ISBN 1-4249-1226-1 (HTML)
ISBN 1-4249-1226-1 (PRINT)
ISBN 1-4249-1226-1 (PDF)

Disclaimer: This web resource has been prepared to assist the workplace parties in understanding some of their obligations under the Occupational Health and Safety Act (OHSA) and the regulations. It is not intended to replace the OHSA or the regulations and reference should always be made to the official version of the legislation.

It is the responsibility of the workplace parties to ensure compliance with the legislation. This web resource does not constitute legal advice. If you require assistance with respect to the interpretation of the legislation and its potential application in specific circumstances, please contact your legal counsel.

While this web resource will also be available to Ministry of Labour inspectors, they will apply and enforce the OHSA and its regulations based on the facts as they may find them in the workplace. This web resource does not affect their enforcement discretion in any way.



Arcadis Canada Inc.

121 Granton Drive, Suite 12

Richmond Hill, Ontario

L4B 3N4

Tel 905 764.9380

www.arcadis.com