

# DESIGNATED SUBSTANCES AND HAZARDOUS BUILDING MATERIALS ASSESSMENT REPORT

Accessibility Upgrades Project  
Downsview Public School  
2829 Keele Street  
North York, Ontario  
M3M 2G4

*Prepared for:*  
Reem Makhoul  
Project Supervisor

Toronto District School Board  
15 Oakburn Crescent  
Toronto, Ontario  
M2N 2T5

*Prepared by:*  
Safetech Environmental Limited

A handwritten signature in black ink, appearing to read "Dan Whittal".

Dan Whittal  
Occupational Health and Safety Technician

*Reviewed by:*

A handwritten signature in black ink, appearing to read "Daniel D'Aloisio".

Daniel D'Aloisio, B.Sc., A.M.R.T  
Senior Project Manager

Safetech Project Number: 1-3260212

Date of Site Work: March 6, 2026  
Date of Issue: March 19, 2026

Revised

## TABLE OF CONTENTS

<b>EXECUTIVE SUMMARY .....</b>	<b>i</b>
<b>1.0 Introduction .....</b>	<b>1</b>
1.1 Background and Objectives .....	1
1.2 Scope of Work.....	2
1.3 Description of Area(s) Assessed .....	3
<b>2.0 Results .....</b>	<b>3</b>
2.1 Designated Substances .....	3
2.1.1 Asbestos.....	3
2.1.2 Lead.....	9
2.1.3 Mercury.....	11
2.1.4 Silica .....	11
2.1.5 Other Designated Substances.....	11
2.2 Other Hazardous Materials .....	11
2.2.1 Chemical Hazards .....	11
2.2.2 Biological Hazards.....	11
2.2.3 Environmental Hazards .....	11
<b>3.0 Conclusions and Recommendations.....</b>	<b>12</b>
3.1 Designated Substances .....	12
3.1.1 Asbestos.....	12
3.1.2 Lead.....	12
3.1.3 Mercury.....	14
3.1.4 Silica .....	15
3.1.5 Other Designated Substances.....	16
3.2 Other Hazardous Materials .....	16
3.2.1 Chemical Hazards .....	16
3.2.2 Biological Hazards.....	16
3.2.3 Environmental Hazards .....	16
<b>4.0 Limitations .....</b>	<b>17</b>

## **LIST OF TABLES**

Table 1: Summary of Hazardous Materials and Designated Substances

Table 2: Bulk Sample Analytical Results for Determination of Asbestos Content

Table 3: Results of Assessment for Asbestos-Containing Materials

Table 4: Results of Paint Condition and Lead Content Assessment

Table 5: Results of Assessment for Lead-Containing Materials

## **LIST OF APPENDICES**

Appendix A: Summary of ACM Occurrences

Appendix B: Site Drawings

Appendix C: Laboratory Certificate of Analysis – Asbestos

Appendix D: Laboratory Certificate of Analysis – Lead

Appendix E: Methodology

## EXECUTIVE SUMMARY

Safetech Environmental Limited (Safetech) was commissioned by Toronto District School Board to conduct a designated substances and hazardous materials assessment in project specific locations of Downsview Public School, 2829 Keele Street, North York, Ontario.

The objective of the assessment was to determine the presence, location, condition and quantities of designated substances and other hazardous materials that have the potential to be disturbed as part of planned construction activities (i.e. Accessibility Upgrades Project) so that appropriate control measures can be implemented to protect workers during the work.

A summary of the assessment results and general recommendations based on our findings are provided in the following table. This table should be considered a summary only. Please refer to the Results (Section 2.0), Conclusions and Recommendations (Section 3.0), Summary of ACM Occurrences (Appendix A) and Site Drawings (Appendix B) of our report for additional details.

**Table 1: Summary of Hazardous Materials and Designated Substances**

Designated Substance	Findings	Recommendations
Asbestos	No asbestos-containing materials were identified in the areas assessed that would be impacted during the project.	No action required.
Lead	<p>Grey and cream paint were confirmed to be lead-containing paint (&gt;0.1% lead content).</p> <p>The following materials are assumed to be lead-containing:</p> <ul style="list-style-type: none"> <li>- paints and surface coatings (not sampled)</li> <li>- solder in copper pipe fittings</li> <li>- solder in electrical components</li> </ul>	Disturbance of lead-containing materials must be conducted in accordance with the Ontario Ministry of Labour, Immigration, Training and Skills Development (MLITSD) <i>Lead on Construction Projects</i> guideline (2011) and/or the Environmental Abatement Council of Canada (EACC) <i>Lead Guideline</i> (October 2014). For additional details, refer to Section 2.1.2 (Results) and Section 3.1.2 (Conclusions and Recommendations). Lead-containing wastes should be recycled if practicable or handled and disposed of according to R.R.O. 1990, Regulation 347, <i>General- Waste Management</i> .

Mercury	Sources of mercury were observed in the subject area and include the following:  - vapour in fluorescent lamps - liquid in thermostats	If required, handle lamps with care and keep intact. All waste lamps are recommended to be sent to a lamp recycling facility.
Silica	Building materials identified that are suspected to contain crystalline silica and may be disturbed as part of the planned construction project include:  - drywall walls/drywall joint compound - concrete - mortar	Any work involving the disturbance of silica-containing materials should follow the procedures outlined in the Ontario MLITSD "Silica on Construction Projects" guideline. For additional information, refer to Section 2.1.4 (Results) and Section 3.1.4 (Conclusions and Recommendations).
Other Designated Substances	No other designated substances are expected to be present in any significant quantities or in a form that would represent an exposure concern.	No protective measures or procedures specific to acrylonitrile, arsenic, benzene, coke oven emissions, ethylene oxide, isocyanates, and vinyl chloride are considered necessary.
<b>Other Hazardous Materials</b>	<b>Findings</b>	<b>Recommendations</b>
Urea Formaldehyde Foam Insulation	No UFFI was identified or is suspected in the subject area.	No action required.
Mould Contamination	No suspect mould contamination was observed on building finishes in the subject area.	No action required.
Pest Infestation	No pest infestations were observed in the areas assessed.	No action required.
Polychlorinated Biphenyls	Fluorescent light ballasts are assumed to contain PCB's.	PCB-containing ballasts should be removed, separated from other waste and disposed of as PCB waste at an authorized destruction facility.
Ozone Depleting and Global Warming Substances	No equipment was observed that is suspected to contain ozone depleting and/or global warming substances	No action required.

This assessment satisfies the Owner's requirements under Section 30 of the Ontario Occupational Health and Safety Act (OHSA), Revised Statutes of Ontario 1990, as amended.

Should you have any questions regarding the information contained in the report, please contact our office.

**Safetech Environmental Limited**



**Dan Whittal**  
**OH&S Technician**

March 19, 2026

Toronto District School Board  
15 Oakburn Crescent  
Toronto, Ontario  
M2N 2T5

Attention: Reem Makhoul  
Project Supervisor

**RE: Designated Substances and Hazardous Materials Assessment  
Accessibility Upgrades Project  
Downsview Public School  
2829 Keele Street, North York, Ontario**

---

## **1.0 INTRODUCTION**

### **1.1 Background and Objectives**

Safetech Environmental Limited (Safetech) was commissioned by Toronto District School Board to conduct a designated substances and hazardous materials assessment in project specific locations at 2829 Keele Street, North York, Ontario (project specific areas). The objective of the assessment was to determine the presence, location, condition and quantities of designated substances and other hazardous materials in the project specific areas that have the potential to be disturbed as part of planned construction activities (i.e. Accessibility Upgrades Project) so that appropriate control measures can be implemented to protect workers during the work.

This assessment satisfies the Owner's requirements under Section 30 of the Ontario Occupational Health and Safety Act (OHSA), Revised Statutes of Ontario 1990, as amended. Section 30(1) requires a building owner to determine if there are any designated substances present at a project site prior to construction or demolition activities. Sections 30(2), (3) and (4) require the Owner and constructors for a project to provide the findings in this report as part of the tendering information for any tendered project or to prospective contractors (and subcontractors) of a project before entering into a binding contract.

This report documents findings of our on-site inspection that was conducted on March 6, 2026 and provides conclusions and recommendations based on our findings and knowledge of the planned construction project.

## 1.2 Scope of Work

In accordance with our fee proposal document, our scope of work included the following activities:

- A review of existing documents, including renovation documents and drawings, floor plans and existing environmental assessment reports, etc., where available;
- A visual assessment of accessible area(s) in the project specific areas to identify the presence, location, condition and quantities of designated substances and other hazardous materials;
- Collection, analysis and interpretation of representative bulk samples of suspect asbestos-containing building materials for the determination of asbestos content and material classification;
- Collection, analysis and interpretation of representative paint chip samples for the determination of lead content; and
- Preparation of a report to document findings and provide recommendations regarding control measures and/or special handling procedures for designated substances or specific hazardous materials that may be disturbed as part of planned construction activities.

Documents reviewed to aid in the assessment included the following:

- *“Designated Substances and Hazardous Materials Assessment Report – PA System Upgrades Project”* Project # 1-3220487, dated June 2022 as prepared by Safetech Environmental for Downsview Public School
- Downsview Public School, Project Floor Plans

This assessment only identified designated substances and hazardous materials that were deemed to be part of the building or somehow otherwise incorporated into the building structure and its finishes. **The following items were not included in our scope of work:**

- Assessing occupant items such as stored products, furnishings, items and materials used or produced as part of a manufacturing process;
- Investigating underground materials or equipment (vessels, drums, underground storage tanks, duct-banks, pipes, or cables);
- Assessing enclosed wall or ceiling cavities; and
- Assessing risers, pipe chases or elevator shafts.

### 1.3 Description of Area(s) Assessed

The area(s) investigated included all accessible locations of the project specific areas. The extent of the area investigated is indicated on the floor plan(s) provided in Appendix B.

## 2.0 RESULTS

Results of our visual assessment and bulk sample analytical findings are summarized in the sections below.

### 2.1 Designated Substances

#### 2.1.1 Asbestos

Results of bulk sample analysis for the determination of asbestos content are summarized in the following table. Materials have been classified as “ACM”, “Non-ACM”, “Suspected ACM” or “Presumed Non-ACM” based on analytical results. Materials classified as Suspected ACM or Presumed Non-ACM may require further analysis (depending on site-specific conditions) to verify whether the material should be classified as ACM or Non-ACM. Please refer to the Limitations section of this report (Section 4.0) for additional details. The Laboratory Certificate of Analysis is included in Appendix C.

**Table 2: Bulk Sample Analytical Results for Determination of Asbestos Content**

Sample No.	Material Description	Sample Location	Asbestos Content	Material Classification
1a	Brick Mortar – Block Fill	Storage Room (3845)	None Detected	NON-ACM
	Mortar		None Detected	NON-ACM
1b	Brick Mortar – Block Fill	Storage Room (3845)	None Detected	NON-ACM
	Mortar		None Detected	NON-ACM
1c	Brick Mortar – Block Fill	Storage Room (3845)	None Detected	NON-ACM
	Mortar		None Detected	NON-ACM
2a	Concrete Block Mortar – Block Fill	Library (3864)	None Detected	NON-ACM
	Mortar		None Detected	NON-ACM
2b	Concrete Block Mortar – Block Fill	Library (3864)	None Detected	NON-ACM
	Mortar		None Detected	NON-ACM
2c	Concrete Block Mortar – Block Fill	Library (3864)	None Detected	NON-ACM
	Mortar		None Detected	NON-ACM
3a	White Door Frame Caulking	Storage Room (3845)	None Detected	NON-ACM
3b	White Door Frame Caulking	Storage Room (3845)	None Detected	NON-ACM
3c	White Door Frame Caulking	Storage Room (3845)	None Detected	NON-ACM





Sample No.	Material Description	Sample Location	Asbestos Content	Material Classification
4a	Brown Interior Door Frame Caulking	Door 3 (90656)	None Detected	NON-ACM
4b	Brown Interior Door Frame Caulking	Door 3 (90656)	None Detected	NON-ACM
4c	Brown Interior Door Frame Caulking	Door 3 (90656)	None Detected	NON-ACM
5a	Grey Interior Door Frame Caulking	Door 4 (90662)	None Detected	NON-ACM
5b	Grey Interior Door Frame Caulking	Door 4 (90662)	None Detected	NON-ACM
5c	Grey Interior Door Frame Caulking	Door 4 (90662)	None Detected	NON-ACM
6a	Black Exterior Door Frame Caulking	Door 4 (68395-1)	None Detected	NON-ACM
6b	Black Exterior Door Frame Caulking	Door 4 (68395-1)	None Detected	NON-ACM
6c	Black Exterior Door Frame Caulking	Door 4 (68395-1)	None Detected	NON-ACM
7a	Plaster Wall	Portable 2	None Detected	NON-ACM
7b		Portable 3	None Detected	NON-ACM
7c		Portable 5	None Detected	NON-ACM
8a	2'x4' Pinhole Ceiling Tile	Staff Room (3829)	None Detected	NON-ACM
8b			None Detected	NON-ACM
8c			None Detected	NON-ACM
9a	2'x4' Large Fissure Ceiling Tile	Portable 5	None Detected	NON-ACM
9b			None Detected	NON-ACM
9c			None Detected	NON-ACM





As per O.Reg. 278/05, ACM contains  $\geq 0.5\%$  asbestos by dry weight.




Materials assessed for asbestos content are summarized in the following table based on the type/use of the material.





**Table 3: Results of Assessment for Asbestos-Containing Materials**

<b>Sprayed and Loose Fill Insulating Materials</b>	<b>Location/Description</b>
Sprayed Fireproofing	None identified in project specific areas.
Sprayed Insulation	None identified in project specific areas.
Loose Fill / Vermiculite Insulation	None identified in project specific areas. Interior portions of concrete block walls could not be assessed. However, it is not expected that these walls are insulated with loose fill or vermiculite insulation
<b>Thermal System Insulation</b>	<b>Location/Description</b>


Mechanical Pipe Insulation – Straights	None identified in project specific areas.	
Mechanical Pipe Insulation – Fittings (elbows, valves, tees, hangars, etc.)	<b>Mechanical Pipe fittings insulation</b> was not identified within the subject areas. However, as per School's Pink Book, Pipe fittings insulation within the other areas of the school has been confirmed to be asbestos-containing. <b>Pipe fittings insulation might be present above within the ceiling cavity.</b>	
HVAC Duct Insulation	None identified in project specific areas.	
Breeching / Exhaust Insulation	None identified in project specific areas.	
Tank Insulation	None identified in project specific areas.	
Boiler Insulation	None identified in project specific areas.	
Other Mechanical Equipment Insulation	None identified in project specific areas.	
<b>Architectural Finishes &amp; Finishing Materials</b>	<b>Location/Description</b>	
Sprayed Texture / Stucco Finishes	None identified in project specific areas.	
Plaster Finishes	Plaster walls were observed in the project specific areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample set 1 in Table 2.	
Drywall Joint Compound	Drywall joint compound was observed in the project specific areas. Bulk samples were collected during the 2022 survey assessment and results of analysis confirmed that this building material is not asbestos-containing.	
<b>Ceiling Tiles</b>	<b>Location/Description</b>	

Lay-in Acoustic Ceiling Tiles	During the 2022 survey, 2x4 fissure and pinhole lay-in ceiling tiles were observed in the project specific areas. This building material was noted to contain a manufacturer's date stamp following the year 2000. Therefore, the material is not suspected to contain asbestos.	
	2'x4' Pinhole lay-in ceiling tiles were observed in the project specific areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample set 7 in Table 2.	
	2'x4' Large fissure lay-in ceiling tiles were observed in the project specific areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample set 8 in Table 2.	
Glued-on Acoustic Ceiling Tiles	1'x1' Pinhole glued-on ceiling tiles were observed in the project specific areas. This material was confirmed to be made of fiberboard and is not expected to contain asbestos.	
Cement Ceiling Panels	None identified in project specific areas.	
<b>Flooring</b>	<b>Location/Description</b>	

Vinyl Floor Tiles	Various patterns of 1'x1' Vinyl Floor Tiles were observed within the subject areas. Samples were not collected during our assessment as this material is not expected to be disturbed as the part of this project. This material is presumed to contain asbestos until proven otherwise.	
Vinyl Sheet Flooring	None identified in project specific areas.	
Mastic	Mastic pertaining to 1'x1' vinyl floor tiles may be present within the subject areas. This material is not expected to be disturbed as the part of this project. Mastic associated with vinyl floor tiles is presumed to contain asbestos until proven otherwise.	
<b>Asbestos Cement Products</b>	<b>Location/Description</b>	
Piping	None identified in subject area.	
Roofing, Siding, Wallboard	None identified in project specific areas.	
Mortar	Interior brick mortar was observed in the project specific areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample set 1 in Table 2.	
	Exterior brick mortar was observed in the project specific areas. Bulk samples were collected during the 2022 assessment and results of analysis confirmed that this building material is not asbestos-containing.	

Mortar	Concrete block mortar was observed in the project specific areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample set 2 in Table 2.	
<b>Exterior Building Materials</b>	<b>Location/Description</b>	
Caulking	White door frame caulking was observed in the project specific areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample set 3 in Table 2.	
	Brown door frame caulking was observed in the project specific areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample set 4 in Table 2.	
	Grey interior door frame caulking was observed in the project specific areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample set 5 in Table 2.	



Caulking	Black exterior door frame caulking was observed in the project specific areas. Bulk samples were collected during the assessment and results of analysis confirmed that this building material is not asbestos-containing. Refer to sample set 6 in Table 2.	
Shingles	None identified in project specific areas.	

## 2.1.2 Lead

Laboratory analytical results for paints tested to determine lead content are summarized in the following table. The Laboratory Certificate of Analysis is included in Appendix D. Refer to Section 3.1.2 of this report for recommended lead abatement procedures (if any) that correspond to the type of proposed construction, renovation, or demolition work.

**Table 4: Results of Paint Condition and Lead Content Assessment**





Sample No.	Location	Surface	Paint Colour	Condition	Lead Conc. (% by wt.)	Material Classification
L1	Storage Room (3845)	Concrete Floor	Grey	Fair	0.34%	LCP
L2	Storage Room (3845)	Brick Wall	Cream	Good	0.11%	LCP
L3	Boiler Room (3859)	Block Wall	Light Grey	Fair	0.11%	LCP
L4	Portable 5	Wall	White	Good	<0.0064%	NLC

LCP: Lead-Containing Paint (>0.1% Lead Content); LLLP: Low-Level Lead Paint (≤0.1% Lead Content)

**Suspect lead-containing materials** observed in the project specific areas included the following:

- paints and surface coatings (not sampled)
- solder in copper pipe fittings
- solder in electrical components

**Table 5: Results of Assessment for Lead-Containing Materials**

Location/Description	Picture
<p>Grey paint associated with concrete floor in storage room (3845) was sampled during our investigation. Results of analysis indicated the presence of 0.34% concentrations of lead. Therefore, the grey paint is considered to be lead-containing. Refer to sample L1 in Table 4.</p>	
<p>Cream paint associated with brick walls in storage room (3845) was sampled during our investigation. Results of analysis indicated the presence of 0.11% concentrations of lead. Therefore, the cream paint is considered to be lead-containing. Refer to sample L2 in Table 4.</p>	
<p>Light grey paint associated block walls in boiler room (3859) was sampled during our investigation. Results of analysis indicated the presence of 0.11% concentrations of lead. Therefore, the light grey paint is considered lead-containing. Refer to sample L3 in Table 4.</p>	
<p>White paint associated with walls in portable 5 was sampled during our investigation. Results of analysis did not indicate the presence of any detectable concentrations of lead. Therefore, the white paint is not considered to be lead-containing. Refer to sample L4 in Table 4.</p>	

### 2.1.3 Mercury

Mercury is present in the project specific areas in the form of:

- vapour in fluorescent lamps
- liquid in thermostats

### 2.1.4 Silica

A number of building materials were identified in the project specific areas that are ***suspected to contain crystalline silica***. This includes the following materials:

- drywall walls/drywall joint compound
- concrete
- mortar

### 2.1.5 Other Designated Substances

Acrylonitrile, arsenic, benzene, coke oven emissions, ethylene oxide, isocyanates, and vinyl chloride were not included in the assessment as these substances are not expected to be a significant component of building materials or present in a form that would represent an exposure concern. Additionally, no specific information regarding their use was provided to us.

## 2.2 Other Hazardous Materials

### 2.2.1 Chemical Hazards

No visible evidence of UFFI installation (i.e. injection openings) or overspray of foam insulation at wall/ceiling joints was identified in the project specific areas.

### 2.2.2 Biological Hazards

#### 2.2.2.1 Mould Contamination

There was no visible evidence of obvious mould growth on building finishes in the project specific areas at the time of the assessment. In addition, there was no visible evidence of any significant water staining or discolouration to building finishes in the project specific areas that would suggest the potential for hidden mould growth behind these finishes.

#### 2.2.2.2 Pest Infestation

There was no visible evidence of a pest infestation in the project specific areas.

### 2.2.3 Environmental Hazards

#### 2.2.3.1 Polychlorinated Biphenyls (PCBs)

Fluorescent light ballasts are assumed to contain PCB's



### **2.2.3.2 Ozone Depleting and Global Warming Substances**

No fixed equipment suspected to contain ODS/GWS was observed in the project specific areas.

## **3.0 CONCLUSIONS AND RECOMMENDATIONS**

### **3.1 Designated Substances**

#### **3.1.1 Asbestos**

As results summarized in Table 2 indicate, no asbestos was detected in any of the bulk samples retrieved for analysis. Therefore, these building materials are considered to be Non-ACM and there are no requirements for management, disturbance or removal of these materials under O. Reg. 278/05. No other suspect asbestos-containing materials were observed in the subject area.

#### **3.1.2 Lead**

Result of paint chip analysis for the determination of lead content indicated that grey and cream paints associated with storage room (3845) was confirmed to be lead-containing (>0.1% lead content based on required of Environmental Abatement Council of Canada (EACC) "Lead Guideline" (October 2014)). ***Paints and surface coatings not sampled are assumed to be lead-containing.*** Any disturbance of the lead-containing paint should be conducted in accordance the procedures outlined in the Environmental Abatement Council of Canada (EACC) "Lead Guideline" (October 2014) and/or the Ontario Ministry of Labour, Immigration, Training and Skills Development (MLITSD) "Lead on Construction Projects" guideline (April 2011). The extent of procedures (Class or Type of operation) necessary depends on the type of work to be conducted.

***Additional suspect lead-containing products*** includes solder on pipe fittings and electrical components. Future testing of these materials and specific handling/disposal requirements may be necessary if/when these materials are to be disturbed.

Any disturbance of the lead-containing materials should be conducted in accordance with the procedures outlined in the Environmental Abatement Council of Canada (EACC) "Lead Guideline" (October 2014) and/or the Ontario Ministry of Labour, Immigration, Training and Skills Development (MLITSD) "Lead on Construction Projects" guideline (April 2011). The extent of procedures required depends on the type of work to be conducted.

At this time the method of disturbance, if any, of lead-containing materials is unknown. It is recommended that any contractor whose work requires lead-containing materials to be disturbed consult the EACC or Ontario MLITSD guidelines prior to the start of work to determine the Class/Type of operation(s) and the corresponding control measures (engineering controls, work/hygiene practices, protective clothing and equipment and worker training) necessary to conduct the work in a manner that will prevent worker

overexposure to lead. The following table outlines the classification of lead disturbance based on the EACC guideline.

Operation	Description
Class 1	<ol style="list-style-type: none"> <li>1. Removal of lead-containing or lead-based paints and surface coatings with a chemical gel/stripper or paste;</li> <li>2. Application of lead-containing or lead-based paints and surface coatings with a brush, roller or sponge.</li> <li>3. Installation or removal of lead sheeting or flashing.</li> <li>4. Installation or removal of lead-containing packing, babbitt, caulking, gasket or similar material.</li> <li>5. Removal of materials coated with lead-containing or lead-based paints and surface coatings, using non-powered hand tools, where the material remains chiefly intact and is not crumbled, pulverized or powdered.</li> <li>6. Operating construction or demolition equipment (e.g. excavator, bulldozer) during building renovation or demolition where lead-based paints or surface coatings are present on building materials and are being disturbed.</li> <li>7. Soldering with lead solder.</li> <li>8. Removing lead-containing or lead-based paints or surface coatings with a heat gun.</li> <li>9. Removing lead-containing and lead-based paints and surface coatings using a high-pressure water jet (e.g. pressure washer).</li> </ol>
Class 2a	<ol style="list-style-type: none"> <li>1. Removal of lead-containing or lead-based paints and surface coatings or lead-containing materials using a power tool that has an effective dust collection system equipped with a HEPA filter*.</li> <li>2. Welding, torching or high temperature cutting of lead-containing materials indoors when using an effective fume collector or smoke eater that filters and exhausts lead fume and expels it directly outdoors (away from occupants, entrances, walkways, rest areas, etc.). Fume collector or smoke eater must have effective source control and capture velocity, minimum of 0.5 metres per second (100 feet per minute) at the work surface.</li> <li>3. Welding, torching or high temperature cutting of lead-containing and lead-based paints and surface coatings or lead-containing materials outdoors.</li> <li>4. Removal of lead-containing mortar using handheld non-powered tools.</li> <li>5. Removal of lead-containing and lead-based paints and surface coatings or lead-containing materials by scraping or sanding (including wet sanding) using non-powered hand tools.</li> <li>6. Demolition of plaster or building components that crumble, pulverize or powder and are covered with lead-containing or lead-based paints or surface coatings.</li> <li>7. Clean up and removal of a significant amount of lead-containing dust and debris (that can be made easily airborne) using wet methods or HEPA vacuums.</li> </ol>
Class 2b	<ol style="list-style-type: none"> <li>1. Spray application of lead-containing paints and surface coatings</li> </ol>

Operation	Description
Class 3a	<ol style="list-style-type: none"> <li>1. Removal of lead-containing or lead-based paints and surface coatings or lead-containing materials using a power tool without an effective dust collection system equipped with a HEPA filter.</li> <li>2. Welding, torching or high temperature cutting of lead-containing materials indoors or in a confined space (e.g. within a ditch or pit).</li> <li>3. Removal of lead-containing mortar using a powered cutting device.</li> <li>4. Burning of a material containing lead.</li> <li>5. Removal, cleaning or repair of a ventilation system or ductwork used for controlling lead exposure.</li> <li>6. Spray application of lead-based paints and surface coatings.</li> <li>7. In the absence of an exposure assessment: <ol style="list-style-type: none"> <li>a. demolition or cleanup of a facility where lead-containing products were manufactured and significant dust and debris, which can be made easily airborne, is present.</li> <li>b. cleanup of dust and debris down range of a firing station in an indoor firing range. an operation that may expose a worker to lead dust, fume or mist that is not a Class 1, Class 2, or Class 3B operation.</li> </ol> </li> </ol>
Class 3b	<ol style="list-style-type: none"> <li>1. Abrasive blasting of lead-containing and lead-based paints and surface coatings or lead-containing materials (including wet, slurry and dry abrasive blasting and dry-ice blasting).</li> </ol>

\* Effective implies that the dust collection system should be capable of controlling airborne lead concentration levels to below 0.05 mg/m<sup>3</sup>. Employers should follow manufacturer's recommendations and maintenance specifications for optimal function.

If practicable, all bulk lead waste materials should be separated from other wastes and sent to a recycling facility. If not practicable, lead-containing waste should be handled and disposed of according to R.R.O. 1990, Regulation 347, *General - Waste Management* (Reg. 347) made under the Environmental Protection Act. Under this regulation (and depending on the quantity of waste generated) the waste may be subject to analysis following the Toxicity Characteristic Leaching Procedure (TCLP) to determine if it is a "leachate toxic waste" based on the leachate quality criteria provided in Schedule 4 of the regulation. Such wastes must meet specific treatment requirements (Schedule 5) or undergo alternative treatment for hazardous debris (Schedule 8) prior to land disposal.

### 3.1.3 Mercury

Fluorescent and HID lamps that require removal should be handled with care and kept intact to avoid potential exposure to mercury vapour present within the lamps. To prevent the release of mercury into the environment, Safetech recommends that all waste lamps be sent to a lamp recycling facility and not disposed of in landfill.

Although no mercury was visibly identified in other equipment, dismantling of equipment was not conducted to verify the presence/absence of mercury. It is cautioned that thermometers, barometers and other measuring devices (pressure gauges/sensors, vacuum gauges, manometers, etc.), thermostats and a variety of other electrical switches (temperature sensitive, tilt switches, float switches, etc.) may contain mercury that may not be visible without dismantling the equipment. Such devices should be assumed to contain mercury until proven otherwise and similar precautions to those outlined above

should be taken if any of these items are to be disturbed or taken out of service in the future.

### 3.1.4 Silica

Suspect silica-containing materials were identified to be present in the project specific areas. In their current state, building materials containing silica do not represent a risk to building occupants or construction workers. Risks associated with exposure to silica arise during demolition activities that cause silica dust to be created (particularly grinding, drilling or cutting operations and during major demolition), resulting in a crystalline silica inhalation hazard.

If any materials suspected to contain silica are to be removed or otherwise disturbed as a result of renovation/demolition activities it is recommended that procedures be put in place to control the generation of dust (such as routine water misting) and thus reduce the potential for worker exposure. Workers that have the potential to be exposed to airborne silica should also wear appropriate protective clothing and respiratory protection. Any work involving the disturbance of silica-containing materials should follow the procedures outlined in the Ontario MLITSD “Silica on Construction Projects” guideline (April 2011). The appropriate engineering controls, work practices, hygiene practices, personal protective measures and training necessary to conduct the work in a safe manner are provided in this guideline. The general measures and procedures (or Type of operation) necessary depends on the type of work to be conducted. The following table outlines the classification of silica disturbance based on the Ontario MLITSD guideline.

Operation	Description
Type 1	<ol style="list-style-type: none"> <li>1. The drilling of holes in concrete or rock that is not part of a tunneling operation or road construction.</li> <li>2. Milling of asphalt from concrete highway pavement</li> <li>3. Charging mixers and hoppers with silica sand (sand consisting of at least 95% silica) or silica flour (finely ground sand consisting of at least 95% silica)</li> <li>4. Any other operation at a project that requires the handling of silica-containing material in a way that may results in a worker being exposed to airborne silica.</li> <li>5. Entry into a dry mortar removal or abrasive blasting area while airborne dust is visible for less than 15 minutes for inspection and/or sampling.</li> <li>6. Working within 25 metres of an area where compressed air is being used to remove silica-containing dust outdoors.</li> </ol>
Type 2	<ol style="list-style-type: none"> <li>1. Removal of silica containing refractory materials with a jackhammer</li> <li>2. The drilling of holes in concrete or rock that is part of a tunneling or road construction.</li> <li>3. The use of a power tool to cut, grind, or polish concrete, masonry, terrazzo or refractory materials.</li> <li>4. The use of a power tool to remove silica containing materials.</li> <li>5. Tunneling (operation of the tunnel boring machine, tunnel drilling, and tunnel mesh installation).</li> <li>6. Tuckpoint and surface grinding</li> <li>7. Dry mortar removal with an electric or pneumatic cutting device</li> <li>8. Dry method dust cleanup from abrasive blasting operations</li> <li>9. The use of compress air outdoors for removing silica dust</li> <li>10. Entry into area where abrasive blasting is being carried out for more than 15 minutes</li> </ol>

Operation	Description
Type 3	<ol style="list-style-type: none"> <li>1. Abrasive blasting with an abrasive that contains &gt;1% silica</li> <li>2. Abrasive blasting of a material that contains &gt;1% silica</li> </ol>

### 3.1.5 Other Designated Substances

No other designated substances are expected to be a component of building materials in the project specific areas in a form that would represent an exposure concern. Therefore, no protective measures or procedures specific to acrylonitrile, arsenic, benzene, coke oven emissions, ethylene oxide, isocyanates, and vinyl chloride are considered necessary.

## 3.2 Other Hazardous Materials

### 3.2.1 Chemical Hazards

As no UFFI was identified or is suspected to be present in the project specific areas, no further action is required. However, given that no destructive testing was conducted, there is a remote possibility that UFFI could be hidden within locations such as exterior wall cavities. If suspect foam insulation is identified during renovation/demolition activities work should be stopped and the area should be re-assessed to evaluate conditions and determine appropriate control measures and worker protection, if necessary.

### 3.2.2 Biological Hazards

#### 3.2.2.1 Mould Contamination

No mould contamination was identified in the project specific areas and no further action is required at this time. Although no obvious mould contamination or evidence to suggest possible hidden mould contamination was identified in the project specific areas, there is still a potential for hidden mould growth to exist behind or underneath building finishes. Should suspect mould growth be discovered during the course of renovation or demolition work, Safetech recommends that all work stop so that the area can be assessed to evaluate proper control measures and remediation protocols in order to avoid worker exposure to mould and possible contamination of adjacent areas.

#### 3.2.2.2 Pest Infestation

No visual evidence of any significant pest infestation was observed in the project specific areas. Therefore, no additional precautionary measures are deemed necessary for protection against biological contaminants potentially associated with pest infestation.

### 3.2.3 Environmental Hazards

#### 3.2.3.1 Polychlorinated Biphenyls (PCBs)

The federal government has set strict regulations for the handling, storage and disposal of PCBs. The PCB Regulations (SOR/2008-273) came into effect on September 5<sup>th</sup>, 2008 and consolidates and replaces the Chlorobiphenyls Regulations (SOR/91-152) and the

Storage of PCB Material Regulations (SOR/92-507). The purpose of the PCB Regulations is to improve the protection of Canada's environment and the health of Canadians by minimizing the risks posed by the use, storage and release of PCBs by accelerating the elimination of these substances.

As of December 31, 2009 all current PCB storage sites are to have been eliminated and there should no longer be any electrical capacitors, electrical transformers, electromagnets, heat transfer equipment or any other equipment in service that contains PCBs at a concentration greater than 500 mg/kg (500 ppm). As of this time, all of this equipment should have been removed from service and sent for destruction. Furthermore, the PCB Regulations restricts the use of equipment containing PCBs (other than light ballasts or pole-top electrical transformers) at concentrations exceeding 50 mg/kg (50 ppm) in sensitive areas (such as drinking water treatment plants, schools, hospitals and senior citizen care facilities) by the same date. All other locations have until December 31, 2025 to decommission equipment containing 50 ppm to 500 ppm PCBs. The assessment confirmed that some of the existing fluorescent light ballasts contain PCB's.

Existing fluorescent light ballasts are assumed to contain PCBs. When light fixtures are to be decommissioned, all ballasts should be verified at this time by determining the date of manufacture and other pertinent information by referring to the Environment Canada document entitled "Identification of Lamp Ballasts Containing PCBs" (Report EPS 2/CC/2 (revised) August 1991) to aid in identification. Any ballasts that meet the criteria outlined in this document must be treated as PCB containing.

When PCB-containing equipment is taken out of service, jurisdiction falls under provincial regulations. As per R.R.O 1990, Regulation 347, *General - Waste Management*, the land disposal of PCB waste is prohibited. PCB wastes in Ontario are regulated under R.R.O 1990, Regulation 362, *Waste Management – PCBs* (Reg. 362), made under the Environmental Protection Act. Under this regulation, PCB waste is defined as any waste material containing PCBs at a concentration of more than fifty (50) parts per million by weight (i.e. >50mg/kg), with the exception of an electrical capacitor that has never contained over 1 kg of PCB's. Any PCB-containing equipment taken out of service should be properly handled and disposed of at an authorized destruction facility in accordance with the requirements of Federal Regulation SOR/2008-273 and Reg. 362.

#### **3.2.3.2 Ozone Depleting and Global Warming Substances**

No equipment was identified in the project specific areas that is expected to contain ozone depleting or global warming substances. As such, no recommendations are considered necessary at this time.

## **4.0 LIMITATIONS**

The information and recommendations detailed in this report were carried out by trained professional and technical staff in accordance with generally accepted environmental and



industrial hygiene work practices and procedures. Recommendations provided in this report have been generated in accordance with accepted industry guidelines and practices. These guidelines and practices are considered acceptable as of the date of this report.

In preparation of this report, Safetech relied on information supplied by others, including without limitation, information pertaining to the history and operation of the site, test results and reports of other consultants and testing services provided by independent laboratories. Except as expressly set out in this report, Safetech has not made any independent verification of information provided by independent entities.

The collection of samples at the location noted was consistent with the scope of work agreed-upon with the person or entity to whom this report is addressed and the information obtained concerning prior site investigations. As conditions between samples may vary, the potential remains for the presence of unknown additional contaminants for which there were no known indicators.

The analytical method used for determination of asbestos content meets the requirements of O. Reg. 278/05. However, small asbestos fibres may be missed by PLM due to resolution limitations of the optical microscope. Interfering binder/matrix and/or low asbestos content may also hinder positive identification by PLM. These conditions are common for vermiculite attic insulation (VAI) and non-friable organically bound (NOB) materials such as vinyl floor tiles, roofing materials, mastics and caulking and can lead to “false negative” results. If PLM analytical results for these types of materials indicate no asbestos detected they have been reported as “Presumed Non-ACM”. Due to limitations of the analytical method we cannot confirm that low quantities of asbestos are not present in these samples using solely PLM analysis. Additional analytical procedures should be considered for such materials to rule out false negative results.

Conclusions are based on site conditions at the time of inspection and can only be extrapolated to an undefined limited area around inspected locations. The extent of the limited area depends on building construction and conditions. Building materials that are not detailed within this survey due to inaccessibility during the time of survey and/or are uncovered during renovation/demolition activities should be properly assessed by a qualified person prior to their disturbance. Safetech cannot warrant against undiscovered environmental liabilities. If any information becomes available that differs from the findings in this report, we request that we be notified immediately to reassess the conclusions provided herein.

No other person or entity is entitled to use or rely upon this report without the express written consent of Safetech and the person or entity to who it is addressed. Any use that a third party makes of this report, or any reliance based on conclusions and recommendations made, are the responsibility of such third parties. Safetech accepts no responsibility for damages suffered by third parties as a result of actions based on this report.

## **Appendix A: Summary of ACM Occurrences**

---




Floor	Room No.	Room Description	System	Material	Description	Classification	Friable/ Non-Friable	Condition	Est. Quantity	Unit	Access	Action
No sources of asbestos were identified in the project specific areas												

## **Appendix B: Site Drawings**

---

LEGEND

AREAS ASSESSED



1) THIS FLOOR PLAN MUST BE READ IN CONJUNCTION WITH THE DESIGNATED SUBSTANCE AND HAZARDOUS MATERIALS ASSESSMENT REPORT.  
2) NOT ALL ASBESTOS-CONTAINING MATERIALS ARE INDICATED IN THE FLOOR PLAN. REFER TO THE DESIGNATED SUBSTANCE AND HAZARDOUS MATERIALS REPORT FOR FURTHER DETAILS.  
3) REMOVAL OR DISTURBANCE OF ASBESTOS-CONTAINING BUILDING MATERIALS MUST BE CONDUCTED IN ACCORDANCE WITH ONTARIO REGULATION 278/05 "DESIGNATED SUBSTANCE - ASBESTOS ON CONSTRUCTION PROJECTS AND IN BUILDINGS AND REPAIR OPERATIONS".

LEVEL 1

ACCESSIBILITY UPGRADES

2829 KEELE ST

DRAWING NO.

DS-1

DATE: MARCH 6, 2026

SAFETECH PROJECT NO.  
1-3260212



3045 SOUTHCREEK RD, UNIT 14  
MISSISSAUGA, ONTARIO  
L4X 2X7

## **Appendix C: Laboratory Certificate of Analysis – Asbestos**

---



# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
<http://www.EMSL.com> / [torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Order 552604622  
Customer ID: 55SELI62  
Customer PO: 1-3260212  
Project ID:

**Attn:** Dan Whittall  
Safetech Environmental Limited  
3045 Southcreek Road  
Unit 14  
Mississauga, ON L4X 2X7  
**Proj:** 1-3260212- Downview PS, North York, ON

**Phone:** (905) 624-2722  
**Fax:** (905) 624-4306  
**Collected:**  
**Received:** 3/09/2026  
**Analyzed:** 3/12/2026

## Summary Test Report for Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05

**Client Sample ID:** 1a-Block Fill **Lab Sample ID:** 552604622-0001

**Sample Description:** Brick Mortar- Storage Room (3845)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	3/10/2026	White	0.0%	100.0%	None Detected	

**Client Sample ID:** 1a-Mortar **Lab Sample ID:** 552604622-0001A

**Sample Description:** Brick Mortar- Storage Room (3845)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	3/10/2026	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** 1b-Block Fill **Lab Sample ID:** 552604622-0002

**Sample Description:** Brick Mortar- Storage Room (3845)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	3/10/2026	White	0.0%	100.0%	None Detected	

**Client Sample ID:** 1b-Mortar **Lab Sample ID:** 552604622-0002A

**Sample Description:** Brick Mortar- Storage Room (3845)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	3/10/2026	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** 1c-Block Fill **Lab Sample ID:** 552604622-0003

**Sample Description:** Brick Mortar- Storage Room (3845)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	3/12/2026	White/Green	0.0%	100.0%	None Detected	

**Client Sample ID:** 1c-Mortar **Lab Sample ID:** 552604622-0003A

**Sample Description:** Brick Mortar- Storage Room (3845)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	3/12/2026	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** 2a-Block Fill **Lab Sample ID:** 552604622-0004

**Sample Description:** Concrete Block Mortar- Library (3864)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	3/10/2026	White	0.0%	100.0%	None Detected	



# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
<http://www.EMSL.com> / [torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Order 552604622  
Customer ID: 55SELI62  
Customer PO: 1-3260212  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05

**Client Sample ID:** 2a-Mortar **Lab Sample ID:** 552604622-0004A

**Sample Description:** Concrete Block Mortar- Library (3864)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	3/10/2026	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** 2b-Block Fill **Lab Sample ID:** 552604622-0005

**Sample Description:** Concrete Block Mortar- Library (3864)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	3/10/2026	White	0.0%	100.0%	None Detected	

**Client Sample ID:** 2b-Mortar **Lab Sample ID:** 552604622-0005A

**Sample Description:** Concrete Block Mortar- Library (3864)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	3/10/2026	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** 2c-Block Fill **Lab Sample ID:** 552604622-0006

**Sample Description:** Concrete Block Mortar- Library (3864)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	3/12/2026	White	0.0%	100.0%	None Detected	

**Client Sample ID:** 2c-Mortar **Lab Sample ID:** 552604622-0006A

**Sample Description:** Concrete Block Mortar- Library (3864)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	3/12/2026	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** 3a **Lab Sample ID:** 552604622-0007

**Sample Description:** White Door Frame Caulking- Storage Room (3845)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	3/12/2026	White/Blue	0.0%	100%	None Detected	

**Client Sample ID:** 3b **Lab Sample ID:** 552604622-0008

**Sample Description:** White Door Frame Caulking- Storage Room (3845)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	3/12/2026	White/Blue	0.0%	100%	None Detected	

**Client Sample ID:** 3c **Lab Sample ID:** 552604622-0009

**Sample Description:** White Door Frame Caulking- Storage Room (3845)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	3/12/2026	White/Blue	0.0%	100%	None Detected	



# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
<http://www.EMSL.com> / [torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Order 552604622  
Customer ID: 55SELI62  
Customer PO: 1-3260212  
Project ID:

## Summary Test Report for Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05

**Client Sample ID:** 4a **Lab Sample ID:** 552604622-0010

**Sample Description:** Brown Interior Door Frame Caulking- Door 3 (90656)

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM Grav. Reduction	3/12/2026	White/Black	0.0%	100%	None Detected	

**Client Sample ID:** 4b **Lab Sample ID:** 552604622-0011

**Sample Description:** Brown Interior Door Frame Caulking- Door 3 (90656)

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM Grav. Reduction	3/12/2026	White/Black	0.0%	100%	None Detected	

**Client Sample ID:** 4c **Lab Sample ID:** 552604622-0012

**Sample Description:** Brown Interior Door Frame Caulking- Door 3 (90656)

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM Grav. Reduction	3/12/2026	White/Black	0.0%	100%	None Detected	

**Client Sample ID:** 5a **Lab Sample ID:** 552604622-0013

**Sample Description:** Grey Interior Door Frame Caulking -Door 4 (90662)

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM Grav. Reduction	3/12/2026	Gray/Black	0.0%	100%	None Detected	

**Client Sample ID:** 5b **Lab Sample ID:** 552604622-0014

**Sample Description:** Grey Interior Door Frame Caulking -Door 4 (90662)

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM Grav. Reduction	3/12/2026	Gray/Black	0.0%	100%	None Detected	

**Client Sample ID:** 5c **Lab Sample ID:** 552604622-0015

**Sample Description:** Grey Interior Door Frame Caulking -Door 4 (90662)

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM Grav. Reduction	3/12/2026	Gray/Black	0.0%	100%	None Detected	

**Client Sample ID:** 6a **Lab Sample ID:** 552604622-0016

**Sample Description:** Black Exterior Door Frame Caulking- Door 4 (168395-1)

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM Grav. Reduction	3/12/2026	Brown	0.0%	100%	None Detected	

**Client Sample ID:** 6b **Lab Sample ID:** 552604622-0017

**Sample Description:** Black Exterior Door Frame Caulking- Door 4 (168395-1)

TEST	Analyzed	Color	Non-Asbestos		Asbestos	Comment
	Date		Fibrous	Non-Fibrous		
PLM Grav. Reduction	3/12/2026	Brown	0.0%	100%	None Detected	



## EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
<http://www.EMSL.com> / [torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Order 552604622  
Customer ID: 55SELI62  
Customer PO: 1-3260212  
Project ID:

### Summary Test Report for Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05

Client Sample ID: 6c

Lab Sample ID: 552604622-0018

Sample Description: Black Exterior Door Frame Caulking- Door 4 (168395-1)

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM Grav. Reduction	3/12/2026	Brown	0.0%	100%	None Detected	

#### Analyst(s):

Ashley Brito PLM Grav. Reduction (8)  
Diana Costantino PLM Grav. Reduction (4)  
Kira Ramphal PLM (4)  
Syed Basim Al- Hashmi PLM (8)

#### Reviewed and approved by:

Matthew Davis or other approved signatory  
or Other Approved Signatory

None Detected = <0.1%. EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This is a summary report; official reports are available on LabConnect or upon request and relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Canada Inc. Mississauga, ON NVLAP Lab Code 200877-0

Initial report from: 03/12/2026 15:09:40





# EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
<http://www.EMSL.com> / [torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Order 552606364  
Customer ID: 55SELI62  
Customer PO: 1-3260212  
Project ID:

**Attn:** Dan Whittall  
Safetech Environmental Limited  
3045 Southcreek Road  
Unit 14  
Mississauga, ON L4X 2X7  
**Phone:** (905) 624-2722  
**Fax:** (905) 624-4306  
**Collected:**  
**Received:** 3/30/2026  
**Analyzed:** 4/01/2026  
**Proj:** 1-3260212 - Downsview Public School, North York, ON

## Summary Test Report for Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05

**Client Sample ID:** 7a **Lab Sample ID:** 552606364-0001  
**Sample Description:** Portable 2/Plaster

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/01/2026	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** 7b **Lab Sample ID:** 552606364-0002  
**Sample Description:** Portable 3/Plaster

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/01/2026	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** 7c **Lab Sample ID:** 552606364-0003  
**Sample Description:** Portable 5/Plaster

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/01/2026	Gray	0.0%	100.0%	None Detected	

**Client Sample ID:** 8a **Lab Sample ID:** 552606364-0004  
**Sample Description:** Staff Room (3829)/2x4 Pinhole Ceiling Tile

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/01/2026	Gray	80.0%	20.0%	None Detected	

**Client Sample ID:** 8b **Lab Sample ID:** 552606364-0005  
**Sample Description:** Staff Room (3829)/2x4 Pinhole Ceiling Tile

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/01/2026	Gray	80.0%	20.0%	None Detected	

**Client Sample ID:** 8c **Lab Sample ID:** 552606364-0006  
**Sample Description:** Staff Room (3829)/2x4 Pinhole Ceiling Tile

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/01/2026	Gray	80.0%	20.0%	None Detected	

**Client Sample ID:** 9a **Lab Sample ID:** 552606364-0007  
**Sample Description:** Portable 5/2x4 Large Fissure Ceiling Tile

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/01/2026	Gray	80.0%	20.0%	None Detected	



## EMSL Canada Inc.

2756 Slough Street Mississauga, ON L4T 1G3  
Phone/Fax: (289) 997-4602 / (289) 997-4607  
<http://www.EMSL.com> / [torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Order 552606364  
Customer ID: 55SELI62  
Customer PO: 1-3260212  
Project ID:

### Summary Test Report for Asbestos Analysis of Bulk Materials for Ontario Regulation 278/05

Client Sample ID: 9b

Lab Sample ID: 552606364-0008

Sample Description: Portable 5/2x4 Large Fissure Ceiling Tile

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/01/2026	Gray	80.0%	20.0%	None Detected	

Client Sample ID: 9c

Lab Sample ID: 552606364-0009

Sample Description: Portable 5/2x4 Large Fissure Ceiling Tile

TEST	Analyzed Date	Color	Non-Asbestos		Asbestos	Comment
			Fibrous	Non-Fibrous		
PLM	4/01/2026	Gray	80.0%	20.0%	None Detected	

#### Analyst(s):

Antonio Peluso PLM (6)  
Nickesh Mistry PLM (3)

#### Reviewed and approved by:

Matthew Davis or other approved signatory  
or Other Approved Signatory

None Detected = <0.1%. EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This is a summary report; official reports are available on LabConnect or upon request and relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Canada Inc. Mississauga, ON NVLAP Lab Code 200877-0

Report amended: 04/07/2026 11:18:18 Replaces initial report from: 04/01/2026 13:53:10 Reason Code: Client-Change to Sample ID

School Name:		Downsview PS								
Date:		17-Mar-26								
Floor	Location		Sample No	Lab Results	Material	System	Quantity		Access	Notes
	Location Name	Monument No					Condition	Total		
1	Storage Room (3845)	3845	1A	None Detected	Brick Mortar	Wall	Good		A	
1	Storage Room (3845)	3845	1B	None Detected	Brick Mortar	Wall	Good		A	
1	Storage Room (3845)	3845	1C	None Detected	Brick Mortar	Wall	Good		A	
1	Library (3864)	3864	2A	None Detected	Concrete Block Mortar	Wall	Good		A	
1	Library (3864)	3864	2B	None Detected	Concrete Block Mortar	Wall	Good		A	
1	Library (3864)	3864	2C	None Detected	Concrete Block Mortar	Wall	Good		A	
1	Storage Room (3845)	3845	3A	None Detected	White Door Frame Caulking	Door	Good		A	
1	Storage Room (3845)	3845	3B	None Detected	White Door Frame Caulking	Door	Good		A	
1	Storage Room (3845)	3845	3C	None Detected	White Door Frame Caulking	Door	Good		A	
1	Door 3 (90656)	90656	4A	None Detected	Brown Interior Door Frame Caulking	Door	Good		A	
1	Door 3 (90656)	90656	4B	None Detected	Brown Interior Door Frame Caulking	Door	Good		A	
1	Door 3 (90656)	90656	4C	None Detected	Brown Interior Door Frame Caulking	Door	Good		A	
1	Door 4 (90662)	90662	5A	None Detected	Grey Interior Door Frame Caulking	Door	Good		A	
1	Door 4 (90662)	90662	5B	None Detected	Grey Interior Door Frame Caulking	Door	Good		A	
1	Door 4 (90662)	90662	5C	None Detected	Grey Interior Door Frame Caulking	Door	Good		A	
1	Door 4 (68395-1)	68395-1	6A	None Detected	Black Exterior Door Frame Caulking	Door	Good		A	
1	Door 4 (68395-1)	68395-1	6B	None Detected	Black Exterior Door Frame Caulking	Door	Good		A	
1	Door 4 (68395-1)	68395-1	6C	None Detected	Black Exterior Door Frame Caulking	Door	Good		A	
1	Portable 2		7A	None Detected	Plaster Wall	Wall	Good		A	
1	Portable 3		7B	None Detected	Plaster Wall	Wall	Good		A	
1	Portable 5		7C	None Detected	Plaster Wall	Wall	Good		A	
1	Staff Room	3829	8A	None Detected	2'x4' Pinhole Ceiling Tile	Ceiling	Good		C	
1	Staff Room	3829	8B	None Detected	2'x4' Pinhole Ceiling Tile	Ceiling	Good		C	
1	Staff Room	3829	8C	None Detected	2'x4' Pinhole Ceiling Tile	Ceiling	Good		C	
1	Portable 5		9A	None Detected	2'x4' Large Fissure Ceiling Tile	Ceiling	Good		C	
1	Portable 5		9B	None Detected	2'x4' Large Fissure Ceiling Tile	Ceiling	Good		C	
1	Portable 5		9C	None Detected	2'x4' Large Fissure Ceiling Tile	Ceiling	Good		C	

## **Appendix D: Laboratory Certificate of Analysis – Lead**

---

**EMSL Canada Inc.**

2756 Slough Street, Mississauga, ON L4T 1G3

Phone/Fax: (289) 997-4602 / (289) 997-4607

<http://www.EMSL.com>[torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Or 552604645

CustomerID: 55SELI62

CustomerPO: 1-3260212

ProjectID:

Attn: **Dan Whittal**  
**Safetech Environmental Limited**  
**3045 Southcreek Road**  
**Unit 14**  
**Mississauga, ON L4X 2X7**

Phone: (905) 624-2722  
Fax: (905) 624-4306  
Received: 3/9/2026 03:23 PM  
Collected:

Project: 1-3260212 - Downsview PS, North York, ON

**Test Report: Lead in Paint Chips by Flame AAS (SW 846 3050B/7000B)\***

<i>Client Sample</i>	<i>Description</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Weight</i>	<i>RDL</i>	<i>Lead Concentration</i>
L1			3/10/2026	0.2538 g	0.0064 % wt	0.34 % wt
552604645-0001	Site: Grey Paint - Storage Room (3845) / Concrete Floor					
L2			3/10/2026	0.2513 g	0.0064 % wt	0.11 % wt
552604645-0002	Site: Cream Paint - Storage Room (3845) / Brick Wall					

Rowena Fanto, Lead Supervisor  
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. \* Analysis following Lead in Paint by EMSL SOP/Determination of Environmental Lead by FLAA. Reporting limit is 0.0064% wt based on the minimum sample weight per our SOP. "<" (less than) result signifies the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. Definitions of modifications are available upon request.

Samples analyzed by EMSL Canada Inc. Mississauga, ON AIHA LAP, LLC-ELLAP Accredited #196142

Initial report from 03/12/2026 10:45:22

**EMSL Canada Inc.**

2756 Slough Street, Mississauga, ON L4T 1G3

Phone/Fax: (289) 997-4602 / (289) 997-4607

<http://www.EMSL.com>[torontolab@emsl.com](mailto:torontolab@emsl.com)

EMSL Canada Or 552606365

CustomerID: 55SELI62

CustomerPO: 1-3260212

ProjectID:

Attn: **Dan Whittal**  
**Safetech Environmental Limited**  
**3045 Southcreek Road**  
**Unit 14**  
**Mississauga, ON L4X 2X7**

Phone: (905) 624-2722  
Fax: (905) 624-4306  
Received: 3/30/2026 03:29 PM  
Collected:

Project: **1-3260212 - Downsview Public School, North York, ON****Test Report: Lead in Paint Chips by Flame AAS (SW 846 3050B/7000B)\***

<i>Client Sample</i>	<i>Description</i>	<i>Collected</i>	<i>Analyzed</i>	<i>Weight</i>	<i>RDL</i>	<i>Lead Concentration</i>
L3			3/31/2026	0.2509 g	0.0064 % wt	0.11 % wt
552606365-0001	Site: Light Grey Paint - Boiler Room (3859)/ Wall					
L4			3/31/2026	0.2575 g	0.0064 % wt	<0.0064 % wt
552606365-0002	Site: White Paint - Portable 5/ Wall					

Rowena Fanto, Lead Supervisor  
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. \* Analysis following Lead in Paint by EMSL SOP/Determination of Environmental Lead by FLAA. Reporting limit is 0.0064% wt based on the minimum sample weight per our SOP. "<" (less than) result signifies the analyte was not detected at or above the reporting limit. Measurement of uncertainty is available upon request. Definitions of modifications are available upon request.

Samples analyzed by EMSL Canada Inc. Mississauga, ON AIHA LAP, LLC-ELLAP Accredited #196142

Report Amended: 04/07/2026 11:18:31 Replaces the Initial Report 04/01/2026 12:28:08. Reason Code: Client-Change to Sample ID

## **Appendix E: Methodology**

---

## A. METHODOLOGY

The presence of hazardous materials was assessed by visual inspection. For the purpose of this assessment and this document, hazardous materials include designated substances as well as other chemical, biological and environmental hazards as defined below:

- Designated Substances (as prescribed by Ontario Regulation 490/09):
  - Acrylonitrile, Arsenic, Asbestos, Benzene, Coke Oven Emissions, Ethylene Oxide, Isocyanates, Lead, Mercury, Silica and Vinyl Chloride.
- Other Hazardous Materials:
  - **Chemical Hazards** – Urea Formaldehyde Foam Insulation (UFFI)
  - **Biological Hazards** – Mould Contamination and Pest Infestation
  - **Environmental Hazards** – Polychlorinated Biphenyls (PCBs) and Ozone Depleting & Global Warming Substances

Concealed locations such as above solid plaster or drywall ceilings, within plaster or drywall wall cavities, enclosed mechanical/pipe shafts and bulkheads, etc. were not investigated, unless otherwise stated in Section 1.3. Similarly, motors, blowers, electrical panels, etc., were not de-energized or disassembled to examine concealed conditions. Building materials that are not detailed within this assessment due to inaccessibility at the time of our site visit and/or uncovered during renovation/demolition activities should be assessed by a qualified person prior to their disturbance.

Bulk sampling followed by laboratory analysis was also conducted to confirm the presence/absence of select hazardous materials. Bulk sampling was limited to asbestos in building materials and lead in paint on building finishes (if flaking paint was present). All other hazardous materials were identified by visual inspection only. Where possible, observations regarding the location, quantity and condition of the hazardous materials identified were made in order to determine the potential for exposure and provide appropriate recommendations for remedial action, if necessary. Specific methodology for each individual hazardous material assessed is further detailed below.

### A.1 Designated Substances

#### A.1.1 Asbestos

A visual inspection for the presence of both friable and non-friable asbestos-containing material (ACM) was performed in the subject area.

If an existing asbestos survey was available for review, Safetech relied on the information present. Building materials that were visually similar to materials previously tested and that were confirmed to be either ACM or non-ACM were considered to have consistent content and were not re-sampled. Additional sampling was only conducted where the investigator believed a need existed.

Bulk samples of building materials suspected to contain asbestos were retrieved by Safetech only for materials that were deemed to have a potential to be disturbed as part



of the construction project. Some suspect materials may not have been sampled during our investigation. Bulk samples were retrieved in accordance with Section 3 and Table 1 of Ontario Regulation 278/05, "Designated Substance – Asbestos on Construction Projects and in Buildings and Repair Operations". The number of samples collected for each material was based on the type and quantity of the material present in the subject area. Each individual sample was placed in a labeled zip-lock bag for transportation to an independent laboratory (EMSL). EMSL is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) for bulk asbestos fiber analysis.

Analysis for asbestos content was performed by the independent laboratory in accordance with the U.S. Environmental Protection Agency (EPA) Test Method *EPA/600/R-93-116: Method for the Determination of Asbestos in Bulk Building Materials (June 1993)*. This method identifies the asbestos fibre content of building materials using polarized light microscopy (PLM) analytical techniques, with confirmation of presence and type of asbestos made by dispersion staining optical microscopy. This analytical method meets the requirements set forth in Section 3 of O. Reg. 278/05.

In accordance with O. Reg. 278/05, an asbestos-containing material is defined as material that contains 0.5 per cent or more asbestos by dry weight. The laboratory was instructed to conduct "stop-positive" analysis for all materials. If a sample was found to be asbestos-containing no further analysis was conducted for samples taken from the same homogeneous material.

Locations where ACM have been identified are detailed in this report. Recommendations pertaining to ACM were made based on the friability, accessibility and condition of the material in conjunction with the potential for the planned renovation work to disturb the ACM.

### **A.1.2 Assessment of Asbestos-Containing Building Materials**

Accessibility, Condition and Action (Priority) ratings for individual items, or defined areas were developed by Safetech to determine remedial action plans specific to the facility's needs.

#### **A.1.2.1 Accessibility**

Accessibility has been assessed as: (A) Accessible to all non-maintenance occupants of the building; (B) Accessible to maintenance staff without a ladder; (C) Accessible to maintenance staff with a ladder and exposed to view without moving a building component; (D) Accessible to maintenance staff with a ladder and concealed from view due to a building component; (E) Not accessible without demolition or removal of fixed building components or building systems

### A.1.2.2 Condition

The condition of asbestos-containing materials identified in the subject area was assessed as Good (G), Fair (F) or Poor (P). The assessment criteria used to determine condition is dependent on material characteristics, such as friability. The following table summarizes the criteria used by Safetech to evaluate the condition of ACM.

<b>Sprayed Fireproofing, Sprayed Insulation and Sprayed Texture Finishes</b>	
<b>Good</b>	<ul style="list-style-type: none"> <li>Surface shows no significant signs of damage, deterioration, or delamination (i.e. &lt;1%).</li> <li>Unencapsulated or unpainted fireproofing or texture finishes, where no delamination or damage is observed.</li> <li>Encapsulated fireproofing or texture finishes where encapsulation applied after damage or fallout.</li> </ul>
<b>Fair</b>	<ul style="list-style-type: none"> <li>Not utilized as part of condition assessment for these materials.</li> </ul>
<b>Poor</b>	<ul style="list-style-type: none"> <li>Greater than 1% damage, delamination, or deterioration to surface.</li> </ul>
<b>In areas where damage exists in isolated locations, both Good and Poor may be applicable.</b>	
<b>Mechanical Insulation</b> (boilers, breeching, ductwork, piping, tanks, equipment, etc.)	
<b>Good</b>	<ul style="list-style-type: none"> <li>Insulation completely covered in jacketing and exhibits no evidence of damage or deterioration.</li> <li>Jacketing may have minor damage (i.e. scuffs or stains), but is not penetrated.</li> </ul>
<b>Fair</b>	<ul style="list-style-type: none"> <li>Minor penetrating damage to jacketed insulation (cuts, tears, nicks, deterioration or delamination).</li> <li>Undamaged insulation that had never been jacketed.</li> <li>Insulation is exposed but not showing surface disintegration.</li> <li>Extent of missing insulation ranges from minor to none.</li> <li>Damage that can be repaired.</li> </ul>
<b>Poor</b>	<ul style="list-style-type: none"> <li>Original insulation jacket is missing, damaged, deteriorated, or delaminated.</li> <li>Insulation is exposed and significant areas have been dislodged.</li> <li>Damage that cannot be easily repaired.</li> </ul>
<b>Non-Friable and Potentially Friable Materials</b> (includes materials such as plaster finishes, drywall compound, ceiling tiles, asbestos cement products, vinyl asbestos tile and asbestos paper backed vinyl sheet flooring, etc., which have the potential to become friable when handled)	
<b>Good</b>	<ul style="list-style-type: none"> <li>No significant damage.</li> <li>Material may be cracked or broken but is stable and not likely to become friable upon casual contact.</li> <li>No friable debris present</li> </ul>
<b>Fair</b>	<ul style="list-style-type: none"> <li>Not utilized as part of condition assessment for these materials.</li> </ul>
<b>Poor</b>	<ul style="list-style-type: none"> <li>Material is severely damaged.</li> <li>Debris is present or binder has disintegrated to the point where the material has become friable.</li> </ul>
<b>Asbestos-Containing Debris</b> (noted separately from the presumed source material)	
<b>Poor</b>	<ul style="list-style-type: none"> <li>Debris is always considered to be in Poor condition.</li> </ul>

### A.1.2.3 Action

Recommended ACTION for compliance and for management of identified asbestos-containing materials has been provided for each condition and component outlined in the above table. Recommendations have been classified under the following 8 ACTIONS:

1. Action dealing with the immediate clean-up of fallen ACM likely to be disturbed.

2. Action dealing with the need to use Type 2 asbestos procedures to enter an area (other than a ceiling space).
3. Action dealing with performing asbestos removal for compliance with regulations.
4. Action dealing with Type 2 asbestos procedures for ceiling entry where friable ACM debris is present on the top side of a ceiling system.
5. Action dealing with the removal of asbestos that goes beyond compliance requirements but simplifies the asbestos management.
6. Action dealing with the repair of asbestos.
7. Action dealing with ACM surveillance requirements of the regulation.
8. Action for dealing with material that may contain asbestos but was not conclusively identified in the survey.

#### **A.1.2.4 Quantity**

The approximate quantity and the units of measure related to the quantity (i.e.: linear feet (LF), square feet (SF) or each (EACH) as appropriate to the item) have only been provided for materials requiring remedial or corrective action (i.e. materials in Fair or Poor condition). In such circumstances any quantities provided should be considered rough estimates only and should not be solely relied upon for bidding purposes. It is the responsibility of the selected Contractor to obtain actual quantities.

#### **A.2 Lead**

If paint samples were collected, they would be collected by scraping the paint down to the base material substrate to ensure collection of all layers of paint. Care would be taken to avoid collection of the underlying substrate to reduce analytical substrate matrix interference.

If collected, paint samples would be submitted to an independent laboratory for the determination of lead content. The laboratory would participate in and accredited by the EPA (U.S. Environmental Protection Agency) for analysis of lead in paint chips through the American Industrial Hygiene Association (AIHA) Environmental Lead Laboratory Accreditation Program (ELLAP). Analysis would be conducted by the laboratory following the EPA "Test Methods for Evaluating Solid Waste, Physical/Chemical Methods" (SW-846), Method 7000B "Flame Atomic Absorption Spectrophotometry". Result of analysis would be reported by the laboratory as the percentage of lead by weight of the total sample (% by wt.).

The presence of lead in other materials, such as lead sheeting, pigmented mortar, lead piping, lead solder, etc. would be noted where observed but not sampled to verify lead content. Lead can be present in these materials to varying degrees, depending on their age of application and should be considered lead-containing until proven otherwise.

### **A.3 Mercury**

The type, quantity and location of mercury-containing equipment and devices in the subject area were determined by visual inspection based on appearance, age and knowledge of historical uses. Sampling for mercury-containing building materials and dismantling of suspect mercury-containing equipment was not performed. Where possible, attempts were made to verify the presence/absence of mercury by gathering additional information such as equipment model number, serial number, etc.

### **A.4 Silica**

The presence of crystalline silica in building materials was determined through visual inspection of building materials only, based on knowledge of the historic use of silica-containing materials in certain building materials. Sampling to verify the presence/absence of silica in building materials was not performed.

### **A.5 Other Designated Substances**

Other designated substances (i.e. acrylonitrile, arsenic, benzene, coke oven emissions, ethylene oxide, isocyanates, and vinyl chloride) are typically not expected to be encountered in building materials as significant constituents or in a form that would represent an exposure concern. These substances were not included in the assessment unless specific information regarding their use (e.g. in a manufacturing process) was provided to us. No sampling for these designated substances was performed.

### **A.6 Other Hazardous Materials**

#### **A.6.1 Chemical Hazards**

##### **A.6.1.1 Urea Formaldehyde Foam Insulation (UFFI)**

A visual inspection to evaluate the possible presence of Urea Formaldehyde Foam Insulation (UFFI) was conducted in the subject area. Our visual inspection was limited to identifying evidence of possible UFFI installation (i.e. repaired nozzle holes in walls) and overspray at wall/ceiling joints, etc. No destructive testing or material sampling was conducted as part of the assessment.

### **A.7 Biological Hazards**

#### **A.7.1.1 Mould Contamination**

A visual inspection to determine the possibility of mould growth was conducted in the subject area. The assessment was limited to identifying evidence of mould growth and water damage (staining, material deterioration, efflorescence, etc.) on the surface of building materials, which may be an indicator of hidden mould growth. No moisture content readings of building materials were taken to determine their current condition. Additionally, destructive testing to confirm the presence/absence of hidden mould growth and material sampling to verify the presence/absence of mould on suspect surfaces was beyond the scope of this assessment.

#### **A.7.1.2 Pest Infestation**

The presence and extent of pest infestation in the subject area was based on visually inspecting for evidence of significant pest activity, including signs of nesting, droppings/fecal accumulation, dead insects/carcass accumulation, etc. Evidence of minor pest presence was not considered to be indicative of pest infestation.

### **A.8 Environmental Hazards**

#### **A.8.1 Polychlorinated Biphenyls (PCBs)**

The presence of PCB-containing electrical equipment in the subject area was identified through visual inspection and knowledge of the timeline of historical use.

For stand-alone transformers and capacitors, information from the manufacturer nameplate (such as the date of manufacture, dielectric fluid trade name or “Type Number”, etc.) was gathered, where possible, to further evaluate if the equipment may contain PCBs. This information was then compared to the information provided in the Environment Canada document entitled “Handbook on PCB’s in Electrical Equipment” (Third Edition, April 1988) to aid in identification. Transformers and capacitors confirmed to be manufactured after 1979 were assumed to not contain PCBs. If appropriate information could not be obtained it was assumed that the transformer or capacitor contained PCBs.

For fluorescent light ballasts, a representative number of fixtures were inspected, if possible, for assessment areas that were constructed prior to 1980 and where there was no history or evidence of a complete lighting retrofit. The light fixtures were examined by removing any lenses and ballast covers to expose the ballast and identify information such as ballast make, model number, serial number, and date code. This information was then compared to the information provided in the Environment Canada document entitled “Identification of Lamp Ballasts Containing PCBs” (Report EPS 2/CC/2 (revised) August 1991) to aid in identification. Ballasts that could not be confirmed Non-PCB-containing were assumed to contain PCBs. The light fixtures were not de-energized and ballasts were not removed to obtain manufacturer information that may be on the back of the ballast. If visual confirmation of ballast type could not be made it was assumed that light fixtures in areas constructed prior to 1980 that have not undergone a complete lighting retrofit have PCB-containing ballasts until proven otherwise.

No sampling of materials or fluids within equipment was conducted to verify the presence/absence of PCBs. Inspection and testing of other materials for PCB content, including (but not limited to) caulking, asphalt, oil-based paint, plastics, switches, electric cables and hydraulic fluids was beyond the scope of the assessment.

#### **A.8.2 Ozone Depleting and Global Warming Substances**

The presence of fixed equipment likely to contain ozone-depleting substances (ODS) and/or global-warming substances (GWS) was identified through visual inspection and

knowledge of the timeline of historical use. This included equipment such as chillers, air-conditioners, walk-in refrigeration and freezer units and fixed dry-chemical fire extinguishers, where chemicals such as hydrochlorofluorocarbons (HCFCs), hydrofluorocarbons (HFCs) or halons may be present. Where possible, information regarding the type and quantity of refrigerant present was obtained from the manufacturer nameplate. Our visual assessment was limited to fixed equipment in the subject area and did not include portable equipment such as stand-alone refrigerators, freezers, water coolers, air-conditioners and fire extinguishers, etc.