



FISHER
ENGINEERING



TORONTO

DESIGNATED SUBSTANCES and HAZARDOUS MATERIALS SURVEY



LONG TERM CARE HOMES & SERVICES **Lakeshore Lodge** **3197 Lake Shore Boulevard West** **Toronto, Ontario**

Presented to:

Sara Reid

City of Toronto
Corporate Real Estate Management

Project Number: FE 23-12800

SEPTEMBER 1, 2023

EXECUTIVE SUMMARY

Fisher Engineering Limited was retained by the City of Toronto, Corporate Real Estate Management to conduct a reassessment survey for designated substances and hazardous materials in the Toronto Long Term Care Homes & Services building named Lakeshore Lodge, located at 3197 Lake Shore Boulevard West in Toronto, Ontario.

The objective of the survey was to determine the condition of previously identified asbestos-containing materials (ACM), identify and assess the condition of designated substances and other hazardous materials, and, if necessary, provide recommendations to assist the City of Toronto in fulfilling requirements to achieve regulatory compliance, as set forth under the Ontario Occupational Health and Safety Act, and enforced by the Ontario Ministry of Labour regulations for designated substances; O. Reg. 490/09 – Designated Substances and O. Reg. 278/05 – Asbestos on Construction Projects and in Buildings and Repair Operations.

This document should be filed as an addendum to the original survey report, which was issued by Fisher Environmental Ltd. on April 14 and 15, 2015.

These Designated Substances and Hazardous Materials survey report is intended for management purposes only. It is not to be used to establish the presence of designated substances or hazardous materials in building materials prior to renovation or demolition activities. A pre-renovation/pre-demolition audit of the work area for designated substances and hazardous materials should be conducted prior to any work activities that may disturb building materials potentially containing designated materials or hazardous substances.

Iqbal Fattah of Fisher Engineering Limited performed the fieldwork on May 17, 2023.

FINDINGS

The following presents a brief outline of findings within the facility. Refer to the main body and appendices of the report for specific details, quantities, conditions and locations of Designated Substances and Hazardous Materials within the facility.

Material	Findings
Asbestos	<p>Confirmed ACM were identified in the facility as follows:</p> <ul style="list-style-type: none">• Black Window Putty – 0.5-5% Chrysotile <p>Assumed ACM were identified in the facility as follows:</p> <ul style="list-style-type: none">• Roofing Materials,• Caulking,• Drywall Joint Compound,• Pipe Insulation,• Vinyl Floor Tile – one (1) variety, and• Vinyl Sheet Flooring – ten (10) varieties. <p>All confirmed or assumed ACM were observed in GOOD condition.</p>

Material	Findings
Lead	Paint finishes were generally noted to be in GOOD condition throughout the Site. It is possible that lead-based paint and lead plumbing are present within the facility.
Mercury	Mercury can be found in fluorescent light bulbs and building thermostats.
Silica	As the building is constructed of concrete block and brick, with concrete floors, silica is expected to be found within these components of the building.
Other Designated Substances	No evidence of Acrylonitrile, Arsenic, Benzene, Coke Oven Emissions, Ethylene Oxide, Isocyanates, and Vinyl Chloride was found during the building survey.
PCB	No PCB containing equipment with the potential exception of fluorescent lighting ballasts was observed.
UFFI	No UFFI containing insulation was observed on site.
Mould	During the visual inspection of the surveyed areas, visible mould growth and water staining on non-ACM ceiling tiles or non-ACM fibreglass insulation were observed.

RECOMMENDATIONS

Fisher Engineering Limited would report any deficiencies and recommendations to the City of Toronto using a 2023 Reassessment Program Corrective Actions Reporting Form. On completion of the recommended actions, an Addendum is made to confirm completion of all corrective actions.

TABLE OF CONTENTS

EXECUTIVE SUMMARY	I
1. INTRODUCTION AND REGULATORY REQUIREMENTS	1
1.1 INTRODUCTION AND SCOPE	1
2. SURVEY METHODOLOGY.....	1
2.1 GENERAL APPROACH.....	1
2.2 SURVEY METHODOLOGY	1
3. FINDINGS AND RECOMMENDATIONS.....	2
3.1 ASBESTOS.....	2
3.1.1 Findings.....	2
3.1.2 Recommendations.....	5
3.2 LEAD.....	6
3.2.1 Findings.....	6
3.2.2 Recommendations.....	6
3.3 ACRYLONITRILE.....	6
3.3.1 Findings.....	7
3.3.2 Recommendations.....	7
3.4 ARSENIC.....	7
3.4.1 Findings.....	7
3.4.2 Recommendations.....	7
3.5 BENZENE.....	7
3.5.1 Findings.....	7
3.5.2 Recommendations.....	8
3.6 COKE OVEN EMISSIONS.....	8
3.6.1 Findings.....	8
3.6.2 Recommendations.....	8
3.7 ETHYLENE OXIDES	8
3.7.1 Findings.....	8
3.7.2 Recommendations.....	8
3.8 ISOCYANATES	8
3.8.1 Findings.....	9
3.8.2 Recommendations.....	9
3.9 MERCURY.....	9
3.9.1 Findings.....	9
3.9.2 Recommendations.....	9
3.10 SILICA.....	9
3.10.1 Findings.....	10
3.10.2 Recommendations.....	10
3.11 VINYL CHLORIDE.....	10
3.11.1 Findings.....	10
3.11.2 Recommendations.....	10
3.12 POLYCHLORINATED BIPHENYLS (PCBS).....	10
3.12.1 Findings.....	11
3.12.2 Recommendations.....	11
3.13 UREA FORMALDEHYDE FOAM INSULATION (UFFI).....	11
3.13.1 Findings.....	11

TABLE OF CONTENTS

3.13.2 Recommendations.....	11
3.14 MOULD.....	11
3.14.1 Findings.....	12
3.14.2 Recommendations.....	12
4. CORRECTIVE ACTIONS	12
5. STATEMENT OF LIMITATIONS	13
6. SIGN-OFF	14
APPENDIX I – DESIGNATED SUBSTANCES AND HAZARDOUS MATERIALS INVENTORY SHEET	
APPENDIX II – RESULTS OF BULK SAMPLE ANALYSIS	
APPENDIX III – SITE DRAWINGS	
APPENDIX IV – SITE PHOTOGRAPHS	
APPENDIX V – CORRECTIVE ACTIONS INSPECTION REPORT	

1. INTRODUCTION AND REGULATORY REQUIREMENTS

1.1 Introduction and Scope

Fisher Engineering Limited was retained by the City of Toronto, Corporate Real Estate Management to conduct a reassessment survey for designated substances and hazardous materials in the Toronto Long Term Care Homes & Services building named Lakeshore Lodge, located at 3197 Lake Shore Boulevard West in Toronto, Ontario.

The objective of the survey was to determine the condition of previously identified asbestos-containing materials (ACM), identify and assess the condition of designated substances and other hazardous materials, and, if necessary, provide recommendations to assist the City of Toronto in fulfilling requirements to achieve regulatory compliance, as set forth under the Ontario Occupational Health and Safety Act, and enforced by the Ontario Ministry of Labour regulations for designated substances; O. Reg. 490/09 – Designated Substances and O. Reg. 278/05 – Asbestos on Construction Projects and in Buildings and Repair Operations.

This document should be filed as an addendum to the original survey, which was completed by Fisher Environmental Ltd. on April 14 and 15, 2015.

The Designated Substances and Hazardous Materials survey report is intended for management purposes only. It is not to be used to establish the presence of designated substances or hazardous materials in building materials prior to renovation or demolition activities. A pre-renovation/pre-demolition audit of the work area for designated substances and hazardous materials should be conducted prior to any work activities that may disturb building materials potentially containing designated materials or hazardous substances.

Iqbal Fattah of Fisher Engineering Limited performed the fieldwork on May 17, 2023.

2. SURVEY METHODOLOGY

2.1 General Approach

To ensure familiarity with the building, the Surveyor made reference to the previous assessment and reassessment reports provided by the City of Toronto prior to commencing the survey. The Surveyor also referred to facility floor plans included in the previous assessment reports, or provided independently by the City of Toronto. Site drawings identifying locations of asbestos-containing materials, if present, are included in Appendix III. Site photographs are included in Appendix IV.

2.2 Survey Methodology

The City of Toronto provided the consultant with the previous Designated Substances and Hazardous Materials Survey report and / or other survey reports identified for the facility, if available. Prior to conducting the current survey, previous reports were reviewed by Fisher

Engineering Limited and the current report is updated with all available information regarding ACM, including that from past assessments and reassessments.

The survey was conducted in compliance with the Ontario Ministry of Labour (MOL) regulations for designated substances; O. Reg. 490/09 - *Designated Substances* and O. Reg. 278/05 - *Asbestos on Construction Projects and in Buildings and Repair Operations* made under the Occupational Health and Safety Act (OHSA), R.S.O. 1990.

The Surveyor conducted a visual reassessment of all known and assumed asbestos-containing materials in all accessible areas of the building, as detailed in past survey reports, and recorded the condition (GOOD, FAIR or POOR) of each known or assumed ACM on the Designated Substances and Hazardous Materials Inventory Sheet. The Surveyor also recorded detailed descriptions of previously-unidentified potential ACM, if observed. Please refer to Appendix I for the updated Designated Substances and Hazardous Materials Inventory Sheet.

Materials confirmed to be asbestos-containing during previous assessments were not sampled for this reassessment survey. Additionally, samples were not collected of materials that were previously confirmed to be non-asbestos by the requirements of O. Reg. 278/05.

Any other potential asbestos-containing materials noted during the reassessment survey that had not been identified in a previous survey, or were not sampled in accordance with the requirements of O. Reg. 278/05, were noted as part of the reassessment.

The Designated Substances and Hazardous Materials Survey is based on a walk-through assessment of the facility and shall be conducted room by room to establish locations, conditions and types of designated substances. The survey shall also include an examination for the presence of polychlorinated biphenyls (PCBs), urea-formaldehyde foam insulation (UFFI), and visible mould growth.

3. FINDINGS AND RECOMMENDATIONS

3.1 Asbestos

Asbestos fibres may be released into the air by the disturbance of ACM during product use, demolition work, building or home maintenance, repair and remodeling. In general, exposure may occur only when the ACM is disturbed in some way to release particles and fibres into the air.

3.1.1 Findings

Previously identified confirmed or assumed ACM include the following:

- Roofing Materials,
- Caulking,
- Drywall Joint Compound,

- Pipe Insulation,
- Ceiling Tiles – one (1) variety,
- Vinyl Floor Tiles – three (3) varieties, and
- Vinyl Sheet Flooring – fourteen (14) varieties.

Drywall Joint Compound (Ceiling) not identified during previous assessment surveys, was observed in following locations: 1-027 Male Staff Changeroom, 4-030 Soiled Linen Room.

Ceiling Tile 1 (2' x 4' Pinholes with Random Fissures) not identified during previous assessment surveys, was observed in the following locations: 1-027 Men's Changeroom and 1-045 Vestibule.

Ceiling Tile 3 (2' x 2' Square Grid with Craters) not identified during previous assessment surveys, was observed in the following location: 1-001 Staff Lounge.

Vinyl Floor Tile 1 (12" x 12" Beige with Brown Specks) not identified during previous assessment surveys, was observed in the following location: B-023 Stairwell.

Vinyl Sheet Flooring 6 (Beige Swirls) not identified during previous assessment surveys, was observed in the following location: 3-035 Nurses Storage.

Vinyl Sheet Flooring 14 (Light Blue with Black Dots) not identified during previous assessment surveys, was observed in the following locations: 2-047 Servery and 4-058 Shower/Tub Room.

Vinyl Sheet Flooring 15 (Beige with Black Dots and Sparkle) not identified during previous assessment surveys, was observed in the following locations: 2-027 Shower/Tub Room, 2-067 Storage and 2-072 Washroom.

Vinyl Sheet Flooring 17 (Grey with White Little Dots) not identified during previous assessment surveys, was observed in the following locations: 2-001 Room 212, 2-002 Room 211, 2-003 Room 210, 2-004 Room 209, 2-005 Room 208, 2-006 Room 207, 2-007 Room 206, 2-008 Room 205, 2-009 Room 204, 2-010 Room 203, 2-013 Room 223, 2-014 Room 222, 2-016 Room 221, 2-017 Room 220, 2-018 Room 219, 2-019 Room 218, 2-020 Room 218, 2-021 Room 216, 2-022 Room 215, 2-023 to Room 214, 2-024 Room 213, 2-039 Room 230, 2-040 Room 229, 2-041 Room 228, 2-042 Room 227, 2-043 Room 226, 2-044 Room 225, 2-045 Room 224, 2-050 Room 231, 2-051 Room 232, 2-052 Room 233, 2-053 Room 234, 2-054 Room 235, 2-055 Room 236, 2-056 Room 237, 2-058 Room 239 and 2-059 Room 240.

Vinyl Sheet Flooring 18 (Grey with Purple Waves) not identified during previous assessment surveys, was observed in the following location: 2-077 North Corridor.

Vinyl Sheet Flooring 19 (Grey with Black Dots) not identified during previous assessment surveys, was observed in the following location: 3-027 Residence Lounge.

Vinyl Sheet Flooring 20 (Green with White, Blue and Dark Dots, Sparkle) not identified during previous assessment surveys, was observed in the following location: 4-070 Cafeteria.

Vinyl Sheet Flooring 7 (Dark Brown Laminate Design) not identified during previous assessment surveys, was observed in the following location: 4-070 Cafeteria.

Vinyl Sheet Flooring 13 (Light Beige with Brown and Grey Specks) not identified during previous assessment surveys, was observed in the following locations: 1-001 Staff Lounge, 2-072 Washroom, 3-001 Room 330, 3-002 Room 329, 3-003 Room 328, 3-004 Room 327, 3-005 Room 326, 3-006 Room 325, 3-007 Room 324, 3-008 Room 323, 3-009 Room 322, 3-011 Room 340, 3-012 Room 339, 3-013 Room 338, 3-014 Room 337, 3-015 Room 336, 3-016 Room 335, 3-017 Room 334, 3-018 Room 333, 3-019 Room 332, 3-020 Room 331, 3-023 Shower/Tub Room, 3-039 Room 321, 3-040 Room 320, 3-041 Room 319, 3-042 Room 318, 3-043 Room 317, 3-044 Room 316, 3-045 Room 315, 3-046 Room 314, 3-047 Room 313, 3-048 Room 312, 3-049 Room 311, 3-050 Room 310, 3-051 Room 309, 3-052 Room 308, 3-053 Room 307, 3-054 Room 306, 3-055 Room 305, 3-056 Room 304, 3-057 Room 303 and 3-069 Shower/Tub Room.

Vinyl Sheet Flooring 16 (Light Beige with Tiny Brown Dots) not identified during previous assessment surveys, was observed in the following location: 3-037 Servery.

Ceiling Tile 1 (2' x 4' Pinholes with Random Fissures) previously identified in location 1-001 Staff Lounge and 4-030 Soiled Linen was not observed during this survey.

Vinyl Floor Tile 1 (12" x 12" Beige with Brown Specks) previously identified in locations 1-001 Staff Lounge, 1-014 Auditorium, 1-015 Storage, 1-016 Kitchen, 2-039 Room 230, 2-040 Room 229, 2-041 Room 228, 2-042 Room 227, 2-043 Room 226, 2-044 Room 225 and 2-045 Room 224 was not observed during this survey.

Vinyl Floor Tile 2 (12"x12" Pink with Light and Dark Pink Flecks) previously identified in locations: 2-001 Room 212, 2-002 Room 211, 2-003 Room 210, 2-004 Room 209, 2-005 Room 208, 2-006 Room 207, 2-007 Room 206, 2-008 Room 205, 2-009 Room 204, 2-010 Room 203, 2-013 Room 223, 2-014 Room 222, 2-016 Room 221, 2-017 Room 220, 2-018 Room 219, 2-019 Room 218, 2-020 Room 217, 2-021 Room 216, 2-022 Room 215, 2-023 Room 214, 2-024 Room 213, 2-050 Room 231, 2-051 Room 232, 2-052 Room 233, 2-053 Room 234, 2-054 Room 235, 2-055 Room 236, 2-056 Room 237, 2-057 Room 238, 2-059 Room 240 and 2-077 North Corridor, was not observed during this survey.

Vinyl Floor Tile 5 (12" x 12" Brown Mosaic) previously identified in location 3-035 Nurses Storage was not observed during this survey.

Vinyl Sheet Flooring 2 (Beige with Faint Blue and Red) previously identified in locations 2-072 Washroom, 3-001 Room 330, 3-002 Room 329, 3-003 Room 328, 3-004 Room 327, 3-005 Room 326, 3-006 Room 325, 3-007 Room 324, 3-009 Room 322, 3-011 Room 340, 3-012 Room 339, 3-013 Room 338, 3-014 Room 337, 3-015 Room 336, 3-016 Room 335,

3-017 Room 334, 3-018 Room 333, 3-019 Room 332, 3-020 Room 331, 3-023 Shower/Tub Room, 3-027 Residence Lounge, 3-039 Room 321, 3-040 Room 320, 3-041 Room 319, 3-042 Room 318, 3-043 Room 317, 3-044 Room 316, 3-045 Room 315, 3-046 Room 314, 3-047 Room 313, 3-048 Room 312, 3-049 Room 311, 3-051 Room 309, 3-052 Room 308, 3-053 Room 307, 3-054 Room 306, 3-055 Room 305, 3-056 Room 304, 3-057 Room 303 and 3-069 Shower/Tub Room was not observed during this survey.

Vinyl Sheet Flooring 3 (Beige with Light Brown Flecks) previously identified in location 3-008 Room 323 was not observed during this survey.

No samples were collected for analysis during the current survey.

Unless previously determined to be non-asbestos, plaster, drywall joint compound, vinyl floor tiles, mastics and window caulking in other areas of the facility should continue to be assumed to be asbestos-containing, and should be sampled prior to renovation and/or demolition activities.

3.1.2 Recommendations

All confirmed and assumed ACM were observed in GOOD condition at the time of the reassessment. Therefore, no recommended corrective actions are made at this time.

Any other building materials suspected to contain asbestos which are not outlined in this report should be assumed to be asbestos-containing until sample analysis determines asbestos content.

O. Reg. 278/05 requires that an Asbestos Management Program (AMP) be implemented as long as ACM are present in a building. The AMP, original survey report and subsequent reassessment reports must be available at the work place, and must identify the type of asbestos, and where asbestos can be found on a room-by-room basis.

NOTE: Interpretation of all sources of asbestos-related information, including but not limited to the original asbestos survey report, asbestos reassessment reports, room-by-room survey data, survey drawings and reports from previous asbestos abatement projects, should be completed by a competent person trained in the historical application of asbestos in building materials, building design and preferably by a person with site-specific knowledge and/or experience.

Information contained within any of the above-noted sources may not relieve the Regulatory responsibility of building Owners, or project Employers/Constructors, to complete a detailed site inspection prior to commencement of a project.

This report should not be used as a substitute for a detailed site inspection to identify asbestos-containing building materials, which must be specifically tailored to the scope and nature of any given project, and completed prior to any maintenance, renovation or demolition work that may cause disturbance to building materials.

3.2 **Lead**

Most lead in the environment comes from human activities such as burning fossil fuels, mining and manufacturing. Lead is used in the production of batteries, ammunition, metal products such as solder and pipes, and x-ray devices. Exposure happens when eating food or drinking water that contains lead. Deteriorated lead paint can contribute to lead dust. The main target for lead toxicity is the nervous system.

The regulation for lead applies to every employer and worker at a workplace where lead is present, produced, processed, used, handled or stored and at which a worker is likely to be exposed to lead.

Additionally, in 2004 the MOL issued *Guideline: Lead on Construction Projects* outlining practices that should be followed during construction projects to protect workers from exposure to lead. This includes the methods and equipment employed in the removal of lead containing coatings that reduce the creation of dust, providing appropriate facilities for workers to wash after each shift, and providing protective clothing and respirators where necessary.

3.2.1 **Findings**

Paint finishes were generally noted to be in GOOD condition throughout the Site. Based on the age of the building, it is possible that lead-based paint and lead plumbing are present within the building. During the current investigation, no lead samples were collected for analysis.

No other indication of lead containing materials was observed during the building survey, with the exception of that which may be contained within batteries.

3.2.2 **Recommendations**

During the disturbance of any painted surfaces that contain lead, it would be recommended that appropriate procedures and use of respirators be followed to protect workers.

No immediate corrective actions were recommended with regard to lead.

3.3 **Acrylonitrile**

Acrylonitrile is used to make other chemicals such as plastics, synthetic rubber and acrylic fibres. Breathing high concentrations of acrylonitrile will cause nose and throat irritation, tightness in chest, difficulty breathing, nausea, dizziness, weakness, headache, impaired judgment and convulsions. These symptoms usually disappear when exposure has stopped. If spilled on the skin, acrylonitrile will burn the skin and cause blisters and redness. Acrylonitrile is believed to be carcinogenic.

3.3.1 Findings

Acrylonitrile based polymers may have been utilized in the production of some of the building construction materials (e.g., paints, sealants, and adhesives). Although these polymers are generally volatile, they are expected to produce significant acrylonitrile exposure only during or shortly after application of the subject material. If present on site, acrylonitrile would not be expected to be a concern during future renovation or demolition works. Acrylonitrile was not evident in its pure form anywhere within the subject areas of the building.

3.3.2 Recommendations

No immediate corrective actions were recommended with regard to acrylonitrile.

3.4 *Arsenic*

Inorganic arsenic compounds are mainly used to preserve wood. Organic arsenic compounds are used as pesticides. Arsenic occurs naturally in soil and minerals and therefore may enter air and water. Breathing high levels of arsenic may cause sore throat and irritated lungs. Ingesting high levels of arsenic can result in death. Arsenic is a suspected carcinogenic substance.

3.4.1 Findings

Low levels of arsenic may be contained within paints or coatings utilized on building construction materials, however exposure levels resulting from personal contact are not expected to be significant. Arsenic or arsenic containing compounds were not encountered during the building survey works.

3.4.2 Recommendations

No immediate corrective actions were recommended with regard to arsenic.

3.5 *Benzene*

Benzene is colourless liquid with a sweet odour. Benzene utilization has historically been associated with solvents, paints, stains, adhesives, and in the manufacturing of various rubber products. While its current use in building materials has greatly decreased due to an increased awareness of associated health concerns, it may still be present in trace quantities in various industrial solvents. Gasoline sold in Canada contains approximately 4% benzene.

Breathing very high levels of benzene can result in death, while high levels may cause drowsiness, dizziness, rapid heart rate, headaches, and unconsciousness.

3.5.1 Findings

While it may be expected, given the age of the building, that the original construction materials utilized did contain some trace levels of benzene, it is likely that any has since

volatized and would not exceed the permissible exposure values. During future renovation or demolition works, it would not be expected to be a concern. No evidence of benzene was noted during the building survey, with the exception of that which may be contained in regular gasoline fuel burning equipment.

3.5.2 Recommendations

No immediate corrective actions were recommended with regard to benzene.

3.6 *Coke Oven Emissions*

Coke oven emissions are released during the carbonization of bituminous coal for the production of coke. Exposure routes include inhalation, skin and / or eye contact. Coke oven emissions are potential occupational carcinogens.

3.6.1 Findings

This substance would not be expected to be found in the building. No evidence of the burning of coke was found during the building survey.

3.6.2 Recommendations

No immediate corrective actions were recommended with regard to coke oven emissions.

3.7 *Ethylene Oxides*

Ethylene oxide is a man-made chemical used primarily to make ethylene glycol (antifreeze and polyester). Breathing low levels of ethylene oxides for a prolonged period of time causes eye, skin and respiratory irritations, and can affect nervous system. Higher levels of exposure for shorter time produce symptoms that are similar but more severe.

3.7.1 Findings

This substance would not be expected to be found in the building. No evidence of ethylene oxides was found during the building survey.

3.7.2 Recommendations

No immediate corrective actions were recommended with regard to ethylene oxides.

3.8 *Isocyanates*

Isocyanates are a family of highly reactive, low molecular weight chemicals. They are widely used in the manufacture of flexible and rigid foams, fibres, and coatings such as paints and varnishes, and elastomers and various building materials (e.g. spray on polyurethane products). Isocyanates are powerful irritants to the eyes, skin, and respiratory and gastrointestinal tracts.

3.8.1 Findings

Use of isocyanates or isocyanate compounds would not be expected in the building. No evidence of isocyanates was found during the building survey.

3.8.2 Recommendations

No immediate corrective actions were recommended with regard to isocyanates.

3.9 Mercury

Mercury is a naturally occurring metal. It is a shiny, silver-white and odourless liquid. It combines with other elements to form inorganic compounds or salts. Metallic mercury is used to produce chlorine gas and caustic soda, and is used in thermostats and thermometers, fluorescent light bulbs, dental fillings and batteries. Exposure occurs when breathing vapours from spills, incinerators, etc.

The nervous system is very sensitive to all forms of mercury. Exposure to high levels of metallic inorganic or organic mercury can permanently damage the brain, kidneys and developing fetus. Short-term exposure may cause lung damage, nausea, vomiting and diarrhea as well as skin and eye irritation.

3.9.1 Findings

Mercury can be found in fluorescent light bulbs and building thermostats. Prior to future renovation or demolition works, it would be recommended that these products be safely removed. The disposal of mercury containing items are regulated under the Environmental Protection Act, and it would be recommended that for disposal purposes any mercury containing thermostats and fluorescent light bulbs be disposed of at an MOE licensed receiver. With the exception of fluorescent light bulbs and building thermostats, no other evidence of mercury was noted during the building survey.

3.9.2 Recommendations

No immediate corrective actions were recommended with regard to mercury.

3.10 Silica

Silica is a crystalline compound occurring abundantly as quartz, sand, and many other minerals, and used to manufacture a variety of materials, especially glass and concrete. When mining this substance, silica can be deadly when it becomes airborne. If inhaled, silica dust can cause silicosis which can be fatal.

Additionally, in 2004 the MOL issued *Guideline: Silica on Construction Projects* outlining practices that should be followed during construction projects to protect workers' from exposure to silica. This includes the methods and equipment employed in the removal of silica containing materials that reduce the creation of dust, providing appropriate facilities

for workers to wash after each shift, and providing protective clothing and respirators where necessary.

3.10.1 Findings

As the building is constructed of concrete block and brick, with concrete floors, silica is expected to be found within these components of the building. During any significant renovation or demolition works where concrete dust is generated, dust suppression techniques should be utilized to control worker exposure to silica. Silica is expected to be present in concrete and masonry products in the building.

3.10.2 Recommendations

No immediate corrective actions were recommended with regard to silica.

3.11 *Vinyl Chloride*

Vinyl chloride is used to make polyvinyl chloride (PVC) which is found in a variety of plastic products, including pipes, wires, cable coatings and packaging materials. Breathing high levels of vinyl chloride can cause dizziness, unconsciousness and death. Prolonged exposure causes changes in liver, nerve damage, immune reactions and changes in blood flow.

3.11.1 Findings

PVC pipe is generally stable and does not allow for the liberation of vinyl chloride, under normal conditions. During future renovation or demolition works, this substance would not be expected to be a concern. Vinyl chloride was not evident in its pure form, anywhere in the subject dwellings.

3.11.2 Recommendations

No immediate corrective actions were recommended with regard to vinyl chloride.

3.12 *Polychlorinated Biphenyls (PCBs)*

PCBs are mixtures of synthetic organic chemicals with the same basic chemical structure and similar physical properties ranging from oily liquids to waxy solids. Due to their non-flammability, chemical stability, high boiling point and electrical insulating properties, PCBs were used in hundreds of industrial and commercial applications including electrical, heat transfer, and hydraulic equipment; as plasticizers in paints, plastics and rubber products; in pigments, dyes and carbonless copy paper and many other applications.

PCBs have been demonstrated to cause a variety of adverse health effects. PCBs have been shown to cause cancer.

3.12.1 Findings

No PCB containing equipment with the potential exception of fluorescent lighting ballasts was observed on site. Fluorescent lighting was observed in use in several areas of the building and inspection of three random light ballasts revealed that they did not contain PCB's. The disposal of PCB containing equipment is regulated under MOE Reg. 558, and it would be recommended that during any ballast replacement works the generated ballasts be evaluated for PCB content, with any PCB ballasts being consolidated and sent for disposal to an MOE licensed PCB receiver under waste class 243D.

3.12.2 Recommendations

It would be recommended that during any ballast replacement works the generated ballasts be evaluated for PCB content. Any PCB ballasts identified should be consolidated and sent for disposal to an MOE licensed PCB receiver under waste class 243D.

3.13 *Urea Formaldehyde Foam Insulation (UFFI)*

UFFI was developed in Europe in the 1950s as an improved means of insulating difficult-to-reach cavities in house walls. UFFI is composed of a mixture of urea-formaldehyde resin, a foaming agent, and compressed air. It was commonly injected into exterior wood frame walls in order to insulate difficult to reach cavities, until its ban in Canada in December 1980. When the mixture is injected into the wall, urea and formaldehyde unite and "cure" into an insulating foam plastic. In the insulating process, a slight excess of formaldehyde was often added to ensure complete "curing" with the urea to produce the urea-formaldehyde foam. That excess was given off during the curing, almost entirely within a day or two of injection. Properly installed, UFFI might not have resulted in any problem. Unfortunately, however, UFFI was sometimes improperly installed or used in locations where it should not have been.

While small amounts of formaldehyde are harmless, it is an irritating and toxic gas in significant concentrations. Symptoms of overexposure to formaldehyde include irritation to eyes, nose, and throat; persistent cough and respiratory distress; skin irritation; nausea; headache; and dizziness.

3.13.1 Findings

No UFFI containing insulation was observed on site.

3.13.2 Recommendations

No immediate corrective action is recommended with regard to UFFI.

3.14 *Mould*

Mould contamination inside buildings has become a concern to both building owners and occupants. Exposure to moulds is known to cause a variety of health effects in some people. Many fungal spores are considered to be allergenic to susceptible persons, though individual susceptibility varies greatly.

Elevated levels of indoor mould are usually attributed to the chronic moist conditions due to water leaks, floods or elevated humidity. Under these conditions, already low levels of fungal spores in air from plants and other sources may multiply on cellulose containing materials such as carpets, wallboards, and wood, and result in mould contamination and, if left untreated, can be destructive to certain building materials.

Currently, no Canadian regulations govern the presence of mould and/or water-damaged materials in the workplace environment. However, the Health Canada document “Fungal Contamination in Public Buildings: Health Effects and Investigation Methodology” (2004) concludes that current knowledge supports the need to prevent damp conditions and mould growth and remediate any fungal growth and/or contamination in buildings.

Therefore, the presence of mould growth, mould-contaminated materials and/or water-damaged materials in the occupied environment is interpreted as a failure of Health Canada guidelines for microbial contamination in indoor environments, and as such, requires remedial action.

The MOL issued a document titled “Alert: Mould in Workplace Buildings.” This document explains the MOL’s position with respect to the presence of mould in workplace buildings.

The Environmental Abatement Council of Canada (EACC) has provided guidelines regarding investigation and remediation works Mould Abatement Guidelines Edition 3 (2015). Mould Guidelines for the EACC to protect the health of workers who may be exposed to mould during building renovations.

3.14.1 Findings

During the visual inspection of the surveyed areas, visible mould growth and water staining on non-ACM ceiling tiles or non-ACM fibreglass insulation were observed in the following locations: B-020 Corridor (South End), B-002 Office Storage, B-007 Disaster Supplies Storage, B-009 Maintenance Workshop, 1-039 Laundry Room, 1-45 Vestibule, 2-066 Clean Linen Room and 3-026 Clean Linen Room.

3.14.2 Recommendations

Removal of the mould-impacted building materials should be conducted as a Level 1 Mould Remediation Operations, based on EACC guidelines. Following abatement, the source of water ingress should be determined and addressed to prevent potential future fungal amplification.

4. CORRECTIVE ACTIONS

Fisher Engineering Limited communicated the reported deficiencies and recommendations for corrective actions to the City of Toronto. These activities have been completed and an Addendum was made to this report to confirm completion of the corrective actions. Details of the abatement work can be found in the Corrective Actions Inspection Report (Project No. FE 23-13254), which are provided in Appendix V.

Fisher Engineering Limited believes that all recommendations made as a result of the findings of the reassessment survey have been addressed.

5. STATEMENT OF LIMITATIONS

Fisher Engineering Limited accepts responsibility for the competent performance of its duties in executing this assignment within the normal standards of the profession, but disclaims responsibility for consequential damages, if any.

The extent of the building survey of designated substances and hazardous materials is based on prior agreement of the scope of work with the client, and the rationale given in this report. The building survey findings rely on professional interpretation of selective sampling and analysis. Sample analysis results have been applied to homogenous materials in unsampled locations; it was not within the scope of work to carry out an exhaustive sampling and analysis program. For non-accessible building spaces, the likelihood of the presence or absence of asbestos and other designated substances has been described, but such assessment is not a definitive statement of presence or absence.

This report was prepared for the City of Toronto, Corporate Real Estate Management. The scope of services performed may not be appropriate for the purposes of other users, and any use or reuse of this document or its findings or recommendations represented herein is at the sole risk of any other user.


We trust that the information provided in the report meets your current requirements. If you have any questions or concerns, please do not hesitate to contact the undersigned.

6. SIGN-OFF

We trust that this report meets with City of Toronto requirements and we thank you for the opportunity to be of service. Should you have any questions, please do not hesitate to contact us.

Fisher Engineering Limited

Prepared By:



Iqbal Fattah, M.Sc.
Project Manager

Reviewed By:



David Fisher, P. Eng., C. Chem.
Principal

APPENDIX I

DESIGNATED SUBSTANCES AND HAZARDOUS MATERIALS INVENTORY SHEET

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Building Address	3197 Lake Shore Boulevard West	Date(s) of Current Reassessment:	May 17, 2023
Building Name	Lakeshore Lodge	Organization Completing Reassessment:	Fisher Engineering Limited / Project FE 23-12800
Original Survey Conducted By:	Fisher Environmental Ltd.	Name of Surveyor:	Iqbal Fattah
Date(s) of Original Survey:	April 14 and 15, 2015	Signature of Surveyor:	

Summary of Findings
 All Hazardous materials were found in GOOD condition.

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
0-00	Exterior	Roof	Roofing Material	Asbestos	Not Sampled	ACM Assumed	33000 SF	Good	
0-00	Exterior	Roof	Caulking	Asbestos	19-2193-04 to 06*	None Detected	N/A	N/A	White/Grey, exterior wall of elevator shaft *From Fisher Project No. 19-9378, dated March 2019
0-00	Exterior	Windows	Window Caulking	Asbestos	Not Sampled	ACM Assumed	All	Good	
0-00	Exterior	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-001	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-001	Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-001	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
B-001	Storage	Ceiling	Ceiling Tile 2	Asbestos	15-2991-41 to 43*	None Detected	N/A	N/A	2' x 4' Pinholes with Width-wise Fissures *From Fisher Project No.15-7543, dated Dec. 2015
B-002	Office Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-002	Office Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-29 to 31	None Detected	N/A	N/A	
B-002	Office Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-002	Office Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
B-003	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-003	Electrical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-003	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-004	Diesel Storage Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-004	Diesel Storage Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-004	Diesel Storage Room	Pipe	Insulation	Asbestos	Not Sampled	ACM Assumed	1 Fitting	Good	
B-004	Diesel Storage Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-005	Common Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-005	Common Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-005	Common Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
B-006	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
B-006	Mechanical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-006	Mechanical Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-29 to 31	None Detected	N/A	N/A	
B-006	Mechanical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-006	Mechanical Room	Pipe	Insulation	Asbestos	Not Sampled	ACM Assumed	4 Fittings	Good	plus 2 valve jackets
B-007	Disaster Supplies Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-007	Disaster Supplies Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-007	Disaster Supplies Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
B-008	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-008	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-29 to 31	None Detected	N/A	N/A	
B-008	Office	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-008	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
B-009	Maintenance Workshop	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-009	Maintenance Workshop	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-009	Maintenance Workshop	Ceiling	Drywall (DJC)	Asbestos	15-2991-29*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
B-009	Maintenance Workshop	Pipe	Insulation	Asbestos	Not Sampled	ACM Assumed	8 Fittings	Good	
B-009	Maintenance Workshop	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-010	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-010	Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-010	Storage	Ceiling	Drywall (DJC)	Asbestos	15-2991-31*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
B-011	Sign/Paint Shop	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-011	Sign/Paint Shop	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-29 to 31	None Detected	N/A	N/A	
B-011	Sign/Paint Shop	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-29 to 31	None Detected	N/A	N/A	
B-012	Dietary Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-012	Dietary Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-29 to 31	None Detected	N/A	N/A	
B-012	Dietary Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-012	Dietary Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
B-013	Programs Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-013	Programs Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-013	Programs Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-014	Nurses Supplies	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-014	Nurses Supplies	Walls	Concrete/Block	N/A	N/A	N/A	N/A	N/A	
B-014	Nurses Supplies	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-015	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-015	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-015	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-016	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-016	Storage	Walls	Masonry/Concrete	N/A	N/A	N/A	N/A	N/A	
B-016	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-016	Storage	Pipe	Insulation	Asbestos	Not Sampled	ACM Assumed	6 Fittings	Good	
B-017	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-017	Stairwell	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-017	Stairwell	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-018	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-018	Corridor	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-018	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
B-019	Elevator Lobby	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-019	Elevator Lobby	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
B-019	Elevator Lobby	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-019	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
B-020	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-020	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
B-020	Corridor	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-020	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
B-021	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-021	Stairwell	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-021	Stairwell	Ceiling	Drywall (DJC)	Asbestos	15-2991-30*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
B-022	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	NO ACCESS
B-022	Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-022	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-023	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
B-023	Stairwell	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-29 to 31	None Detected	N/A	N/A	
B-023	Stairwell	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-29 to 31	None Detected	N/A	N/A	
1-001	Staff Lounge	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
1-001	Staff Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
1-001	Staff Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-001	Staff Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures NOT OBSERVED
1-001	Staff Lounge	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 15-2991-32 to 34	None Detected	N/A	N/A	2' x 2' Square Grid with Craters
1-002	Storage								No Longer Exists, Merged with 1-001
1-003	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-003	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-003	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-004	Reception	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-004	Reception	Walls	Drywall (DJC)	Asbestos	18-8220-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 18-8679, dated March 2018
1-004	Reception	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-005	Administrative Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-005	Administrative Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-005	Administrative Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-006	Administrative Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-006	Administrative Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-006	Administrative Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-007	Manager Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-007	Manager Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-007	Manager Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-008	Supplies	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-008	Supplies	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-008	Supplies	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-009	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-009	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-009	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-010	Community Programs	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-010	Community Programs	Walls	Drywall (DJC)	Asbestos	18-8220-04 to 05*	None Detected	N/A	N/A	*From Fisher Project No. 18-8679, dated March 2018
1-010	Community Programs	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-011	Chapel	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 23-1056-16 to 18	None Detected	N/A	N/A	Wood Laminate like Pattern
1-011	Chapel	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-011	Chapel	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-012	Vestry	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-012	Vestry	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-012	Vestry	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-013	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-013	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-013	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-014	Auditorium	Floor	Vinyl Sheet Flooring 7	Asbestos	Not Sampled	ACM Assumed	600 SF	Good	Dark Brown Laminate Design
1-014	Auditorium	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
1-014	Auditorium	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-014	Auditorium	Ceiling	Ceiling Tile 3	Asbestos	15-2991-34*	None Detected	N/A	N/A	2' x 2' Square Grid with Craters *From Fisher Project No.15-7543, dated Dec. 2015
1-015	Storage	Floor	Vinyl Sheet Flooring 7	Asbestos	Not Sampled	ACM Assumed	600 SF	Good	Dark Brown Laminate Design
1-015	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
1-015	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-015	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-016	Kitchen	Floor	Vinyl Sheet Flooring 7	Asbestos	Not Sampled	ACM Assumed	600 SF	Good	Dark Brown Laminate Design
1-016	Kitchen	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
1-016	Kitchen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-016	Kitchen	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-017	Multi-purpose	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-017	Multi-purpose	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-017	Multi-purpose	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-018	Servery	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-018	Servery	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-018	Servery	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-019	Housekeeping	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-019	Housekeeping	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-019	Housekeeping	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-020	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Beige Terrazzo
1-020	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-020	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-021	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Beige Terrazzo
1-021	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-021	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-022	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-022	Electrical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-022	Electrical Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-023	Beauty Salon	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-023	Beauty Salon	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
1-023	Beauty Salon	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-023	Beauty Salon	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-024	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-024	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-024	Office	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-025	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Beige Terrazzo
1-025	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-025	Washroom	Ceiling	Drywall (DJC)	Asbestos	15-2991-24*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
1-026	Washroom	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-026	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-026	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-027	Men's Changeroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-027	Men's Changeroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-027	Men's Changeroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-027	Men's Changeroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-028	Women's Changeroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-028	Women's Changeroom	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-028	Women's Changeroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-028	Women's Changeroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-029	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-029	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-029	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-030	Soiled Linen	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-030	Soiled Linen	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-030	Soiled Linen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-031	Vault	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-031	Vault	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-031	Vault	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-032	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-032	Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-032	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-032	Storage	Pipe	Insulation	Asbestos	Not Sampled	ACM Assumed	1 Fitting	Good	
1-033	Receiving	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	NO ACCESS
1-033	Receiving	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-033	Receiving	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-034	Receiving	Floor	Vinyl Floor Tile 1	Asbestos	15-1568-01 to 03*	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks *From Fisher Project No.15-7261, dated July 2015
1-034	Receiving	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-034	Receiving	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-035	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-035	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-035	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-036	Kitchen	Floor	Vinyl Sheet Flooring 14	Asbestos	Homogeneous w/ 23-1322-7 to 9	None Detected	N/A	N/A	Light Blue with Black Dots
1-036	Kitchen	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 23-1322-4 to 6	None Detected	N/A	N/A	Beige with Black Dots and Sparkle
1-036	Kitchen	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-036	Kitchen	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 15-2991-35 to 37	None Detected	N/A	N/A	2' x 4' Smooth White
1-037	Dry Storage	Floor	Vinyl Sheet Flooring 14	Asbestos	Homogeneous w/ 23-1322-7 to 9	None Detected	N/A	N/A	Light Blue with Black Dots
1-037	Dry Storage	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-037	Dry Storage	Ceiling	Ceiling Tile 4	Asbestos	15-2991-35 to 37*	None Detected	N/A	N/A	2' x 4' Smooth White *From Fisher Project No.15-7543, dated Dec. 2015
1-038	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-038	Stairwell	Walls	Drywall (DJC)	Asbestos	15-2991-22*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
1-038	Stairwell	Ceiling	Drywall (DJC)	Asbestos	15-2991-23*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
1-039	Laundry Room	Floor	Vinyl Floor Tile 1	Asbestos	17-7556-01 to 03*	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks *From Fisher Project No. 17-8527, dated Nov. 2017
1-039	Laundry Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-039	Laundry Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-039	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	17-7556-04 to 06*	None Detected	N/A	N/A	*From Fisher Project No. 17-8527, dated Nov. 2017
1-040	Laundry Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-040	Laundry Room	Walls	Drywall (DJC)	Asbestos	15-2991-25*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
1-040	Laundry Room	Ceiling	Ceiling Tile 3	Asbestos	15-2991-32, 33*	None Detected	N/A	N/A	2' x 2' Square Grid with Craters *From Fisher Project No.15-7543, dated Dec. 2015
1-041	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-041	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-041	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-042	Director of Care	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-042	Director of Care	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-042	Director of Care	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-043	Teaching Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-043	Teaching Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-043	Teaching Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-044	Closet	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-044	Closet	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-044	Closet	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-045	Vestibule	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-045	Vestibule	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-045	Vestibule	Ceiling	Drywall (DJC)	Asbestos	15-2991-26*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
1-045	Vestibule	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-046	Gift Shop	Floor	Vinyl Floor Tile 3	Asbestos	23-1056-1 to 3*	None Detected	N/A	N/A	12" x 12" Beige with Larger Black and White Flecks *From Fisher Project No. 23-12907, dated April 2023
1-046	Gift Shop	Floor	Mastic	Asbestos	23-1056-4 to 6*	None Detected	N/A	N/A	Black, under VFT-3 *From Fisher Project No. 23-12907, dated April 2023
1-046	Gift Shop	Walls	Drywall (DJC)	Asbestos	23-1056-10*	None Detected	N/A	N/A	*From Fisher Project No. 23-12907, dated April 2023
1-046	Gift Shop	Windows	Putty	Asbestos	23-1056-7 to 9*	0.5-5% Chrysotile	200 LF	Good	Black, around window frame *From Fisher Project No. 23-12907, dated April 2023
1-046	Gift Shop	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 15-2991-32 to 34	None Detected	N/A	N/A	2' x 2' Square Grid with Craters
1-047	Storage	Floor	Vinyl Floor Tile 3	Asbestos	Homogeneous w/ 23-1056-1 to 3	None Detected	N/A	N/A	12" x 12" Beige with Larger Black and White Flecks
1-047	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-047	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-048	Cafeteria	Floor	Vinyl Sheet Flooring 21	Asbestos	23-1056-13 and 14*	None Detected	N/A	N/A	Light Grey with Dark Grey and White Flecks *From Fisher Project No. 23-12907, dated April 2023
1-048	Cafeteria	Floor	Mastic	Asbestos	23-1056-19 to 21*	None Detected	N/A	N/A	Black, under VSF-21 *From Fisher Project No. 23-12907, dated April 2023
1-048	Cafeteria	Walls	Drywall (DJC)	Asbestos	23-1056-11*	None Detected	N/A	N/A	*From Fisher Project No. 23-12907, dated April 2023
1-048	Cafeteria	Ceiling	Drywall (DJC)	Asbestos	23-1056-12*	None Detected	N/A	N/A	*From Fisher Project No. 23-12907, dated April 2023
1-048	Cafeteria	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 15-2991-32 to 34	None Detected	N/A	N/A	2' x 2' Square Grid with Craters
1-049	Dishwashing	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-049	Dishwashing	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-049	Dishwashing	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-049	Dishwashing	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 15-2991-32 to 34	None Detected	N/A	N/A	2' x 2' Square Grid with Craters

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-050	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-050	Stairwell	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-050	Stairwell	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-051	Corridor	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-051	Corridor	Floor	Grout	Asbestos	23-1056-24*	None Detected	N/A	N/A	*From Fisher Project No. 23-12907, dated April 2023
1-051	Corridor	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-051	Corridor	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-052	Main Foyer	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-052	Main Foyer	Floor	Grout	Asbestos	23-1056-23*	None Detected	N/A	N/A	*From Fisher Project No. 23-12907, dated April 2023
1-052	Main Foyer	Floor	Vinyl Sheet Flooring 21	Asbestos	23-1056-15*	None Detected	N/A	N/A	Light Grey with Dark Grey and White Flecks *From Fisher Project No. 23-12907, dated April 2023
1-052	Main Foyer	Floor	Vinyl Sheet Flooring 10	Asbestos	18-8220-06 to 08*	None Detected	N/A	N/A	Beige with Grey and Brown Smears *From Fisher Project No. 18-8679, dated March 2018
1-052	Main Foyer	Floor	Vinyl Sheet Flooring 9	Asbestos	23-1056-16 to 18*	None Detected	N/A	N/A	Wood Laminate like Pattern *From Fisher Project No. 23-12907, dated April 2023
1-052	Main Foyer	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	*From Fisher Project No. 23-120907, dated April 2023
1-052	Main Foyer	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-052	Main Foyer	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-053	Corridor	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-053	Corridor	Floor	Grout	Asbestos	23-1056-22*	None Detected	N/A	N/A	*From Fisher Project No. 23-12907, dated April 2023
1-053	Corridor	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-053	Corridor	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-054	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-054	Corridor	Floor	Mastic	Asbestos	19-2995-01, 02*	None Detected	N/A	N/A	Black, under VFT-1 *From Fisher Project No. 19-9617, dated Aug. 2019
1-054	Corridor	Walls	Drywall (DJC)	Asbestos	19-2193-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 19-9378, dated March 2019
1-054	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
1-055	Flammables Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	NO ACCESS
1-055	Flammables Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-055	Flammables Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-056	Washroom	Floor	Vinyl Sheet Flooring 5	Asbestos	Homogeneous w/ 23-1322-25 to 27	None Detected	N/A	N/A	NO ACCESS Grey with White, Green and Black Dots
1-056	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-056	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-057	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
1-057	Stairwell	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-057	Stairwell	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-058	Entrance Vestibule	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-058	Entrance Vestibule	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
1-058	Entrance Vestibule	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-22 to 28	None Detected	N/A	N/A	
2-001	Room 212	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-001	Room 212	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-001	Room 212	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-001	Room 212	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-001	Room 212	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-001	Room 212	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-002	Room 211	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-002	Room 211	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-002	Room 211	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-002	Room 211	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-002	Room 211	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-002	Room 211	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-003	Room 210	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-003	Room 210	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-003	Room 210	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-003	Room 210	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-003	Room 210	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-003	Room 210	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-004	Room 209	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-004	Room 209	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-004	Room 209	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-004	Room 209	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-004	Room 209	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-004	Room 209	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-005	Room 208	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-005	Room 208	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-005	Room 208	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-005	Room 208	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-005	Room 208	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-005	Room 208	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-006	Room 207	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-006	Room 207	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-006	Room 207	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-006	Room 207	Walls	Drywall (DJC)	Asbestos	15-2991-06*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
2-006	Room 207	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-006	Room 207	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-007	Room 206	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-007	Room 206	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-007	Room 206	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-007	Room 206	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-007	Room 206	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-007	Room 206	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-008	Room 205	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-008	Room 205	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-008	Room 205	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-008	Room 205	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-008	Room 205	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-008	Room 205	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-009	Room 204	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-009	Room 204	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-009	Room 204	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-009	Room 204	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-009	Room 204	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-009	Room 204	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-010	Room 203	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-010	Room 203	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-010	Room 203	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-010	Room 203	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-010	Room 203	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-010	Room 203	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-011	Activity Room	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Grey with Purple Waves
2-011	Activity Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-011	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-011	Activity Room	Ceiling	Ceiling Tile 5	Asbestos	22-7862-5*	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures *From Fisher Project No. 22-11869, dated Feb. 2022
2-012	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-012	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-012	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-013	Room 223	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-013	Room 223	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-013	Room 223	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-013	Room 223	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-013	Room 223	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-013	Room 223	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-014	Room 222	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-014	Room 222	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-014	Room 222	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-014	Room 222	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-014	Room 222	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-014	Room 222	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-015	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	NO ACCESS 12" x 12" Beige with Brown Specks
2-015	Stairwell	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-015	Stairwell	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-016	Room 221	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-016	Room 221	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-016	Room 221	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-016	Room 221	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-016	Room 221	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-016	Room 221	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-017	Room 220	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-017	Room 220	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-017	Room 220	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-017	Room 220	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-017	Room 220	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-017	Room 220	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-018	Room 219	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-018	Room 219	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-018	Room 219	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-018	Room 219	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-018	Room 219	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-018	Room 219	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-019	Room 218	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-019	Room 218	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-019	Room 218	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-019	Room 218	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-019	Room 218	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-019	Room 218	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-020	Room 217	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-020	Room 217	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-020	Room 217	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-020	Room 217	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-020	Room 217	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-020	Room 217	Ceiling	Drywall (DJC)	Asbestos	15-2991-02*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
2-021	Room 216	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-021	Room 216	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-021	Room 216	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-021	Room 216	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-021	Room 216	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-021	Room 216	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-022	Room 215	Floor	Vinyl Sheet Flooring 3	Asbestos	19-2995-09*	None Detected	N/A	N/A	Beige with Light Brown Flecks *From Fisher Project No. 19-9617, dated Aug. 2019
2-022	Room 215	Floor	Mastic	Asbestos	19-2995-12*	None Detected	N/A	N/A	Tan, under VSF-3 *From Fisher Project No. 19-9617, dated Aug. 2019
2-022	Room 215	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-022	Room 215	Floor	Vinyl Floor Tile 2	Asbestos	19-2995-06*	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks *From Fisher Project No. 19-9617, dated Aug. 2019 NOT OBSERVED
2-022	Room 215	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-022	Room 215	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-022	Room 215	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-023	Room 214	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-023	Room 214	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-023	Room 214	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-023	Room 214	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-023	Room 214	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-023	Room 214	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-024	Room 213	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-024	Room 213	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-024	Room 213	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-024	Room 213	Walls	Drywall (DJC)	Asbestos	15-2991-07*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
2-024	Room 213	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-024	Room 213	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-025	Washroom	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	35 SF	Good	Pinkish Terrazzo
2-025	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-025	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-026	Housekeeping	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	Grey with White Little Dots
2-026	Housekeeping	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-026	Housekeeping	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-026	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-027	Shower/Tub Room	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A	
2-027	Shower/Tub Room	Floor	Vinyl Sheet Flooring 15	Asbestos	23-1322-4 and 5*	None Detected	N/A	N/A	Beige with Black Dots and Sparkle *From Fisher Project No. 23-13081, dated June 19, 2023
2-027	Shower/Tub Room	Floor	Mastic	Asbestos	23-1322-29 and 30*	None Detected	N/A	N/A	Grey, under VSF-15 *From Fisher Project No. 23-13081, dated June 19, 2023
2-027	Shower/Tub Room	Walls	Drywall (DJC)	Asbestos	16-3757-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 16-7701, dated April 2016
2-027	Shower/Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-028	Electrical Room	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with Purple Waves
2-028	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-028	Electrical Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-028	Electrical Room	Duct	Sealant	Asbestos	22-7862-7 to 9*	None Detected	N/A	N/A	Brown *From Fisher Project No. 22-11869, dated Feb. 2022
2-029	Office	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey with Purple Waves
2-029	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-029	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-030	Clean Linen	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with Purple Waves
2-030	Clean Linen	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-030	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-030	Clean Linen	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-031	Storage	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Grey with Sparkly Black & Brown Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-031	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-031	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-032	Soiled Linen	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with Purple Waves
2-032	Soiled Linen	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-032	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-032	Soiled Linen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-033	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	NO ACCESS 12" x 12" Beige with Brown Specks
2-033	Stairwell	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-033	Stairwell	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-034	Lounge	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey with Purple Waves
2-034	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-034	Lounge	Walls	Drywall (DJC)	Asbestos	15-2991-05*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
2-034	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-035	Conference Room	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Grey with Purple Waves
2-035	Conference Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-035	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-035	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-036	Washroom	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	35 SF	Good	Pinkish Terrazzo
2-036	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-036	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-037	Office	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	35 SF	Good	Grey with Purple Waves
2-037	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-037	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-038	Meeting Room	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Grey with Purple Waves
2-038	Meeting Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-038	Meeting Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-038	Meeting Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-039	Room 230	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-039	Room 230	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-039	Room 230	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-039	Room 230	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-039	Room 230	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-039	Room 230	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-040	Room 229	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-040	Room 229	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-040	Room 229	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-040	Room 229	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-040	Room 229	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-040	Room 229	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-041	Room 228	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-041	Room 228	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-041	Room 228	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-041	Room 228	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-041	Room 228	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-041	Room 228	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-042	Room 227	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-042	Room 227	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-042	Room 227	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-042	Room 227	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-042	Room 227	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-042	Room 227	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-043	Room 226	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-043	Room 226	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-043	Room 226	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-043	Room 226	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-043	Room 226	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-043	Room 226	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-044	Room 225	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-044	Room 225	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-044	Room 225	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-044	Room 225	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-044	Room 225	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-044	Room 225	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-045	Room 224	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-045	Room 224	Floor	Vinyl Sheet Flooring 3	Asbestos	19-2995-08*	None Detected	N/A	N/A	Beige with Light Brown Flecks *From Fisher Project No. 19-9617, dated Aug. 2019
2-045	Room 224	Floor	Mastic	Asbestos	19-2995-11*	None Detected	N/A	N/A	Tan, under VSF-3 *From Fisher Project No. 19-9617, dated Aug. 2019
2-045	Room 224	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-045	Room 224	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-045	Room 224	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-045	Room 224	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-046	Cafeteria	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	Grey with Purple Waves
2-046	Cafeteria	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-046	Cafeteria	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-046	Cafeteria	Ceiling	Ceiling Tile 5	Asbestos	22-7862-6*	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures *From Fisher Project No. 22-11869, dated Feb. 2022
2-047	Servery	Floor	Vinyl Sheet Flooring 14	Asbestos	23-1322-7 and 8*	None Detected	N/A	N/A	Light Blue with Black Dots *From Fisher Project No. 23-13081, dated June 19, 2023
2-047	Servery	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks NOT OBSERVED
2-047	Servery	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-047	Servery	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-048	Cafeteria	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	Grey with Purple Waves
2-048	Cafeteria	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-048	Cafeteria	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-048	Cafeteria	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-049	Activity Room	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Grey with Purple Waves
2-049	Activity Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-049	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-049	Activity Room	Ceiling	Ceiling Tile 5	Asbestos	22-7862-4*	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures *From Fisher Project No. 22-11869, dated Feb. 2022
2-050	Room 231	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-050	Room 231	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-050	Room 231	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-050	Room 231	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-050	Room 231	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-050	Room 231	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-051	Room 232	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-051	Room 232	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-051	Room 232	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-051	Room 232	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-051	Room 232	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-051	Room 232	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-051	Room 232	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-052	Room 233	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-052	Room 233	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-052	Room 233	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-052	Room 233	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-052	Room 233	Walls	Drywall (DJC)	Asbestos	15-2991-03*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
2-052	Room 233	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-052	Room 233	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-053	Room 234	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-053	Room 234	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-053	Room 234	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-053	Room 234	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-053	Room 234	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-053	Room 234	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-053	Room 234	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-054	Room 235	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-054	Room 235	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-054	Room 235	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-054	Room 235	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-054	Room 235	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-054	Room 235	Ceiling	Drywall (DJC)	Asbestos	15-2991-04*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
2-054	Room 235	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-055	Room 236	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-055	Room 236	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-055	Room 236	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-055	Room 236	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-055	Room 236	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-055	Room 236	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-055	Room 236	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-056	Room 237	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-056	Room 237	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-056	Room 237	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-056	Room 237	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-056	Room 237	Walls	Drywall (DJC)	Asbestos	15-2991-01*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
2-056	Room 237	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-056	Room 237	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-057	Room 238	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-057	Room 238	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-057	Room 238	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-057	Room 238	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-057	Room 238	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-057	Room 238	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-057	Room 238	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-058	Room 239	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-058	Room 239	Floor	Vinyl Sheet Flooring 3	Asbestos	19-2995-07*	None Detected	N/A	N/A	Beige with Light Brown Flecks *From Fisher Project No. 19-9617, dated Aug. 2019
2-058	Room 239	Floor	Mastic	Asbestos	19-2995-10*	None Detected	N/A	N/A	Tan, under VSF-3 *From Fisher Project No. 19-9617, dated Aug. 2019
2-058	Room 239	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-058	Room 239	Floor	Vinyl Floor Tile 2	Asbestos	19-2995-04*	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks *From Fisher Project No. 19-9617, dated Aug. 2019
2-058	Room 239	Floor	Mastic	Asbestos	19-2995-03*	None Detected	N/A	N/A	Black, under VFT-2 *From Fisher Project No. 19-9617, dated Aug. 2019
2-058	Room 239	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-058	Room 239	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-058	Room 239	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-059	Room 240	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with White Little Dots
2-059	Room 240	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
2-059	Room 240	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-059	Room 240	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-059	Room 240	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-059	Room 240	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-059	Room 240	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-060	Storage	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Purple Waves
2-060	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-060	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-060	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-061	Medical Storage	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Purple Waves
2-061	Medical Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-061	Medical Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-061	Medical Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-062	Office	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Grey with Purple Waves
2-062	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-062	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-063	Office	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Pinkish Terrazzo
2-063	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-063	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-064	Lounge	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	120 SF	Good	Grey with Purple Waves
2-064	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-064	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-064	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-065	Family Room	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	120 SF	Good	Grey with Purple Waves
2-065	Family Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-065	Family Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-066	Clean Linen	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with Purple Waves
2-066	Clean Linen	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-066	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-066	Clean Linen	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-067	Storage	Floor	Vinyl Sheet Flooring 15	Asbestos	Homogeneous w/ 23-1322-4 to 6	None Detected	N/A	N/A	Beige with Black Dots and Sparkle
2-067	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-067	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-068	Soiled Linen	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with Purple Waves
2-068	Soiled Linen	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-068	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-068	Soiled Linen	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-069	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	NO ACCESS 12" x 12" Beige with Brown Specks
2-069	Stairwell	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-069	Stairwell	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-070	Washroom	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Pinkish Terrazzo
2-070	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-070	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-071	Housekeeping	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with White Little Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-071	Housekeeping	Floor	Vinyl Floor Tile 2	Asbestos	19-2995-05*	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks *From Fisher Project No. 19-9617, dated Aug. 2019 NOT OBSERVED
2-071	Housekeeping	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-071	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-072	Washroom	Floor	Vinyl Sheet Flooring 13	Asbestos	23-1322-10*	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks *From Fisher Project No. 23-13081, dated June 19, 2023
2-072	Washroom	Floor	Vinyl Sheet Flooring 15	Asbestos	23-1322-6*	None Detected	N/A	N/A	Beige with Black Dots and Sparkle *From Fisher Project No. 23-13081, dated June 19, 2023
2-072	Washroom	Floor	Mastic	Asbestos	23-1322-28*	None Detected	N/A	N/A	Grey, under VSF-15 *From Fisher Project No. 23-13081, dated June 19, 2023
2-072	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-072	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-073	Electrical Room	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	NO ACCESS Grey with Purple Waves
2-073	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-073	Electrical Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-074	South Corridor	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	2500 SF	Good	Grey with Purple Waves
2-074	South Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-074	South Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-074	South Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-075	Elevator Lobby	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	Grey with Purple Waves
2-075	Elevator Lobby	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks NOT OBSERVED
2-075	Elevator Lobby	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-075	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-075	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-076	Central Foyer	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	500 SF	Good	Grey with Purple Waves
2-076	Central Foyer	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-076	Central Foyer	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-076	Central Foyer	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-077	North Corridor	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	500 SF	Good	Grey with Purple Waves
2-077	North Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-077	North Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-077	North Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-078	Corridor	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	500 SF	Good	Grey with Purple Waves
2-078	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 19-2995-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
2-078	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-078	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
2-079	Medical Storage	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with Purple Waves
2-079	Medical Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-01 to 07	None Detected	N/A	N/A	
2-079	Medical Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-001	Room 330	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-001	Room 330	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-001	Room 330	Walls	Drywall (DJC)	Asbestos	15-2991-08*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
3-001	Room 330	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-001	Room 330	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-002	Room 329	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-002	Room 329	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Beige Swirls
3-002	Room 329	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-002	Room 329	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-002	Room 329	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-003	Room 328	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-003	Room 328	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-003	Room 328	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-003	Room 328	Ceiling	Drywall (DJC)	Asbestos	15-2991-09*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
3-003	Room 328	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-003	Room 328	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-004	Room 327	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-004	Room 327	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-004	Room 327	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-004	Room 327	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-004	Room 327	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-005	Room 326	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-005	Room 326	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Beige Swirls
3-005	Room 326	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-005	Room 326	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-005	Room 326	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-006	Room 325	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-006	Room 325	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-006	Room 325	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-006	Room 325	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-006	Room 325	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-007	Room 324	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-007	Room 324	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-007	Room 324	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-007	Room 324	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-007	Room 324	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-008	Room 323	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-008	Room 323	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Beige Swirls
3-008	Room 323	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks NOT OBSERVED
3-008	Room 323	Walls	Drywall (DJC)	Asbestos	15-2991-10*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
3-008	Room 323	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-008	Room 323	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-009	Room 322	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-009	Room 322	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Beige Swirls
3-009	Room 322	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-009	Room 322	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-009	Room 322	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-010	Activity Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	Beige Swirls
3-010	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-010	Activity Room	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-011	Room 340	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-011	Room 340	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	130 SF	Good	Beige Swirls
3-011	Room 340	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-011	Room 340	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-011	Room 340	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-012	Room 339	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-012	Room 339	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-012	Room 339	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-012	Room 339	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-012	Room 339	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-013	Room 338	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-013	Room 338	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Beige Swirls
3-013	Room 338	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-013	Room 338	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-013	Room 338	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-014	Room 337	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-014	Room 337	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-014	Room 337	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-014	Room 337	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-014	Room 337	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-015	Room 336	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-015	Room 336	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-015	Room 336	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-015	Room 336	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-015	Room 336	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-016	Room 335	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-016	Room 335	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Beige Swirls

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-016	Room 335	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-016	Room 335	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-016	Room 335	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-017	Room 334	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-017	Room 334	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-017	Room 334	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-017	Room 334	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-017	Room 334	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-018	Room 333	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-018	Room 333	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-018	Room 333	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-018	Room 333	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-018	Room 333	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-019	Room 332	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-019	Room 332	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Beige Swirls
3-019	Room 332	Walls	Drywall (DJC)	Asbestos	15-2991-11*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
3-019	Room 332	Ceiling	Drywall (DJC)	Asbestos	15-2991-12*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
3-019	Room 332	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-020	Room 331	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-020	Room 331	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-020	Room 331	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-020	Room 331	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-020	Room 331	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-021	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Beige with Faint Blue and Red
3-021	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-021	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-022	Housekeeping	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Beige with Faint Blue and Red
3-022	Housekeeping	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-022	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-023	Shower/Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	23-1322-11*	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks *From Fisher Project No. 23-13081, dated June 19, 2023
3-023	Shower/Tub Room	Floor	Mastic	Asbestos	23-1322-33*	None Detected	N/A	N/A	Cream, under VSF-13 *From Fisher Project No. 23-13081, dated June 19, 2023
3-023	Shower/Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-023	Shower/Tub Room	Walls	Paint	Lead	23-1322-34*	<10 ppm	N/A	N/A	Pink *From Fisher Project No. 23-13081, dated June 19, 2023
3-023	Shower/Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-024	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
3-024	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-024	Electrical Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-025	Family Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Beige Swirls
3-025	Family Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-025	Family Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-025	Family Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-026	Clean Linen	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Beige with Faint Blue and Red
3-026	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-026	Clean Linen	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-027	Residence Lounge	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	20 SF	Good	Grey with Black Dots
3-027	Residence Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-027	Residence Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-028	Soiled Linen	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Beige with Faint Blue and Red
3-028	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-028	Soiled Linen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-029	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
3-029	Stairwell	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-029	Stairwell	Ceiling	Drywall (DJC)	Asbestos	15-1568-04 to 06*	None Detected	N/A	N/A	*From Fisher Project No.15-7261, dated July 2015
3-030	Cafeteria	Floor	Vinyl Floor Tile 5	Asbestos	Not Sampled	ACM Assumed	1250 SF	Good	12" x 12" Brown Mosaic
3-030	Cafeteria	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-030	Cafeteria	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-031	Conference Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-031	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-031	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-032	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-032	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-032	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-033	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Beige with Faint Blue and Red
3-033	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-033	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-034	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	NO ACCESS
3-034	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-034	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-035	Nurses Storage	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Beige Swirls
3-035	Nurses Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-035	Nurses Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-036	Storage	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Beige Swirls
3-036	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-036	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-037	Servery	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A	
3-037	Servery	Floor	Vinyl Sheet Flooring 16	Asbestos	23-1322-13 to 15*	None Detected	N/A	N/A	Light Beige with Tiny Brown Dots *From Fisher Project No. 23-13081, dated June 18, 2023
3-037	Servery	Walls	Paint	Lead	19-1712-07*	<10 ppm	N/A	N/A	Cream *From Fisher Project No. 19-9243, dated Jan. 2019
3-037	Servery	Walls	Drywall (DJC)	Asbestos	19-1712-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 19-9243, dated Jan. 2019
3-037	Servery	Walls	Caulking	Asbestos	19-1712-04 to 06*	None Detected	N/A	N/A	White *From Fisher Project No. 19-9243, dated Jan. 2019
3-037	Servery	Ceiling	Paint	Lead	19-1712-08*	<10 ppm	N/A	N/A	White *From Fisher Project No. 19-9243, dated Jan. 2019
3-037	Servery	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-038	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	Beige with Faint Blue and Red
3-038	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-038	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-039	Room 321	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-039	Room 321	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-039	Room 321	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-039	Room 321	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-039	Room 321	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-040	Room 320	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-040	Room 320	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-040	Room 320	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-040	Room 320	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-040	Room 320	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-041	Room 319	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-041	Room 319	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-041	Room 319	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-041	Room 319	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-041	Room 319	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-042	Room 318	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-042	Room 318	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-042	Room 318	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks NOT OBSERVED
3-042	Room 318	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-042	Room 318	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-042	Room 318	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-043	Room 317	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-043	Room 317	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-043	Room 317	Walls	Drywall (DJC)	Asbestos	15-2991-13*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
3-043	Room 317	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-043	Room 317	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-044	Room 316	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-044	Room 316	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-044	Room 316	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks NOT OBSERVED
3-044	Room 316	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-044	Room 316	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-044	Room 316	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-045	Room 315	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-045	Room 315	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-045	Room 315	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks NOT OBSERVED
3-045	Room 315	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-045	Room 315	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-045	Room 315	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-046	Room 314	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-046	Room 314	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-046	Room 314	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-046	Room 314	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-046	Room 314	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-047	Room 313	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-047	Room 313	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-047	Room 313	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-047	Room 313	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-047	Room 313	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-048	Room 312	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-048	Room 312	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-048	Room 312	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-048	Room 312	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-048	Room 312	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-049	Room 311	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-049	Room 311	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-049	Room 311	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-049	Room 311	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-049	Room 311	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-050	Room 310	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-050	Room 310	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-050	Room 310	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks NOT OBSERVED
3-050	Room 310	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-050	Room 310	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-050	Room 310	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-051	Room 309	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-051	Room 309	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-051	Room 309	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks NOT OBSERVED
3-051	Room 309	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-051	Room 309	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-051	Room 309	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-052	Room 308	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-052	Room 308	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-052	Room 308	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks NOT OBSERVED
3-052	Room 308	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-052	Room 308	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-052	Room 308	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-053	Room 307	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-053	Room 307	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-053	Room 307	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-053	Room 307	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-053	Room 307	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-054	Room 306	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-054	Room 306	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-054	Room 306	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-054	Room 306	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-054	Room 306	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-055	Room 305	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-055	Room 305	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-055	Room 305	Walls	Drywall (DJC)	Asbestos	15-2991-14*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
3-055	Room 305	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-055	Room 305	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-056	Room 304	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-056	Room 304	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-056	Room 304	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-056	Room 304	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-056	Room 304	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-057	Room 303	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-057	Room 303	Floor	Vinyl Sheet Flooring 13	Asbestos	Homogeneous w/ 23-1322-10 to 12	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks
3-057	Room 303	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-057	Room 303	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-057	Room 303	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-058	Office	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Beige Swirls
3-058	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-058	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-059	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-059	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-059	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-060	Staff Development	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-060	Staff Development	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-060	Staff Development	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-061	Staff Library	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	NO ACCESS
3-061	Staff Library	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-061	Staff Library	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-062	Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Swirls
3-062	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-062	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-063	Clean Linen	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	125 SF	Good	Beige with Faint Blue and Red
3-063	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-063	Clean Linen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	NOT OBSERVED
3-063	Clean Linen	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
3-064	Storage	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	125 SF	Good	Beige with Faint Blue and Red
3-064	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-064	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-065	Soiled Linen	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	125 SF	Good	Beige with Faint Blue and Red
3-065	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-065	Soiled Linen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-066	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	NO ACCESS 12" x 12" Beige with Brown Specks
3-066	Stairwell	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-066	Stairwell	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-067	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	Beige with Faint Blue and Red
3-067	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-067	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-068	Housekeeping	Floor	Vinyl Sheet Flooring 2	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Beige with Faint Blue and Red
3-068	Housekeeping	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-068	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-069	Shower/Tub Room	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A	
3-069	Shower/Tub Room	Floor	Vinyl Sheet Flooring 13	Asbestos	23-1322-12*	None Detected	N/A	N/A	Light Beige with Brown and Grey Specks *From Fisher Project No. 23-13081, dated June 19, 2023
3-069	Shower/Tub Room	Walls	Drywall (DJC)	Asbestos	16-3757-04 to 06*	None Detected	N/A	N/A	*From Fisher Project No. 16-7701, dated April 2016
3-069	Shower/Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-070	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-070	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-070	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
3-071	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
3-071	Stairwell	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-071	Stairwell	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-072	South Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	2500 SF	Good	Beige Swirls
3-072	South Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-072	South Corridor	Ceiling	Ceiling Tile 1	Asbestos	16-3757-10 to 12*	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures *From Fisher Project No.16-7701, dated April 2016
3-073	Elevator Lobby	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	500 SF	Good	Beige Swirls
3-073	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-073	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-074	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	500 SF	Good	Beige Swirls
3-074	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-074	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-075	Corridor	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	2500 SF	Good	Beige Swirls
3-075	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-075	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
3-076	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	NO ACCESS 12" x 12" Beige with Brown Specks
3-076	Stairwell	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
3-076	Stairwell	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-08 to 14	None Detected	N/A	N/A	
4-001	Room 412	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-001	Room 412	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-001	Room 412	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-001	Room 412	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-001	Room 412	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-002	Room 411	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-002	Room 411	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-002	Room 411	Walls	Drywall (DJC)	Asbestos	15-2991-15*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-002	Room 411	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-002	Room 411	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-003	Room 410	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-003	Room 410	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-003	Room 410	Walls	Drywall (DJC)	Asbestos	15-2991-16*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
4-003	Room 410	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-003	Room 410	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-004	Room 409	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-004	Room 409	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-004	Room 409	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-004	Room 409	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-004	Room 409	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-005	Room 408	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-005	Room 408	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-005	Room 408	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-005	Room 408	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-005	Room 408	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-006	Room 407	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-006	Room 407	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-006	Room 407	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-006	Room 407	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-006	Room 407	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-007	Room 406	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-007	Room 406	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-007	Room 406	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-007	Room 406	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-007	Room 406	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-008	Room 405	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-008	Room 405	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-008	Room 405	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-008	Room 405	Ceiling	Drywall (DJC)	Asbestos	15-2991-17*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
4-008	Room 405	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-009	Room 404	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-009	Room 405	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-009	Room 404	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-009	Room 404	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-009	Room 404	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-010	Room 403	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-010	Room 403	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-010	Room 403	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-010	Room 403	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-010	Room 403	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-011	Activity Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 23-1056-16 to 18	None Detected	N/A	N/A	Wood Laminate like Pattern
4-011	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-011	Activity Room	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-012	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
4-012	Stairwell	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-012	Stairwell	Ceiling	Drywall (DJC)	Asbestos	15-1568-07 to 09*	None Detected	N/A	N/A	*From Fisher Project No.15-7261, dated July 2015
4-013	Room 421	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-013	Room 421	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-013	Room 421	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-013	Room 421	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-013	Room 421	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-014	Room 420	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-014	Room 420	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-014	Room 420	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-014	Room 420	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-014	Room 420	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-015	Room 419	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-015	Room 419	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-015	Room 419	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-015	Room 419	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-015	Room 419	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-016	Room 418	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-016	Room 418	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-016	Room 418	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-016	Room 418	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-016	Room 418	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-017	Room 417	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-017	Room 417	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-017	Room 417	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-017	Room 417	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-017	Room 417	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-018	Room 416	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-018	Room 416	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-018	Room 416	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-018	Room 416	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-018	Room 416	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-019	Room 415	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-019	Room 415	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-019	Room 415	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-019	Room 415	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-019	Room 415	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-020	Room 414	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-020	Room 414	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-020	Room 414	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-020	Room 414	Ceiling	Drywall (DJC)	Asbestos	15-2991-18*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
4-020	Room 414	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-021	Room 413	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-021	Room 413	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-021	Room 413	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-021	Room 413	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-021	Room 413	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-022	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
4-022	Stairwell	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-022	Stairwell	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-023	Washroom	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	Green Terrazzo
4-023	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-023	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-024	Housekeeping	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-024	Housekeeping	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-024	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-025	Shower/Tub Room	Floor	Terrazzo	N/A	N/A	N/A	N/A	N/A	
4-025	Shower/Tub Room	Floor	Vinyl Sheet Flooring 20	Asbestos	23-1322-22*	None Detected	N/A	N/A	Green with White, Blue & Dark Dots, Sparkly *From Fisher Project No. 23-13081, dated June 19, 2023
4-025	Shower/Tub Room	Floor	Vinyl Sheet Flooring 5	Asbestos	23-1322-25*	None Detected	N/A	N/A	Grey with White, Green and Black Dots *From Fisher Project No. 23-13081, dated June 19,2023
4-025	Shower/Tub Room	Walls	Drywall (DJC)	Asbestos	16-3757-07 to 09*	None Detected	N/A	N/A	*From Fisher Project No. 16-7701, dated April 2016
4-025	Shower/Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-026	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-026	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-026	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
4-027	Lounge	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-027	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-027	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-028	Clean Linen	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-028	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-028	Clean Linen	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-029	Storage	Floor	Vinyl Sheet Flooring 5	Asbestos	Homogeneous w/ 23-1322-25 to 27	None Detected	N/A	N/A	Grey with White, Green and Black Dots
4-029	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-029	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-030	Soiled Linen	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-030	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-030	Soiled Linen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-030	Soiled Linen	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures NOT OBSERVED
4-031	Rehab. Services	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
4-031	Rehab. Services	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-031	Rehab. Services	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-032	Rehab. Services	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
4-032	Rehab. Services	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-032	Rehab. Services	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-033	Washroom	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	Green Terrazzo
4-033	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-033	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-034	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
4-034	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-034	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-035	Recreation Services	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
4-035	Recreation Services	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-035	Recreation Services	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-036	Room 430	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-036	Room 430	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-036	Room 430	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-036	Room 430	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-036	Room 430	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-037	Room 429	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-037	Room 429	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-037	Room 429	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-037	Room 429	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-037	Room 429	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-038	Room 428	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-038	Room 428	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-038	Room 428	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-038	Room 428	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-038	Room 428	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-039	Room 427	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-039	Room 427	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-039	Room 427	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-039	Room 427	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-039	Room 427	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-040	Room 426	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-040	Room 426	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-040	Room 426	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-040	Room 426	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-040	Room 426	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-041	Room 425	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-041	Room 425	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-041	Room 425	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-041	Room 425	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-041	Room 425	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-042	Room 424	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-042	Room 424	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-042	Room 424	Walls	Drywall (DJC)	Asbestos	15-2991-20*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
4-042	Room 424	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-042	Room 424	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-043	Room 423	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-043	Room 423	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-043	Room 423	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-043	Room 423	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-043	Room 423	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-044	Room 422	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-044	Room 422	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-044	Room 422	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-044	Room 422	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-044	Room 422	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-045	Washroom	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	Green Terrazzo
4-045	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-045	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-046	Room 440	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-046	Room 440	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-046	Room 440	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-046	Room 440	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-046	Room 440	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-047	Room 439	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-047	Room 439	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-047	Room 439	Walls	Drywall (DJC)	Asbestos	15-2991-19*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
4-047	Room 439	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-047	Room 439	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-048	Room 438	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-048	Room 438	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-048	Room 438	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-048	Room 438	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-048	Room 438	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-049	Room 437	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-049	Room 437	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-049	Room 437	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-049	Room 437	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-049	Room 437	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-050	Room 436	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-050	Room 436	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-050	Room 436	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-050	Room 436	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-050	Room 436	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-051	Room 435	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-051	Room 435	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-051	Room 435	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-051	Room 435	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-051	Room 435	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-052	Room 434	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-052	Room 434	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-052	Room 434	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-052	Room 434	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-052	Room 434	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-053	Room 433	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-053	Room 433	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-053	Room 433	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-053	Room 433	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-053	Room 433	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-054	Room 432	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-054	Room 432	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-054	Room 432	Walls	Drywall (DJC)	Asbestos	15-2991-21*	None Detected	N/A	N/A	*From Fisher Project No.15-7543, dated Dec. 2015
4-054	Room 432	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-054	Room 432	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-055	Room 431	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-055	Room 431	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2995-07 to 09	None Detected	N/A	N/A	Beige with Light Brown Flecks
4-055	Room 431	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-055	Room 431	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-055	Room 431	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-056	Washroom	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	Green Terrazzo
4-056	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-056	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-057	Housekeeping	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-057	Housekeeping	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-057	Housekeeping	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-058	Shower/Tub Room	Floor	Vinyl Sheet Flooring 5	Asbestos	23-1322-26, 27*	None Detected	N/A	N/A	Grey with White, Green and Black Dots *From Fisher Project No. 23-13081, dated June 19, 2023
4-058	Shower/Tub Room	Floor	Vinyl Sheet Flooring 20	Asbestos	23-1322-23*	None Detected	N/A	N/A	Green with White, Blue & Dark Dots, Sparkly *From Fisher Project No. 23-13081, dated June 19, 2023
4-058	Shower/Tub Room	Floor	Mastic	Asbestos	23-1322-31*	None Detected	N/A	N/A	Cream, under VSF-20 *From Fisher Project No. 23-13081, dated June 19, 2023
4-058	Shower/Tub Room	Floor	Vinyl Sheet Flooring 14	Asbestos	23-1322-9*	None Detected	N/A	N/A	Light Blue with Black Dots *From Fisher Project No. 23-13081, dated June 19, 2023
4-058	Shower/Tub Room	Floor	Mastic	Asbestos	23-1322-32*	None Detected	N/A	N/A	Cream, under VSF-14 *From Fisher Project No. 23-13081, dated June 19, 2023
4-058	Shower/Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-058	Shower/Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-058	Shower/Tub Room	Duct	Sealant	Asbestos	22-7862-3*	None Detected	N/A	N/A	Grey *From Fisher Project No. 22-11869, dated Feb. 2022
4-059	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-059	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-059	Electrical Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-060	Family Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
4-060	Family Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-060	Family Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-061	Clean Linen	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-061	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-061	Clean Linen	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-062	Rehab. Exercise Room	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-062	Rehab. Exercise Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-062	Rehab. Exercise Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-063	Soiled Linen	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-063	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-063	Soiled Linen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-064	Stairwell	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 17-7556-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Brown Specks
4-064	Stairwell	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-064	Stairwell	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-065	Conference Room	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-065	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-065	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-066	Dentist	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-066	Dentist	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-066	Dentist	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-067	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
4-067	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-067	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-068	Storage	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-068	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-068	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-069	Nurses Storage	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-069	Nurses Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-069	Nurses Storage	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-070	Cafeteria	Floor	Vinyl Floor Tile 4	Asbestos	23-1322-16 to 18*	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks *From Fisher Project No. 23-13081, dated June 19, 2023
4-070	Cafeteria	Floor	Mastic	Asbestos	23-1322-19 to 21*	None Detected	N/A	N/A	Black, under VFT-4 *From Fisher Project No. 23-13081, dated June 19, 2023
4-070	Cafeteria	Floor	Vinyl Sheet Flooring 20	Asbestos	23-1322-24*	None Detected	N/A	N/A	Green with White, Blue & Dark Dots, Sparkly *From Fisher Project No. 23-13081, dated June 19, 2023
4-070	Cafeteria	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-070	Cafeteria	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 22-7862-4 to 6	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
4-070	Cafeteria	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-071	Corridor	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-071	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-071	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-072	Corridor	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-072	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-072	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-073	Corridor	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-073	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-073	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
4-074	Corridor	Floor	Vinyl Floor Tile 4	Asbestos	Homogeneous w/ 23-1322-16 to 18	None Detected	N/A	N/A	12" x 12" Turquoise with Light and Dark Turquoise Flecks
4-074	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 15-2991-15 to 21	None Detected	N/A	N/A	
4-074	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 16-3757-10 to 12	None Detected	N/A	N/A	2' x 4' Pinholes with Random Fissures
PH-001	Elevator Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
PH-001	Elevator Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
PH-001	Elevator Room	Ceiling	Not Found	N/A	N/A	N/A	N/A	N/A	Open to metal above
PH-002	South Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
PH-002	South Mechanical Room	Walls	Metal	N/A	N/A	N/A	N/A	N/A	
PH-002	South Mechanical Room	Pipe	Insulation	Asbestos	Not Sampled	ACM Assumed	5 Fittings	Good	
PH-002	South Mechanical Room	Duct	Sealant	Asbestos	22-7862-2*	None Detected	N/A	N/A	Grey *From Fisher Project No. 22-11869, dated Feb. 2022

APPENDIX II

RESULTS OF BULK SAMPLE ANALYSIS

(NO INFORMATION TO REPORT)

APPENDIX III

SITE DRAWINGS



Legend




Asbestos-Containing Material

1-01

Location Number

NAR

No Access to Room



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 1

LOCATION:
3197 Lake Shore Boulevard West
Toronto, Ontario

BUILDING NAME:
Lakeshore Lodge

**Basement Floor Plan
Asbestos-Containing Material Locations**

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800 **DATE:** July 2023 **DRW BY:** A.M.

CAD FILE: FIG1 **SCALE:** Not to Scale **CHK BY:** I.F.





Legend



Asbestos-Containing Material

1-01


Location Number

NAR

No Access to Room



Area Not Surveyed- Daycare



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 2

LOCATION:
3197 Lake Shore Boulevard West
Toronto, Ontario

BUILDING NAME:
Lakeshore Lodge

First Floor Plan
Asbestos-Containing Material Locations

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800 **DATE:** July 2023 **DRW BY:** A.M.

CAD FILE: FIG2 **SCALE:** Not to Scale **CHK BY:** I.F.





Legend




Asbestos-Containing Material



Location Number



No Access to Room



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 3

LOCATION:
3197 Lake Shore Boulevard West
Toronto, Ontario

BUILDING NAME:
Lakeshore Lodge

Second Floor Plan Asbestos-Containing Material Locations

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800 **DATE:** July 2023 **DRW BY:** A.M.

CAD FILE: FIG3 **SCALE:** Not to Scale **CHK BY:** I.F.





Legend




Asbestos-Containing Material

1-01

Location Number

NAR

No Access to Room



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 4

LOCATION:
3197 Lake Shore Boulevard West
Toronto, Ontario

BUILDING NAME:
Lakeshore Lodge

Third Floor Plan
Asbestos-Containing Material Locations

CLIENT: City of Toronto


PROJECT NUMBER: FE-P 23-12800 **DATE:** July 2023 **DRW BY:** A.M.

CAD FILE: FIG4 **SCALE:** Not to Scale **CHK BY:** I.F.





Legend




Asbestos-Containing Material

1-01

Location Number

NAR

No Access to Room



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 5

LOCATION:
3197 Lake Shore Boulevard West
Toronto, Ontario

BUILDING NAME:
Lakeshore Lodge

Fourth Floor Plan
Asbestos-Containing Material Locations

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800 **DATE:** July 2023 **DRW BY:** A.M.

CAD FILE: FIG5 **SCALE:** Not to Scale **CHK BY:** I.F.





Legend



Asbestos-Containing Material

1-01

Location Number

NAR

No Access to Room

The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.




Figure 6

LOCATION:
3197 Lake Shore Boulevard West
Toronto, Ontario

BUILDING NAME:
Lakeshore Lodge

Roof Plan
Asbestos-Containing Material Locations

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800 **DATE:** July 2023 **DRW BY:** A.M.

CAD FILE: FIG6 **SCALE:** Not to Scale **CHK BY:** I.F.



APPENDIX IV

SITE PHOTOGRAPHS

(NO INFORMATION TO REPORT)

APPENDIX V

CORRECTIVE ACTIONS INSPECTION REPORT



September 1, 2023

City of Toronto, Corporate Real Estate Management
Metro Hall, 55 John Street
Toronto ON, M5V 3C6

Inder Bhamra, EP, PMP, CSM
Environmental Coordinator

Re: Level I Mould Abatement at Long Term Care Home, 3197 Lakeshore Blvd West, Toronto, ON

As requested, Fisher Engineering Limited (Fisher) has provided environmental monitoring services with respect to mould abatement activities recently undertaken at Lakeshore Lodge Long Term Care Home, located at 3197 Lakeshore Blvd West, Toronto, Ontario (the "Site"). Mould remediation was initiated following the discovery of mould impacted and water-stained ceiling tiles and pipe insulation, during the Annual Survey, conducted on May 17, 2023, Fisher Project No. FE 23-12800.

The City of Toronto retained Fisher as the environmental health and safety consultant to provide project monitoring. Fisher retained Furcon Environmental Inc. (Furcon) as the environmental contractor to undertake the specified remedial action. Abatement work was conducted in accordance with Level 1 mould remediation protocols, as outlined by the Environmental Abatement Council of Canada (EACC) Mould Abatement Guidelines, Edition 3 (2015). The fieldwork was conducted on August 28, 2023.

Based on the recommendations provided in a corrective action form, the ceiling tiles and pipe insulation are to be removed from the rooms listed below, following Level 1 Mould Remediation Procedures, and replaced with new materials.

Loc. B-020, Corridor
Loc. B-002, Office Storage
Loc. B-007, Disaster Supplies

Loc. B-009, Workshop
Loc. 1-039, Laundry Room
Loc. 1-045, Vestibule

Loc. 2-066, Clean Linen Room
Loc. 3-026, Clean Linen Room

Based on the Site observation, the remediation scope of work had been completed and the work area was cleaned to an acceptable level.

Respectfully submitted,

Prepared by:

Reviewed by:

Yvonne Hoogeveen, P. Eng.
Project Manager

David A. Fisher, B.A.Sc., C.Chem., P.Eng.
Principal

Attachment A – Site Photos



Photo 1: Mould Impacted pipe insulation in Location B-009.



Photo 2: View of the pipe in Location B-009 after remediation works



Photo 3: Mould Impacted ceiling tiles in Location B-007.



Photo 4: View of the replacement ceiling tile in Location B-007.



Photo 5: Mould Impacted ceiling tiles in Location B-007.



Photo 6: View of the replacement ceiling tile in Location B-007.



Photo 7: Mould Impacted ceiling tiles in Location 1-045.



Photo 8: View of the replacement ceiling tile in Location 1-045.



Photo 9: Mould Impacted ceiling tiles in Location 3-026.



Photo 10: View of the replacement ceiling tile in Location 3-026.



Photo 11: Mould Impacted ceiling tiles in Location 1-039.



Photo 12: View of the replacement ceiling tile in Location 1-039.



Photo 13: Mould Impacted ceiling tiles in Location 2-066.



Photo 14: View of the replacement ceiling tile in Location 2-066.