

**DESIGNATED SUBSTANCES and HAZARDOUS
MATERIALS SURVEY**



**LONG TERM CARE HOMES & SERVICES
Cummer Lodge
205 Cummer Avenue
Toronto, Ontario**

Presented to:

Sara Reid

City of Toronto
Corporate Real Estate Management

Project Number: FE-P 23-12800

SEPTEMBER 1, 2023

EXECUTIVE SUMMARY

Fisher Engineering Limited was retained by the City of Toronto, Corporate Real Estate Management to conduct a reassessment survey for designated substances and hazardous materials in the Toronto Long Term Care Homes & Services building named Cummer Lodge, located at 205 Cummer Avenue in Toronto, Ontario.

The objective of the survey was to determine the condition of previously identified asbestos-containing materials (ACM), identify and assess the condition of designated substances and other hazardous materials, and, if necessary, provide recommendations to assist the City of Toronto in fulfilling requirements to achieve regulatory compliance, as set forth under the Ontario Occupational Health and Safety Act, and enforced by the Ontario Ministry of Labour regulations for designated substances; O. Reg. 490/09 – Designated Substances and O. Reg. 278/05 – Asbestos on Construction Projects and in Buildings and Repair Operations.

This document should be filed as an addendum to the original survey report, which was issued by Fisher Environmental Ltd. on April 7 and 8, 2015.

These Designated Substances and Hazardous Materials survey report is intended for management purposes only. It is not to be used to establish the presence of designated substances or hazardous materials in building materials prior to renovation or demolition activities. A pre-renovation/pre-demolition audit of the work area for designated substances and hazardous materials should be conducted prior to any work activities that may disturb building materials potentially containing designated materials or hazardous substances.

Renata Stec of Fisher Engineering Limited performed the current fieldwork on May 26, 2023.

FINDINGS

The following presents a brief outline of findings within the facility. Refer to the main body and appendices of the report for specific details, quantities, conditions and locations of Designated Substances and Hazardous Materials within the facility.

Material	Findings
Asbestos	<p>Confirmed ACM were identified in the facility as follows:</p> <ul style="list-style-type: none">• Brown Putty (on the roof) – 5-25 % Chrysotile <p>Assumed ACM were identified in the facility as follows:</p> <ul style="list-style-type: none">• Roofing Material;• Caulking;• Drywall Joint Compound;• Vinyl Floor Tiles – seven (7) varieties; and• Vinyl Sheet Flooring – nine (9) varieties. <p>All confirmed or assumed ACM were observed in GOOD condition.</p>

Material	Findings
Lead	Paint finishes were generally noted to be in GOOD condition throughout the Site. It is possible that lead-based paint and lead plumbing are present within the facility.
Mercury	Mercury can be found in fluorescent light bulbs and building thermostats.
Silica	As the building is constructed of concrete block and brick, with concrete floors, silica is expected to be found within these components of the building.
Other Designated Substances	No evidence of Acrylonitrile, Arsenic, Benzene, Coke Oven Emissions, Ethylene Oxide, Isocyanates, and Vinyl Chloride was found during the building survey.
PCB	No PCB containing equipment with the potential exception of fluorescent lighting ballasts was observed.
UFFI	No UFFI containing insulation was observed on site.
Mould	During the visual inspection of the surveyed areas, visible mould growth and water staining on non-ACM ceiling tile were observed

RECOMMENDATIONS

Fisher Engineering Limited would report any deficiencies and recommendations to the City of Toronto using a 2023 Reassessment Program Corrective Actions Reporting Form. On completion of the recommended actions, an Addendum is made to confirm completion of all corrective actions.

TABLE OF CONTENTS

EXECUTIVE SUMMARY	I
1. INTRODUCTION AND REGULATORY REQUIREMENTS	1
1.1 INTRODUCTION AND SCOPE	1
2. SURVEY METHODOLOGY.....	1
2.1 GENERAL APPROACH.....	1
2.2 SURVEY METHODOLOGY	1
3. FINDINGS AND RECOMMENDATIONS.....	2
3.1 <i>ASBESTOS</i>	2
3.1.1 <i>Findings</i>	2
3.1.2 <i>Recommendations</i>	3
3.2 <i>LEAD</i>	4
3.2.1 <i>Findings</i>	4
3.2.2 <i>Recommendations</i>	4
3.3 <i>ACRYLONITRILE</i>	5
3.3.1 <i>Findings</i>	5
3.3.2 <i>Recommendations</i>	5
3.4 <i>ARSENIC</i>	5
3.4.1 <i>Findings</i>	5
3.4.2 <i>Recommendations</i>	5
3.5 <i>BENZENE</i>	5
3.5.1 <i>Findings</i>	6
3.5.2 <i>Recommendations</i>	6
3.6 <i>COKE OVEN EMISSIONS</i>	6
3.6.1 <i>Findings</i>	6
3.6.2 <i>Recommendations</i>	6
3.7 <i>ETHYLENE OXIDES</i>	6
3.7.1 <i>Findings</i>	6
3.7.2 <i>Recommendations</i>	7
3.8 <i>ISOCYANATES</i>	7
3.8.1 <i>Findings</i>	7
3.8.2 <i>Recommendations</i>	7
3.9 <i>MERCURY</i>	7
3.9.1 <i>Findings</i>	7
3.9.2 <i>Recommendations</i>	7
3.10 <i>SILICA</i>	8
3.10.1 <i>Findings</i>	8
3.10.2 <i>Recommendations</i>	8
3.11 <i>VINYL CHLORIDE</i>	8
3.11.1 <i>Findings</i>	8
3.11.2 <i>Recommendations</i>	8
3.12 <i>POLYCHLORINATED BIPHENYLS (PCBS)</i>	9
3.12.1 <i>Findings</i>	9
3.12.2 <i>Recommendations</i>	9
3.13 <i>UREA FORMALDEHYDE FOAM INSULATION (UFFI)</i>	9
3.13.1 <i>Findings</i>	9

TABLE OF CONTENTS

3.13.2 Recommendations.....	10
3.14 MOULD.....	10
3.14.1 Findings.....	10
3.14.2 Recommendations.....	10
4. CORRECTIVE ACTIONS	11
5. STATEMENT OF LIMITATIONS	11
6. SIGN-OFF	12
APPENDIX I – DESIGNATED SUBSTANCES AND HAZARDOUS MATERIALS INVENTORY SHEET	
APPENDIX II – RESULTS OF BULK SAMPLE ANALYSIS	
APPENDIX III – SITE DRAWINGS	
APPENDIX IV – SITE PHOTOGRAPHS	
APPENDIX V – CORRECTIVE ACTIONS INSPECTION REPORT	

1. INTRODUCTION AND REGULATORY REQUIREMENTS

1.1 Introduction and Scope

Fisher Engineering Limited was retained by the City of Toronto, Corporate Real Estate Management to conduct a reassessment survey for designated substances and hazardous materials in the Toronto Long Term Care Homes & Services building named Cummer Lodge, located at 205 Cummer Avenue in Toronto, Ontario.

The objective of the survey was to determine the condition of previously identified asbestos-containing materials (ACM), identify and assess the condition of designated substances and other hazardous materials, and, if necessary, provide recommendations to assist the City of Toronto in fulfilling requirements to achieve regulatory compliance, as set forth under the Ontario Occupational Health and Safety Act, and enforced by the Ontario Ministry of Labour regulations for designated substances; O. Reg. 490/09 – Designated Substances and O. Reg. 278/05 – Asbestos on Construction Projects and in Buildings and Repair Operations.

This document should be filed as an addendum to the original survey report, which was issued by Fisher Environmental Ltd. on April 7 and 8, 2015.

The Designated Substances and Hazardous Materials survey report is intended for management purposes only. It is not to be used to establish the presence of designated substances or hazardous materials in building materials prior to renovation or demolition activities. A pre-renovation/pre-demolition audit of the work area for designated substances and hazardous materials should be conducted prior to any work activities that may disturb building materials potentially containing designated materials or hazardous substances.

Renata Stec of Fisher Engineering Limited performed the current fieldwork on May 24, 2023.

2. SURVEY METHODOLOGY

2.1 General Approach

To ensure familiarity with the building, the Surveyor made reference to the previous assessment and reassessment reports provided by the City of Toronto prior to commencing the survey. The Surveyor also referred to facility floor plans included in the previous assessment reports, or provided independently by the City of Toronto. Site drawings identifying locations of asbestos-containing materials, if present, are included in Appendix III. Site photographs are included in Appendix IV.

2.2 Survey Methodology

The City of Toronto provided the consultant with the previous Designated Substances and Hazardous Materials Survey report and / or other survey reports identified for the facility, if

available. Prior to conducting the current survey, previous reports were reviewed by Fisher Engineering Limited and the current report is updated with all available information regarding ACM, including that from past assessments and reassessments.

The survey was conducted in compliance with the Ontario Ministry of Labour (MOL) regulations for designated substances; O. Reg. 490/09 - *Designated Substances* and O. Reg. 278/05 - *Asbestos on Construction Projects and in Buildings and Repair Operations* made under the Occupational Health and Safety Act (OHSA), R.S.O. 1990.

The Surveyor conducted a visual reassessment of all known and assumed asbestos-containing materials in all accessible areas of the building, as detailed in past survey reports, and recorded the condition (GOOD, FAIR or POOR) of each known or assumed ACM on the Designated Substances and Hazardous Materials Inventory Sheet. The Surveyor also recorded detailed descriptions of previously-unidentified potential ACM, if observed. Please refer to Appendix I for the updated Designated Substances and Hazardous Materials Inventory Sheet.

Materials confirmed to be asbestos-containing during previous assessments were not sampled for this reassessment survey. Additionally, samples were not collected of materials that were previously confirmed to be non-asbestos by the requirements of O. Reg. 278/05.

Any other potential asbestos-containing materials noted during the reassessment survey that had not been identified in a previous survey, or were not sampled in accordance with the requirements of O. Reg. 278/05, were noted as part of the reassessment.

The Designated Substances and Hazardous Materials Survey is based on a walk-through assessment of the facility and shall be conducted room by room to establish locations, conditions, and types of designated substances. The survey shall also include an examination for the presence of polychlorinated biphenyls (PCBs), urea-formaldehyde foam insulation (UFFI), and visible mould growth.

3. FINDINGS AND RECOMMENDATIONS

3.1 Asbestos

Asbestos fibres may be released into the air by the disturbance of ACM during product use, demolition work, building or home maintenance, repair, and remodelling. In general, exposure may occur only when the ACM is disturbed in some way to release particles and fibres into the air.

3.1.1 Findings

Previously confirmed or assumed ACM include the following:

- Roofing Material;
- Caulking;

- Putty;
- Drywall Joint Compound;
- Vinyl Floor Tiles – six (6) varieties; and
- Vinyl Sheet Flooring – ten (10) varieties.

Vinyl Floor Tile 13 (1.5' × 1.5' Beige with Brown Splatters) not identified during previous assessment surveys, was observed in location 4-078 Corridor.

Vinyl Sheet Flooring 12 (Grey) not identified during previous assessment surveys, was observed in all residents room on 4th floor in North wing, and additionally in the following locations: Elevator Lobby 4-001, Exercise Therapy 4-005, Dining Room 4-014, Corridor 4-036, Electrical Closet 4-037, Office 4-038, Nurses Station 4-040, Medical Supply 4-041, Corridor 4-042, Family Lounge 4-043, Activity Room 4-056, Corridor 4-057, Lounge 4-058, Storage 4-062, Housekeeping 4-087, Office 4-088, Dining Room 4-089, and in Change Locker 4-164.

Vinyl Sheet Flooring 11 (Grey with Dark Dots) previously identified in the building was also observed inside washrooms in all resident's room on 4th floor in North Wing.

Vinyl Sheet Flooring 2 (Beige with Black Specks) previously identified in the building was not observed in Janitor's Closet 4-138.

No samples were collected for analysis during the current survey.

Unless previously determined to be non-asbestos, plaster, drywall joint compound, vinyl floor tiles, mastics and window caulking in other areas of the facility should continue to be assumed to be asbestos-containing, and should be sampled prior to renovation and/or demolition activities

3.1.2 Recommendations

All confirmed and assumed ACM were observed in GOOD condition at the time of the reassessment. Therefore, no recommended corrective actions are made currently.

Any other building materials suspected to contain asbestos which are not outlined in this report should be assumed to be asbestos-containing until sample analysis determines asbestos content.

Ontario Ministry of Labour Regulation 278/05 requires that an Asbestos Management Program (AMP) be implemented if asbestos-containing materials are present in a building. The AMP, original survey report and subsequent reassessment reports must be available at the work place, and must identify the type of asbestos, and where asbestos can be found on a room-by-room basis.

NOTE: Interpretation of all sources of asbestos-related information, including but not limited to the original asbestos survey report, asbestos reassessment reports, room-by-room

survey data, survey drawings and reports from previous asbestos abatement projects, should be completed by a competent person trained in the historical application of asbestos in building materials, building design and preferably by a person with site-specific knowledge and/or experience.

Information contained within any of the above-noted sources may not relieve the Regulatory responsibility of building Owners, or project Employers/Constructors, to complete a detailed site inspection prior to commencement of a project.

This report should not be used as a substitute for a detailed site inspection to identify asbestos-containing building materials, which must be specifically tailored to the scope and nature of any given project, and completed prior to any maintenance, renovation or demolition work that may cause disturbance to building materials.

3.2 **Lead**

Most lead in the environment comes from human activities such as burning fossil fuels, mining, and manufacturing. Lead is used in the production of batteries, ammunition, metal products such as solder and pipes, and x-ray devices. Exposure happens when eating food or drinking water that contains lead. Deteriorated lead paint can contribute to lead dust. The main target for lead toxicity is the nervous system.

The regulation for lead applies to every employer and worker at a workplace where lead is present, produced, processed, used, handled, or stored and at which a worker is likely to be exposed to lead.

Additionally, in 2004 the MOL issued *Guideline: Lead on Construction Projects* outlining practices that should be followed during construction projects to protect workers from exposure to lead. This includes the methods and equipment employed in the removal of lead containing coatings that reduce the creation of dust, providing appropriate facilities for workers to wash after each shift, and providing protective clothing and respirators where necessary.

3.2.1 **Findings**

Paint finishes were generally noted to be in GOOD condition throughout the Site. Based on the age of the building, it is possible that lead-based paint and lead plumbing are present within the building. During the current investigation, no samples were collected for lead analysis.

No other indication of lead containing materials was observed during the building audit, except for potential lead contained within batteries.

3.2.2 **Recommendations**

During the disturbance of any painted surfaces that contain lead, it would be recommended that appropriate procedures and use of respirators be followed to protect workers.

No immediate corrective actions were recommended about lead.

3.3 Acrylonitrile

Acrylonitrile is used to make other chemicals such as plastics, synthetic rubber, and acrylic fibres. Breathing high concentrations of acrylonitrile will cause nose and throat irritation, tightness in chest, difficulty breathing, nausea, dizziness, weakness, headache, impaired judgment, and convulsions. These symptoms usually disappear when exposure has stopped. If spilled on the skin, acrylonitrile will burn the skin and cause blisters and redness. Acrylonitrile is believed to be carcinogenic.

3.3.1 Findings

Acrylonitrile based polymers may have been utilized in the production of some of the building construction materials (e.g., paints, sealants, and adhesives). Although these polymers are generally volatile, they are expected to produce significant acrylonitrile exposure only during or shortly after application of the subject material. If present on site, acrylonitrile would not be expected to be a concern during future renovation or demolition works. Acrylonitrile was not evident in its pure form anywhere within the subject areas of the building.

3.3.2 Recommendations

No immediate corrective actions were recommended about acrylonitrile.

3.4 Arsenic

Inorganic arsenic compounds are mainly used to preserve wood. Organic arsenic compounds are used as pesticides. Arsenic occurs naturally in soil and minerals and therefore may enter air and water. Breathing high levels of arsenic may cause sore throat and irritated lungs. Ingesting high levels of arsenic can result in death. Arsenic is a suspected carcinogenic substance.

3.4.1 Findings

Low levels of arsenic may be contained within paints or coatings utilized on building construction materials, however exposure levels resulting from personal contact are not expected to be significant. Arsenic or arsenic containing compounds were not encountered during the building survey works.

3.4.2 Recommendations

No immediate corrective actions were recommended about arsenic.

3.5 Benzene

Benzene is colourless liquid with a sweet odour. Benzene utilization has historically been associated with solvents, paints, stains, adhesives, and in the manufacturing of various rubber products. While its current use in building materials has greatly decreased due to an

increased awareness of associated health concerns, it may still be present in trace quantities in various industrial solvents. Gasoline sold in Canada contains approximately 4% benzene.

Breathing very high levels of benzene can result in death, while high levels may cause drowsiness, dizziness, rapid heart rate, headaches, and unconsciousness.

3.5.1 Findings

While it may be expected, given the age of the building, that the original construction materials utilized did contain some trace levels of benzene, it is likely that any has since volatilized and would not exceed the permissible exposure values. During future renovation or demolition works, it would not be expected to be a concern. No evidence of benzene was noted during the building survey, except for that which may be contained in regular gasoline fuel burning equipment.

3.5.2 Recommendations

No immediate corrective actions were recommended about benzene.

3.6 *Coke Oven Emissions*

Coke oven emissions are released during the carbonization of bituminous coal to produce coke. Exposure routes include inhalation, skin and / or eye contact. Coke oven emissions are potential occupational carcinogens.

3.6.1 Findings

This substance would not be expected to be found in the building. No evidence of the burning of coke was found during the building survey.

3.6.2 Recommendations

No immediate corrective actions were recommended about coke oven emissions.

3.7 *Ethylene Oxides*

Ethylene oxide is a man-made chemical used primarily to make ethylene glycol (antifreeze and polyester). Breathing low levels of ethylene oxides for a prolonged period causes eye, skin, and respiratory irritations, and can affect nervous system. Higher levels of exposure for shorter time produce symptoms that are similar but more severe.

3.7.1 Findings

This substance would not be expected to be found in the building. No evidence of ethylene oxides was found during the building survey.

3.7.2 Recommendations

No immediate corrective actions were recommended about ethylene oxides.

3.8 *Isocyanates*

Isocyanates are a family of highly reactive, low molecular weight chemicals. They are widely used in the manufacture of flexible and rigid foams, fibres, and coatings such as paints and varnishes, and elastomers and various building materials (e.g., spray on polyurethane products). Isocyanates are powerful irritants to the eyes, skin, and respiratory and gastrointestinal tracts.

3.8.1 Findings

Use of isocyanates or isocyanate compounds would not be expected in the building. No evidence of isocyanates was found during the building survey.

3.8.2 Recommendations

No immediate corrective actions were recommended about isocyanates.

3.9 *Mercury*

Mercury is a naturally occurring metal. It is a shiny, silver-white, and odourless liquid. It combines with other elements to form inorganic compounds or salts. Metallic mercury is used to produce chlorine gas and caustic soda, and is used in thermostats and thermometers, fluorescent light bulbs, dental fillings, and batteries. Exposure occurs when breathing vapours from spills, incinerators, etc.

The nervous system is very sensitive to all forms of mercury. Exposure to high levels of metallic inorganic or organic mercury can permanently damage the brain, kidneys and developing fetus. Short-term exposure may cause lung damage, nausea, vomiting and diarrhea as well as skin and eye irritation.

3.9.1 Findings

Mercury can be found in fluorescent light bulbs and building thermostats. Prior to future renovation or demolition works, it would be recommended that these products be safely removed. The disposal of mercury containing items are regulated under the Environmental Protection Act, and it would be recommended that for disposal purposes any mercury containing thermostats and fluorescent light bulbs be disposed of at an MOE licensed receiver. Except for fluorescent light bulbs and building thermostats, no other evidence of mercury was noted during the building survey.

3.9.2 Recommendations

No immediate corrective actions were recommended about mercury.

3.10 *Silica*

Silica is a crystalline compound occurring abundantly as quartz, sand, and many other minerals, and used to manufacture a variety of materials, especially glass and concrete. When mining this substance, silica can be deadly when it becomes airborne. If inhaled, silica dust can cause silicosis which can be fatal.

Additionally, in 2004 the MOL issued *Guideline: Silica on Construction Projects* outlining practices that should be followed during construction projects to protect workers from exposure to silica. This includes the methods and equipment employed in the removal of silica containing materials that reduce the creation of dust, providing appropriate facilities for workers to wash after each shift, and providing protective clothing and respirators where necessary.

3.10.1 Findings

As the building is constructed of concrete block and brick, with concrete floors, silica is expected to be found within these components of the building. During any significant renovation or demolition works where concrete dust is generated, dust suppression techniques should be utilized to control worker exposure to silica. Silica is expected to be present in concrete and masonry products in the building.

3.10.2 Recommendations

No immediate corrective actions were recommended about silica.

3.11 *Vinyl Chloride*

Vinyl chloride is used to make polyvinyl chloride (PVC) which is found in a variety of plastic products, including pipes, wires, cable coatings and packaging materials. Breathing high levels of vinyl chloride can cause dizziness, unconsciousness, and death. Prolonged exposure causes changes in liver, nerve damage, immune reactions, and changes in blood flow.

3.11.1 Findings

PVC pipe is generally stable and does not allow for the liberation of vinyl chloride, under normal conditions. During future renovation or demolition works, this substance would not be expected to be a concern. Vinyl chloride was not evident in its pure form, anywhere in the subject dwellings.

3.11.2 Recommendations

No immediate corrective actions were recommended about vinyl chloride.

3.12 Polychlorinated Biphenyls (PCBs)

PCBs are mixtures of synthetic organic chemicals with the same basic chemical structure and similar physical properties ranging from oily liquids to waxy solids. Due to their non-flammability, chemical stability, high boiling point and electrical insulating properties, PCBs were used in hundreds of industrial and commercial applications including electrical, heat transfer, and hydraulic equipment; as plasticizers in paints, plastics, and rubber products; in pigments, dyes and carbonless copy paper and many other applications.

PCBs have been demonstrated to cause a variety of adverse health effects. PCBs have been shown to cause cancer.

3.12.1 Findings

No PCB containing equipment with the potential exception of fluorescent lighting ballasts was observed on site. The disposal of PCB containing equipment is regulated under MOE Reg. 558, and it would be recommended that during any ballast replacement works the generated ballasts be evaluated for PCB content, with any PCB ballasts being consolidated and sent for disposal to an MOE licensed PCB receiver under waste class 243D.

3.12.2 Recommendations

It would be recommended that during any ballast replacement works the generated ballasts be evaluated for PCB content. Any PCB ballasts identified should be consolidated and sent for disposal to an MOE licensed PCB receiver under waste class 243D.

3.13 Urea Formaldehyde Foam Insulation (UFFI)

UFFI was developed in Europe in the 1950s as an improved means of insulating difficult-to-reach cavities in house walls. UFFI is composed of a mixture of urea-formaldehyde resin, a foaming agent, and compressed air. It was commonly injected into exterior wood frame walls in order to insulate difficult to reach cavities, until its ban in Canada in December 1980. When the mixture is injected into the wall, urea and formaldehyde unite and "cure" into an insulating foam plastic. In the insulating process, a slight excess of formaldehyde was often added to ensure complete "curing" with the urea to produce the urea-formaldehyde foam. That excess was given off during the curing, almost entirely within a day or two of injection. Properly installed, UFFI might not have resulted in any problem. Unfortunately, however, UFFI was sometimes improperly installed or used in locations where it should not have been.

While small amounts of formaldehyde are harmless, it is an irritating and toxic gas in significant concentrations. Symptoms of overexposure to formaldehyde include irritation to eyes, nose, and throat; persistent cough and respiratory distress; skin irritation; nausea; headache; and dizziness.

3.13.1 Findings

No UFFI containing insulation was observed on site.

3.13.2 Recommendations

No immediate corrective action is recommended with regard to UFFI.

3.14 *Mould*

Mould contamination inside buildings has become a concern to both building owners and occupants. Exposure to moulds is known to cause a variety of health effects in some people. Many fungal spores are allergenic to susceptible persons, though individual susceptibility varies greatly.

Elevated levels of indoor mould are usually attributed to the chronic moist conditions due to water leaks, floods, or elevated humidity. Under these conditions, already low levels of fungal spores in air from plants and other sources may multiply on cellulose containing materials such as carpets, wallboards, and wood, and result in mould contamination and, if left untreated, can be destructive to certain building materials.

Currently, no Canadian regulations govern the presence of mould and/or water-damaged materials in the workplace environment. However, the Health Canada document “Fungal Contamination in Public Buildings: Health Effects and Investigation Methodology” (2004) concludes that current knowledge supports the need to prevent damp conditions and mould growth and remediate any fungal growth and/or contamination in buildings.

Therefore, the presence of mould growth, mould-contaminated materials and/or water-damaged materials in the occupied environment is interpreted as a failure of Health Canada guidelines for microbial contamination in indoor environments, and as such, requires remedial action.

The MOL issued a document titled “Alert: Mould in Workplace Buildings.” This document explains the MOL’s position with respect to the presence of mould in workplace buildings.

The Environmental Abatement Council of Canada (EACC) has provided guidelines regarding investigation and remediation works Mould Abatement Guidelines Edition 3 (2015). Mould Guidelines for the EACC to protect the health of workers who may be exposed to mould during building renovations.

3.14.1 Findings

During the visual inspection of the surveyed areas, water stains and mould growth on non-ACM ceiling tile was observed in location 4-137 Reading Room.

3.14.2 Recommendations

Removal of the mould-impacted building materials should be conducted as a Level 1 Mould Remediation Operations, based on EACC guidelines. Following abatement, the source of water ingress should be determined and addressed to prevent potential future fungal amplification.

4. CORRECTIVE ACTIONS

Fisher Engineering Limited communicated the reported deficiencies and recommendations for corrective actions to the City of Toronto. These activities have been completed and an Addendum was made to this report to confirm completion of the corrective actions. Details of the abatement work can be found in the Corrective Actions Inspection Report (Project No. FE 23-13254), which are provided in Appendix V.

Fisher Engineering Limited believes that all recommendations made as a result of the findings of the reassessment survey have been addressed.

5. STATEMENT OF LIMITATIONS

Fisher Engineering Limited accepts responsibility for the competent performance of its duties in executing this assignment within the normal standards of the profession, but disclaims responsibility for consequential damages, if any.

The extent of the building survey of designated substances and hazardous materials is based on prior agreement of the scope of work with the client, and the rationale given in this report. The building survey findings rely on professional interpretation of selective sampling and analysis. Sample analysis results have been applied to homogenous materials in unsampled locations; it was not within the scope of work to carry out an exhaustive sampling and analysis program. For non-accessible building spaces, the likelihood of the presence or absence of asbestos and other designated substances has been described, but such assessment is not a definitive statement of presence or absence.

This report was prepared for the City of Toronto, Corporate Real Estate Management. The scope of services performed may not be appropriate for the purposes of other users, and any use or reuse of this document or its findings or recommendations represented herein is at the sole risk of any other user.

We trust that the information provided in the report meets your current requirements. If you have any questions or concerns, please do not hesitate to contact the undersigned.

6. SIGN-OFF

We trust that this report meets with City of Toronto requirements and we thank you for the opportunity to be of service. Should you have any questions, please do not hesitate to contact us.


Fisher Engineering Limited

Prepared By:



Renata Stec, M.Sc.
Project Manager

Reviewed By:



David Fisher, P. Eng., C. Chem.
Principal



APPENDIX I

DESIGNATED SUBSTANCES AND HAZARDOUS MATERIALS INVENTORY SHEET

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Building Address	205 Cummer Avenue	Date(s) of Current Reassessment:	May 26, 2023
Building Name	Cummer Lodge	Organization Completing Reassessment:	Fisher Engineering Limited / Project FE 23-12800
Original Survey Conducted By:	Fisher Environmental Ltd.	Name of Surveyor:	Renata Stec 
Date(s) of Original Survey:	April 7 and 8, 2015	Signature of Surveyor:	

Summary of Findings
All Hazardous Materials observed in GOOD condition.

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
0-00	Exterior	Roof	Roofing Material	Asbestos	Not Sampled	ACM Assumed	48500 SF	Good	
0-00	Exterior	Roof	Caulking	Asbestos	20-4597-1 to 3*	None Detected	N/A	N/A	Grey Sealant, Chiller, pipe system *From Fisher Project No. 20-10353, dated June 2020
0-00	Exterior	Roof	Caulking	Asbestos	19-3288-01 to 03*	None Detected	N/A	N/A	Red, around the Joint of Exhaust Stack *From Fisher Project No. 19-9791, dated Sept. 2019
0-00	Exterior	Roof	Mastic	Asbestos	19-3288-04 to 06*	None Detected	N/A	N/A	Black, around the base of the Duct Supporting *From Fisher Project No. 19-9791, dated Sept. 2019
0-00	Exterior	Roof	Caulking	Asbestos	19-3288-07 to 09*	None Detected	N/A	N/A	Light Grey, around the base of the Duct Work *From Fisher Project No. 19-9791, dated Sept. 2019
0-00	Exterior	Roof	Mastic	Asbestos	19-3288-10 to 12*	None Detected	N/A	N/A	Black, around the Duct Work *From Fisher Project No. 19-9791, dated Sept. 2019
0-00	Exterior	Roof	Caulking	Asbestos	19-3288-13 to 15*	None Detected	N/A	N/A	Tan, around the Joint of the Duct Work *From Fisher Project No. 19-9791, dated Sept. 2019
0-00	Exterior	Roof	Caulking	Asbestos	19-3288-16 to 18*	None Detected	N/A	N/A	Dark Grey, around the base of Duct Work *From Fisher Project No. 19-9791, dated Sept. 2019
0-00	Exterior	Roof	Caulking	Asbestos	22-8676-7 to 9*	None Detected	N/A	N/A	Cream, on the RTU Units *From Fisher Project No. 22-12281, dated June 2022
0-00	Exterior	Roof	Caulking	Asbestos	22-8676-10 to 12*	None Detected	N/A	N/A	Grey, on the RTU Units *From Fisher Project No. 22-12281, dated June 2022
0-00	Exterior	Roof	Putty	Asbestos	22-8676-13 to 15*	5-25% Chrysotile	3 openings	Good	Brown, around the wiring inside RTU-9 Unit *From Fisher Project No. 22-12281, dated June 2022
0-00	Exterior	Roof	Gasket	Asbestos	22-8676-16 to 18*	None Detected	N/A	N/A	Inside RTU Units *From Fisher Project No. 22-12281, dated June 2022
0-00	Exterior	Windows	Window Caulking	Asbestos	Not Sampled	ACM Assumed	All	Good	
0-00	Exterior	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-001	Cable Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-001	Cable Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-001	Cable Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-002	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-002	Electrical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-002	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-003	Generator	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-003	Generator	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-003	Generator	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-003	Generator	Pipe	Caulking	Asbestos	16-3753-04 to 06*	None Detected	N/A	N/A	Inside Pipe *From Fisher Project No. 16-7701, dated April 2016
B-003	Generator	Pipe	Caulking	Asbestos	16-3753-07 to 09*	None Detected	N/A	N/A	Outside Pipe *From Fisher Project No. 16-7701, dated April 2016
B-004	Vault Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	NO ACCESS
B-004	Vault Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-004	Vault Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-005	Access Well	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	NO ACCESS
B-005	Access Well	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-005	Access Well	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-006	Exhaust Well	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	NO ACCESS
B-006	Exhaust Well	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-006	Exhaust Well	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-007	Intake Well	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	NO ACCESS
B-007	Intake Well	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-007	Intake Well	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-008	Boiler Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-008	Boiler Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-008	Boiler Room	Walls	Paint	Lead	16-3753-10*	<10 ppm	N/A	N/A	Off-White *From Fisher Project No. 16-7701, dated April 2016
B-008	Boiler Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-008	Boiler Room	Ceiling	Boiler Block	Asbestos	16-3753-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 16-7701, dated April 2016
B-009	Diesel Tank	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-009	Diesel Tank	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-009	Diesel Tank	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-010	Chiller Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-010	Chiller Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
B-010	Chiller Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-011	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-011	Mechanical Room	Other	Paint	Lead	22-8676-19*	156 ppm	N/A	N/A	Grey, on the base of AHU Unit *From Fisher Project No. 22-12281, dated June, 2022
B-011	Mechanical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-011	Mechanical Room	Walls	Paint	Lead	20-4597-4* 22-7864-19*	<10 ppm <10 ppm	N/A	N/A	White *From Fisher Project No. 20-10353, dated June 2020 *From Fisher Project No.22-11904, dated Jan. 2022
B-011	Mechanical Room	Duct	Sealant	Asbestos	22-8676-1 to 3*	None Detected	N/A	N/A	Red, on AHU Units *From Fisher Project No. 22-12281, dated June, 2022
B-011	Mechanical Room	Other	Sealant	Asbestos	22-8676-4 to 6*	None Detected	N/A	N/A	Black, on AHU-4 Units, around pipe penetrations *From Fisher Project No. 22-12281, dated June, 2022
B-011	Mechanical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-012	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-012	Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-012	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-013	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-013	Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-013	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-014	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-014	Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-014	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-015	Elevator Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-015	Elevator Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-015	Elevator Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-016	Fire Alarm Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-016	Fire Alarm Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-016	Fire Alarm Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-017	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-017	Mechanical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-017	Mechanical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
B-018	Vestibule	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-018	Vestibule	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-018	Vestibule	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-019	Mortuary	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
B-019	Mortuary	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
B-019	Mortuary	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-020	Vestibule	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
B-020	Vestibule	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-020	Vestibule	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-021	Washroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
B-021	Washroom	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-021	Washroom	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-022	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-022	Mechanical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-022	Mechanical Room	Walls	Mortar	Asbestos	22-7864-16 to 18*	None Detected	N/A	N/A	*From Fisher Project No.22-11904, dated Jan. 2022
B-022	Mechanical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-023	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-023	Electrical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-023	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-024	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-024	Mechanical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-024	Mechanical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-024	Mechanical Room	Ceiling	Sprayed Fireproofing	Asbestos	081607-01 to 03*	None Detected	N/A	N/A	*From Building Asbestos Survey Report, Aug. 2007
B-025	Maintenance Supply	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-025	Maintenance Supply	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-025	Maintenance Supply	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
B-026	Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-026	Office	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-026	Office	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-027	Maintenance Workshop	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-027	Maintenance Workshop	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-027	Maintenance Workshop	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-028	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-028	Electrical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-028	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-029	Corridor	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
B-029	Corridor	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-029	Corridor	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-030	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-030	Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
B-030	Storage	Walls	Firestop-Red	Asbestos	22-7864-6*	None Detected	N/A	N/A	*From Fisher Project No.22-11904, dated Jan. 2022
B-030	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-001	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-001	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-001	Office	Ceiling	Ceiling Tile 11	Asbestos	21-7672-68 to 70*	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture *From Fisher Project No.21-11790, dated Dec. 2021
1-002	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-002	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-002	Office	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-003	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-003	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-003	Office	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-003	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-004	Corridor	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-004	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks NOT OBSERVED
1-004	Corridor	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-004	Corridor	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-005	Wellness Centre	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-005	Wellness Centre	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-005	Wellness Centre	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture NOT OBSERVED
1-005	Wellness Centre	Ceiling	Ceiling Tile 10	Asbestos	21-7672-56 to 58*	None Detected	N/A	N/A	2' x 4' Tiny Pinholes *From Fisher Project No.21-11790, dated Dec. 2021
1-006	Stair No 2	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-006	Stair No 2	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-006	Stair No 2	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-007	Training Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-007	Training Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-007	Training Room	Ceiling	Ceiling Tile 10	Asbestos	Homogeneous w/ 21-7672-56 to 58	None Detected	N/A	N/A	2' x 4' Tiny Pinholes NOT OBSERVED
1-007	Training Room	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-008	Vestibule	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-008	Vestibule	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks NOT OBSERVED
1-008	Vestibule	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-008	Vestibule	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-009	Day Centre	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-009	Day Centre	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-009	Day Centre	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-010	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-010	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-010	Office	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-011	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-011	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-011	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-012	Washroom	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-012	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-012	Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-012	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-013	Quiet Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-013	Quiet Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-013	Quiet Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-014	Kitchenette	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-014	Kitchenette	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-014	Kitchenette	Ceiling	Ceiling Tile 10	Asbestos	Homogeneous w/ 21-7672-56 to 58	None Detected	N/A	N/A	2' x 4' Tiny Pinholes
1-015	Corridor	Floor	Carpet/Ceramic	N/A	N/A	N/A	N/A	N/A	
1-015	Corridor	Walls	Drywall (DJC)	Asbestos	18-8954-06*	None Detected	N/A	N/A	*From Fisher Project No. 18-8828, dated May 2018
1-015	Corridor	Ceiling	Drywall (DJC)	Asbestos	21-7672-30*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
1-015	Corridor	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-016	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-016	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-016	Office	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-017	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-017	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-017	Office	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-018	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-018	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-018	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-019	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-019	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-019	Office	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-020	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-020	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-020	Office	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-021	Administration	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-021	Administration	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-021	Administration	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-022	Conference Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-022	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-022	Conference Room	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-023	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-023	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-023	Office	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-024	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-024	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-024	Office	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-025	Administration	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-025	Administration	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-025	Administration	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-026	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-026	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-026	Office	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-027	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-027	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-027	Office	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-028	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-028	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-028	Office	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-029	Corridor	Floor	Vinyl Sheet Flooring 7	Asbestos	22-7864-13 to 15*	None Detected	N/A	N/A	Beige Swirls *From Fisher Project No.22-11904, dated Jan. 2022
1-029	Corridor	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-029	Corridor	Walls	Drywall (DJC)	Asbestos	18-8954-07*	None Detected	N/A	N/A	*From Fisher Project No. 18-8828, dated May 2018
1-029	Corridor	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-030	Copy Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
1-030	Copy Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-030	Copy Room	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-031	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
1-031	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-031	Storage	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-032	Washroom	Floor	Vinyl Sheet Flooring 7	Asbestos	Homogeneous w/ 22-7864-13 to 15	None Detected	N/A	N/A	Beige Swirls
1-032	Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks NOT OBSERVED
1-032	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-032	Washroom	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture
1-033	Conference Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-033	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-033	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-034	Security	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	NO ACCESS Grey with Dark Dots
1-034	Security	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-034	Security	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-035	Reception	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-035	Reception	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-035	Reception	Ceiling	Ceiling Tile 11	Asbestos	Homogeneous w/ 21-7672-68 to 70	None Detected	N/A	N/A	2' x 4' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-035	Reception	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-036	Lounge	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-036	Lounge	Walls	Drywall (DJC)	Asbestos	18-8954-08*	None Detected	N/A	N/A	*From Fisher Project No. 18-8828, dated May 2018
1-036	Lounge	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-036	Lounge	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-037	Men's Washroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-037	Men's Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-037	Men's Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-038	Women's Washroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-038	Women's Washroom	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-038	Women's Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-039	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-039	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-039	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-040	Auditorium	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-040	Auditorium	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks NOT OBSERVED
1-040	Auditorium	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-040	Auditorium	Ceiling	Drywall (DJC)	Asbestos	21-7672-28, 29*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
1-040	Auditorium	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-041	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-041	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-041	Storage	Ceiling	Ceiling Tile 9	Asbestos	21-7672-25 to 27*	None Detected	N/A	N/A	2' x 4' Clustered Pinholes *From Fisher Project No.21-11790, dated Dec. 2021
1-041A	Storage	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-041A	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-041A	Storage	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
1-042	Cafeteria	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	320 SF	Good	Grey with Dark Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-042	Cafeteria	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-042	Cafeteria	Floor	Vinyl Floor Tile 2	Asbestos	15-1531-05, 06*	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks * From Annual Survey Report, August 2015
1-042	Cafeteria	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-042	Cafeteria	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-042	Cafeteria	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-043	Pot/Pan Wash	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-043	Pot/Pan Wash	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-043	Pot/Pan Wash	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
1-044	Kitchen	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-044	Kitchen	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-044	Kitchen	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-044	Kitchen	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
1-045	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-045	Electrical Closet	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-045	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-046	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-046	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-046	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-047	Loading Area	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-047	Loading Area	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-047	Loading Area	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-048	Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-048	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-048	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-049	Storage	Floor	Vinyl Floor Tile 12	Asbestos	Not Sampled	ACM Assumed	145 SF	Good	12" x 12" Light Grey Mosaic
1-049	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-049	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-049	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-050	Office	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
1-050	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-050	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-051	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-051	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-051	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-052	Office	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
1-052	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-052	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-053	Storage	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-053	Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-053	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-054	Linen Storage	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-054	Linen Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-054	Linen Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-055	Storage	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-055	Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-055	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-056	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-056	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-056	Janitor's Closet	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-057	Staff Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
1-057	Staff Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-057	Staff Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-058	Elevator Room	Floor	Vinyl Floor Tile 4	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	12" x 12" Painted Red
1-058	Elevator Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-058	Elevator Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-059	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	15-1531-02, 03*	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks * From Annual Survey Report, August 2015
1-059	Corridor	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-059	Corridor	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-060	Garbage Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-060	Garbage Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-060	Garbage Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-061	Elevator Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-061	Elevator Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-061	Elevator Room	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-062	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-062	Electrical Closet	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-062	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-063	Residents Bar	Floor	Vinyl Floor Tile 3	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	12" x 12" Beige with Light and Dark Beige Flecks
1-063	Residents Bar	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-063	Residents Bar	Ceiling	Ceiling Tile 3	Asbestos	21-7672-22 to 24*	None Detected	N/A	N/A	2' x 2' Texture with Pinholes *From Fisher Project No.21-11790, dated Dec. 2021
1-064	Washroom	Floor	Vinyl Floor Tile 3	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	12" x 12" Beige with Light and Dark Beige Flecks
1-064	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-064	Washroom	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 21-7672-22 to 24	None Detected	N/A	N/A	2' x 2' Texture with Pinholes
1-065	Storage	Floor	Vinyl Floor Tile 3	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	12" x 12" Beige with Light and Dark Beige Flecks
1-065	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-065	Storage	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-066	Library & Activity Room	Floor	Vinyl Floor Tile 3	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	12" x 12" Beige with Light and Dark Beige Flecks
1-066	Library & Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-066	Library & Activity Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-067	Vestibule	Floor	Vinyl Floor Tile 3	Asbestos	Not Sampled	ACM Assumed	25 SF	Good	12" x 12" Beige with Light and Dark Beige Flecks
1-067	Vestibule	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-067	Vestibule	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-068	Tuck Shop	Floor	Vinyl Floor Tile 3	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	12" x 12" Beige with Light and Dark Beige Flecks
1-068	Tuck Shop	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-068	Tuck Shop	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-069	Lobby	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-069	Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-069	Lobby	Ceiling	Drywall (DJC)	Asbestos	21-7672-31*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
1-069	Lobby	Ceiling	Texture Coat	Asbestos	21-7672-1,3*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
1-070	Entrance Vestibule	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-070	Entrance Vestibule	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-070	Entrance Vestibule	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-070	Entrance Vestibule	Ceiling	Texture Coat	Asbestos	18-8954-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 18-8828, dated May 2018
1-071	Elevator Lobby	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-071	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	18-8954-04 and 05*	None Detected	N/A	N/A	*From Fisher Project No. 18-8828, dated May 2018
1-071	Elevator Lobby	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-072	Phone Room	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-072	Phone Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-072	Phone Room	Walls	Paint	Lead	18-8954-25*	<10 ppm	N/A	N/A	Yellow *From Fisher Project No. 18-8828, dated May 2018
1-072	Phone Room	Ceiling	Texture Coat	Asbestos	20-5186-1 to 3*	None Detected	N/A	N/A	*From Fisher Project No. 20-10577, dated Sept. 2020
1-073	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-073	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-073	Office	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-074	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-074	Electrical Closet	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-074	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-075	Stair No 1	Floor	Vinyl Sheet Flooring 9	Asbestos	Not Sampled	ACM Assumed	1200 SF	Good	Beige with Brown Specks
1-075	Stair No 1	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-075	Stair No 1	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-075	Stair No 1	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-076	Employee Entrance	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-076	Employee Entrance	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-076	Employee Entrance	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-077	Storage	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-077	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-077	Storage	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-078	Worship Centre	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-078	Worship Centre	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-078	Worship Centre	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-079	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-079	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-079	Corridor	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-080	Waiting Room	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-080	Waiting Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-080	Waiting Room	Ceiling	Drywall (DJC)	Asbestos	21-7672-32,33*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
1-081	Washroom	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-081	Washroom	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-081	Washroom	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-082	Housekeeping Storage	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-082	Housekeeping Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-082	Housekeeping Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-082	Housekeeping Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-083	Nurses Station	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
1-083	Nurses Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-083	Nurses Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-084	Receiving Area	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-084	Receiving Area	Floor	Vinyl Floor Tile 1	Asbestos	15-1531-01*	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks * From Annual Survey Report, August 2015 NOT OBSERVED
1-084	Receiving Area	Floor	Vinyl Floor Tile 2	Asbestos	15-1531-04*	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks * From Annual Survey Report, August 2015 NOT OBSERVED
1-084	Receiving Area	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-084	Receiving Area	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-085	Housekeeping Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-085	Housekeeping Office	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-085	Housekeeping Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-085	Housekeeping Office	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-086	Shipping Area	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-086	Shipping Area	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-086	Shipping Area	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-087	Soiled Laundry	Floor	Vinyl Floor Tile 5	Asbestos	17-7568-06*	None Detected	N/A	N/A	12" x 12" White with Light Blue Flecks *From Fisher Project No. 17-8527, dated Nov. 2017
1-087	Soiled Laundry	Floor	Vinyl Floor Tile 11	Asbestos	17-7568-07 to 09*	None Detected	N/A	N/A	12" x 12" White with Beige Flecks *From Fisher Project No. 17-8527, dated Nov. 2017
1-087	Soiled Laundry	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-087	Soiled Laundry	Walls	Drywall (DJC)	Asbestos	17-7568-03*	None Detected	N/A	N/A	*From Fisher Project No. 17-8527, dated Nov. 2017
1-087	Soiled Laundry	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-088	Clean Laundry	Floor	Vinyl Floor Tile 5	Asbestos	17-7568-04, 05*	None Detected	N/A	N/A	12" x 12" White with Light Blue Flecks *From Fisher Project No. 17-8527, dated Nov. 2017
1-088	Clean Laundry	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-088	Clean Laundry	Walls	Drywall (DJC)	Asbestos	17-7568-01, 02* 18-8954-10**	None Detected	N/A	N/A	*From Fisher Project No. 17-8527, dated Nov. 2017 **From Fisher Project No. 18-8828, dated May 2018
1-088	Clean Laundry	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-089	Garage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-089	Garage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-089	Garage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-090	Stair No 5	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-090	Stair No 5	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-090	Stair No 5	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-090	Stair No 5	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-091	Stair No 5A	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-091	Stair No 5A	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-091	Stair No 5A	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-091	Stair No 5A	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-092	Women's Lockers	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-092	Women's Lockers	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-092	Women's Lockers	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-092	Women's Lockers	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-092	Women's Lockers	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-093	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-093	Corridor	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-093	Corridor	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-094	Men's Lockers	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
1-094	Men's Lockers	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-094	Men's Lockers	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-094	Men's Lockers	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-094	Men's Lockers	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-095	Disaster Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	NO ACCESS
1-095	Disaster Storage	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-095	Disaster Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-096	Beauty Shop	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-096	Beauty Shop	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-096	Beauty Shop	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-097	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
1-097	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-097	Storage	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
1-098	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-098	Electrical Room	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-098	Electrical Room	Walls	Paint	Lead	18-8954-24*	<10 ppm	N/A	N/A	White *From Fisher Project No. 18-8828, dated May 2018
1-098	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-099	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-099	Electrical Closet	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
1-099	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-100	Dining Room	Floor	Vinyl Sheet Flooring 5	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	Brown with White and Black Specks
1-100	Dining Room	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	750 SF	Good	Beige with Pink and Blue Flecks
1-100	Dining Room	Walls	Drywall (DJC)	Asbestos	18-8954-09*	None Detected	N/A	N/A	*From Fisher Project No. 18-8828, dated May 2018
1-100	Dining Room	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
1-100	Dining Room	Ceiling	Texture Coat	Asbestos	21-7672-4,5*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
1-101	Corridor	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	Beige with Pink and Blue Flecks
1-101	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-101	Corridor	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-102	Stair No 6	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-102	Stair No 6	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-102	Stair No 6	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-103	Room S135	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-103	Room S135	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-103	Room S135	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-103	Room S135	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-103	Room S135	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-104	Room S136	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-104	Room S136	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-104	Room S136	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-104	Room S136	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-104	Room S136	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-105	Room S137	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-105	Room S137	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-105	Room S137	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-105	Room S137	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-105	Room S137	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-106	Room S138	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-106	Room S138	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-106	Room S138	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-106	Room S138	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-106	Room S138	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-107	Room S139	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-107	Room S139	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-107	Room S139	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-107	Room S139	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-107	Room S139	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-108	Room S140	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-108	Room S140	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-108	Room S140	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-108	Room S140	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-108	Room S140	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-109	Room S141	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-109	Room S141	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-109	Room S141	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-109	Room S141	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-109	Room S141	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-110	Room S142	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-110	Room S142	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-110	Room S142	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-110	Room S142	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-110	Room S142	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-111	Room S143	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-111	Room S143	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-111	Room S143	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-111	Room S143	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-111	Room S143	Ceiling	Texture Coat	Asbestos	21-7672-6,7*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
1-112	Room S144	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-112	Room S144	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-112	Room S144	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-112	Room S144	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-112	Room S144	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-113	Room S145	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-113	Room S145	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-113	Room S145	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-113	Room S145	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-113	Room S145	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-114	Room S146	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-114	Room S146	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-114	Room S146	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-114	Room S146	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-114	Room S146	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-115	Clean Utility	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
1-115	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-115	Clean Utility	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
1-116	Soiled Utility	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
1-116	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-116	Soiled Utility	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
1-117	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-117	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-117	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-118	Exam Room	Floor	Vinyl Floor Tile 6	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	12" x 12" Grey with Black Specks
1-118	Exam Room	Floor	Vinyl Floor Tile 7	Asbestos	Homogeneous w/ 22-7864-7 to 9	None Detected	N/A	N/A	12" x 12" Cream
1-118	Exam Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-118	Exam Room	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 21-7672-59 to 61	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
1-119	Tub Room/Storage	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
1-119	Tub Room/Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-119	Tub Room/Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-120	Lounge	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-120	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-120	Lounge	Ceiling	Ceiling Tile 5	Asbestos	21-7672-59 to 61*	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures *From Fisher Project No.21-11790, dated Dec. 2021

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-121	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
1-121	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-121	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-122	Conference Room	Floor	Vinyl Sheet Flooring 1	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Flecks
1-122	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-122	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-123	Corridor	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	Beige with Pink and Blue Flecks
1-123	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-123	Corridor	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-124	Office	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	Beige with Pink and Blue Flecks
1-124	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-124	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-124	Office	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
1-125	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
1-125	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-125	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-126	Clean Linen	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
1-126	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-126	Clean Linen	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
1-127	Day Centre/Storage	Floor	Vinyl Floor Tile 7	Asbestos	Homogeneous w/ 22-7864-7 to 9	None Detected	N/A	N/A	12" x 12" Cream
1-127	Day Centre/Storage	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
1-127	Day Centre/Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-127	Day Centre/Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-128	Electrical Room	Floor	Vinyl Floor Tile 7	Asbestos	22-7864-7 to 9*	None Detected	N/A	N/A	12" x 12" Cream *From Fisher Project No.22-11904, dated Jan. 2022
1-128	Electrical Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-128	Electrical Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-129	Room S156	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-129	Room S156	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-129	Room S156	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-129	Room S156	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-129	Room S156	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-130	Room S157	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-130	Room S157	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-130	Room S157	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-130	Room S157	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-130	Room S157	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-131	Room S158	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-131	Room S158	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-131	Room S158	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-131	Room S158	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-131	Room S158	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-132	Room S159	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-132	Room S159	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-132	Room S159	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-132	Room S159	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-132	Room S159	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-133	Room S160	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-133	Room S160	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-133	Room S160	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-133	Room S160	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-133	Room S160	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-134	Room S161	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-134	Room S161	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-134	Room S161	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-134	Room S161	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-134	Room S161	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-135	Room S162	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-135	Room S162	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-135	Room S162	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-135	Room S162	Ceiling	Drywall (DJC)	Asbestos	21-7672-34*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
1-135	Room S162	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-136	Room S163	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-136	Room S163	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-136	Room S163	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-136	Room S163	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-136	Room S163	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-137	Room S164	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-137	Room S164	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-137	Room S164	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-137	Room S164	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-137	Room S164	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-138	Room S165	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-138	Room S165	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-138	Room S165	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-138	Room S165	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-138	Room S165	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-139	Room S166	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-139	Room S166	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-139	Room S166	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-139	Room S166	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-139	Room S166	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-140	Room S167	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
1-140	Room S167	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-140	Room S167	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-140	Room S167	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-140	Room S167	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-1 to 7	None Detected	N/A	N/A	
1-141	Stair No 7	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-141	Stair No 7	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-141	Stair No 7	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-142	Recreation Room	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Beige with Pink and Blue Flecks
1-142	Recreation Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-142	Recreation Room	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
1-143	Kitchenette	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Beige with Pink and Blue Flecks
1-143	Kitchenette	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-143	Kitchenette	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
1-144	Lift Room	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Beige with Pink and Blue Flecks
1-144	Lift Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-144	Lift Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	
1-145	Clean Utility	Floor	Vinyl Sheet Flooring 2	Asbestos	22-7864-10 to 12*	None Detected	N/A	N/A	Beige with Black Specks *From Fisher Project No.22-11904, dated Jan. 2022
1-145	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-145	Clean Utility	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
1-146	Shower/Tub Room	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
1-146	Shower/Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-146	Shower/Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-28 to 34	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-147	Lounge	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige with Pink and Blue Flecks
1-147	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-147	Lounge	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 21-7672-59 to 61	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
1-148	Corridor	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	Beige with Pink and Blue Flecks
1-148	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-148	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
1-148	Corridor	Ceiling	Texture Coat	Asbestos	21-7672-2*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
1-149	Stair No 3	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-149	Stair No 3	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-149	Stair No 3	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-150	Stair No 4	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-150	Stair No 4	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
1-150	Stair No 4	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-151	Medical Supply	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
1-151	Medical Supply	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-151	Medical Supply	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 21-7672-59 to 61	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
1-152	Office	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
1-152	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-04 to 10	None Detected	N/A	N/A	
1-152	Office	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 21-7672-59 to 61	None Detected	N/A	N/A	2' x 2' Pinholes with Random Fissures
2-001	Elevator Lobby	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
2-001	Elevator Lobby	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-001	Elevator Lobby	Floor	Vinyl Floor Tile 8	Asbestos	19-3372-09 to 11*	None Detected	N/A	N/A	12" x 12" Grey *From Fisher Project No. 19-9820, dated Oct. 2019
2-001	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-001	Elevator Lobby	Ceiling	Drywall (DJC)	Asbestos	21-7672-35*	None Detected	N/A	N/A	Bulkhead *From Fisher Project No.21-11790, dated Dec. 2021
2-001	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-002	Laundry Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-002	Laundry Room	Walls	Drywall (DJC)	Asbestos	19-3372-01*	None Detected	N/A	N/A	*From Fisher Project No. 19-9820, dated Oct. 2019
2-002	Laundry Room	Ceiling	Ceiling Tile 4	Asbestos	19-3372-06 to 08*	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes *From Fisher Project No. 19-9820, dated Oct. 2019
2-003	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-003	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
2-003	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2-004	Touchdown Space	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-004	Touchdown Space	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks NOT OBSERVED
2-004	Touchdown Space	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-004	Touchdown Space	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
2-005	Exercise Therapy	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
2-005	Exercise Therapy	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-005	Exercise Therapy	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
2-006	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
2-006	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-006	Storage	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
2-007	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-007	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-007	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-008	Conference Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-008	Conference Room	Floor	Vinyl Sheet Flooring 1	Asbestos	Not Sampled	ACM Assumed	N/A	N/A	Beige Flecks NOT OBSERVED
2-008	Conference Room	Walls	Paint	Lead	19-3372-12*	<10 ppm	N/A	N/A	Blue *From Fisher Project No. 19-9820, dated Oct. 2019
2-008	Conference Room	Walls	Drywall (DJC)	Asbestos	19-3372-02*	None Detected	N/A	N/A	*From Fisher Project No. 19-9820, dated Oct. 2019
2-008	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-009	Dining Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-009	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-009	Dining Room	Ceiling	Drywall (DJC)	Asbestos	21-7672-38*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-009	Dining Room	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
2-010	Dishwashing	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-010	Dishwashing	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
2-010	Dishwashing	Walls	Drywall (DJC)	Asbestos	19-3372-04*	None Detected	N/A	N/A	*From Fisher Project No. 19-9820, dated Oct. 2019
2-010	Dishwashing	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
2-011	Servery	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	320 SF	Good	Grey with Dark Dots
2-011	Servery	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	N/A	N/A	Turquoise with Light and Dark Turquoise Flecks NOT OBSERVED
2-011	Servery	Walls	Drywall (DJC)	Asbestos	19-3372-05*	None Detected	N/A	N/A	*From Fisher Project No. 19-9820, dated Oct. 2019
2-011	Servery	Walls	Paint	Lead	19-3372-13*	<10 ppm	N/A	N/A	Cream *From Fisher Project No. 19-9820, dated Oct. 2019
2-011	Servery	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
2-012	Cart Storage	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-012	Cart Storage	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	N/A	N/A	Turquoise with Light and Dark Turquoise Flecks NOT OBSERVED
2-012	Cart Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-012	Cart Storage	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
2-013	Storage	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-013	Storage	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	N/A	N/A	Turquoise with Light and Dark Turquoise Flecks NOT OBSERVED
2-013	Storage	Walls	Drywall (DJC)	Asbestos	19-3372-03*	None Detected	N/A	N/A	*From Fisher Project No. 19-9820, dated Oct. 2019
2-013	Storage	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
2-014	Dining Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-014	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-014	Dining Room	Ceiling	Drywall (DJC)	Asbestos	21-7672-37*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
2-014	Dining Room	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
2-015	Elevator Lobby	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-015	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-015	Elevator Lobby	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
2-016	Room N203	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-016	Room N203	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-016	Room N203	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-016	Room N203	Ceiling	Drywall (DJC)	Asbestos	21-7672-36*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
2-016	Room N203	Ceiling	Texture Coat	Asbestos	21-7672-8*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
2-017	Room N204	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-017	Room N204	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-017	Room N204	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-017	Room N204	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-017	Room N204	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-018	Room N205	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-018	Room N205	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-018	Room N205	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-018	Room N205	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-018	Room N205	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-019	Room N206	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-019	Room N206	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-019	Room N206	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-019	Room N206	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-019	Room N206	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-020	Room N207	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-020	Room N207	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-020	Room N207	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-020	Room N207	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-020	Room N207	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-021	Room N208	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-021	Room N208	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-021	Room N208	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-021	Room N208	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-021	Room N208	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-022	Room N209	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-022	Room N209	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-022	Room N209	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-022	Room N209	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-022	Room N209	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-023	Room N210	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-023	Room N210	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-023	Room N210	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-023	Room N210	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-023	Room N210	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-024	Room N212	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-024	Room N212	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-024	Room N212	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-024	Room N212	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-024	Room N212	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-025	Room N214	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-025	Room N214	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-025	Room N214	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-025	Room N214	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-025	Room N214	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-026	Room N216	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-026	Room N216	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-026	Room N216	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-026	Room N216	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-026	Room N216	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-027	Room N218	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-027	Room N218	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-027	Room N218	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-027	Room N218	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-027	Room N218	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-028	Room N219	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-028	Room N219	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-028	Room N219	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-028	Room N219	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-028	Room N219	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-029	Room N217	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-029	Room N217	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-029	Room N217	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-029	Room N217	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-029	Room N217	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-030	Room N215	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-030	Room N215	Floor	Vinyl Sheet Flooring 7	Asbestos	Homogeneous w/ 22-7864-13 to 15	None Detected	N/A	N/A	Beige Swirls
2-030	Room N215	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-030	Room N215	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-030	Room N215	Ceiling	Texture Coat	Asbestos	21-7672-9*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
2-031	Room N213	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-031	Room N213	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-031	Room N213	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-031	Room N213	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-031	Room N213	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-032	Room N211	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-032	Room N211	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-032	Room N211	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-032	Room N211	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-032	Room N211	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-033	Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-033	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-033	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-034	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-034	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-034	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-034	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-035	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-035	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
2-035	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-035	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-036	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
2-036	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-036	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
2-036	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-036	Corridor	Ceiling	Drywall (DJC)	Asbestos	21-7672-40,41*	None Detected	N/A	N/A	Bulkhead *From Fisher Project No.21-11790, dated Dec. 2021
2-036	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-037	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-037	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
2-037	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2-038	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-038	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-038	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-039	Staff Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-039	Staff Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-039	Staff Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-040	Nurses Station	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-040	Nurses Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-040	Nurses Station	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
2-041	Medical Supply	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-041	Medical Supply	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-041	Medical Supply	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 21-7672-22 to 24	None Detected	N/A	N/A	2' x 2' Texture with Pinholes
2-042	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
2-042	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-042	Corridor	Walls	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
2-042	Corridor	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-042	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-043	Family Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-043	Family Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-043	Family Lounge	Ceiling	Ceiling Tile 7	Asbestos	21-7672-65 to 67*	None Detected	N/A	N/A	2' x 2' Tiny Pinholes *From Fisher Project No.21-11790, dated Dec. 2021
2-044	Room N241	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-044	Room N241	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-044	Room N241	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-044	Room N241	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-044	Room N241	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-045	Room N242	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-045	Room N242	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-045	Room N242	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-045	Room N242	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-045	Room N242	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-046	Room N243	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-046	Room N243	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-046	Room N243	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-046	Room N243	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-046	Room N243	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-047	Room N244	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-047	Room N244	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-047	Room N244	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-047	Room N244	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-047	Room N244	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-048	Room N245	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-048	Room N245	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-048	Room N245	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-048	Room N245	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-048	Room N245	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-049	Room N246	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-049	Room N246	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-049	Room N246	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-049	Room N246	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-049	Room N246	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-050	Room N247	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-050	Room N247	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-050	Room N247	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-050	Room N247	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-050	Room N247	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-051	Room N248	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-051	Room N248	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-051	Room N248	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-051	Room N248	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-051	Room N248	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-052	Room N249	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-052	Room N249	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-052	Room N249	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-052	Room N249	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-052	Room N249	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-053	Room N250	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-053	Room N250	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-053	Room N250	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-053	Room N250	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-053	Room N250	Ceiling	Texture Coat	Asbestos	21-7672-12*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
2-054	Room N251	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-054	Room N251	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-054	Room N251	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-054	Room N251	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-054	Room N251	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-055	Room N252	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-055	Room N252	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-055	Room N252	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-055	Room N252	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-055	Room N252	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-056	Activity Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-056	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-056	Activity Room	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
2-057	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-057	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
2-057	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-057	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-058	Nurses Supply Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-058	Nurses Supply Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-058	Nurses Supply Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-058a	Changeroom	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-058a	Changeroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-058a	Changeroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-059	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-059	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-059	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-059	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-060	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-060	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-060	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-061	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-061	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-061	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-062	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-062	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-062	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-063	Reading Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-063	Reading Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-063	Reading Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-064	Room N260	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-064	Room N260	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-064	Room N260	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-064	Room N260	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-064	Room N260	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-065	Room N261	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-065	Room N261	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-065	Room N261	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-065	Room N261	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-065	Room N261	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-066	Room N262	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-066	Room N262	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-066	Room N262	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-066	Room N262	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-066	Room N262	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-067	Room N263	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-067	Room N263	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-067	Room N263	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-067	Room N263	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-067	Room N263	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-068	Room N264	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-068	Room N264	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-068	Room N264	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-068	Room N264	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-068	Room N264	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-069	Room N265	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-069	Room N265	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-069	Room N265	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-069	Room N265	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-069	Room N265	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-070	Room N266	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-070	Room N266	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-070	Room N266	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-070	Room N266	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-070	Room N266	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-071	Room N267	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-071	Room N267	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-071	Room N267	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-071	Room N267	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-071	Room N267	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-072	Room N268	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-072	Room N268	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-072	Room N268	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-072	Room N268	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-072	Room N268	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-073	Room N269	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-073	Room N269	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-073	Room N269	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-073	Room N269	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-073	Room N269	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-074	Room N270	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-074	Room N270	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-074	Room N270	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-074	Room N270	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-074	Room N270	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-075	Room N271	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-075	Room N271	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-075	Room N271	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-075	Room N271	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-075	Room N271	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-076	Room N272	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-076	Room N272	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-076	Room N272	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-076	Room N272	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-076	Room N272	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-077	Room N273	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-077	Room N273	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-077	Room N273	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-077	Room N273	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-077	Room N273	Ceiling	Texture Coat	Asbestos	21-7672-14*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
2-078	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-078	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
2-078	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-078	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-079	Clean Linen	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-079	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-079	Clean Linen	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
2-080	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-080	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
2-080	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2-081	Shower/Tub Room	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	320 SF	Good	Grey with Dark Dots
2-081	Shower/Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-081	Shower/Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-081	Shower/Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-082	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-082	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-082	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-082a	Sprinkler Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-082a	Sprinkler Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
2-082a	Sprinkler Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2-083	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-083	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-083	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-084	Soiled Utility	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-084	Soiled Utility	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
2-084	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-084	Soiled Utility	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
2-085	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-085	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-085	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-086	Washroom	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Grey with Dark Dots
2-086	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-086	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-087	Housekeeping	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-087	Housekeeping	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
2-087	Housekeeping	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-087	Housekeeping	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 21-7672-22 to 24	None Detected	N/A	N/A	2' x 2' Texture with Pinholes
2-088	Office	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-088	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-088	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-089	Dining Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-089	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-089	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-089	Dining Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-090	Room S204	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-090	Room S204	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-090	Room S204	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-090	Room S204	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-090	Room S204	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-091	Room S205	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-091	Room S205	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-091	Room S205	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-091	Room S205	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-091	Room S205	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-092	Room S206	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-092	Room S206	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-092	Room S206	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-092	Room S206	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-092	Room S206	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-093	Room S207	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-093	Room S207	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-093	Room S207	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-093	Room S207	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-093	Room S207	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-094	Room S208	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-094	Room S208	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-094	Room S208	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-094	Room S208	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-094	Room S208	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-095	Laundry Chute	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-095	Laundry Chute	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-095	Laundry Chute	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-096	Room S209	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-096	Room S209	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-096	Room S209	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-096	Room S209	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-096	Room S209	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-097	Room S210	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-097	Room S210	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-097	Room S210	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-097	Room S210	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-097	Room S210	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-098	Room S212	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-098	Room S212	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-098	Room S212	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-098	Room S212	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-098	Room S212	Ceiling	Texture Coat	Asbestos	21-7672-10*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
2-099	Room S214	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-099	Room S214	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-099	Room S214	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-099	Room S214	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-099	Room S214	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-100	Room S216	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-100	Room S216	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-100	Room S216	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-100	Room S216	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-100	Room S216	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-101	Room S218	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-101	Room S218	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-101	Room S218	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-101	Room S218	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-101	Room S218	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-102	Room S219	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-102	Room S219	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-102	Room S219	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-102	Room S219	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-102	Room S219	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-103	Room S217	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-103	Room S217	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-103	Room S217	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-103	Room S217	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-103	Room S217	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-104	Room S215	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-104	Room S215	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-104	Room S215	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-104	Room S215	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-104	Room S215	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-105	Room S213	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-105	Room S213	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-105	Room S213	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-105	Room S213	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-105	Room S213	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-106	Room S211	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-106	Room S211	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-106	Room S211	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-106	Room S211	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-106	Room S211	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-107	Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-107	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-107	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-108	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-108	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-108	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-108	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-109	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-109	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-109	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-110	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
2-110	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-110	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
2-110	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-110	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-111	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-111	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
2-111	Electrical Closet	Ceiling	Paint	Lead	18-9976-01*	<10 ppm	N/A	N/A	White *From Fisher Project No. 18-8787, dated Sept. 2018
2-111	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2-112	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-112	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-112	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-113	Staff Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	NO ACCESS Beige with Black Specks
2-113	Staff Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-113	Staff Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-114	Nurses Station	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-114	Nurses Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-114	Nurses Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-115	Medical Supply	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-115	Medical Supply	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-115	Medical Supply	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 21-7672-22 to 24	None Detected	N/A	N/A	2' x 2' Texture with Pinholes
2-116	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
2-116	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-116	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
2-116	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-116	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-117	Family Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-117	Family Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-117	Family Lounge	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
2-118	Room S240	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-118	Room S240	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-118	Room S240	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-118	Room S240	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-118	Room S240	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-119	Room S241	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-119	Room S241	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-119	Room S241	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-119	Room S241	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-119	Room S241	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-120	Room S242	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-120	Room S242	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-120	Room S242	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-120	Room S242	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-120	Room S242	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-121	Room S243	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-121	Room S243	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-121	Room S243	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-121	Room S243	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-121	Room S243	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-122	Room S244	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-122	Room S244	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-122	Room S244	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-122	Room S244	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-122	Room S244	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-123	Room S245	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-123	Room S245	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-123	Room S245	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-123	Room S245	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-123	Room S245	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-124	Room S246	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-124	Room S246	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-124	Room S246	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-124	Room S246	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-124	Room S246	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-125	Room S247	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-125	Room S247	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-125	Room S247	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-125	Room S247	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-125	Room S247	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-126	Room S248	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-126	Room S248	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-126	Room S248	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-126	Room S248	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-126	Room S248	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-127	Room S249	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-127	Room S249	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-127	Room S249	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-127	Room S249	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-127	Room S249	Ceiling	Texture Coat	Asbestos	21-7672-13*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
2-128	Room S250	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-128	Room S250	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-128	Room S250	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-128	Room S250	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-128	Room S250	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-129	Room S251	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-129	Room S251	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-129	Room S251	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-129	Room S251	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-129	Room S251	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-130	Activity Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-130	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-130	Activity Room	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
2-131	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-131	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
2-131	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-131	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-132	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-132	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-132	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-133	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-133	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-133	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-133	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-134	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-134	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-134	Janitor's Closet	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-135	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-135	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-135	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-136	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	NO ACCESS 12" x 12" Pink with Light and Dark Pink Flecks
2-136	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-136	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-137	Reading Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-137	Reading Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-137	Reading Room	Ceiling	Ceiling Tile 10	Asbestos	Homogeneous w/ 21-7672-56 to 58	None Detected	N/A	N/A	2' x 4' Tiny Pinholes
2-138	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-138	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-138	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-139	Room S259	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-139	Room S259	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-139	Room S259	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-139	Room S259	Ceiling	Drywall (DJC)	Asbestos	21-7672-39*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
2-139	Room S259	Ceiling	Texture Coat	Asbestos	21-7672-11*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
2-140	Room S260	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-140	Room S260	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-140	Room S260	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-140	Room S260	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-140	Room S260	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-141	Room S261	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-141	Room S261	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-141	Room S261	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-141	Room S261	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-141	Room S261	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-142	Room S262	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-142	Room S262	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-142	Room S262	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-142	Room S262	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-142	Room S262	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-143	Room S263	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-143	Room S263	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-143	Room S263	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-143	Room S263	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-143	Room S263	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-144	Room S264	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-144	Room S264	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-144	Room S264	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-144	Room S264	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-144	Room S264	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-145	Room S265	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-145	Room S265	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-145	Room S265	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-145	Room S265	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-145	Room S265	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-146	Room S266	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-146	Room S266	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-146	Room S266	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-146	Room S266	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-146	Room S266	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-147	Room S267	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-147	Room S267	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-147	Room S267	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-147	Room S267	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-147	Room S267	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-148	Room S268	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-148	Room S268	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-148	Room S268	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-148	Room S268	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-148	Room S268	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-149	Room S269	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-149	Room S269	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-149	Room S269	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-149	Room S269	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-149	Room S269	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-150	Room S270	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-150	Room S270	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-150	Room S270	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-150	Room S270	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-150	Room S270	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-151	Room S271	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-151	Room S271	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-151	Room S271	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-151	Room S271	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-151	Room S271	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-8 to 14	None Detected	N/A	N/A	
2-152	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-152	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
2-152	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-152	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-153	Clean Linen	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-153	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-153	Clean Linen	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
2-154	Clean Utility	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-154	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-154	Clean Utility	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
2-155	Shower/Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-155	Shower/Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-155	Shower/Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-155	Shower/Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-35 to 41	None Detected	N/A	N/A	
2-156	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-156	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-156	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-157	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-157	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
2-157	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2-158	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	NO ACCESS Beige with Black Specks
2-158	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-158	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-159	Soiled Linen	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-159	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-159	Soiled Linen	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
2-160	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
2-160	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-160	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-161	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-161	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-161	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
2-162	Housekeeping	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
2-162	Housekeeping	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-162	Housekeeping	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
2-163	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-163	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 19-3372-1 to 5	None Detected	N/A	N/A	
2-163	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-001	Elevator Lobby	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
3-001	Elevator Lobby	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-001	Elevator Lobby	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
3-001	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	1500 SF	N/A	
3-001	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-002	Laundry Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-002	Laundry Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-002	Laundry Room	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
3-003	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
3-003	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-003	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
3-004	Dentist Office	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-004	Dentist Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-004	Dentist Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-005	Exercise Therapy	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-005	Exercise Therapy	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-005	Exercise Therapy	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-006	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-006	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	75 SF	N/A	
3-006	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-007	Washroom	Floor	Vinyl Floor Tile 10	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	12" x 12" Light Pink with Dark Pink Specks
3-007	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-007	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-008	Conference Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-008	Conference Room	Floor	Vinyl Sheet Flooring 1	Asbestos	Not Sampled	ACM Assumed	N/A	N/A	Beige Flecks NOT OBSERVED
3-008	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	200 SF	N/A	
3-008	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-009	Dining Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-009	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	1750 SF	N/A	
3-009	Dining Room	Ceiling	Drywall (DJC)	Asbestos	21-7672-42*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
3-009	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-010	Dishwashing	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-010	Dishwashing	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
3-010	Dishwashing	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	200 SF	N/A	
3-010	Dishwashing	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
3-011	Servery	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-011	Servery	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	N/A	N/A	Turquoise with Light and Dark Turquoise Flecks NOT OBSERVED
3-011	Servery	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	200 SF	N/A	
3-011	Servery	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
3-011	Servery	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
3-012	Cart Storage	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Turquoise with Light and Dark Turquoise Flecks
3-012	Cart Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	100 SF	N/A	
3-012	Cart Storage	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
3-013	Storage	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Turquoise with Light and Dark Turquoise Flecks
3-013	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	100 SF	N/A	
3-013	Storage	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
3-014	Dining Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-014	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	1000 SF	N/A	
3-014	Dining Room	Ceiling	Drywall (DJC)	Asbestos	21-7672-43*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
3-014	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-015	Elevator Lobby	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-015	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-015	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-016	Room N303	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-016	Room N303	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-016	Room N303	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-016	Room N303	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-016	Room N303	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-017	Room N304	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-017	Room N304	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-017	Room N304	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-017	Room N304	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-017	Room N304	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-018	Room N305	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-018	Room N305	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-018	Room N305	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-018	Room N305	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-018	Room N305	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-019	Room N306	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-019	Room N306	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-019	Room N306	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-019	Room N306	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-019	Room N306	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-020	Room N307	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-020	Room N307	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-020	Room N307	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-020	Room N307	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-020	Room N307	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-021	Room N308	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-021	Room N308	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-021	Room N308	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-021	Room N308	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-021	Room N308	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-022	Room N309	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-022	Room N310	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-022	Room N311	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-022	Room N312	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-022	Room N313	Ceiling	Texture Coat	Asbestos	21-7672-20*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-023	Room N310	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-023	Room N310	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-023	Room N310	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-023	Room N310	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-023	Room N310	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-024	Room N312	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-024	Room N312	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-024	Room N312	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-024	Room N312	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-024	Room N312	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-025	Room N314	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-025	Room N314	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-025	Room N314	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-025	Room N314	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-025	Room N314	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-026	Room N316	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-026	Room N316	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-026	Room N316	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-026	Room N316	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-026	Room N316	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-027	Room N318	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-027	Room N318	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-027	Room N318	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-027	Room N318	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-027	Room N318	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-028	Room N319	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-028	Room N319	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-028	Room N319	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-028	Room N319	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-028	Room N319	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-029	Room N317	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-029	Room N317	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-029	Room N317	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-029	Room N317	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-029	Room N317	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-030	Room N315	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-030	Room N315	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-030	Room N315	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-030	Room N315	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-030	Room N315	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-031	Room N313	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-031	Room N313	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-031	Room N313	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-031	Room N313	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-031	Room N313	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-032	Room N311	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-032	Room N311	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-032	Room N311	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-032	Room N311	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-032	Room N311	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-033	Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-033	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-033	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-034	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-034	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-034	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-034	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-035	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
3-035	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	75 SF	N/A	
3-035	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-036	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
3-036	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-036	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
3-036	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	1500 SF	N/A	
3-036	Corridor	Ceiling	Drywall (DJC)	Asbestos	21-7672-46*	None Detected	N/A	N/A	Bulkhead *From Fisher Project No.21-11790, dated Dec. 2021
3-036	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-037	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
3-037	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
3-037	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
3-038	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-038	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-038	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-039	Staff Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	NO ACCESS Beige with Black Specks
3-039	Staff Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-039	Staff Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-040	Nurses Station	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-040	Nurses Station	Walls	Drywall (DJC)	Asbestos	18-8954-17*	None Detected	N/A	N/A	*From Fisher Project No. 18-8828, dated May 2018
3-040	Nurses Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-041	Medical Supply	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-041	Medical Supply	Walls	Drywall (DJC)	Asbestos	18-8954-16*	None Detected	N/A	N/A	*From Fisher Project No. 18-8828, dated May 2018
3-041	Medical Supply	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-042	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
3-042	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-042	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
3-042	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	1500 SF	N/A	
3-042	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-043	Family Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-043	Family Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	200 SF	N/A	
3-043	Family Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-044	Room N341	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-044	Room N341	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-044	Room N341	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-044	Room N341	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-044	Room N341	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-045	Room N342	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-045	Room N342	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-045	Room N342	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-045	Room N342	Ceiling	Drywall (DJC)	Asbestos	21-7672-45*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
3-045	Room N342	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-046	Room N343	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-046	Room N343	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-046	Room N343	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-046	Room N343	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-046	Room N343	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-047	Room N344	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-047	Room N344	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-047	Room N344	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-047	Room N344	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-047	Room N344	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-048	Room N345	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-048	Room N345	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-048	Room N345	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-048	Room N345	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-048	Room N345	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-049	Room N346	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-049	Room N346	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-049	Room N346	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-049	Room N346	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-049	Room N346	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-050	Room N347	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-050	Room N347	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-050	Room N347	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-050	Room N347	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-050	Room N347	Ceiling	Texture Coat	Asbestos	21-7672-21*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
3-051	Room N348	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-051	Room N348	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-051	Room N348	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-051	Room N348	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-051	Room N348	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-052	Room N349	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-052	Room N349	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-052	Room N349	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-052	Room N349	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-052	Room N349	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-053	Room N350	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-053	Room N350	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-053	Room N350	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-053	Room N350	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-053	Room N350	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-054	Room N351	Floor	Vinyl Floor Tile 9	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	12" x 12" Pink with Dark Pink and Brown Flecks
3-054	Room N351	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-054	Room N351	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-054	Room N351	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-054	Room N351	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-055	Room N352	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-055	Room N352	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-055	Room N352	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-055	Room N352	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-055	Room N352	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-056	Activity Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-056	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	400 SF	N/A	
3-056	Activity Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-057	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-057	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
3-057	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	1500 SF	N/A	
3-057	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-058	Storage	Floor	Vinyl Floor Tile 9	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	12" x 12" Pink with Dark Pink and Brown Flecks
3-058	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-058	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-058	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-059	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-059	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-059	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	300 SF	N/A	
3-059	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-059a	Nurses Supply Room	Floor	Vinyl Sheet Flooring 1	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Beige Flecks
3-059a	Nurses Supply Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-059a	Nurses Supply Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-060	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
3-060	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	40 SF	N/A	
3-060	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-061	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	25 SF	Good	Green with Black Specks
3-061	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	100 SF	N/A	
3-061	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-062	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-062	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-062	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-063	Reading Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-063	Reading Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-063	Reading Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-064	Room N360	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-064	Room N360	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-064	Room N360	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-064	Room N360	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-064	Room N360	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-065	Room N361	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-065	Room N361	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-065	Room N361	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-065	Room N361	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-065	Room N361	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-066	Room N362	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-066	Room N362	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-066	Room N362	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-066	Room N362	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-066	Room N362	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-067	Room N363	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-067	Room N363	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-067	Room N363	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-067	Room N363	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-067	Room N363	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-068	Room N364	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-068	Room N364	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-068	Room N364	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-068	Room N364	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-068	Room N364	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-069	Room N365	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-069	Room N365	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-069	Room N365	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-069	Room N365	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-069	Room N365	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-070	Room N366	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-070	Room N366	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-070	Room N366	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-070	Room N366	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-070	Room N366	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-071	Room N367	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-071	Room N367	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-071	Room N367	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-071	Room N367	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-071	Room N367	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-072	Room N368	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-072	Room N368	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-072	Room N368	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-072	Room N368	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-072	Room N368	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-073	Room N369	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-073	Room N369	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-073	Room N369	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-073	Room N369	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-073	Room N369	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-074	Room N370	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-074	Room N370	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-074	Room N370	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-074	Room N370	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-074	Room N370	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-075	Room N371	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-075	Room N371	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-075	Room N371	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-075	Room N371	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-075	Room N371	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-076	Room N372	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-076	Room N372	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-076	Room N372	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-076	Room N372	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-076	Room N372	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-077	Room N373	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-077	Room N373	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-077	Room N373	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-077	Room N373	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-077	Room N373	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-078	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-078	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
3-078	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	1500 SF	N/A	
3-078	Corridor	Ceiling	Drywall (DJC)	Asbestos	21-7672-44*	None Detected	N/A	N/A	Bulkhead *From Fisher Project No.21-11790, dated Dec. 2021
3-078	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-079	Clean Linen	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Green with Black Specks
3-079	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-079	Clean Linen	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
3-080	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
3-080	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
3-080	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-081	Shower/Tub Room	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	320 SF	Good	Grey with Dark Dots
3-081	Shower/Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	300 SF	N/A	
3-081	Shower/Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-081	Shower/Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-082	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
3-082	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	40 SF	N/A	
3-082	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-083	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
3-083	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-083	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-084	Soiled Utility	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
3-084	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-084	Soiled Utility	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
3-085	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-085	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-085	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-086	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	65 SF	Good	Green with Black Specks
3-086	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	100 SF	N/A	
3-086	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-087	Housekeeping	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
3-087	Housekeeping	Walls	Drywall (DJC)	Asbestos	18-8954-15*	None Detected	N/A	N/A	*From Fisher Project No. 18-8828, dated May, 2018
3-087	Housekeeping	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
3-088	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-088	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	100 SF	N/A	
3-088	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-089	Dining Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-089	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	750 SF	N/A	
3-089	Dining Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-089	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-090	Room S304	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-090	Room S304	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-090	Room S304	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-090	Room S304	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-090	Room S304	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-091	Room S305	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-091	Room S305	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-091	Room S305	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-091	Room S305	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-091	Room S305	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-092	Room S306	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-092	Room S306	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-092	Room S306	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-092	Room S306	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-092	Room S306	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-093	Room S307	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-093	Room S307	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-093	Room S307	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-093	Room S307	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-093	Room S307	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-094	Room S308	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-094	Room S308	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-094	Room S308	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-094	Room S308	Ceiling	Drywall (DJC)	Asbestos	21-7672-47*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
3-094	Room S308	Ceiling	Texture Coat	Asbestos	21-7672-19*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
3-095	Laundry Chute	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-095	Laundry Chute	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	75 SF	N/A	
3-095	Laundry Chute	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-096	Room S309	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-096	Room S309	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-096	Room S309	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-096	Room S309	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-096	Room S309	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-097	Room S310	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-097	Room S310	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-097	Room S310	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-097	Room S310	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-097	Room S310	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-098	Room S312	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-098	Room S312	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-098	Room S312	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-098	Room S312	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-098	Room S312	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-099	Room S314	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-099	Room S314	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-099	Room S314	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-099	Room S314	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-099	Room S314	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-100	Room S316	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-100	Room S316	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-100	Room S316	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-100	Room S316	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-100	Room S316	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-101	Room S318	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-101	Room S318	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-101	Room S318	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-101	Room S318	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-101	Room S318	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-102	Room S319	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-102	Room S319	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-102	Room S319	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-102	Room S319	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-102	Room S319	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-103	Room S317	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-103	Room S317	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-103	Room S317	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-103	Room S317	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-103	Room S317	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-104	Room S315	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-104	Room S315	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-104	Room S315	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-104	Room S315	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-104	Room S315	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-105	Room S313	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-105	Room S313	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-105	Room S313	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-105	Room S313	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-105	Room S313	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-106	Room S311	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-106	Room S311	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-106	Room S311	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-106	Room S311	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-106	Room S311	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-107	Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-107	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	300 SF	N/A	
3-107	Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-107	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-108	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-108	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-108	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	400 SF	N/A	
3-108	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-109	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
3-109	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	75 SF	N/A	
3-109	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-110	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
3-110	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-110	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
3-110	Corridor	Walls	Drywall (DJC)	Asbestos	18-8954-14*	None Detected	N/A	N/A	*From Fisher Project No. 18-8828, dated May 2018
3-110	Corridor	Ceiling	Drywall (DJC)	Asbestos	21-7672-48*	None Detected	N/A	N/A	Bulkhead *From Fisher Project No.21-11790, dated Dec. 2021
3-110	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-111	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-111	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
3-111	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
3-112	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-112	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-112	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-113	Staff Washroom	Floor	Vinyl Sheet Flooring 10	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Green with Black Dots
3-113	Staff Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	N/A	N/A	
3-113	Staff Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-114	Nurses Station	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-114	Nurses Station	Walls	Drywall (DJC)	Asbestos	18-8954-11*	None Detected	N/A	N/A	*From Fisher Project No. 18-8828, dated May 2018
3-114	Nurses Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-115	Medical Supply	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-115	Medical Supply	Walls	Drywall (DJC)	Asbestos	18-8954-12*	None Detected	N/A	N/A	*From Fisher Project No. 18-8828, dated May 2018
3-115	Medical Supply	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-116	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
3-116	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-116	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
3-116	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	1500 SF	N/A	
3-116	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-117	Family Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-117	Family Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-117	Family Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-118	Room S340	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-118	Room S340	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-118	Room S340	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-118	Room S340	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-118	Room S340	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-119	Room S341	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-119	Room S341	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-119	Room S341	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-119	Room S341	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-119	Room S341	Ceiling	Texture Coat	Asbestos	21-7672-15*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
3-120	Room S342	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-120	Room S342	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-120	Room S342	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-120	Room S342	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-120	Room S342	Ceiling	Texture Coat	Asbestos	21-7672-16*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
3-121	Room S343	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-121	Room S343	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-121	Room S343	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-121	Room S343	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-121	Room S343	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-122	Room S344	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-122	Room S344	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-122	Room S344	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-122	Room S344	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-122	Room S344	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-123	Room S345	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-123	Room S345	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-123	Room S345	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-123	Room S345	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-123	Room S345	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-124	Room S346	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-124	Room S346	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-124	Room S346	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-124	Room S346	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-124	Room S346	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-125	Room S347	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-125	Room S347	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-125	Room S347	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-125	Room S347	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-125	Room S347	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-126	Room S348	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-126	Room S348	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-126	Room S348	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-126	Room S348	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-126	Room S348	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-127	Room S349	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-127	Room S349	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-127	Room S349	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-127	Room S349	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-127	Room S349	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-128	Room S350	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-128	Room S350	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-128	Room S350	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-128	Room S350	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-128	Room S350	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-129	Room S351	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-129	Room S351	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-129	Room S351	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-129	Room S351	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-129	Room S351	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-130	Activity Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-130	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	400 SF	N/A	
3-130	Activity Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-131	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-131	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
3-131	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	1500 SF	N/A	
3-131	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-132	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-132	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-132	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-133	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-133	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-133	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	400 SF	N/A	
3-133	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-134	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
3-134	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	40 SF	N/A	
3-134	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-135	Washroom	Floor	Vinyl Sheet Flooring 10	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	Green with Black Dots
3-135	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-135	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-136	Medication Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	NO ACCESS 12" x 12" Pink with Light and Dark Pink Flecks
3-136	Medication Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-136	Medication Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-137	Reading Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-137	Reading Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-137	Reading Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-138	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-138	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
3-138	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	40 SF	N/A	
3-138	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-139	Room S359	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-139	Room S359	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-139	Room S359	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-139	Room S359	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-139	Room S359	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-140	Room S360	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-140	Room S360	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-140	Room S360	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-140	Room S360	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-140	Room S360	Ceiling	Texture Coat	Asbestos	21-7672-17*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
3-141	Room S361	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-141	Room S361	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-141	Room S361	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-141	Room S361	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-141	Room S361	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-142	Room S362	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-142	Room S362	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-142	Room S362	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-142	Room S362	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-142	Room S362	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-143	Room S363	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-143	Room S363	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-143	Room S363	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-143	Room S363	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-143	Room S363	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-144	Room S364	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-144	Room S364	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-144	Room S364	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-144	Room S364	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-144	Room S364	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-145	Room S365	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-145	Room S365	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-145	Room S365	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-145	Room S365	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-145	Room S365	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-146	Room S366	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-146	Room S366	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-146	Room S366	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-146	Room S366	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-146	Room S366	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-147	Room S367	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-147	Room S367	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-147	Room S367	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-147	Room S367	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-147	Room S367	Ceiling	Texture Coat	Asbestos	21-7672-18*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
3-148	Room S368	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-148	Room S368	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-148	Room S368	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-148	Room S368	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-148	Room S368	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-149	Room S369	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-149	Room S369	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-149	Room S369	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-149	Room S369	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-149	Room S369	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-150	Room S370	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-150	Room S370	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-150	Room S370	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-150	Room S370	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-150	Room S370	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-151	Room S371	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-151	Room S371	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Green with Black Specks
3-151	Room S371	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-151	Room S371	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-151	Room S371	Ceiling	Texture Coat	Asbestos	Homogeneous w/ 21-7672-15 to 21	None Detected	N/A	N/A	
3-152	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-152	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
3-152	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	1500 SF	N/A	
3-152	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-153	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-153	Storage	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
3-153	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-153	Storage	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
3-154	Clean Utility	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
3-154	Clean Utility	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
3-154	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-154	Clean Utility	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
3-155	Shower/Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-155	Shower/Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	400 SF	N/A	
3-155	Shower/Tub Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-155	Shower/Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-42 to 48	None Detected	N/A	N/A	
3-156	Nurses Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-156	Nurses Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-156	Nurses Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-157	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
3-157	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
3-157	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
3-158	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
3-158	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	250 SF	N/A	
3-158	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-159	Soiled Linen	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
3-159	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-159	Soiled Linen	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
3-160	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-160	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	450 SF	N/A	
3-160	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
3-161	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Not Sampled	ACM Assumed	65 SF	Good	Green with Black Specks
3-161	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	150 SF	N/A	
3-161	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
3-162	Housekeeping	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
3-162	Housekeeping	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
3-162	Housekeeping	Walls	Drywall (DJC)	Asbestos	18-8954-13*	None Detected	N/A	N/A	*From Fisher Project No. 18-8828, dated May 2018
3-162	Housekeeping	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
3-163	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-163	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 18-8954-11 to 17	None Detected	100 SF	N/A	
3-163	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-001	Elevator Lobby	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	1600 SF	Good	Grey
4-001	Elevator Lobby	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks NOT OBSERVED
4-001	Elevator Lobby	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-001	Elevator Lobby	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
4-001	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	
4-001	Elevator Lobby	Ceiling	Drywall (DJC)	Asbestos	21-7672-49,50*	None Detected	N/A	N/A	Bulkhead *From Fisher Project No.21-11790, dated Dec. 2021
4-001	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	21-7672-62 to 64*	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture *From Fisher Project No.21-11790, dated Dec. 2021
4-002	Laundry Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-002	Laundry Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	125 SF	Good	
4-002	Laundry Room	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
4-003	Electrical Closet	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-003	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
4-003	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
4-004	Office	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-004	Office	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-004	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-005	Exercise Therapy	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	Grey
4-005	Exercise Therapy	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks NOT OBSERVED
4-005	Exercise Therapy	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-005	Exercise Therapy	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-005	Exercise Therapy	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-006	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
4-006	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-006	Storage	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	
4-006	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-007	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-007	Washroom	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-007	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-008	Conference Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
4-008	Conference Room	Floor	Vinyl Sheet Flooring 1	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Beige Flecks
4-008	Conference Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	
4-008	Conference Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-009	Dining Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-009	Dining Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	1750 SF	Good	
4-009	Dining Room	Ceiling	Drywall (DJC)	Asbestos	21-7672-52*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
4-009	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-010	Dishwashing	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-010	Dishwashing	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-010	Dishwashing	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	
4-010	Dishwashing	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
4-011	Servery	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-011	Servery	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	N/A	N/A	Turquoise with Light and Dark Turquoise Flecks NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-011	Servery	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	
4-011	Servery	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
4-012	Cart Storage	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-012	Cart Storage	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	N/A	N/A	Turquoise with Light and Dark Turquoise Flecks NOT OBSERVED
4-012	Cart Storage	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-012	Cart Storage	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
4-013	Storage	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Turquoise with Light and Dark Turquoise Flecks
4-013	Storage	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-013	Storage	Ceiling	Ceiling Tile 2	N/A	N/A	N/A	N/A	N/A	2' x 4' Fine Textured - Gypsum
4-014	Dining Room	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	500 SF	Good	Grey
4-014	Dining Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-014	Dining Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	1000 SF	Good	
4-014	Dining Room	Ceiling	Drywall (DJC)	Asbestos	21-7672-51*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
4-014	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-015	Elevator Lobby	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-015	Elevator Lobby	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-015	Elevator Lobby	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-016	Room N403	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	Grey
4-016	Room N403	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-016	Room N403	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-016	Room N403	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-016	Room N403	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-016	Room N403	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-016	Room N403	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-017	Room N404	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-017	Room N404	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-017	Room N404	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-017	Room N404	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-017	Room N404	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-017	Room N404	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-017	Room N404	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-018	Room N405	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-018	Room N405	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-018	Room N405	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-018	Room N405	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-018	Room N405	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-018	Room N405	Ceiling	Drywall (DJC)	Asbestos	21-7672-53*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
4-018	Room N405	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-019	Room N406	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-019	Room N406	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-019	Room N406	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-019	Room N406	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-019	Room N406	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-019	Room N406	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-019	Room N406	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-020	Room N407	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-020	Room N407	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-020	Room N407	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-020	Room N407	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-020	Room N407	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-020	Room N407	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-021	Room N408	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-021	Room N408	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-021	Room N408	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-021	Room N408	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-021	Room N408	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-021	Room N408	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-021	Room N408	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-022	Room N409	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-022	Room N409	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-022	Room N409	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-022	Room N409	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-022	Room N409	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-022	Room N409	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-022	Room N409	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-023	Room N410	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-023	Room N410	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-023	Room N410	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-023	Room N410	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-023	Room N410	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-023	Room N410	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-023	Room N410	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-024	Room N412	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-024	Room N412	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-024	Room N412	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-024	Room N412	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-024	Room N412	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-024	Room N412	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-024	Room N412	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-025	Room N414	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-025	Room N414	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-025	Room N414	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-025	Room N414	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-025	Room N414	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-025	Room N414	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-025	Room N414	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-026	Room N416	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-026	Room N416	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-026	Room N416	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-026	Room N416	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-026	Room N416	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-026	Room N416	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-026	Room N416	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-027	Room N418	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-027	Room N418	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-027	Room N418	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-027	Room N418	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-027	Room N418	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-027	Room N418	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-027	Room N418	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-028	Room N419	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-028	Room N419	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-028	Room N419	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-028	Room N419	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-028	Room N419	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-028	Room N419	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-028	Room N419	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-029	Room N417	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-029	Room N417	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-029	Room N417	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-029	Room N417	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-029	Room N417	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-029	Room N417	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-029	Room N417	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-030	Room N415	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-030	Room N415	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-030	Room N415	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-030	Room N415	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-030	Room N415	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-030	Room N415	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-030	Room N415	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-031	Room N413	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-031	Room N413	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-031	Room N413	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-031	Room N413	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-031	Room N413	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-031	Room N413	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-031	Room N413	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-032	Room N411	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-032	Room N411	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-032	Room N411	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-032	Room N411	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-032	Room N411	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-032	Room N411	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-032	Room N411	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-033	Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-033	Tub Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	
4-033	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-034	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-034	Shower Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	
4-034	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-035	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-035	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-035	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	
4-035	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-036	Corridor	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	1600 SF	Good	Grey
4-036	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks NOT OBSERVED
4-036	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-036	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
4-036	Corridor	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	
4-036	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-037	Electrical Closet	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	Grey
4-037	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
4-037	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
4-038	Office	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Grey
4-038	Office	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-038	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-039	Staff Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-039	Staff Washroom	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-039	Staff Washroom	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
4-040	Nurses Station	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-040	Nurses Station	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-040	Nurses Station	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	
4-040	Nurses Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-041	Medical Supply	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Grey
4-041	Medical Supply	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-041	Medical Supply	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	
4-041	Medical Supply	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-042	Corridor	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	Grey
4-042	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks NOT OBSERVED
4-042	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-042	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
4-042	Corridor	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	
4-042	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-043	Family Lounge	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-043	Family Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-043	Family Lounge	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	
4-043	Family Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-044	Room N441	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	Grey
4-044	Room N441	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-044	Room N441	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-044	Room N441	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-044	Room N441	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-044	Room N441	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-044	Room N441	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-045	Room N442	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-045	Room N442	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-045	Room N442	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-045	Room N442	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-045	Room N442	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-045	Room N442	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-045	Room N442	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-046	Room N443	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-046	Room N443	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-046	Room N443	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-046	Room N443	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-046	Room N443	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-046	Room N443	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-046	Room N443	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-047	Room N444	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-047	Room N444	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-047	Room N444	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-047	Room N444	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-047	Room N444	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-047	Room N444	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-047	Room N444	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-048	Room N445	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-048	Room N445	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-048	Room N445	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-048	Room N445	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-048	Room N445	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-048	Room N445	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-048	Room N445	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-049	Room N446	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-049	Room N446	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-049	Room N446	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-049	Room N446	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-049	Room N446	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-049	Room N446	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-049	Room N446	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-050	Room N447	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-050	Room N447	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-050	Room N447	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-050	Room N447	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-050	Room N447	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-050	Room N447	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-050	Room N447	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-051	Room N448	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-051	Room N448	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-051	Room N448	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-051	Room N448	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-051	Room N448	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-051	Room N448	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-051	Room N448	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-052	Room N449	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-052	Room N449	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-052	Room N449	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-052	Room N449	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-052	Room N449	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-052	Room N449	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-052	Room N449	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-053	Room N450	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-053	Room N450	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-053	Room N450	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-053	Room N450	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-053	Room N450	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-053	Room N450	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-053	Room N450	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-054	Room N451	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-054	Room N451	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-054	Room N451	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-054	Room N451	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-054	Room N451	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-054	Room N451	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-054	Room N451	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-055	Room N452	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-055	Room N452	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-055	Room N452	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-055	Room N452	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-055	Room N452	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-055	Room N452	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-055	Room N452	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-056	Activity Room	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	Grey
4-056	Activity Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-056	Activity Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	
4-056	Activity Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-057	Corridor	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	1450 SF	Good	Grey
4-057	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-057	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
4-057	Corridor	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	
4-057	Corridor	Ceiling	Drywall (DJC)	Asbestos	21-7672-54*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
4-057	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-058	Lounge	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Grey
4-058	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-058	Lounge	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-058	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-059	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-059	Shower Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	300 SF	Good	
4-059	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-060	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-060	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-060	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	
4-060	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-061	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	NO ACCESS Beige with Black Specks
4-061	Washroom	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-061	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-062	Storage	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Grey

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-062	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-062	Storage	Floor	Firestop-Red	Asbestos	22-7864-5*	None Detected	N/A	N/A	*From Fisher Project No.22-11904, dated Jan. 2022
4-062	Storage	Walls	Drywall (DJC)	Asbestos	22-7864-2*	None Detected	N/A	N/A	*From Fisher Project No.22-11904, dated Jan. 2022
4-062	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-063	Reading Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-063	Reading Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-063	Reading Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-064	Room N460	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-064	Room N460	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-064	Room N460	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-064	Room N460	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-064	Room N460	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-064	Room N460	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-064	Room N460	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-065	Room N461	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-065	Room N461	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-065	Room N461	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-065	Room N461	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-065	Room N461	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-065	Room N461	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-065	Room N461	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-066	Room N462	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-066	Room N462	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-066	Room N462	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-066	Room N462	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-066	Room N462	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-066	Room N462	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-066	Room N462	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-067	Room N463	Floor	Vinyl Sheet Flooring 12						
4-067	Room N463	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-067	Room N463	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-067	Room N463	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-067	Room N463	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-067	Room N463	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-067	Room N463	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-068	Room N464	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-068	Room N464	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-068	Room N464	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-068	Room N464	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-068	Room N464	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-068	Room N464	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-068	Room N464	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-069	Room N465	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-069	Room N465	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-069	Room N465	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-069	Room N465	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-069	Room N465	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-069	Room N465	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-069	Room N465	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-070	Room N466	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-070	Room N466	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-070	Room N466	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-070	Room N466	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-070	Room N466	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-070	Room N466	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-070	Room N466	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-071	Room N467	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-071	Room N467	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-071	Room N467	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-071	Room N467	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-071	Room N467	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-071	Room N467	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-071	Room N467	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-072	Room N468	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-072	Room N468	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-072	Room N468	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-072	Room N468	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-072	Room N468	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-072	Room N468	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-072	Room N468	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-073	Room N469	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-073	Room N469	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-073	Room N469	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-073	Room N469	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-073	Room N469	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-073	Room N469	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-073	Room N469	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-074	Room N470	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-074	Room N470	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-074	Room N470	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-074	Room N470	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-074	Room N470	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-074	Room N470	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-074	Room N470	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-075	Room N471	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-075	Room N471	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-075	Room N471	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-075	Room N471	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-075	Room N471	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-075	Room N471	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-075	Room N471	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-076	Room N472	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-076	Room N472	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-076	Room N472	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-076	Room N472	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-076	Room N472	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-076	Room N472	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-076	Room N472	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-077	Room N473	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Grey
4-077	Room N473	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Grey with Dark Dots
4-077	Room N473	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-077	Room N473	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-077	Room N473	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-077	Room N473	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-077	Room N473	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-078	Corridor	Floor	Vinyl Floor Tile 13	Asbestos	Not Sampled	ACM Assumed	1450 SF	Good	1.5' x 1.5' Beige with Brown Splatters
4-078	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-078	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
4-078	Corridor	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	
4-078	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-079	Soiled Linen	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-079	Soiled Linen	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-079	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-079	Soiled Linen	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
4-080	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-080	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
4-080	Electrical Closet	Walls	Drywall (DJC)	Asbestos	22-7864-1*	None Detected	N/A	N/A	*From Fisher Project No.22-11904, dated Jan. 2022
4-080	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
4-081	Shower/Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-081	Shower/Tub Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	
4-081	Shower/Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-082	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-082	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	
4-082	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-083	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-083	Washroom	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-083	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-084	Soiled Utility	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-084	Soiled Utility	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-084	Soiled Utility	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-084	Soiled Utility	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
4-085	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-085	Lounge	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-085	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-086	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	NO ACCESS Beige with Black Specks
4-086	Washroom	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-086	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-087	Housekeeping	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Grey
4-087	Housekeeping	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-087	Housekeeping	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-087	Housekeeping	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	125 SF	Good	
4-087	Housekeeping	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
4-088	Office	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	Grey
4-088	Office	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-088	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-089	Dining Room	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	350 SF	Good	Grey
4-089	Dining Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED
4-089	Dining Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	750 SF	Good	
4-089	Dining Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-089	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-090	Room S404	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-090	Room S404	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-090	Room S404	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-090	Room S404	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-090	Room S404	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-091	Room S405	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-091	Room S405	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-091	Room S405	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-091	Room S405	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-091	Room S405	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-092	Room S406	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-092	Room S406	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-092	Room S406	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-092	Room S406	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-092	Room S406	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-093	Room S407	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-093	Room S407	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-093	Room S407	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-093	Room S407	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-093	Room S407	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-094	Room S408	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-094	Room S408	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-094	Room S408	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-094	Room S408	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-094	Room S408	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-095	Laundry Chute	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-095	Laundry Chute	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	
4-095	Laundry Chute	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-096	Room S409	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-096	Room S409	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-096	Room S409	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-096	Room S409	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-096	Room S409	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-097	Room S410	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-097	Room S410	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-097	Room S410	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-097	Room S410	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-097	Room S410	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-098	Room S412	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-098	Room S412	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-098	Room S412	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-098	Room S412	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-098	Room S412	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-099	Room S414	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-099	Room S414	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-099	Room S414	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-099	Room S414	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-099	Room S414	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-100	Room S416	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-100	Room S416	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-100	Room S416	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-100	Room S416	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-100	Room S416	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-101	Room S418	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-101	Room S418	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-101	Room S418	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-101	Room S418	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-101	Room S418	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-102	Room S419	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-102	Room S419	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-102	Room S419	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-102	Room S419	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-102	Room S419	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-103	Room S417	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-103	Room S417	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-103	Room S417	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-103	Room S417	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-103	Room S417	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-104	Room S415	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-104	Room S415	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-104	Room S415	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-104	Room S415	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-104	Room S415	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-105	Room S413	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-105	Room S413	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-105	Room S413	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-105	Room S413	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-105	Room S413	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-106	Room S411	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-106	Room S411	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-106	Room S411	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-106	Room S411	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-106	Room S411	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-107	Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-107	Tub Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	500 SF	Good	
4-107	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-108	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-108	Shower Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-108	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-109	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-109	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	
4-109	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-110	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
4-110	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-110	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
4-110	Corridor	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	
4-110	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-111	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-111	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
4-111	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
4-112	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
4-112	Office	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-112	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-113	Staff Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-113	Staff Washroom	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-113	Staff Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture NOT OBSERVED
4-113	Staff Washroom	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
4-114	Nurses Station	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-114	Nurses Station	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	
4-114	Nurses Station	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-115	Medical Supply	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-115	Medical Supply	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	120 SF	Good	
4-115	Medical Supply	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-116	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 15-1531-01 to 03	None Detected	N/A	N/A	12" x 12" Grey with Light and Dark Grey Flecks
4-116	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-116	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
4-116	Corridor	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	
4-116	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-117	Family Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-117	Family Lounge	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-117	Family Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-118	Room S440	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-118	Room S440	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-118	Room S440	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-118	Room S440	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-118	Room S440	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-119	Room S441	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-119	Room S441	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-119	Room S441	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-119	Room S441	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-119	Room S441	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-120	Room S442	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-120	Room S442	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-120	Room S442	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-120	Room S442	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-120	Room S442	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-121	Room S443	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-121	Room S443	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-121	Room S443	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-121	Room S443	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-121	Room S443	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-122	Room S444	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-122	Room S444	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-122	Room S444	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-122	Room S444	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-122	Room S444	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-123	Room S445	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-123	Room S445	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-123	Room S445	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-123	Room S445	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-123	Room S445	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-124	Room S446	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-124	Room S446	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-124	Room S446	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-124	Room S446	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-124	Room S446	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-125	Room S447	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-125	Room S447	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-125	Room S447	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-125	Room S447	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-125	Room S447	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-126	Room S448	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-126	Room S448	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-126	Room S448	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-126	Room S448	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-126	Room S448	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-127	Room S449	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-127	Room S449	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-127	Room S449	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-127	Room S449	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-127	Room S449	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-128	Room S450	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-128	Room S450	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-128	Room S450	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-128	Room S450	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-128	Room S450	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-129	Room S451	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-129	Room S451	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-129	Room S451	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-129	Room S451	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-129	Room S451	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-130	Activity Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-130	Activity Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	
4-130	Activity Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-131	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-131	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
4-131	Corridor	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	
4-131	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-132	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-132	Lounge	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-132	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-133	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-133	Shower Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	
4-133	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-134	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-134	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	
4-134	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-135	Washroom	Floor	Vinyl Sheet Flooring 11	Asbestos	Not Sampled	ACM Assumed	320 SF	Good	Grey with Dark Dots
4-135	Washroom	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-135	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-136	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-136	Storage	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-136	Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-137	Reading Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-137	Reading Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-137	Reading Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-138	Janitor's Closet	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-138	Janitor's Closet	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-138	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	
4-138	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-139	Room S459	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-139	Room S459	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-139	Room S459	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-139	Room S459	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-139	Room S459	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-140	Room S460	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-140	Room S460	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-140	Room S460	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-140	Room S460	Ceiling	Drywall (DJC)	Asbestos	21-7672-55*	None Detected	N/A	N/A	*From Fisher Project No.21-11790, dated Dec. 2021
4-140	Room S460	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-141	Room S461	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-141	Room S461	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-141	Room S461	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-141	Room S461	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-141	Room S461	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-142	Room S462	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-142	Room S462	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-142	Room S462	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-142	Room S462	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-142	Room S462	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-143	Room S463	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-143	Room S463	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-143	Room S463	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-143	Room S463	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-143	Room S463	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-144	Room S464	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-144	Room S464	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-144	Room S464	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-144	Room S464	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-144	Room S464	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-145	Room S465	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-145	Room S465	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-145	Room S465	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-145	Room S465	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-145	Room S465	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-146	Room S466	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-146	Room S466	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-146	Room S466	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-146	Room S466	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-146	Room S466	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-147	Room S467	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-147	Room S467	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-147	Room S467	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-147	Room S467	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-147	Room S467	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-148	Room S468	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-148	Room S468	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-148	Room S468	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-148	Room S468	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-148	Room S468	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-149	Room S469	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-149	Room S469	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-149	Room S469	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-149	Room S469	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-149	Room S469	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-150	Room S470	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-150	Room S470	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-150	Room S470	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-150	Room S470	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-150	Room S470	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-151	Room S471	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-151	Room S471	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-151	Room S471	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	250 SF	Good	
4-151	Room S471	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-151	Room S471	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-152	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-152	Corridor	Floor	Vinyl Floor Tile 8	Asbestos	Homogeneous w/ 19-3372-09 to 11	None Detected	N/A	N/A	12" x 12" Grey
4-152	Corridor	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	1500 SF	Good	
4-152	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-153	Nurses Supply Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-153	Nurses Supply Room	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-153	Nurses Supply Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-153	Nurses Supply Room	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
4-154	Clean Utility	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-154	Clean Utility	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks NOT OBSERVED
4-154	Clean Utility	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-154	Clean Utility	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
4-155	Shower/Tub Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-155	Shower/Tub Room	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	
4-155	Shower/Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 21-7672-49 to 55	None Detected	N/A	N/A	
4-156	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-156	Lounge	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-156	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-157	Electrical Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-157	Electrical Closet	Floor	Firestop-Red	Asbestos	22-7864-4*	None Detected	N/A	N/A	*From Fisher Project No.22-11904, dated Jan. 2022
4-157	Electrical Closet	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
4-157	Electrical Closet	Walls	Drywall (DJC)	Asbestos	22-7864-3*	None Detected	N/A	N/A	*From Fisher Project No.22-11904, dated Jan. 2022
4-157	Electrical Closet	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
4-158	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	NO ACCESS Beige with Black Specks
4-158	Washroom	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-158	Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-159	Soiled Linen	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-159	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	
4-159	Soiled Linen	Ceiling	Ceiling Tile 6	N/A	N/A	N/A	N/A	N/A	2' x 2' Bubbled with Random Pinholes - Fibreglass
4-160	Lounge	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks
4-160	Lounge	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-160	Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-161	Washroom	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-161	Washroom	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	
4-161	Washroom	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 19-3372-06 to 08	None Detected	N/A	N/A	2'x4' Large and Small Random Pinholes
4-162	Housekeeping	Floor	Vinyl Sheet Flooring 2	Asbestos	Homogeneous w/ 22-7864-10 to 12	None Detected	N/A	N/A	Beige with Black Specks
4-162	Housekeeping	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	125 SF	Good	
4-162	Housekeeping	Ceiling	Ceiling Tile 7	Asbestos	Homogeneous w/ 21-7672-65 to 67	None Detected	N/A	N/A	2' x 2' Tiny Pinholes
4-163	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
4-163	Office	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	
4-163	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
4-164	Change Locker	Floor	Vinyl Sheet Flooring 12	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Grey
4-164	Change Locker	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 15-1531-04 to 06	None Detected	N/A	N/A	12" x 12" Pink with Light and Dark Pink Flecks NOT OBSERVED

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-164	Change Locker	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	
4-164	Change Locker	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 21-7672-62 to 64	None Detected	N/A	N/A	2' x 2' Medium, Woven Texture
<i>Surveyor's Field Notes</i>									


APPENDIX II

RESULTS OF BULK SAMPLE ANALYSIS


(NO INFORMATION TO REPORT)

APPENDIX III

SITE DRAWINGS



Legend

-  Asbestos-Containing Material
-  Location Number
-  No Access to Room

The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 1

LOCATION:
205 Cumber Avenue
Toronto, Ontario

BUILDING NAME:
Cumber Lodge

Basement Floor Plan Asbestos-Containing Material Locations

CLIENT: City of Toronto


PROJECT NUMBER: FE-P 23-12800 **DATE:** June 2023 **DRW BY:** DC

CAD FILE: FIG1 **SCALE:** Not to Scale **CHK BY:** RS






Legend




Asbestos-Containing Material



Location Number



No Access to Room



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 2

LOCATION:
205 Cumber Avenue
Toronto, Ontario

BUILDING NAME:
Cumber Lodge


First Floor Plan Asbestos-Containing Material Locations

CLIENT: City of Toronto		
PROJECT NUMBER: FE-P 23-12800	DATE: June 2023	DRW BY: ZA
CAD FILE: FIG2	SCALE: Not to Scale	CHK BY: RS






Legend




Asbestos-Containing Material



Location Number



No Access to Room



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 5

LOCATION: 205 Cummer Avenue
Toronto, Ontario

BUILDING NAME: Cummer Lodge

Fourth Floor Plan Asbestos-Containing Material Locations

CLIENT: City of Toronto		
PROJECT NUMBER: FE-P 23-12800	DATE: June 2023	DRW BY: ZA
CAD FILE: FIG5	SCALE: Not to Scale	CHK BY: RS



APPENDIX IV

SITE PHOTOGRAPHS

(NO INFORMATION TO REPORT)

APPENDIX V

CORRECTIVE ACTIONS INSPECTION



August 28, 2023

City of Toronto
55 John Street
Toronto ON, M5V 3C6

Inder Bhamra, EP, PMP, CSM
Environmental Coordinator

Re: Mould Abatement & Assessment at Cummer Lodge, 205 Cummer Ave., Toronto, ON

As requested, Fisher Engineering Limited (Fisher) has provided environmental monitoring services with respect to mould abatement activities at Cummer Lodge Long Term Care Home, located at 205 Cummer Avenue, Toronto, ON (the "Site"). Mould remediation was initiated following the discovery of mould impacted non-asbestos-containing ceiling tile during the Annual Survey, conducted on May 26, 2023, Fisher Project No. FE 23-12800.

In addition, the corrective action reporting form recommended a mould assessment in Stair 3 (Loc. 1-149). However, the black mark on the concrete wall pictured in the reporting form was discovered in Stair 6 (Loc. 1-102), not in Stair 3. Fisher conducted the mould assessment.

The scope of work associated with the mould assessment is as follows:

- Conduct a visual inspection of accessible areas to review current conditions;
- Identify visible mould growth and concerns for potential hidden mould growth;
- Provide a report with findings, conclusions, and recommendations for remediation.

The purpose of the assessment was to observe current Site conditions and to provide recommendations for remediation. The assessment scope includes an area on the wall in Stairwell 6. The scope of the current assessment did not include the entire building. The assessment was conducted by Iqbal Fattah on August 17, 2023.

The City of Toronto retained Fisher as the environmental health and safety consultant to provide project monitoring. Fisher retained Furcon Environmental Inc. as the environmental contractor to undertake the specified remedial action. Abatement work was conducted in accordance with Level 1 mould remediation protocols, as outlined by the Environmental Abatement Council of Canada (EACC) Mould Abatement Guidelines, Edition 3 (2015).

Based on the recommendations provided in the corrective actions reporting form, the non-asbestos containing ceiling tile was removed from Reading Room, Location Number 4-137, following Level 1 Mould Remediation Procedures, and replaced with new tile.

FINDINGS AND OBSERVATIONS

Fisher conducted a non-intrusive inspection of all accessible surfaces in the area of Stairwell 6. The building materials in this area were mainly concrete on the floor, walls, and ceiling.

The visual assessment was completed within the accessible areas. The black marks on the concrete wall were determined to not be mould. It is unknown the source of the black marks on, but are not considered to be an environmental concern. Moisture readings confirmed that the wall of the stairwell was dry at the time of the assessment.

CONCLUSIONS AND RECOMMENDATIONS

Based on the findings and the observations outlined above, Fisher concludes the black marks on the wall is not mould growth. Fisher suggests to clean the black stain (approximately one square foot) on the concrete wall following general health and safety procedures.

Should you have any questions or concerns please do not hesitate to contact us.

Regards,

Prepared by:

Reviewed by:



Iqbal Fattah, M.Sc.
Project Manager



David A. Fisher, B.A.Sc., C.Chem., P.Eng.
Principal

Attachment A: Site Photos

ATTACHMENT A – SITE PHOTOS



Photo 1: Moisture reading indicated the wall was dry at the time of assessment



Photo 2: Black stain on the concrete wall in the Stairwell 6 (Loc. 1-102).