



FISHER
ENGINEERING



TORONTO

DESIGNATED SUBSTANCES and HAZARDOUS MATERIALS SURVEY



LONG TERM CARE HOMES & SERVICES Seven Oaks 9 Neilson Road Toronto, Ontario

Presented to:

Sara Reid

City of Toronto
Corporate Real Estate Management

Project Number: FE 23-12800

SEPTEMBER 8, 2023

EXECUTIVE SUMMARY

Fisher Engineering Limited was retained by the City of Toronto, Corporate Real Estate Management to conduct a reassessment survey for designated substances and hazardous materials in the Toronto Long Term Care Homes & Services building named Seven Oaks, located at 9 Neilson Road in Toronto, Ontario.

The objective of the survey was to determine the condition of previously identified asbestos-containing materials (ACM), identify and assess the condition of designated substances and other hazardous materials, and, if necessary, provide recommendations to assist the City of Toronto in fulfilling requirements to achieve regulatory compliance, as set forth under the Ontario Occupational Health and Safety Act, and enforced by the Ontario Ministry of Labour regulations for designated substances; O. Reg. 490/09 – Designated Substances and O. Reg. 278/05 – Asbestos on Construction Projects and in Buildings and Repair Operations.

This document should be filed as an addendum to the original survey report, which was issued by Fisher Environmental Ltd. on April 29, 2015.

These Designated Substances and Hazardous Materials survey report is intended for management purposes only. It is not to be used to establish the presence of designated substances or hazardous materials in building materials prior to renovation or demolition activities. A pre-renovation/pre-demolition audit of the work area for designated substances and hazardous materials should be conducted prior to any work activities that may disturb building materials potentially containing designated materials or hazardous substances.

Renata Stec of Fisher Engineering Limited performed the fieldwork on May 25, 2023.

FINDINGS

The following presents a brief outline of findings within the facility. Refer to the main body and appendices of the report for specific details, quantities, conditions and locations of Designated Substances and Hazardous Materials within the facility.

Material	Findings
Asbestos	Assumed ACM were identified in the facility as follows: <ul style="list-style-type: none">• Roofing Materials,• Caulking,• Drywall Joint Compound,• Vinyl Floor Tiles – seven (7) varieties, and• Vinyl Sheet Flooring – seventeen (17) varieties. All assumed ACM were observed in GOOD condition.
Lead	Paint finishes were generally noted to be in GOOD condition throughout the Site. During the disturbance of any painted surfaces that contain lead, it is recommended that appropriate procedures and use of respirators be followed to protect workers.
Mercury	Mercury can be found in fluorescent light bulbs and building thermostats.
Silica	As the building is constructed of concrete block and brick, with concrete floors, silica is expected to be found within these components of the building.

Material	Findings
Other Designated Substances	No evidence of Acrylonitrile, Arsenic, Benzene, Coke Oven Emissions, Ethylene Oxide, Isocyanates, and Vinyl Chloride was found during the building survey.
PCB	No PCB containing equipment with the potential exception of fluorescent lighting ballasts was observed.
UFFI	No UFFI containing insulation was observed on site.
Mould	During the visual inspection of the surveyed areas, visible mould growth and water staining on non-ACM ceiling tiles were observed

RECOMMENDATIONS

Fisher Engineering Limited would report any deficiencies and recommendations to the City of Toronto using a 2023 Reassessment Program Corrective Actions Reporting Form. On completion of the recommended actions, an Addendum is made to confirm completion of all corrective actions.

TABLE OF CONTENTS

EXECUTIVE SUMMARY	I
1. INTRODUCTION AND REGULATORY REQUIREMENTS	1
1.1 INTRODUCTION AND SCOPE	1
2. SURVEY METHODOLOGY.....	1
2.1 GENERAL APPROACH.....	1
2.2 SURVEY METHODOLOGY	1
3. FINDINGS AND RECOMMENDATIONS.....	2
3.1 ASBESTOS.....	2
3.1.1 Findings.....	2
3.1.2 Recommendations.....	3
3.2 LEAD.....	4
3.2.1 Findings.....	4
3.2.2 Recommendations.....	5
3.3 ACRYLONITRILE.....	5
3.3.1 Findings.....	5
3.3.2 Recommendations.....	5
3.4 ARSENIC.....	5
3.4.1 Findings.....	5
3.4.2 Recommendations.....	5
3.5 BENZENE.....	5
3.5.1 Findings.....	6
3.5.2 Recommendations.....	6
3.6 COKE OVEN EMISSIONS.....	6
3.6.1 Findings.....	6
3.6.2 Recommendations.....	6
3.7 ETHYLENE OXIDES	6
3.7.1 Findings.....	6
3.7.2 Recommendations.....	6
3.8 ISOCYANATES	6
3.8.1 Findings.....	7
3.8.2 Recommendations.....	7
3.9 MERCURY.....	7
3.9.1 Findings.....	7
3.9.2 Recommendations.....	7
3.10 SILICA.....	7
3.10.1 Findings.....	8
3.10.2 Recommendations.....	8
3.11 VINYL CHLORIDE.....	8
3.11.1 Findings.....	8
3.11.2 Recommendations.....	8
3.12 POLYCHLORINATED BIPHENYLS (PCBS).....	8
3.12.1 Findings.....	8
3.12.2 Recommendations.....	9
3.13 UREA FORMALDEHYDE FOAM INSULATION (UFFI).....	9
3.13.1 Findings.....	9
3.13.2 Recommendations.....	9

TABLE OF CONTENTS

3.14	<i>MOULD</i>	9
3.14.1	<i>Findings</i>	10
3.14.2	<i>Recommendations</i>	10
4.	CORRECTIVE ACTIONS	10
5.	STATEMENT OF LIMITATIONS	10
6.	SIGN-OFF	11

APPENDIX I – DESIGNATED SUBSTANCES AND HAZARDOUS MATERIALS INVENTORY SHEET

APPENDIX II – RESULTS OF BULK SAMPLE ANALYSIS

APPENDIX III – SITE DRAWINGS

APPENDIX IV – SITE PHOTOGRAPHS

APPENDIX V – CORRECTIVE ACTIONS INSPECTION REPORT

1. INTRODUCTION AND REGULATORY REQUIREMENTS

1.1 Introduction and Scope

Fisher Engineering Limited was retained by the City of Toronto, Corporate Real Estate Management to conduct a reassessment survey for designated substances and hazardous materials in Toronto Long Term Care Homes & Services building named Seven Oaks, located at 9 Neilson Road in Toronto, Ontario

The objective of the survey was to determine the condition of previously identified asbestos-containing materials (ACM), identify and assess the condition of designated substances and other hazardous materials, and, if necessary, provide recommendations to assist the City of Toronto in fulfilling requirements to achieve regulatory compliance, as set forth under the Ontario Occupational Health and Safety Act, and enforced by the Ontario Ministry of Labour regulations for designated substances; O. Reg. 490/09 – Designated Substances and O. Reg. 278/05 – Asbestos on Construction Projects and in Buildings and Repair Operations.

This document should be filed as an addendum to the original survey report, which was issued by Fisher Environmental Ltd. on April 29, 2015.

The Designated Substances and Hazardous Materials survey report is intended for management purposes only. It is not to be used to establish the presence of designated substances or hazardous materials in building materials prior to renovation or demolition activities. A pre-renovation/pre-demolition audit of the work area for designated substances and hazardous materials should be conducted prior to any work activities that may disturb building materials potentially containing designated materials or hazardous substances.

Renata Stec of Fisher Engineering Limited performed the fieldwork on May 25, 2023.

2. SURVEY METHODOLOGY

2.1 General Approach

To ensure familiarity with the building, the Surveyor made reference to the previous assessment and reassessment reports provided by the City of Toronto prior to commencing the survey. The Surveyor also made reference to facility floor plans included in the previous assessment reports, or provided independently by the City of Toronto. Site drawings identifying locations of asbestos-containing materials, if present, are included in Appendix III. Site photographs are included in Appendix IV.

2.2 Survey Methodology

The City of Toronto provided the consultant with the previous Designated Substances and Hazardous Materials Survey report and / or other survey reports identified for the facility, if available. Prior to conducting the current survey, previous reports were reviewed by Fisher Engineering Limited and the current report is updated with all available information regarding ACM, including that from past assessments and reassessments.

The survey was conducted in compliance with the Ontario Ministry of Labour (MOL) regulations for designated substances; O. Reg. 490/09 - *Designated Substances* and O. Reg. 278/05 - *Asbestos on Construction Projects and in Buildings and Repair Operations* made under the Occupational Health and Safety Act (OHSA), R.S.O. 1990.

The Surveyor conducted a visual reassessment of all known and assumed asbestos-containing materials in all accessible areas of the building, as detailed in past survey reports, and recorded the condition (GOOD, FAIR or POOR) of each known or assumed ACM on the Designated Substances and Hazardous Materials Inventory Sheet. The Surveyor also recorded detailed descriptions of previously-unidentified potential ACM, if observed. Please refer to Appendix I for the updated Designated Substances and Hazardous Materials Inventory Sheet.

Materials confirmed to be asbestos-containing during previous assessments were not sampled for this reassessment survey. Additionally, samples were not collected of materials that were previously confirmed to be non-asbestos by the requirements of O. Reg. 278/05. Any other potential asbestos-containing materials noted during the reassessment survey that had not been identified in a previous survey, or were not sampled in accordance with the requirements of O. Reg. 278/05, were noted as part of the reassessment.

The Designated Substances and Hazardous Materials Survey is based on a walk-through inspection of the facility and shall be conducted room by room to establish locations, conditions and types of designated substances. The survey shall also include an examination for the presence of polychlorinated biphenyls (PCBs), urea-formaldehyde foam insulation (UFFI), and visible mould growth.

3. FINDINGS AND RECOMMENDATIONS

3.1 Asbestos

Asbestos fibres may be released into the air by the disturbance of ACM during product use, demolition work, building or home maintenance, repair and remodeling. In general, exposure may occur only when the ACM is disturbed in some way to release particles and fibres into the air.

3.1.1 Findings

Previously identified assumed ACM include the following:

- Roofing Materials,
- Window Caulking,
- Drywall Joint Compound,
- Vinyl Floor Tiles – seven (7) varieties, and
- Vinyl Sheet Flooring – nineteen (19) varieties.

Vinyl Floor Tile 2 (12"×12" Beige with Grey and White Smears) not identified during the previous assessment surveys was observed in location 1-094 Servery.

Vinyl Floor Tile 9 (12"×12" Pink with Brown and White Smears) not identified during the previous assessment surveys was observed in locations 1-015 Male Locker Room and 1-017 Soiled Linen Room.

Vinyl Sheet Flooring 1 (Yellow) not identified during the previous assessment surveys was observed in locations 1-059 Room 114, 1-065 Room 108, 2-079 Laundry Room.

Vinyl Sheet Flooring 5 (Green with Black Dots) not identified during the previous assessment surveys was observed in locations 2-005 Room 204, 2-054 Lounge.

Vinyl Sheet Flooring 20 (Light Grey and Light Brown Design) not identified during the previous assessment surveys was observed in location 2-054 Lounge.

Vinyl Sheet Flooring 21 (Grey) not identified during the previous assessment surveys was observed in location 1-053 Washroom.

Vinyl Sheet Flooring 23 (Off-White with Grey Mosaic) not identified during the previous assessment surveys was observed in location B-022 Male Locker Room.

Ceiling Tile 1 (2'× 2' Small Pinhole) not identified during the previous assessment surveys was observed in locations 2-003 Servery.

Vinyl Floor Tile 1 (12"×12" Beige Mosaic) previously identified in locations 2-054 Lounge was not observed during the survey.

Vinyl Floor Tile 3 (12"×12" Pink Mosaic) previously identified in locations 1-017 Soiled Linen Room was not observed during the survey.

Vinyl Sheet Flooring 3 (Blue) previously identified in locations B-017 Kitchen; and 1-053 Washroom was not observed during the survey.

Vinyl Sheet Flooring 4 (Beige) previously identified in locations 2-079 Laundry Room was not observed during the survey

No samples were collected for analysis during the current survey.

Unless previously determined to be non-asbestos, plaster, drywall joint compound, vinyl floor tiles, mastics and window caulking in other areas of the facility should continue to be assumed to be asbestos-containing, and should be sampled prior to renovation and/or demolition activities.

3.1.2 Recommendations

All assumed ACM were observed in GOOD condition at the time of the reassessment. Therefore, no recommended corrective actions are made at this time.

Any other building materials suspected to contain asbestos which are not outlined in this report should be assumed to be asbestos-containing until sample analysis determines asbestos content.

O. Reg. 278/05 requires that an Asbestos Management Program (AMP) be implemented as long as ACM are present in a building. The AMP, original survey report and subsequent

reassessment reports must be available at the work place, and must identify the type of asbestos, and where asbestos can be found on a room-by-room basis.

NOTE: Interpretation of all sources of asbestos-related information, including but not limited to the original asbestos survey report, asbestos reassessment reports, room-by-room survey data, survey drawings and reports from previous asbestos abatement projects, should be completed by a competent person trained in the historical application of asbestos in building materials, building design and preferably by a person with site-specific knowledge and/or experience.

Information contained within any of the above-noted sources may not relieve the Regulatory responsibility of building Owners, or project Employers/Constructors, to complete a detailed site inspection prior to commencement of a project.

This report should not be used as a substitute for a detailed site inspection to identify asbestos-containing building materials, which must be specifically tailored to the scope and nature of any given project, and completed prior to any maintenance, renovation or demolition work that may cause disturbance to building materials.

3.2 **Lead**

Most lead in the environment comes from human activities such as burning fossil fuels, mining and manufacturing. Lead is used in the production of batteries, ammunition, metal products such as solder and pipes, and x-ray devices. Exposure happens when eating food or drinking water that contains lead. Deteriorated lead paint can contribute to lead dust. The main target for lead toxicity is the nervous system.

The regulation for lead applies to every employer and worker at a workplace where lead is present, produced, processed, used, handled or stored and at which a worker is likely to be exposed to lead.

Additionally, in 2004 the MOL issued *Guideline: Lead on Construction Projects* outlining practices that should be followed during construction projects to protect workers' from exposure to lead. This includes the methods and equipment employed in the removal of lead containing coatings that reduce the creation of dust, providing appropriate facilities for workers to wash after each shift, and providing protective clothing and respirators where necessary.

3.2.1 **Findings**

Paint finishes were generally noted to be in GOOD condition throughout the Site. Based on the age of the building, it is possible that lead-based paint and lead plumbing are present within the building. During the current investigation, no lead samples were collected for analysis.

No other indication of lead containing materials was observed during the building survey, with the exception of that which may be contained within batteries.

3.2.2 Recommendations

During the disturbance of any painted surfaces that contain lead, it would be recommended that appropriate procedures and use of respirators be followed to protect workers.

No immediate corrective actions were recommended with regard to lead.

3.3 *Acrylonitrile*

Acrylonitrile is used to make other chemicals such as plastics, synthetic rubber and acrylic fibres. Breathing high concentrations of acrylonitrile will cause nose and throat irritation, tightness in chest, difficulty breathing, nausea, dizziness, weakness, headache, impaired judgment and convulsions. These symptoms usually disappear when exposure has stopped. If spilled on the skin, acrylonitrile will burn the skin and cause blisters and redness. Acrylonitrile is believed to be carcinogenic.

3.3.1 Findings

Acrylonitrile based polymers may have been utilized in the production of some of the building construction materials (e.g., paints, sealants, and adhesives). Although these polymers are generally volatile, they are expected to produce significant acrylonitrile exposure only during or shortly after application of the subject material. If present on site, acrylonitrile would not be expected to be a concern during future renovation or demolition works. Acrylonitrile was not evident in its pure form anywhere within the subject areas of the building.

3.3.2 Recommendations

No immediate corrective actions were recommended with regard to acrylonitrile.

3.4 *Arsenic*

Inorganic arsenic compounds are mainly used to preserve wood. Organic arsenic compounds are used as pesticides. Arsenic occurs naturally in soil and minerals and therefore may enter air and water. Breathing high levels of arsenic may cause sore throat and irritated lungs. Ingesting high levels of arsenic can result in death. Arsenic is a suspected carcinogenic substance.

3.4.1 Findings

Low levels of arsenic may be contained within paints or coatings utilized on building construction materials, however exposure levels resulting from personal contact are not expected to be significant. Arsenic or arsenic containing compounds were not encountered during the building survey works.

3.4.2 Recommendations

No immediate corrective actions were recommended with regard to arsenic.

3.5 *Benzene*

Benzene is colourless liquid with a sweet odour. Benzene utilization has historically been associated with solvents, paints, stains, adhesives, and in the manufacturing of various rubber products. While its current use in building materials has greatly decreased due to an

increased awareness of associated health concerns, it may still be present in trace quantities in various industrial solvents. Gasoline sold in Canada contains approximately 4% benzene.

Breathing very high levels of benzene can result in death, while high levels may cause drowsiness, dizziness, rapid heart rate, headaches, and unconsciousness.

3.5.1 Findings

While it may be expected, given the age of the building, that the original construction materials utilized did contain some trace levels of benzene, it is likely that any has since volatilized and would not exceed the permissible exposure values. During future renovation or demolition works, it would not be expected to be a concern. No evidence of benzene was noted during the building survey, with the exception of that which may be contained in regular gasoline fuel burning equipment.

3.5.2 Recommendations

No immediate corrective actions were recommended with regard to benzene.

3.6 *Coke Oven Emissions*

Coke oven emissions are released during the carbonization of bituminous coal for the production of coke. Exposure routes include inhalation, skin and / or eye contact. Coke oven emissions are potential occupational carcinogens.

3.6.1 Findings

This substance would not be expected to be found in the building. No evidence of the burning of coke was found during the building survey.

3.6.2 Recommendations

No immediate corrective actions were recommended with regard to coke oven emissions.

3.7 *Ethylene Oxides*

Ethylene oxide is a man-made chemical used primarily to make ethylene glycol (antifreeze and polyester). Breathing low levels of ethylene oxides for a prolonged period of time causes eye, skin and respiratory irritations, and can affect nervous system. Higher levels of exposure for shorter time produce symptoms that are similar but more severe.

3.7.1 Findings

This substance would not be expected to be found in the building. No evidence of ethylene oxides was found during the building survey.

3.7.2 Recommendations

No immediate corrective actions were recommended with regard to ethylene oxides.

3.8 *Isocyanates*

Isocyanates are a family of highly reactive, low molecular weight chemicals. They are widely used in the manufacture of flexible and rigid foams, fibres, and coatings such as paints and

varnishes, and elastomers and various building materials (e.g. spray on polyurethane products). Isocyanates are powerful irritants to the eyes, skin, and respiratory and gastrointestinal tracts.

3.8.1 Findings

Use of isocyanates or isocyanate compounds would not be expected in the building. No evidence of isocyanates was found during the building survey.

3.8.2 Recommendations

No immediate corrective actions were recommended with regard to isocyanates.

3.9 Mercury

Mercury is a naturally occurring metal. It is a shiny, silver-white and odourless liquid. It combines with other elements to form inorganic compounds or salts. Metallic mercury is used to produce chlorine gas and caustic soda, and is used in thermostats and thermometers, fluorescent light bulbs, dental fillings and batteries. Exposure occurs when breathing vapours from spills, incinerators, etc.

The nervous system is very sensitive to all forms of mercury. Exposure to high levels of metallic inorganic or organic mercury can permanently damage the brain, kidneys and developing fetus. Short-term exposure may cause lung damage, nausea, vomiting and diarrhea as well as skin and eye irritation.

3.9.1 Findings

Mercury can be found in fluorescent light bulbs and building thermostats. Prior to future renovation or demolition works, it would be recommended that these products be safely removed. The disposal of mercury containing items are regulated under the Environmental Protection Act, and it would be recommended that for disposal purposes any mercury containing thermostats and fluorescent light bulbs be disposed of at an MOE licensed receiver. With the exception of fluorescent light bulbs and building thermostats, no other evidence of mercury was noted during the building survey.

3.9.2 Recommendations

No immediate corrective actions were recommended with regard to mercury.

3.10 Silica

Silica is a crystalline compound occurring abundantly as quartz, sand, and many other minerals, and used to manufacture a variety of materials, especially glass and concrete. When mining this substance, silica can be deadly when it becomes airborne. If inhaled, silica dust can cause silicosis which can be fatal.

Additionally, in 2004 the MOL issued *Guideline: Silica on Construction Projects* outlining practices that should be followed during construction projects to protect workers' from exposure to silica. This includes the methods and equipment employed in the removal of silica containing materials that reduce the creation of dust, providing appropriate facilities

for workers to wash after each shift, and providing protective clothing and respirators where necessary.

3.10.1 Findings

As the building is constructed of concrete block and brick, with concrete floors, silica is expected to be found within these components of the building. During any significant renovation or demolition works where concrete dust is generated, dust suppression techniques should be utilized to control worker exposure to silica. Silica is expected to be present in concrete and masonry products in the building.

3.10.2 Recommendations

No immediate corrective actions were recommended with regard to silica.

3.11 *Vinyl Chloride*

Vinyl chloride is used to make polyvinyl chloride (PVC) which is found in a variety of plastic products, including pipes, wires, cable coatings and packaging materials. Breathing high levels of vinyl chloride can cause dizziness, unconsciousness and death. Prolonged exposure causes changes in liver, nerve damage, immune reactions and changes in blood flow.

3.11.1 Findings

PVC pipe is generally stable and does not allow for the liberation of vinyl chloride, under normal conditions. During future renovation or demolition works, this substance would not be expected to be a concern. Vinyl chloride was not evident in its pure form, anywhere in the subject dwellings.

3.11.2 Recommendations

No immediate corrective actions were recommended with regard to vinyl chloride.

3.12 *Polychlorinated Biphenyls (PCBs)*

PCBs are mixtures of synthetic organic chemicals with the same basic chemical structure and similar physical properties ranging from oily liquids to waxy solids. Due to their non-flammability, chemical stability, high boiling point and electrical insulating properties, PCBs were used in hundreds of industrial and commercial applications including electrical, heat transfer, and hydraulic equipment; as plasticizers in paints, plastics and rubber products; in pigments, dyes and carbonless copy paper and many other applications.

PCBs have been demonstrated to cause a variety of adverse health effects. PCBs have been shown to cause cancer.

3.12.1 Findings

No PCB containing equipment with the potential exception of fluorescent lighting ballasts was observed on site. The disposal of PCB containing equipment is regulated under MOE Reg. 558, and it would be recommended that during any ballast replacement works the

generated ballasts be evaluated for PCB content, with any PCB ballasts being consolidated and sent for disposal to an MOE licensed PCB receiver under waste class 243D.

3.12.2 Recommendations

It would be recommended that during any ballast replacement works the generated ballasts be evaluated for PCB content. Any PCB ballasts identified should be consolidated and sent for disposal to an MOE licensed PCB receiver under waste class 243D.

3.13 *Urea Formaldehyde Foam Insulation (UFFI)*

UFFI was developed in Europe in the 1950s as an improved means of insulating difficult-to-reach cavities in house walls. UFFI is composed of a mixture of urea-formaldehyde resin, a foaming agent, and compressed air. It was commonly injected into exterior wood frame walls in order to insulate difficult to reach cavities, until its ban in Canada in December 1980. When the mixture is injected into the wall, urea and formaldehyde unite and "cure" into an insulating foam plastic. In the insulating process, a slight excess of formaldehyde was often added to ensure complete "curing" with the urea to produce the urea-formaldehyde foam. That excess was given off during the curing, almost entirely within a day or two of injection. Properly installed, UFFI might not have resulted in any problem. Unfortunately, however, UFFI was sometimes improperly installed or used in locations where it should not have been.

While small amounts of formaldehyde are harmless, it is an irritating and toxic gas in significant concentrations. Symptoms of overexposure to formaldehyde include irritation to eyes, nose, and throat; persistent cough and respiratory distress; skin irritation; nausea; headache; and dizziness.

3.13.1 Findings

No UFFI containing insulation was observed on site.

3.13.2 Recommendations

No immediate corrective action is recommended with regard to UFFI.

3.14 *Mould*

Mould contamination inside buildings has become a concern to both building owners and occupants. Exposure to moulds is known to cause a variety of health effects in some people. Many fungal spores are considered to be allergenic to susceptible persons, though individual susceptibility varies greatly.

Elevated levels of indoor mould are usually attributed to the chronic moist conditions due to water leaks, floods or elevated humidity. Under these conditions, already low levels of fungal spores in air from plants and other sources may multiply on cellulose containing materials such as carpets, wallboards, and wood, and result in mould contamination and, if left untreated, can be destructive to certain building materials.

Currently, no Canadian regulations govern the presence of mould and/or water-damaged materials in the workplace environment. However, the Health Canada document "Fungal

Contamination in Public Buildings: Health Effects and Investigation Methodology” (2004) concludes that current knowledge supports the need to prevent damp conditions and mould growth and remediate any fungal growth and/or contamination in buildings.

Therefore, the presence of mould growth, mould-contaminated materials and/or water-damaged materials in the occupied environment is interpreted as a failure of Health Canada guidelines for microbial contamination in indoor environments, and as such, requires remedial action.

The MOL issued a document titled “Alert: Mould in Workplace Buildings.” This document explains the MOL’s position with respect to the presence of mould in workplace buildings.

The Environmental Abatement Council of Canada (EACC) has provided guidelines regarding investigation and remediation works Mould Abatement Guidelines Edition 3 (2015). Mould Guidelines for the EACC to protect the health of workers who may be exposed to mould during building renovations.

3.14.1 Findings

During the visual inspection of the surveyed areas, visible mould growth and water staining on non-ACM ceiling tiles were observed in the following locations: Corridor, B-008, Lounge 2-020, Lounge 3-046 and Lounge 4-046.

3.14.2 Recommendations

Removal of the mould-impacted building materials should be conducted as a Level 1 Mould Remediation Operations, based on EACC guidelines. Following abatement, the source of water ingress should be determined and addressed to prevent potential future fungal amplification.

4. CORRECTIVE ACTIONS

Fisher Engineering Limited communicated the reported deficiencies and recommendations for corrective actions to the City of Toronto. These activities have been completed and an Addendum was made to this report to confirm completion of the corrective actions. Details of the abatement work can be found in the Corrective Actions Inspection Report (Project No. FE 23-13254), which are provided in Appendix V.

Fisher Engineering Limited believes that all recommendations made as a result of the findings of the reassessment survey have been addressed.

5. STATEMENT OF LIMITATIONS

Fisher Engineering Limited accepts responsibility for the competent performance of its duties in executing this assignment within the normal standards of the profession, but disclaims responsibility for consequential damages, if any.

The extent of the building survey of designated substances and hazardous materials is based on prior agreement of the scope of work with the client, and the rationale given in this report. The building survey findings rely on professional interpretation of selective sampling

and analysis. Sample analysis results have been applied to homogenous materials in unsampled locations; it was not within the scope of work to carry out an exhaustive sampling and analysis program. For non-accessible building spaces, the likelihood of the presence or absence of asbestos and other designated substances has been described, but such assessment is not a definitive statement of presence or absence.

This report was prepared for the City of Toronto, Corporate Real Estate Management. The scope of services performed may not be appropriate for the purposes of other users, and any use or reuse of this document or its findings or recommendations represented herein is at the sole risk of any other user.

We trust that the information provided in the report meets your current requirements. If you have any questions or concerns, please do not hesitate to contact the undersigned.

6. SIGN-OFF

We trust that this report meets with City of Toronto requirements and we thank you for the opportunity to be of service. Should you have any questions, please do not hesitate to contact us.

Fisher Engineering Limited

Prepared By:



Renata Stec, M.Sc.
Project Manager

Reviewed By:



David Fisher, P. Eng., C. Chem.
Principal

APPENDIX I

DESIGNATED SUBSTANCES AND HAZARDOUS MATERIALS INVENTORY SHEET

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Building Address:	9 Neilson Road, Toronto, ON	Date(s) of Current Reassessment:	May 25, 2023
Building Name:	Seven Oaks	Organization Completing Reassessment:	Fisher Engineering Limited / Project FE 23-12800
Original Survey Conducted By:	Fisher Environmental Ltd.	Name of Surveyor:	Renata Stec
Date(s) of Original Survey:	April 29, 2015	Signature of Surveyor:	

Summary of Findings
All Hazardous materials were found in GOOD condition.

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
0-00	Exterior	Roof	Roofing Material	Asbestos	Not Sampled	ACM Assumed	33000 SF	Good	
0-00	Exterior	Windows	Window Caulking	Asbestos	Not Sampled	ACM Assumed	All	Good	
0-00	Exterior	Walls	Masonry	N/A	N/A	N/A	N/A	N/A	
0-00	Exterior	Door	Door Caulking	Asbestos	17-7482-22 to 24*	None Detected	N/A	N/A	White *From Fisher Project No. 17-8486, dated Nov. 2017
0-00	Exterior	Door	Door Caulking	Asbestos	17-7482-25 to 27*	None Detected	N/A	N/A	Green *From Fisher Project No. 17-8486, dated Nov. 2017
B-001	Corridor	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
B-001	Corridor	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	
B-001	Corridor	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-001	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
B-001	Corridor	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure
B-002	Generator Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-002	Generator Room	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
B-002	Generator Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-003	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-003	Electrical Room	Walls	Block / Concrete	N/A	N/A	N/A	N/A	N/A	
B-003	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-004	Telephone Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-004	Telephone Room	Walls	Block / Concrete	N/A	N/A	N/A	N/A	N/A	
B-004	Telephone Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-005	Mechanical Room	Floor	Vinyl Floor Tile 2	Asbestos	16-3752-02a to 04a*	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears *From Fisher Project No. 16-7701, dated April 2016
B-005	Mechanical Room	Floor	Mastic	Asbestos	16-3752-02b to 04b*	None Detected	N/A	N/A	*From Fisher Project No. 16-7701, dated April 2016
B-005	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-005	Mechanical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-005	Mechanical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-006	Pump Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-006	Pump Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-006	Pump Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-007	Elevator Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-007	Elevator Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-007	Elevator Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
B-008	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
B-008	Corridor	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	720 SF	Good	
B-008	Corridor	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-008	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
B-009	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-009	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	225 SF	Good	
B-009	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	45 SF	Good	
B-010	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-010	Mechanical Room	Walls	Block / Concrete	N/A	N/A	N/A	N/A	N/A	
B-010	Mechanical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-011	Office	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
B-011	Office	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-011	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
B-012	Storage	Floor	Vinyl Sheet Flooring 15	Asbestos	Not Sampled	ACM Assumed	360 SF	Good	Yellow Striped
B-012	Storage	Walls	Block / Concrete	N/A	N/A	N/A	N/A	N/A	
B-012	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-013	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-013	Storage	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
B-013	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-014	Mechanical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-014	Mechanical Room	Walls	Block / Concrete	N/A	N/A	N/A	N/A	N/A	
B-014	Mechanical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-015	Cold Storage	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	260 SF	Good	Beige with Black Dots
B-015	Cold Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-015	Cold Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-016	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
B-016	Storage	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	270 SF	Good	
B-016	Storage	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
B-017	Kitchen	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
B-017	Kitchen	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue NOT OBSERVED
B-017	Kitchen	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
B-017	Kitchen	Ceiling	Drywall (DJC)	Asbestos	19-3375-1 to 3*	None Detected	N/A	N/A	*From Fisher Project No. 19-9829, dated Oct. 2019
B-018	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
B-018	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-018	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-019	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	NO ACCESS 12" x 12" Beige with Grey and White Smears
B-019	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-019	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-020	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-020	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-020	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-021	Female Locker Room	Floor	Vinyl Sheet Flooring 5	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Green with Black Dots
B-021	Female Locker Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
B-021	Female Locker Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-021	Female Locker Room	Ceiling	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	180 SF	Good	
B-022	Male Locker Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-022	Male Locker Room	Floor	Vinyl Sheet Flooring 5	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	Green with Black Dots
B-022	Male Locker Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-022	Male Locker Room	Walls	Paint - Pink	Lead	17-6463-04*	<10 ppm	N/A	N/A	*From Fisher Project No. 17-8181, dated Sep. 2017
B-022	Male Locker Room	Ceiling	Drywall (DJC)	Asbestos	17-6718-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 17-8181, dated Sep. 2017
B-022	Male Locker Room	Ceiling	Paint - Cream	Lead	17-6718-04*	<10 ppm	N/A	N/A	*From Fisher Project No. 17-8181, dated Sep. 2017
B-023	Maintenance Room	Floor	Vinyl Floor Tile 10	Asbestos	Not Sampled	ACM Assumed	520 SF	Good	12" x12" Light Beige with White Specks
B-023	Maintenance Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-023	Maintenance Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-024	Nurse's Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-024	Nurse's Storage	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
B-024	Nurse's Storage	Walls	Paint - Beige	Lead	16-3752-01*	<10 ppm	N/A	N/A	*From Fisher Project No. 16-7701, dated April 2016
B-024	Nurse's Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-025	Housekeeping Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-025	Housekeeping Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-025	Housekeeping Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-026	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-026	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-026	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-027	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-027	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
B-027	Storage	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	385 SF	Good	
B-027	Storage	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
B-028	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
B-028	Storage	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	350 SF	Good	
B-028	Storage	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
B-029	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
B-029	Storage	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	385 SF	Good	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
B-029	Storage	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
B-030	Stairs #5	Floor	Vinyl Floor Tile 10	Asbestos	Not Sampled	ACM Assumed	100 SF	Good	12" x12" Light Beige with White Specks
B-030	Stairs #5	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears NOT OBSERVED
B-030	Stairs #5	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-030	Stairs #5	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-031	Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	NO ACCESS
B-031	Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-031	Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-032	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-032	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-032	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
B-033	Elevator Machine Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
B-033	Elevator Machine Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
B-033	Elevator Machine Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
B-034	Storage	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	260 SF	Good	Beige with Black Dots
B-034	Storage	Walls	Drywall (DJC)	Asbestos	Not Sampled	ACM Assumed	270 SF	Good	
B-034	Storage	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-001	Lobby	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
1-001	Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-001	Lobby	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-001	Lobby	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-002	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
1-002	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-002	Corridor	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-002	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-003	Holding Area	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-003	Holding Area	Walls	Block / Concrete	N/A	N/A	N/A	N/A	N/A	
1-003	Holding Area	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-004	Office	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-004	Office	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-004	Office	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-005	Loading Dock	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-005	Loading Dock	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-005	Loading Dock	Walls	Block / Concrete	N/A	N/A	N/A	N/A	N/A	
1-005	Loading Dock	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-006	Garbage Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-006	Garbage Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-006	Garbage Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-006	Garbage Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-007	Linen Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
1-007	Linen Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-007	Linen Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-008	Morgue	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-008	Morgue	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-008	Morgue	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-009	Flammable Storage	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-009	Flammable Storage	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-009	Flammable Storage	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-010	Linen Storage	Floor	Vinyl Floor Tile 2	Asbestos	17-7564-01 and 02*	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears *From Fisher Project No. 17-8527, dated Nov., 2017
1-010	Linen Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-010	Linen Storage	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-011	Utility Room	Floor	Vinyl Floor Tile 2	Asbestos	17-7564-03*	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears *From Fisher Project No. 17-8527, dated Nov., 2017

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-011	Utility Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-011	Utility Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-011	Utility Room	Ceiling	Ceiling Tile 1	Asbestos	17-6463-01 to 03*	None Detected	N/A	N/A	2' x 2' Small Pinhole *From Fisher Project No.17-8181, dated Sep. 2017
1-012	Stairs #3	Floor	Vinyl Floor Tile 3	Asbestos	Not Sampled	ACM Assumed	1000 SF	Good	12" x 12" Pink Mosaic
1-012	Stairs #3	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-012	Stairs #3	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-013	Vestibule	Floor	Vinyl Floor Tile 9	Asbestos	Not Sampled	ACM Assumed	35 SF	Good	12"x12" Pink With Brown and White Smears
1-013	Vestibule	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears NOT OBSERVED
1-013	Vestibule	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-013	Vestibule	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-014	Washroom	Floor	Vinyl Sheet Flooring 16	Asbestos	Not Sampled	ACM Assumed	165 SF	Good	Beige with Mosaic Design
1-014	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-014	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-015	Male Locker Room	Floor	Vinyl Floor Tile 9	Asbestos	Not Sampled	ACM Assumed	35 SF	Good	12"x12" Pink With Brown and White Smears
1-015	Male Locker Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears NOT OBSERVED
1-015	Male Locker Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-015	Male Locker Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-016	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-016	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-016	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-017	Soiled Linen	Floor	Vinyl Floor Tile 9	Asbestos	Not Sampled	ACM Assumed	190 SF	Good	12"x12" Pink With Brown and White Smears
1-017	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-017	Soiled Linen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-018	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-018	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-018	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-019	Vestibule	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
1-019	Vestibule	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-019	Vestibule	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-020	Female Locker Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
1-020	Female Locker Room	Floor	Vinyl Floor Tile 9	Asbestos	Not Sampled	ACM Assumed	290 SF	Good	12"x12" Pink With Brown and White Smears
1-020	Female Locker Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-020	Female Locker Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-021	Washroom	Floor	Vinyl Sheet Flooring 5	Asbestos	Not Sampled	ACM Assumed	165 SF	Good	Green with Black Dots
1-021	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-021	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-022	Female Locker Room	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
1-022	Female Locker Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-022	Female Locker Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-023	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
1-023	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-023	Storage	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-024	Corridor	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
1-024	Corridor	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-024	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-025	Soiled Linen	Floor	Vinyl Sheet Flooring 17	Asbestos	Not Sampled	ACM Assumed	65 SF	Good	Beige with Black Dots

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-025	Soiled Linen	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears NOT OBSERVED
1-025	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-025	Soiled Linen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-026	Activity Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	500 SF	Good	Grey with Orange Smears
1-026	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-026	Activity Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-026	Activity Room	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-026	Activity Room	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure
1-027	Accessible Washroom	Floor	Vinyl Sheet Flooring 5	Asbestos	Not Sampled	ACM Assumed	35 SF	Good	Green with Black Dots
1-027	Accessible Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-027	Accessible Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-028	Accessible Washroom	Floor	Vinyl Sheet Flooring 5	Asbestos	Not Sampled	ACM Assumed	35 SF	Good	Green with Black Dots
1-028	Accessible Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-028	Accessible Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-029	Med. Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-029	Med. Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-029	Med. Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-030	Nurse's Station	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-030	Nurse's Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-030	Nurse's Station	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-031	Waiting Area	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-031	Waiting Area	Walls	Drywall (DJC)	Asbestos	17-7482-04 and 05*	None Detected	N/A	N/A	*From Fisher Project No.17-8486, dated Nov. 2017
1-031	Waiting Area	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-032	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-032	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-032	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-033	Conference Room	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-033	Conference Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-033	Conference Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-034	Room 130 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-034	Room 130 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-034	Room 130 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-034	Room 130 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-034	Room 130 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-035	Room 129 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-035	Room 129 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-035	Room 129 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-035	Room 129 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-035	Room 129 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-036	Room 128 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-036	Room 128 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-036	Room 128 & Washroom	Walls	Drywall (DJC)	Asbestos	17-7482-06 to 08*	None Detected	N/A	N/A	*From Fisher Project No.17-8486, dated Nov. 2017
1-036	Room 128 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-036	Room 128 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-037	Room 127 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-037	Room 127 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-037	Room 127 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-037	Room 127 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-037	Room 127 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-038	Room 126 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-038	Room 126 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-038	Room 126 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-038	Room 126 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-038	Room 126 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-039	Room 125	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-039	Room 125	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-039	Room 125	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-040	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-040	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-040	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-041	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-041	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-041	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-042	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-042	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-042	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-043	Room 124 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-043	Room 124 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-043	Room 124 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-043	Room 124 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-043	Room 124 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-044	Room 123 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-044	Room 123 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-044	Room 123 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-044	Room 123 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-044	Room 123 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-045	Room 122 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-045	Room 122 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-045	Room 122 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-045	Room 122 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-045	Room 122 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-046	Room 121	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-046	Room 121	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-046	Room 121	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-046	Room 121	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-047	Room 120 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-047	Room 120 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-047	Room 120 & Washroom	Walls	Drywall (DJC)	Asbestos	19-2833-10*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
1-047	Room 120 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-047	Room 120 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-048	Room 119 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-048	Room 119 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-048	Room 119 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-048	Room 119 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-048	Room 119 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-049	Room 118 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-049	Room 118 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-049	Room 118 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-049	Room 118 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-049	Room 118 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-050	Room 117 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-050	Room 117 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-050	Room 117 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-050	Room 117 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-050	Room 117 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-051	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-051	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-051	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-052	Tub Room	Floor	Vinyl Sheet Flooring 3	Asbestos	19-2833-04 to 06*	None Detected	N/A	N/A	Blue *From Fisher Project No. 19-9595, dated July 2019
1-052	Tub Room	Walls	Drywall (DJC)	Asbestos	19-2833-12*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
1-052	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-053	Washroom	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 19-2833-07 to 09	None Detected	N/A	N/A	Grey
1-053	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-053	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-054	Shower Room	Floor	Vinyl Sheet Flooring 21	Asbestos	19-2833-07 to 09*	None Detected	N/A	N/A	Grey *From Fisher Project No. 19-9595, dated July 2019
1-054	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-054	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-054	Shower Room	Walls	Paint - Peach	Lead	19-2833-32*	<10 ppm	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
1-054	Shower Room	Walls	Paint - Yellow	Lead	19-2833-33*	<10 ppm	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
1-054	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-055	Stairs #2	Floor	Vinyl Floor Tile 3	Asbestos	Not Sampled	ACM Assumed	1000 SF	Good	12" x 12" Pink Mosaic
1-055	Stairs #2	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-055	Stairs #2	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-056	Social Support	Floor	Hardwood	N/A	N/A	N/A	N/A	N/A	
1-056	Social Support	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-056	Social Support	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-057	Office	Floor	Hardwood	N/A	N/A	N/A	N/A	N/A	
1-057	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-057	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-058	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-058	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-058	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-059	Room 114	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-059	Room 114	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-059	Room 114	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-059	Room 114	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-060	Room 113 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-060	Room 113 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-060	Room 113 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-060	Room 113 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-060	Room 113 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-061	Room 112 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-061	Room 112 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-061	Room 112 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-061	Room 112 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-061	Room 112 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-062	Room 111 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-062	Room 111 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-062	Room 111 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-062	Room 111 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-062	Room 111 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-063	Room 110 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-063	Room 110 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-063	Room 110 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-063	Room 110 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-063	Room 110 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-064	Room 109 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-064	Room 109 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-064	Room 109 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-064	Room 109 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-064	Room 109 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-065	Room 108	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-065	Room 108	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-065	Room 108	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-065	Room 108	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-066	Room 107 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-066	Room 107 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-066	Room 107 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-066	Room 107 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-066	Room 107 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-067	Room 106 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-067	Room 106 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-067	Room 106 & Washroom	Walls	Drywall (DJC)	Asbestos	19-2833-11*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
1-067	Room 106 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-067	Room 106 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-068	Room 105 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-068	Room 105 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-068	Room 105 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-068	Room 105 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-068	Room 105 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-069	Room 104	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-069	Room 104	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-069	Room 104	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-069	Room 104	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-070	Room 103 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-070	Room 103 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-070	Room 103 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-070	Room 103 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-070	Room 103 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-071	Stairs #1	Floor	Vinyl Floor Tile 3	Asbestos	Not Sampled	ACM Assumed	1000 SF	Good	12" x 12" Pink Mosaic
1-071	Stairs #1	Walls	Drywall (DJC)	Asbestos	18-8489-07 to 09*	None Detected	N/A	N/A	*From Fisher Project No. 18-8763, dated April 2018
1-071	Stairs #1	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-072	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-072	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-072	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-073	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-073	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-073	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-074	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-074	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-074	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
1-075	Clean Linen	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-075	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-075	Clean Linen	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-076	Staff Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-076	Staff Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic NOT OBSERVED
1-076	Staff Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-076	Staff Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-077	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-077	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-077	Storage	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-078	Tub Room	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
1-078	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-078	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-079	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
1-079	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-079	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-080	Shower Room	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 19-2833-07 to 09	None Detected	N/A	N/A	Grey
1-080	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-080	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-080	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-081	Dining Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
1-081	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-081	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-082	Servery	Floor	Vinyl Sheet Flooring 18	Asbestos	Not Sampled	ACM Assumed	140 SF	Good	White with Black Dots
1-082	Servery	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-082	Servery	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-082	Servery	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-083	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic NOT OBSERVED
1-083	Corridor	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
1-083	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-083	Corridor	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-084	Dish Wash	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
1-084	Dish Wash	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-084	Dish Wash	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-085	Staff Lunch Room	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	600 SF	Good	Grey with Orange Smears
1-085	Staff Lunch Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-085	Staff Lunch Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-085	Staff Lunch Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-086	Elevator Lobby	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-086	Elevator Lobby	Walls	Brick	N/A	N/A	N/A	N/A	N/A	
1-086	Elevator Lobby	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 16-3752-08 to 10	None Detected	N/A	N/A	2' x 2' Inlay NOT OBSERVED
1-086	Elevator Lobby	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-086	Elevator Lobby	Ceiling	Spray On Fireproofing	Asbestos	Homogeneous w/ 15-1633-1 to 5	None Detected	N/A	N/A	
1-087	Stairs #4	Floor	Vinyl Floor Tile 5	Asbestos	Not Sampled	ACM Assumed	320 SF	Good	12" x 12" Light Grey Mosaic
1-087	Stairs #4	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-087	Stairs #4	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-088	Beauty Salon	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	350 SF	Good	Grey with Orange Smears
1-088	Beauty Salon	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-088	Beauty Salon	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-089	Interfaith Chapel	Floor	Vinyl Sheet Flooring 7	Asbestos	Not Sampled	ACM Assumed	380 SF	Good	Teal

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-089	Interfaith Chapel	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	1150 SF	Good	Teal with White and Taupe Smears
1-089	Interfaith Chapel	Walls	Drywall (DJC)	Asbestos	19-2833-13 and 14*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
1-089	Interfaith Chapel	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-089	Interfaith Chapel	Ceiling	Spray On Fireproofing	Asbestos	19-2833-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
1-089	Interfaith Chapel	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-090	Vestry	Floor	Vinyl Floor Tile 6	Asbestos	Not Sampled	ACM Assumed	65 SF	Good	NO ACCESS 12" x 12" Dark Grey with Black Specks
1-090	Vestry	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-090	Vestry	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-091	Storage	Floor	Vinyl Floor Tile 7	Asbestos	Not Sampled	ACM Assumed	70 SF	Good	12" x 12" Beige with Brown Smears
1-091	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-091	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-092	Auditorium	Floor	Vinyl Sheet Flooring 7	Asbestos	Not Sampled	ACM Assumed	550 SF	Good	Teal
1-092	Auditorium	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	1000 SF	Good	Teal with White and Taupe Smears
1-092	Auditorium	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-092	Auditorium	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-092	Auditorium	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-093	Storage	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-093	Storage	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears Under Carpet
1-093	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-093	Storage	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-094	Servery	Floor	Vinyl Sheet Flooring 8	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Teal with White and Taupe Smears
1-094	Servery	Floor	Vinyl Floor Tile 2	Asbestos	Homogeneous w/ 17-7564-01 to 03	None Detected	N/A	N/A	12" x 12" Beige with Grey and White Smears
1-094	Servery	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-094	Servery	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-094	Servery	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-095	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-095	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-095	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-096	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
1-096	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-096	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-097	Corridor	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-097	Corridor	Walls	Brick	N/A	N/A	N/A	N/A	N/A	
1-097	Corridor	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-097	Corridor	Ceiling	Ceiling Tile 5	Asbestos	Homogeneous w/ 16-3752-08 to 10	None Detected	N/A	N/A	2' x 2' Inlay
1-097	Corridor	Ceiling	Spray On Fireproofing	Asbestos	15-1633-1 to 5*	None Detected	N/A	N/A	Above Ceiling Tile *From Fisher Project No.15-7261, dated July 2015
1-098	Staff Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	305 SF	Good	Grey with Orange Smears
1-098	Staff Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-098	Staff Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-099	Staff Lounge	Floor	Vinyl Sheet Flooring 6	Asbestos	Not Sampled	ACM Assumed	295 SF	Good	Grey with Orange Smears
1-099	Staff Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-099	Staff Lounge	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-100	Oak Room Pub	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-100	Oak Room Pub	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-100	Oak Room Pub	Walls	Brick	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-100	Oak Room Pub	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-101	Washroom	Floor	Vinyl Sheet Flooring 5	Asbestos	Not Sampled	ACM Assumed	180 SF	Good	Green with Black Dots
1-101	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-101	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-102	Washroom	Floor	Vinyl Sheet Flooring 5	Asbestos	Not Sampled	ACM Assumed	180 SF	Good	Green with Black Dots
1-102	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-102	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-103	Teaching Room	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-103	Teaching Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-103	Teaching Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-104	Office	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-104	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-104	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-105	Office	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-105	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-105	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-106	Office	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-106	Office	Walls	Drywall (DJC)	Asbestos	16-3752-11*	None Detected	N/A	N/A	*From Fisher Project No. 16-7701, dated April 2016
1-106	Office	Ceiling	Ceiling Tile 2	Asbestos	16-3752-05 to 07*	None Detected	N/A	N/A	2' x 4' Small Pinhole *From Fisher Project No. 16-7701, dated April 2016
1-107	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-107	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-107	Electrical Room	Ceiling	Spray On Fireproofing	Asbestos	Homogeneous w/ 15-1633-1 to 5	None Detected	N/A	N/A	
1-108	Main Lobby	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-108	Main Lobby	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-108	Main Lobby	Walls	Brick / Glass	N/A	N/A	N/A	N/A	N/A	
1-108	Main Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-108	Main Lobby	Ceiling	Glass	N/A	N/A	N/A	N/A	N/A	
1-108	Main Lobby	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-109	Gift Shop	Floor	Vinyl Sheet Flooring 13	Asbestos	Not Sampled	ACM Assumed	325 SF	Good	Grey with Black, White & Brown Streaks
1-109	Gift Shop	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-109	Gift Shop	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
1-109	Gift Shop	Ceiling	Ceiling Tile 5	Asbestos	16-3752-08 to 10*	None Detected	N/A	N/A	2' x 2' Inlay *From Fisher Project No. 16-7701, dated April 2016
1-110	Gift Shop Storage	Floor	Vinyl Floor Tile 8	Asbestos	Not Sampled	ACM Assumed	105 SF	Good	12" x 12" Pink with Grey Smears
1-110	Gift Shop Storage	Walls	Drywall (DJC)	Asbestos	16-3752-12*	None Detected	N/A	N/A	*From Fisher Project No. 16-7701, dated April 2016
1-110	Gift Shop Storage	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-110	Gift Shop Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-111	Volunteer Services	Floor	Vinyl Floor Tile 8	Asbestos	Not Sampled	ACM Assumed	260 SF	Good	12" x 12" Pink with Grey Smears
1-111	Volunteer Services	Walls	Drywall (DJC)	Asbestos	16-3752-13*	None Detected	N/A	N/A	*From Fisher Project No. 16-7701, dated April 2016
1-111	Volunteer Services	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-112	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-112	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-112	Office	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-113	Entrance	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-113	Entrance	Walls	Glass	N/A	N/A	N/A	N/A	N/A	
1-113	Entrance	Ceiling	Metal Grid	N/A	N/A	N/A	N/A	N/A	
1-114	Reception	Floor	Vinyl Sheet Flooring 24	Asbestos	Not Sampled	ACM Assumed	150 SF	Good	Parquet Pattern
1-114	Reception	Walls	Brick	N/A	N/A	N/A	N/A	N/A	
1-114	Reception	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-114	Reception	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-115	Vestibule	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-115	Vestibule	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-115	Vestibule	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-116	Meeting Room	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-116	Meeting Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-116	Meeting Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-117	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-117	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-117	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-118	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-118	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-118	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-119	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-119	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-119	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-120	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-120	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-120	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-121	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-121	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-121	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-122	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
1-122	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-122	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-123	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-123	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-123	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-124	File Storage	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-124	File Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-124	File Storage	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
1-125	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
1-125	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-125	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-126	Office	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-126	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-126	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-127	Copy Room	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-127	Copy Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-127	Copy Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-128	General Office	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
1-128	General Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-128	General Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-129	Corridor	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-129	Corridor	Walls	Brick	N/A	N/A	N/A	N/A	N/A	
1-129	Corridor	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
1-130	Telephone Room	Floor	Ceramic	N/A	N/A	N/A	N/A	N/A	
1-130	Telephone Room	Walls	Brick	N/A	N/A	N/A	N/A	N/A	
1-130	Telephone Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-131	Washroom	Floor	Vinyl Sheet Flooring 5	Asbestos	Not Sampled	ACM Assumed	35 SF	Good	NO ACCESS Green with Black Dots
1-131	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-131	Washroom	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-132	Washroom	Floor	Vinyl Sheet Flooring 5	Asbestos	Not Sampled	ACM Assumed	35 SF	Good	NO ACCESS Green with Black Dots
1-132	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-132	Washroom	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
1-133	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-133	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
1-133	Electrical Room	Ceiling	Spray On Fireproofing	Asbestos	Homogeneous w/ 15-1633-1 to 5	None Detected	N/A	N/A	
1-134	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
1-134	Janitor's Closet	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-04 to 08 & 16-3752-11 to 13	None Detected	N/A	N/A	
1-134	Janitor's Closet	Ceiling	Spray On Fireproofing	Asbestos	Homogeneous w/ 15-1633-1 to 5	None Detected	N/A	N/A	
2-001	Lobby	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	1150 SF	Good	Light Grey and Light Brown Design
2-001	Lobby	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic NOT OBSERVED
2-001	Lobby	Walls	Drywall (DJC)	Asbestos	16-3994-01,02*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
2-001	Lobby	Ceiling	Ceiling Tile 3	Asbestos	16-3994-08, 09*	None Detected	N/A	N/A	2' x 4' Pinhole Fissure *From Fisher Project No. 16-7778, dated May 2016
2-001	Lobby	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
2-002	Dining Room	Floor	Vinyl Sheet Flooring 10	Asbestos	Not Sampled	ACM Assumed	1600 SF	Good	Wood Design
2-002	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-002	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-002	Dining Room	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure NOT OBSERVED
2-003	Servery	Floor	Vinyl Sheet Flooring 11	Asbestos	19-3375-10*	None Detected	N/A	N/A	Off White with Black Dots *From Fisher Project No. 19-9829, dated Oct. 2019

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-003	Servery	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-003	Servery	Walls	Drywall (DJC)	Asbestos	19-3375-4*	None Detected	N/A	N/A	*From Fisher Project No. 19-9829, dated Oct. 2019
2-003	Servery	Ceiling	Drywall (DJC)	Asbestos	19-3375-5 to 6*	None Detected	N/A	N/A	*From Fisher Project No. 19-9829, dated Oct. 2019
2-003	Servery	Ceiling	Ceiling Tile 2	Asbestos	19-3375-7 to 9*	None Detected	N/A	N/A	2' x 4' Small Pinhole *From Fisher Project No. 19-9829, dated Oct. 2019
2-003	Servery	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-004	Room 203 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	19-2833-18 to 20*	None Detected	N/A	N/A	12" x 12" Beige Mosaic *From Fisher Project No. 19-9595, dated July 2019
2-004	Room 203 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-004	Room 203 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-004	Room 203 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-004	Room 203 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-005	Room 204 & Washroom	Floor	Vinyl Sheet Flooring 23	Asbestos	Not Sampled	ACM Assumed	220 SF	Good	Off-White with Grey Mosaic
2-005	Room 204 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic NOT OBSERVED
2-005	Room 204 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-005	Room 204 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-005	Room 204 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-005	Room 204 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-006	Room 205 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-006	Room 205 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-006	Room 205 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-006	Room 205 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-006	Room 205 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-007	Room 206 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-007	Room 206 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-007	Room 206 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-007	Room 206 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-007	Room 206 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-008	Room 207 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-008	Room 207 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-008	Room 207 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-008	Room 207 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-008	Room 207 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-009	Room 208	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-009	Room 208	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-009	Room 208	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-009	Room 208	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-010	Room 209 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-010	Room 209 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-010	Room 209 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-010	Room 209 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-010	Room 209 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-011	Room 210 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-011	Room 210 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-011	Room 210 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-011	Room 210 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-011	Room 210 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-012	Room 211 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-012	Room 211 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-012	Room 211 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-012	Room 211 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-012	Room 211 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-013	Room 212	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-013	Room 212	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-013	Room 212	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-013	Room 212	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-014	Room 213 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-014	Room 213 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-014	Room 213 & Washroom	Walls	Drywall (DJC)	Asbestos	19-2833-15*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
2-014	Room 213 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-014	Room 213 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-015	Room 214 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-015	Room 214 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-015	Room 214 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-015	Room 214 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-015	Room 214 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-016	Room 215 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-016	Room 215 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-016	Room 215 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-016	Room 215 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-016	Room 215 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-017	Room 216 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-017	Room 216 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-017	Room 216 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-017	Room 216 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-017	Room 216 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-018	Washroom	Floor	Vinyl Sheet Flooring 14	Asbestos	Not Sampled	ACM Assumed	50 SF	Good	Multi Coloured
2-018	Washroom	Walls	Drywall (DJC)	Asbestos	16-3994-03*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
2-018	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-019	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-019	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-019	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
2-020	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-020	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-020	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
2-020	Lounge	Ceiling	Ceiling Tile 3	Asbestos	16-3994-10*	None Detected	N/A	N/A	2' x 4' Pinhole Fissure *From Fisher Project No. 16-7778, dated May 2016
2-020	Lounge	Ceiling	Ceiling Tile 4	Asbestos	16-3994-11 to 13*	None Detected	N/A	N/A	2' x 4' Small Fissure *From Fisher Project No. 16-7778, dated May 2016
2-021	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-021	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
2-021	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-022	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-022	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
2-022	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2-023	Shower Room	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Light Green
2-023	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-023	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-023	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-024	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
2-024	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-024	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-025	Tub Room	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
2-025	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-025	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-026	Storage	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-026	Storage	Walls	Drywall (DJC)	Asbestos	16-3994-04*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
2-026	Storage	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
2-027	Clean Linen	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic NOT OBSERVED
2-027	Clean Linen	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	80 SF	Good	Light Grey and Light Brown Design
2-027	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-027	Clean Linen	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-028	Med. Room	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-028	Med. Room	Walls	Drywall (DJC)	Asbestos	16-3994-05*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
2-028	Med. Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-029	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-029	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-029	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
2-030	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-030	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-030	Lounge	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-031	Room 220 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-031	Room 220 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-031	Room 220 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-031	Room 220 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-031	Room 220 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-032	Room 221 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-032	Room 221 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-032	Room 221 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-032	Room 221 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-032	Room 221 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-033	Room 222 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-033	Room 222 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-033	Room 222 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-033	Room 222 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-033	Room 222 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-034	Room 223 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-034	Room 223 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-034	Room 223 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-034	Room 223 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-034	Room 223 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-035	Room 224 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-035	Room 224 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-035	Room 224 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-035	Room 224 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-035	Room 224 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-036	Room 225	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-036	Room 225	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-036	Room 225	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-036	Room 225	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-037	Room 226 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-037	Room 226 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-037	Room 226 & Washroom	Walls	Drywall (DJC)	Asbestos	19-2833-16*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
2-037	Room 226 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-037	Room 226 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-038	Room 227 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-038	Room 227 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-038	Room 227 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-038	Room 227 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-038	Room 227 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-039	Room 228 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-039	Room 228 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-039	Room 228 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-039	Room 228 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-039	Room 228 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-040	Room 229	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-040	Room 229	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-040	Room 229	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-040	Room 229	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-041	Room 230 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-041	Room 230 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-041	Room 230 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-041	Room 230 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-041	Room 230 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-042	Room 231 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-042	Room 231 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-042	Room 231 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-042	Room 231 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-042	Room 231 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-043	Room 232 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-043	Room 232 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-043	Room 232 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-043	Room 232 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-043	Room 232 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-044	Room 233 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-044	Room 233 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-044	Room 233 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-044	Room 233 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-044	Room 233 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-045	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-045	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-045	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
2-046	Tub Room	Floor	Vinyl Sheet Flooring 4	Asbestos	Not Sampled	ACM Assumed	180 SF	Good	Beige

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-046	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-046	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-047	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-047	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
2-047	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-048	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-048	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
2-048	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2-049	Shower Room	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Light Green
2-049	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-049	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-049	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-050	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
2-050	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-050	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-051	Tub Room	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
2-051	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-051	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-052	Social Support	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
2-052	Social Support	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-052	Social Support	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
2-053	Clean Linen	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	Light Grey and Light Brown Design
2-053	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-053	Clean Linen	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
2-054	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic NOT OBSERVED
2-054	Lounge	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	450 SF	Good	Light Grey and Light Brown Design
2-054	Lounge	Walls	Drywall (DJC)	Asbestos	16-3994-06*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-054	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
2-055	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-055	Washroom	Walls	Drywall (DJC)	Asbestos	16-3994-07*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
2-055	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-056	Room 237 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-056	Room 237 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-056	Room 237 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-056	Room 237 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-056	Room 237 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-057	Room 238 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-057	Room 238 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-057	Room 238 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-057	Room 238 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-057	Room 238 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-058	Room 239 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-058	Room 239 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-058	Room 239 & Washroom	Walls	Drywall (DJC)	Asbestos	19-2833-17*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
2-058	Room 239 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-058	Room 239 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-059	Room 240 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-059	Room 240 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-059	Room 240 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-059	Room 240 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-059	Room 240 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-060	Room 241 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-060	Room 241 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-060	Room 241 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-060	Room 241 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-060	Room 241 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-061	Room 242	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-061	Room 242	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-061	Room 242	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-062	Room 243 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-062	Room 243 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-062	Room 243 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-062	Room 243 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-062	Room 243 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-063	Room 244 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-063	Room 244 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-063	Room 244 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-063	Room 244 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-063	Room 244 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-064	Room 245 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-064	Room 245 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-064	Room 245 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-064	Room 245 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-064	Room 245 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-065	Room 246	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-065	Room 246	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-065	Room 246	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-065	Room 246	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-066	Room 247 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-066	Room 247 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-066	Room 247 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-066	Room 247 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-066	Room 247 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-067	Room 248 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-067	Room 248 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-067	Room 248 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-067	Room 248 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-067	Room 248 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-068	Room 249 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-068	Room 249 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-068	Room 249 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-068	Room 249 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-068	Room 249 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-069	Room 250 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-069	Room 250 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-069	Room 250 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-069	Room 250 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-069	Room 250 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
2-070	Activity Room	Floor	Vinyl Sheet Flooring 10	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	Wood Design
2-070	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-070	Activity Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
2-070	Activity Room	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-071	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-071	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-071	Corridor	Duct	Sealant	Asbestos	22-7883-3*	None Detected	N/A	N/A	Brown *From Fisher Project No. 22-11869, dated Jan. 2022
2-071	Corridor	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
2-071	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
2-072	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
2-072	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-072	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
2-073	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-073	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
2-073	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-074	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
2-074	Electrical Room	Floor	Firestop	Asbestos	22-7883-7*	None Detected	N/A	N/A	Tan *From Fisher Project No. 22-11869, dated Jan. 2022
2-074	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
2-074	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
2-075	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
2-075	Shower Room	Walls	Drywall (DJC)	Asbestos	21-5987-9*	None Detected	N/A	N/A	*From Fisher Project No. 21-10979, dated Feb.2021
2-075	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
2-075	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-076	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
2-076	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-076	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-077	Tub Room	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
2-077	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-077	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-078	Soiled Linen	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
2-078	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-078	Soiled Linen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-079	Laundry Room	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
2-079	Laundry Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-079	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-080	Nurse's Station	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic NOT OBSERVED
2-080	Nurse's Station	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	140 SF	Good	Light Grey and Light Brown Design

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
2-080	Nurse's Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-080	Nurse's Station	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
2-081	Med. Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic NOT OBSERVED
2-081	Med. Room	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	65 SF	Good	Light Grey and Light Brown Design
2-081	Med. Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-081	Med. Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-082	Med. Room	Floor	Vinyl Sheet Flooring 20	Asbestos	Not Sampled	ACM Assumed	65 SF	Good	NO ACCESS Light Grey and Light Brown Design
2-082	Med. Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
2-082	Med. Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3994-01 to 07	None Detected	N/A	N/A	
3-001	Lobby	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
3-001	Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-001	Lobby	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-001	Lobby	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole NOT OBSERVED
3-002	Dining Room	Floor	Vinyl Sheet Flooring 10	Asbestos	Not Sampled	ACM Assumed	1600 SF	Good	Wood Design
3-002	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-002	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-003	Servery	Floor	Vinyl Sheet Flooring 11	Asbestos	19-3375-11*	None Detected	N/A	N/A	Off White with Black Dots *From Fisher Project No. 19-9829, dated Oct. 2019
3-003	Servery	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-003	Servery	Walls	Drywall (DJC)	Asbestos	19-2833-21*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
3-003	Servery	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-004	Room 302 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-004	Room 302 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-004	Room 302 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-004	Room 302 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-004	Room 302 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-005	Room 303 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-005	Room 303 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-005	Room 303 & Washroom	Walls	Drywall (DJC)	Asbestos	17-7482-12 and 13*	None Detected	N/A	N/A	*From Fisher Project No. 17-8486, dated Nov. 2017
3-005	Room 303 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-005	Room 303 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	17-7482-29 and 30*	None Detected	N/A	N/A	2' x 2' Small Pinhole *From Fisher Project No.17-8486, dated Nov. 2017
3-006	Room 304 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-006	Room 304 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-006	Room 304 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-006	Room 304 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-006	Room 304 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-007	Room 305 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-007	Room 305 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-007	Room 305 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-007	Room 305 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-007	Room 305 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-008	Room 306 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-008	Room 306 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-008	Room 306 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-008	Room 306 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-008	Room 306 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-009	Room 307	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-009	Room 307	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-009	Room 307	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-010	Room 308 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-010	Room 308 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-010	Room 308 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-010	Room 308 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-010	Room 308 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-011	Room 309 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-011	Room 309 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-011	Room 309 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-011	Room 309 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-011	Room 309 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-012	Room 310 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-012	Room 310 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-012	Room 310 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-012	Room 310 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-012	Room 310 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-013	Room 311	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-013	Room 311	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-013	Room 311	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-013	Room 311	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-014	Room 312 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-014	Room 312 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-014	Room 312 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-014	Room 312 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-014	Room 312 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-015	Room 313 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-015	Room 313 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-015	Room 313 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-015	Room 313 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-015	Room 313 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-016	Room 314 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-016	Room 314 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-016	Room 314 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-016	Room 314 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-016	Room 314 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-017	Room 315 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-017	Room 315 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-017	Room 315 & Washroom	Walls	Drywall (DJC)	Asbestos	17-7482-09 to 11*	None Detected	N/A	N/A	*From Fisher Project No. 17-8486, dated Nov. 2017
3-017	Room 315 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-017	Room 315 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	17-7482-28*	None Detected	N/A	N/A	2' x 2' Small Pinhole *From Fisher Project No.17-8486, dated Nov. 2017
3-018	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-018	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-018	Lounge	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure
3-019	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-019	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-019	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-020	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	NO ACCESS 12" x 12" Beige Mosaic

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-020	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-020	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-020	Lounge	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-020	Lounge	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure
3-021	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
3-021	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
3-021	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-022	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
3-022	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
3-022	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
3-023	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
3-023	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-023	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-023	Shower Room	Ceiling	Drywall (DJC)	Asbestos	21-5987-8*	None Detected	N/A	N/A	*From Fisher Project No. 21-10979, dated Feb.2021
3-024	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
3-024	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-024	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-025	Tub Room	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
3-025	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-025	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-026	Equipment Storage	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
3-026	Equipment Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-026	Equipment Storage	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-027	File Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
3-027	File Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-027	File Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-028	Med. Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
3-028	Med. Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-028	Med. Room	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-028	Med. Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole NOT OBSERVED
3-029	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-029	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-029	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-030	Social Support	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
3-030	Social Support	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-030	Social Support	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-031	Room 328 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-031	Room 328 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-031	Room 328 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-031	Room 328 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-031	Room 328 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-032	Room 329 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-032	Room 329 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-032	Room 329 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-032	Room 329 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-032	Room 329 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-033	Room 330 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-033	Room 330 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-033	Room 330 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-033	Room 330 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-033	Room 330 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-034	Room 331 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-034	Room 331 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-034	Room 331 & Washroom	Walls	Drywall (DJC)	Asbestos	19-2833-22*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
3-034	Room 331 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-034	Room 331 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-035	Room 332 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-035	Room 332 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-035	Room 332 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-035	Room 332 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-035	Room 332 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-036	Room 333	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-036	Room 333	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-036	Room 333	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-037	Room 334 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-037	Room 334 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-037	Room 334 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-037	Room 334 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-037	Room 334 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-038	Room 335 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-038	Room 335 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-038	Room 335 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-038	Room 335 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-038	Room 335 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-039	Room 336 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-039	Room 336 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-039	Room 336 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-039	Room 336 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-039	Room 336 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-040	Room 337	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-040	Room 337	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-040	Room 337	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-040	Room 337	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-041	Room 338 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-041	Room 338 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-041	Room 338 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-041	Room 338 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-041	Room 338 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-042	Room 339 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-042	Room 339 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-042	Room 339 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-042	Room 339 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-042	Room 339 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-043	Room 340 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-043	Room 340 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-043	Room 340 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-043	Room 340 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-043	Room 340 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-044	Room 341 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-044	Room 341 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-044	Room 341 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-044	Room 341 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-044	Room 341 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-045	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-045	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-045	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-046	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-046	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-046	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-046	Lounge	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure
3-047	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
3-047	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
3-047	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-048	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
3-048	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
3-048	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-049	Shower Room	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Light Green
3-049	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-049	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-049	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-050	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
3-050	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-050	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-051	Tub Room	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
3-051	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-051	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-052	Rehab	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
3-052	Rehab	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-052	Rehab	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-052	Rehab	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole NOT OBSERVED
3-053	Clean Linen	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
3-053	Clean Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-053	Clean Linen	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-054	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-054	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-054	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-055	Physio	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-055	Physio	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-055	Physio	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-056	Room 352 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-056	Room 352 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-056	Room 352 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-056	Room 352 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-056	Room 352 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-057	Room 353 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-057	Room 353 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-057	Room 353 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-057	Room 353 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-057	Room 353 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-058	Room 354 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-058	Room 354 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-058	Room 354 & Washroom	Walls	Drywall (DJC)	Asbestos	19-2833-23*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
3-058	Room 354 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-058	Room 354 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-059	Room 355 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-059	Room 355 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-059	Room 355 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-059	Room 355 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-059	Room 355 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-060	Room 356 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-060	Room 356 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-060	Room 356 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-060	Room 356 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-060	Room 356 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-061	Room 357	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-061	Room 357	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-061	Room 357	Door	Paint - Red	Lead	19-2833-34*	14 ppm	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
3-061	Room 357	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-062	Room 358 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-062	Room 358 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-062	Room 358 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-062	Room 358 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-062	Room 358 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-063	Room 359 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-063	Room 359 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-063	Room 359 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-063	Room 359 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-063	Room 359 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-064	Room 360 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-064	Room 360 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-064	Room 360 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-064	Room 360 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-064	Room 360 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-065	Room 361	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-065	Room 361	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-065	Room 361	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-066	Room 362 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-066	Room 362 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-066	Room 362 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-066	Room 362 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-066	Room 362 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-067	Room 363 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-067	Room 363 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-067	Room 363 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-067	Room 363 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-067	Room 363 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-068	Room 364 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-068	Room 364 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-068	Room 364 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-068	Room 364 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-068	Room 364 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-069	Room 365 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-069	Room 365 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-069	Room 365 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-069	Room 365 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-069	Room 365 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-070	Activity Room	Floor	Vinyl Sheet Flooring 10	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	Wood Design

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-070	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-070	Activity Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
3-071	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-071	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-071	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-071	Corridor	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-072	Activity Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-072	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-072	Activity Room	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
3-073	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
3-073	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
3-073	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-074	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
3-074	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
3-074	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
3-075	Shower Room	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Light Green
3-075	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-075	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
3-075	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-076	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
3-076	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-076	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-077	Tub Room	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-077	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-077	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-078	Soiled Linen	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
3-078	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-078	Soiled Linen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-079	Laundry Room	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-079	Laundry Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-079	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-080	Washroom	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe NOT OBSERVED
3-080	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-080	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-080	Washroom	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-081	Washroom	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe NOT OBSERVED
3-081	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
3-081	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-081	Washroom	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-082	Nurse's Station	Floor	Vinyl Sheet Flooring 9	Asbestos	17-7482-21*	None Detected	N/A	N/A	Beige and Taupe *From Fisher Project No. 17-8486, dated Nov. 2017
3-082	Nurse's Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-082	Nurse's Station	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-083	Kitchette	Floor	Vinyl Sheet Flooring 10	Asbestos	Not Sampled	ACM Assumed	40 SF	Good	Wood Design
3-083	Kitchette	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-083	Kitchette	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
3-084	TV Lounge	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
3-084	TV Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-09 to 13 & 19-2833-21 to 23	None Detected	N/A	N/A	
3-084	TV Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
3-084	TV Lounge	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure
4-001	Lobby	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
4-001	Lobby	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-001	Lobby	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-002	Dining Room	Floor	Vinyl Sheet Flooring 10	Asbestos	Not Sampled	ACM Assumed	1600 SF	Good	Wood Design
4-002	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-002	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-003	Servery	Floor	Vinyl Sheet Flooring 11	Asbestos	19-3375-12*	None Detected	N/A	N/A	Off White with Black Dots *From Fisher Project No. 19-9829, dated Oct. 2019
4-003	Servery	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-003	Servery	Walls	Drywall (DJC)	Asbestos	19-3375-13*	None Detected	N/A	N/A	*From Fisher Project No. 19-9829, dated Oct. 2019
4-003	Servery	Ceiling	Drywall (DJC)	Asbestos	19-3375-14, 15*	None Detected	N/A	N/A	*From Fisher Project No. 19-9829, dated Oct. 2019
4-004	Room 402 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-004	Room 402 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-004	Room 402 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-004	Room 402 & Washroom	Ceiling	Drywall (DJC)	Asbestos	19-2833-27*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
4-004	Room 402 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-005	Room 403 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-005	Room 403 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-005	Room 403 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-005	Room 403 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-005	Room 403 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-006	Room 404 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-006	Room 404 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-006	Room 404 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-006	Room 404 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-006	Room 404 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-007	Room 405 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-007	Room 405 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-007	Room 405 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-007	Room 405 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-007	Room 405 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-008	Room 406 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-008	Room 406 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-008	Room 406 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-008	Room 406 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-008	Room 406 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-009	Room 407	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-009	Room 407	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-009	Room 407	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-010	Room 408 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-010	Room 408 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-010	Room 408 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-010	Room 408 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-010	Room 408 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-011	Room 409 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-011	Room 409 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-011	Room 409 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-011	Room 409 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-011	Room 409 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-012	Room 410 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-012	Room 410 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-012	Room 410 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-012	Room 410 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-012	Room 410 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-013	Room 411	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-013	Room 411	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-013	Room 411	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-014	Room 412 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-014	Room 412 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-014	Room 412 & Washroom	Walls	Drywall (DJC)	Asbestos	19-2833-24*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
4-014	Room 412 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-014	Room 412 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-015	Room 413 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-015	Room 413 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-015	Room 413 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-015	Room 413 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-015	Room 413 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-016	Room 414 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-016	Room 414 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-016	Room 414 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-016	Room 414 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-016	Room 414 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-017	Room 415 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-017	Room 415 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-017	Room 415 & Washroom	Walls	Drywall (DJC)	Asbestos	17-7482-17 and 18*	None Detected	N/A	N/A	*From Fisher Project No. 17-8486, dated Nov. 2017
4-017	Room 415 & Washroom	Door	Paint - Green	Lead	19-2833-35*	<10 ppm	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
4-017	Room 415 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-017	Room 415 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-018	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-018	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-018	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-019	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-019	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-019	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-020	Break Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-020	Break Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-020	Break Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-021	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-021	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
4-021	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-022	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-022	Electrical Room	Floor	Firestop	Asbestos	22-7883-8*	None Detected	N/A	N/A	Tan *From Fisher Project No. 22-11869, dated Jan. 2022
4-022	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
4-022	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
4-023	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-023	Shower Room	Walls	Drywall (DJC)	Asbestos	21-5987-6*	None Detected	N/A	N/A	*From Fisher Project No. 21-10979, dated Feb.2021
4-023	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-023	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-024	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
4-024	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-024	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-025	Tub Room	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
4-025	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-025	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-026	Equipment Storage	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
4-026	Equipment Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-026	Equipment Storage	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure
4-027	File Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
4-027	File Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-027	File Room	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure
4-028	Med. Room	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	NO ACCESS Beige and Taupe
4-028	Med. Room	Walls	Drywall (DJC)	Asbestos	17-7482-14 to 16*	None Detected	N/A	N/A	*From Fisher Project No. 17-8486, dated Nov. 2017
4-028	Med. Room	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure
4-029	Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-029	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-029	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-030	Social Support	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	
4-030	Social Support	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-030	Social Support	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-031	Room 428 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-031	Room 428 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-031	Room 428 & Washroom	Walls	Drywall (DJC)	Asbestos	19-2833-28*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
4-031	Room 428 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-031	Room 428 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-032	Room 429 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-032	Room 429 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-032	Room 429 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-032	Room 429 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-032	Room 429 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-033	Room 430 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-033	Room 430 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-033	Room 430 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-033	Room 430 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-033	Room 430 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-034	Room 431 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-034	Room 431 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-034	Room 431 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-034	Room 431 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-034	Room 431 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-035	Room 432 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-035	Room 432 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-035	Room 432 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-035	Room 432 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-035	Room 432 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-036	Room 433	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-036	Room 433	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-036	Room 433	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-037	Room 434 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-037	Room 434 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-037	Room 434 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-037	Room 434 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-037	Room 434 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-038	Room 435 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-038	Room 435 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-038	Room 435 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-038	Room 435 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-038	Room 435 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-039	Room 436 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-039	Room 436 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-039	Room 436 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-039	Room 436 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-039	Room 436 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-040	Room 437	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-040	Room 437	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-040	Room 437	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-041	Room 438 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-041	Room 438 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-041	Room 438 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-041	Room 438 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-041	Room 438 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-042	Room 439 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-042	Room 439 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-042	Room 439 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-042	Room 439 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-042	Room 439 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-043	Room 440 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-043	Room 440 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-043	Room 440 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-043	Room 440 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-043	Room 440 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-044	Room 441 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-044	Room 441 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-044	Room 441 & Washroom	Walls	Drywall (DJC)	Asbestos	19-2833-25*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-044	Room 441 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-044	Room 441 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-045	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-045	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-045	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-045	Corridor	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-046	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-046	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-046	Lounge	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-046	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-047	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-047	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
4-047	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-048	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-048	Electrical Room	Floor	Firestop	Asbestos	22-7883-6*	None Detected	N/A	N/A	Red *From Fisher Project No. 22-11869, dated Jan. 2022
4-048	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
4-048	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
4-049	Shower Room	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 19-2833-07 to 09	None Detected	N/A	N/A	Grey
4-049	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-049	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-049	Shower Room	Walls	Mastic	Asbestos	21-5987-3*	None Detected	N/A	N/A	*From Fisher Project No. 21-10979, dated Feb.2021
4-049	Shower Room	Ceiling	Drywall (DJC)	Asbestos	21-5987-7*	None Detected	N/A	N/A	*From Fisher Project No. 21-10979, dated Feb.2021
4-050	Washroom	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
4-050	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-050	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-051	Tub Room	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue NOT OBSERVED
4-051	Tub Room	Floor	Vinyl Sheet Flooring 21	Asbestos	Homogeneous w/ 19-2833-07 to 09	None Detected	N/A	N/A	Grey
4-051	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-051	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-052	Nurse's Storage	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
4-052	Nurse's Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-052	Nurse's Storage	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-052	Nurse's Storage	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure
4-053	Spiritual & Religious Care	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
4-053	Spiritual & Religious Care	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-053	Spiritual & Religious Care	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-054	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-054	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-054	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-055	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-055	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-055	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-055	Lounge	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure
4-056	Room 452 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-056	Room 452 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-056	Room 452 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-056	Room 452 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-056	Room 452 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-057	Room 453 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-057	Room 453 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-057	Room 453 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-057	Room 453 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-057	Room 453 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-058	Room 454 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-058	Room 454 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-058	Room 454 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-058	Room 454 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-058	Room 454 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-059	Room 455 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-059	Room 455 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-059	Room 455 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-059	Room 455 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-059	Room 455 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-060	Room 456 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-060	Room 456 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-060	Room 456 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-060	Room 456 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-060	Room 456 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-061	Room 457	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-061	Room 457	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-061	Room 457	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-061	Room 457	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-062	Room 458 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-062	Room 458 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-062	Room 458 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-062	Room 458 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-062	Room 458 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-063	Room 459 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-063	Room 459 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-063	Room 459 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-063	Room 459 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-063	Room 459 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-064	Room 460 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-064	Room 460 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-064	Room 460 & Washroom	Walls	Drywall (DJC)	Asbestos	19-2833-26*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
4-064	Room 460 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-064	Room 460 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-065	Room 461	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-065	Room 461	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-065	Room 461	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-066	Room 462 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-066	Room 462 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-066	Room 462 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-066	Room 462 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-066	Room 462 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-067	Room 463 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-067	Room 463 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-067	Room 463 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-067	Room 463 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-067	Room 463 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-068	Room 464 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-068	Room 464 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-068	Room 464 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-068	Room 464 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-068	Room 464 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-069	Room 465 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-069	Room 465 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-069	Room 465 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-069	Room 465 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-069	Room 465 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-070	Activity Room	Floor	Vinyl Sheet Flooring 10	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	Wood Design
4-070	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-070	Activity Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
4-070	Activity Room	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-071	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-071	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
4-071	Corridor	Duct	Sealant	Asbestos	22-7883-1, 2*	None Detected	N/A	N/A	Brown *From Fisher Project No. 22-11869, dated Jan. 2022
4-071	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-072	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
4-072	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-072	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-073	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-073	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
4-073	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-074	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
4-074	Electrical Room	Floor	Firestop	Asbestos	22-7883-4, 5*	None Detected	N/A	N/A	Red *From Fisher Project No. 22-11869, dated Jan. 2022
4-074	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
4-074	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
4-075	Shower Room	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Light Green
4-075	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-075	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
4-075	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-076	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
4-076	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-076	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-077	Tub Room	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
4-077	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-077	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-078	Soiled Linen	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
4-078	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-078	Soiled Linen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-079	Laundry Room	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
4-079	Laundry Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-079	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-080	Washroom	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
4-080	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-080	Washroom	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-081	Washroom	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
4-081	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-081	Washroom	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-082	Nurse's Station	Floor	Vinyl Sheet Flooring 9	Asbestos	17-7482-19 and 20*	None Detected	N/A	N/A	Beige and Taupe *From Fisher Project No. 17-8486, dated Nov. 2017
4-082	Nurse's Station	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-082	Nurse's Station	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-083	TV Lounge	Floor	Vinyl Sheet Flooring 9	Asbestos	Homogeneous w/ 17-7482-19 to 21	None Detected	N/A	N/A	Beige and Taupe
4-083	TV Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 17-7482-14 to 18 & 19-2833-24 to 28	None Detected	N/A	N/A	
4-083	TV Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
4-083	TV Lounge	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
4-083	TV Lounge	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure
5-001	Lobby	Floor	Vinyl Floor Tile 1	Asbestos	16-3993-08*	None Detected	N/A	N/A	12" x 12" Beige Mosaic *From Fisher Project No. 16-7778, dated May 2016 NOT OBSERVED
5-001	Lobby	Floor	Vinyl Sheet Flooring 22	Asbestos	Not Sampled	ACM Assumed	1150 SF	Good	Tan with Light Brown design
5-001	Lobby	Walls	Drywall (DJC)	Asbestos	16-3993-01*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
5-001	Lobby	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-001	Lobby	Ceiling	Ceiling Tile 2	Asbestos	16-3993-14 to 16*	None Detected	N/A	N/A	2' x 4' Small Pinhole *From Fisher Project No. 16-7778, dated May 2016 NOT OBSERVED
5-002	Dining Room	Floor	Vinyl Sheet Flooring 10	Asbestos	Not Sampled	ACM Assumed	1600 SF	Good	Wood Design
5-002	Dining Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-002	Dining Room	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-003	Servery	Floor	Vinyl Sheet Flooring 11	Asbestos	Homogeneous w/ 19-3375-10 to 12	None Detected	N/A	N/A	Off White with Black Dots
5-003	Servery	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-003	Servery	Walls	Drywall (DJC)	Asbestos	19-2833-30*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
5-003	Servery	Ceiling	Drywall (DJC)	Asbestos	19-3375-16 to 18*	None Detected	N/A	N/A	*From Fisher Project No. 19-9829, dated Oct. 2019
5-003	Servery	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-004	Room 502 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-004	Room 502 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-004	Room 502 & Washroom	Walls	Drywall (DJC)	Asbestos	19-2833-31*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
5-004	Room 502 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-004	Room 502 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-005	Room 503 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-005	Room 503 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-005	Room 503 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-005	Room 503 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-005	Room 503 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-006	Room 504 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-006	Room 504 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-006	Room 504 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-006	Room 504 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-006	Room 504 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-007	Room 505 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-007	Room 505 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-007	Room 505 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-007	Room 505 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-007	Room 505 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-008	Room 506 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-008	Room 506 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-008	Room 506 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-008	Room 506 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-008	Room 506 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-009	Room 507	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-009	Room 507	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-009	Room 507	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-010	Room 508 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-010	Room 508 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-010	Room 508 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-010	Room 508 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-010	Room 508 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-011	Room 509 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-011	Room 509 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-011	Room 509 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-011	Room 509 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-011	Room 509 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-012	Room 510 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-012	Room 510 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-012	Room 510 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-012	Room 510 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-012	Room 510 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-013	Room 511	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-013	Room 511	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-013	Room 511	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-014	Room 512 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-014	Room 512 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-014	Room 512 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-014	Room 512 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-014	Room 512 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-015	Room 513 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-015	Room 513 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-015	Room 513 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-015	Room 513 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-015	Room 513 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-016	Room 514 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-016	Room 514 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-016	Room 514 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-016	Room 514 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-016	Room 514 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-017	Room 515 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-017	Room 515 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-017	Room 515 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-017	Room 515 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-017	Room 515 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-018	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-018	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-018	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-019	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-019	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-019	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-020	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-020	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-020	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-021	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
5-021	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
5-021	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-022	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
5-022	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
5-022	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
5-023	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-023	Shower Room	Walls	Drywall (DJC)	Asbestos	21-5987-4*	None Detected	N/A	N/A	*From Fisher Project No. 21-10979, dated Feb.2021
5-023	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-023	Shower Room	Walls	Mastic	Asbestos	21-5987-1*	None Detected	N/A	N/A	*From Fisher Project No. 21-10979, dated Feb.2021
5-023	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-024	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
5-024	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-024	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-025	Tub Room	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
5-025	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-025	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-026	Reception	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	No Longer Exist. Merged with 5-027 12" x 12" Beige Mosaic NOT OBSERVED
5-026	Reception	Floor	Vinyl Sheet Flooring 22	Asbestos	Not Sampled	ACM Assumed	130 SF	Good	Tan with Light Brown design
5-026	Reception	Walls	Drywall (DJC)	Asbestos	16-3993-02*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
5-026	Reception	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-027	Nurse's Station	Floor	Vinyl Floor Tile 1	Asbestos	16-3993-09*	None Detected	N/A	N/A	12" x 12" Beige Mosaic *From Fisher Project No. 16-7778, dated May 2016 NOT OBSERVED
5-027	Nurse's Station	Floor	Vinyl Sheet Flooring 22	Asbestos	Not Sampled	ACM Assumed	130 SF	Good	Tan with Light Brown design

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-027	Nurse's Station	Walls	Drywall (DJC)	Asbestos	16-3993-03*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
5-027	Nurse's Station	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-027	Nurse's Station	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole NOT OBSERVED
5-028	Med. Room	Floor	Vinyl Sheet Flooring 22	Asbestos	Not Sampled	ACM Assumed	60 SF	Good	Tan with Light Brown design
5-028	Med. Room	Floor	Vinyl Sheet Flooring 1	Asbestos	16-3993-11 to 13*	None Detected	N/A	N/A	Yellow *From Fisher Project No. 16-7778, dated May 2016 NOT OBSERVED
5-028	Med. Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-028	Med. Room	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-028	Med. Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-029	Head Nurse Office	Floor	Vinyl Sheet Flooring 22	Asbestos	Not Sampled	ACM Assumed	130 SF	Good	Tan with Light Brown design
5-029	Head Nurse Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-029	Head Nurse Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-030	Supervisor's Office	Floor	Carpet	N/A	N/A	N/A	N/A	N/A	NO ACCESS
5-030	Supervisor's Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-030	Supervisor's Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-031	Room 528 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-031	Room 528 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-031	Room 528 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-031	Room 528 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-031	Room 528 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-032	Room 529 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-032	Room 529 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-032	Room 529 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-032	Room 529 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-032	Room 529 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-033	Room 530 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-033	Room 530 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-033	Room 530 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-033	Room 530 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-033	Room 530 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-034	Room 531 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-034	Room 531 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-034	Room 531 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-034	Room 531 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-034	Room 531 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-035	Room 532 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-035	Room 532 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-035	Room 532 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-035	Room 532 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-035	Room 532 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-036	Room 533	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-036	Room 533	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-036	Room 533	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-037	Room 534 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-037	Room 534 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-037	Room 534 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-037	Room 534 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-037	Room 534 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-038	Room 535 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-038	Room 535 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-038	Room 535 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-038	Room 535 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-038	Room 535 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-039	Room 536 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-039	Room 536 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-039	Room 536 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-039	Room 536 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-039	Room 536 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-040	Room 537	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-040	Room 537	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-040	Room 537	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-041	Room 538 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-041	Room 538 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-041	Room 538 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-041	Room 538 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-041	Room 538 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-042	Room 539 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-042	Room 539 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-042	Room 539 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-042	Room 539 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-042	Room 539 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-043	Room 540 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-043	Room 540 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-043	Room 540 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-043	Room 540 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-043	Room 540 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-044	Room 541 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-044	Room 541 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-044	Room 541 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-044	Room 541 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-044	Room 541 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-045	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-045	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-045	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-046	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-046	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-046	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-047	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
5-047	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
5-047	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-048	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
5-048	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
5-048	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
5-049	Shower Room	Floor	Vinyl Sheet Flooring 19	Asbestos	Not Sampled	ACM Assumed	75 SF	Good	Light Green
5-049	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-049	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-049	Shower Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-050	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
5-050	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-050	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-051	Storage	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
5-051	Storage	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-051	Storage	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-052	Conference Room	Floor	Laminate	N/A	N/A	N/A	N/A	N/A	
5-052	Conference Room	Walls	Drywall (DJC)	Asbestos	16-3993-04*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
5-052	Conference Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-053	Office	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	ROOM NO LONGER EXISTS 12" x 12" Beige Mosaic
5-053	Office	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-053	Office	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
5-054	Exam Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	ROOM NO LONGER EXISTS 12" x 12" Beige Mosaic
5-054	Exam Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-054	Exam Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-055	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	16-3993-10*	None Detected	N/A	N/A	12" x 12" Beige Mosaic *From Fisher Project No. 16-7778, dated May 2016 NOT OBSERVED
5-055	Lounge	Floor	Vinyl Sheet Flooring 22	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	Tan with Light Brown design
5-055	Lounge	Walls	Drywall (DJC)	Asbestos	16-3993-05*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
5-055	Lounge	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-055	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole NOT OBSERVED
5-056	Room 552 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-056	Room 552 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-056	Room 552 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-056	Room 552 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-056	Room 552 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-057	Room 553 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-057	Room 553 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-057	Room 553 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-057	Room 553 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-057	Room 553 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-058	Room 554 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-058	Room 554 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-058	Room 554 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-058	Room 554 & Washroom	Walls	Paint - Cream	Lead	19-2833-36*	<10 ppm	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
5-058	Room 554 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-058	Room 554 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-059	Room 555 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-059	Room 555 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-059	Room 555 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-059	Room 555 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-059	Room 555 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-060	Room 556 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-060	Room 556 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-060	Room 556 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-060	Room 556 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-060	Room 556 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-061	Room 557	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-061	Room 557	Walls	Drywall (DJC)	Asbestos	19-2833-29*	None Detected	N/A	N/A	*From Fisher Project No. 19-9595, dated July 2019
5-061	Room 557	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-062	Room 558 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-062	Room 558 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-062	Room 558 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-062	Room 558 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-062	Room 558 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-063	Room 559 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-063	Room 559 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-063	Room 559 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-063	Room 559 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-063	Room 559 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-064	Room 560 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-064	Room 560 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-064	Room 560 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-064	Room 560 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-064	Room 560 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-065	Room 561	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-065	Room 561	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-065	Room 561	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-066	Room 562 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-066	Room 562 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-066	Room 562 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-066	Room 562 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-066	Room 562 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-067	Room 563 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-067	Room 563 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-067	Room 563 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-067	Room 563 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-067	Room 563 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-068	Room 564 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-068	Room 564 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-068	Room 564 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-068	Room 564 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-068	Room 564 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-069	Room 565 & Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 19-2833-18 to 20	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-069	Room 565 & Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-069	Room 565 & Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-069	Room 565 & Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-069	Room 565 & Washroom	Ceiling	Ceiling Tile 1	Asbestos	Homogeneous w/ 17-7482-28 to 30	None Detected	N/A	N/A	2' x 2' Small Pinhole
5-070	Activity Room	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic NOT OBSERVED
5-070	Activity Room	Floor	Vinyl Sheet Flooring 10	Asbestos	Not Sampled	ACM Assumed	400 SF	Good	Wood Design
5-070	Activity Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-070	Activity Room	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-070	Activity Room	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-070	Activity Room	Ceiling	Ceiling Tile 4	Asbestos	Homogeneous w/ 16-3994-11 to 13	None Detected	N/A	N/A	2' x 4' Small Fissure

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

<i>Location Number</i>	<i>Location Name</i>	<i>Building System</i>	<i>Material Observed</i>	<i>Potential Hazardous Material</i>	<i>Sample ID</i>	<i>Analytical Result</i>	<i>Quantity</i>	<i>Condition</i>	<i>Notes/Required Action</i>
5-071	Corridor	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-071	Corridor	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-071	Corridor	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-071	Corridor	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-072	Lounge	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-072	Lounge	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-072	Lounge	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-073	Janitor's Closet	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
5-073	Janitor's Closet	Walls	Block	N/A	N/A	N/A	N/A	N/A	
5-073	Janitor's Closet	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-074	Electrical Room	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
5-074	Electrical Room	Walls	Block	N/A	N/A	N/A	N/A	N/A	
5-074	Electrical Room	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
5-075	Shower Room	Floor	Epoxy	N/A	N/A	N/A	N/A	N/A	
5-075	Shower Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-075	Shower Room	Walls	Ceramic	N/A	N/A	N/A	N/A	N/A	
5-075	Shower Room	Walls	Mastic	Asbestos	21-5987-2*	None Detected	N/A	N/A	*From Fisher Project No. 21-10979, dated Feb.2021
5-075	Shower Room	Ceiling	Drywall (DJC)	Asbestos	21-5987-5*	None Detected	N/A	N/A	*From Fisher Project No. 21-10979, dated Feb.2021
5-076	Washroom	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
5-076	Washroom	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-076	Washroom	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-077	Tub Room	Floor	Vinyl Sheet Flooring 3	Asbestos	Homogeneous w/ 19-2833-04 to 06	None Detected	N/A	N/A	Blue
5-077	Tub Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-077	Tub Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-078	Soiled Linen	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic
5-078	Soiled Linen	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-078	Soiled Linen	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	

APPENDIX I - Designated Substances and Hazardous Materials Inventory Sheet

Location Number	Location Name	Building System	Material Observed	Potential Hazardous Material	Sample ID	Analytical Result	Quantity	Condition	Notes/Required Action
5-079	Laundry Room	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-079	Laundry Room	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-079	Laundry Room	Ceiling	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-080	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-080	Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic NOT OBSERVED
5-080	Washroom	Walls	Drywall (DJC)	Asbestos	16-3993-06*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
5-080	Washroom	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-081	Washroom	Floor	Vinyl Sheet Flooring 1	Asbestos	Homogeneous w/ 16-3993-11 to 13	None Detected	N/A	N/A	Yellow
5-081	Washroom	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic NOT OBSERVED
5-081	Washroom	Walls	Drywall (DJC)	Asbestos	16-3993-07*	None Detected	N/A	N/A	*From Fisher Project No. 16-7778, dated May 2016
5-081	Washroom	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
5-082	Clean Utility	Floor	Vinyl Sheet Flooring 22	Asbestos	Not Sampled	ACM Assumed	200 SF	Good	Tan with Light Brown design
5-082	Clean Utility	Floor	Vinyl Floor Tile 1	Asbestos	Homogeneous w/ 16-3993-08 to 10	None Detected	N/A	N/A	12" x 12" Beige Mosaic NOT OBSERVED
5-082	Clean Utility	Walls	Drywall (DJC)	Asbestos	Homogeneous w/ 16-3993-01 to 07	None Detected	N/A	N/A	
5-082	Clean Utility	Ceiling	Ceiling Tile 3	Asbestos	Homogeneous w/ 16-3994-08 to 10	None Detected	N/A	N/A	2' x 4' Pinhole Fissure
5-082	Clean Utility	Ceiling	Ceiling Tile 2	Asbestos	Homogeneous w/ 16-3752-05 to 07	None Detected	N/A	N/A	2' x 4' Small Pinhole
PH-001	Elevator Lobby	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
PH-001	Elevator Lobby	Walls	Concrete	N/A	N/A	N/A	N/A	N/A	
PH-001	Elevator Lobby	Ceiling	Concrete	N/A	N/A	N/A	N/A	N/A	
PH-002	Penthouse	Floor	Concrete	N/A	N/A	N/A	N/A	N/A	
PH-002	Penthouse	Walls	Block / Concrete	N/A	N/A	N/A	N/A	N/A	
PH-002	Penthouse	Walls	Firestop	Asbestos	22-7883-9*	None Detected	N/A	N/A	Tan *From Fisher Project No. 22-11869, dated Jan. 2022
PH-002	Penthouse	Walls	Plaster	Asbestos	18-8489-01 to 03*	None Detected	N/A	N/A	*From Fisher Project No. 18-8763, dated April 2018
PH-002	Penthouse	Walls	Drywall (DJC)	Asbestos	22-7883-13 to 15*	None Detected	N/A	N/A	*From Fisher Project No. 22-11869, dated Jan. 2022
PH-002	Penthouse	Duct	Sealant	Asbestos	22-7883-10 to 12*	None Detected	N/A	N/A	Grey *From Fisher Project No. 22-11869, dated Jan. 2022
PH-002	Penthouse	Ceiling	Concrete / Metal	N/A	N/A	N/A	N/A	N/A	
PH-002	Penthouse	Other	Caulking	Asbestos	18-8489-04 to 06*	None Detected	N/A	N/A	Red caulking, Boiler #2 *From Fisher Project No. 18-8763, dated April 2018


APPENDIX II

RESULTS OF BULK SAMPLE ANALYSIS

(NO INFORMATION TO REPORT)

APPENDIX III

SITE DRAWINGS



Legend



Asbestos-Containing Material



Location Number



No Access to Room

The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 1

LOCATION:

9 Neilson Road
Toronto, Ontario

BUILDING NAME:

SEVEN OAKS

Basement Floor Plan Asbestos-Containing Material Locations

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800	DATE: June 2023	DRW BY: ZA
-------------------------------	-----------------	------------


CAD FILE: FIG1	SCALE: Not to Scale	CHK BY: RS
----------------	---------------------	------------





Legend

-  Asbestos-Containing Material
-  Location Number
-  No Access to Room
-  Area Not Surveyed
-  Under Construction



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 2

LOCATION:
9 Neilson Road
Toronto, Ontario

BUILDING NAME:
SEVEN OAKS

Ground Floor Plan
Asbestos-Containing Material Locations

CLIENT: City of Toronto


PROJECT NUMBER: FE-P 23-12800 **DATE:** June 2023 **DRW BY:** ZA

CAD FILE: FIG2 **SCALE:** Not to Scale **CHK BY:** RS






Legend



Asbestos-Containing Material



Location Number



No Access to Room

The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.




Figure 4

LOCATION:
9 Neilson Road
Toronto, Ontario

BUILDING NAME:
SEVEN OAKS

Level 3 Floor Plan Asbestos-Containing Material Locations

CLIENT: City of Toronto


PROJECT NUMBER: FE-P 23-12800 **DATE:** June 2023 **DRW BY:** DC

CAD FILE: FIG4 **SCALE:** Not to Scale **CHK BY:** RS






Legend




Asbestos-Containing Material



Location Number

NAR

No Access to Room



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 5

LOCATION:
9 Neilson Road
Toronto, Ontario

BUILDING NAME:
SEVEN OAKS

Level 4 Floor Plan Asbestos-Containing Material Locations

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800 **DATE:** June 2023 **DRW BY:** DC

CAD FILE: FIG5 **SCALE:** Not to Scale **CHK BY:** RS





Legend




Asbestos-Containing Material



Location Number

NAR

No Access to Room



The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 6

LOCATION:
9 Neilson Road
Toronto, Ontario

BUILDING NAME:
SEVEN OAKS


Level 5 Floor Plan Asbestos-Containing Material Locations

CLIENT: City of Toronto



PROJECT NUMBER: FE-P 23-12800 **DATE:** June 2023 **DRW BY:** DC

CAD FILE: FIG6 **SCALE:** Not to Scale **CHK BY:** RS





Legend

-  Asbestos-Containing Material
-  Location Number
-  No Access to Room

The drawing does not illustrate locations of drywall joint compound, plaster, window caulking or roofing materials, for reasons discussed in Section 6 of the Standard Operating Procedure for Designated Substance Surveys. Please refer to the Designated Substance Survey Form in Appendix I for information regarding the locations and asbestos or lead-content of these materials.

Figure 7

LOCATION:
9 Neilson Road
Toronto, Ontario

BUILDING NAME:
SEVEN OAKS

Penthouse Floor Plan Asbestos-Containing Material Locations

CLIENT: City of Toronto

PROJECT NUMBER: FE-P 23-12800	DATE: June 2023	DRW BY: DC
--------------------------------------	------------------------	-------------------

CAD FILE: FIG7	SCALE: Not to Scale	CHK BY: RS
-----------------------	----------------------------	-------------------



APPENDIX IV

SITE PHOTOGRAPHS

(NO INFORMATION TO REPORT)

APPENDIX V

CORRECTIVE ACTIONS INSPECTION REPORT



September 6, 2023

City of Toronto, Corporate Real Estate Management
Metro Hall, 55 John Street
Toronto ON, M5V 3C6

Inder Bhamra, EP, PMP, CSM
Environmental Coordinator

Re: Level I Mould Abatement at Long Term Care Home, 9 Neilson Road, Toronto, ON

As requested, Fisher Engineering Limited (Fisher) has provided environmental monitoring services with respect to mould abatement activities recently undertaken at Seven Oaks Long Term Care Home, located at 9 Neilson Road, Toronto, Ontario (the "Site"). Mould remediation was initiated following the discovery of mould impacted and water-stained non-asbestos-containing ceiling tiles during the Annual Survey, conducted on May 25, 2023, Fisher Project No. FE 23-12800.

The City of Toronto retained Fisher as the environmental health and safety consultant to provide project monitoring. Fisher retained Furcon Environmental Inc. as the environmental contractor to undertake the specified remedial action. Abatement work was conducted in accordance with Level 1 mould remediation protocols, as outlined by the Environmental Abatement Council of Canada (EACC) Mould Abatement Guidelines, Edition 3 (2015). The fieldwork was conducted on September 6, 2023.

Based on the recommendations provided in a corrective action reporting form, the ceiling tiles were removed from the rooms listed below, following Level 1 Mould Remediation Procedures, and replaced with new tiles.

Corridor, B-008
Lounge, 4-046

Lounge, 3-046
Lounge, 2-020

Based on the Site observation, the remediation scope of work was completed and the work area was cleaned to an acceptable level.

Respectfully submitted,

Prepared by:

Reviewed by:


Yvonne Hoogeveen, P. Eng.
Project Manager

David A. Fisher, B.A.Sc., C.Chem., P.Eng.
Principal

Attachment A – Site Photos



Before abatement



After Abatement



Before abatement



After Abatement



Before abatement



After Abatement