



Toned services indicated in blue overlay.

Blue painter tape was used to mark location of each service. Depths were observed to range from 5"-12". Tape was labelled with conduit sources.

There were still embedded objects that were visible in GPR data, that were not located using induction clamping.

Area in storage room was not GPR scanned due to shelving in place full of materials. There were red markings from a previous locate on area in storage room. Previously trenched area marked on drawing, one pass of GPR data was collected at end of shelves and two objects were visible in GPR data.

Given congestion of services, and soil composition below slab, GPR data into grade is adversely affected.