

Yellow denotes area previously trenched. GPR data poor into grade due to soil compaction, multiple objects observed in previously trenched area.

Due to office furniture and walls it was difficult to get whole trench path scanned.

Multiple data conduit were both visible on GPR data and toned. They were observed embedded in slab in patient waiting area.

